HistoricBridges.org - National Bridge Inventory Data Sheet

The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Info	ormation									47-40-39.99 =	117-21-49.53		
Washingto	on [53]	Spokane Cour	nty [063]	Spokar	Spokane [67000] 1.65 N OF I-90					47.677775	= -117.363758		
85146000	0000000	Highway	agency district 6	Owner	City or Municip	oal Highway A	Highway Agency [04] Maintenance responsibility				City or Municipal Highway Agency [04]		
Route 80)2		GREENE STREET		Toll On f	ree road [3]		eatures interse	ected SPOKANE	RIV,UPRIVER DR			
main	Concrete [1 Arch - Deck		approach	Concrete [1] Slab [01]		Year built Skew angl	1955 e 17	Structure I	econstructed 199	e for the NRHP. [3]			
Total length 132.3 m = 434.1 ft Length of maximum span 40.5 m = 132.9 ft Deck width, out-to-out 21.5 m = 70.5 ft Bridge roadway width, cur Inventory Route, Total Horizontal Clearance 8.1 m = 26.6 ft Curb or sidewalk width - left 1.6 m = 5.2 ft Curb or sidewalk width - rig								dway width, curb-to-cu	16.1 m = 52.8 ft 1.6 m = 5.2 ft				
Deck struc	cture type		Concrete Cast-	in-Place [1]									
Type of we	earing surfac	ce	Latex Concrete	or similar addi	tive [3]								
·	Deck protection Type of membrane/wearing surface												
Weight Li	mits												
J.	Bypass, detour length 0.8 km = 0.5 mi Method to dete			Ü	Load Factor(LF) [1] Load Factor(LF) [1]			ventory rating perating rating	18 metric ton = 29.7 metric ton				
Bridge postin			ting Equal to or al	g Equal to or above legal loads [5]				Design Load MS 18 / HS 20 [5]					

Functional Details										
Average Daily Traffic 41500 Average daily tr	uck traffi 7 % Year 2010 Future average daily traffic	54199 Year 2032								
Road classification Other Principal Arterial (Urban)	[14] Lanes on structure 4	Approach roadway width 14.6 m = 47.9 ft								
Type of service on bridge Highway-pedestrian [5] Direction of traffic 2 - way traffic [2] Bridge median Closed median with non-										
Parallel structure designation No parallel structure	exists. [N]									
Type of service under bridge Highway-waterway [6]	Lanes under structure 4 Navigation control									
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A									
Minimum navigation vertical clearance, vertical lift brid	dge Minimum vertical clearar	nce over bridge roadway 99.99 m = 328.1 ft								
Minimum lateral underclearance reference feature H	ghway beneath structure [H]									
Minimum lateral underclearance on right 2.7 m = 8.9	ft Minimum lateral underclear	rance on left 0 = N/A								
Minimum Vertical Underclearance 4.32 m = 14.2 ft	Minimum vertical underclearance reference featu	ure Highway beneath structure [H]								
Appraisal ratings - underclearances Meets minimum	tolerable limits to be left in place as is [4]									
Don't and Don't arranged Plans										
Repair and Replacement Plans										
Type of work to be performed	Work done by Work to be done by contract [1]									
Bridge rehabilitation because of general structure deterioration or inadequate strength. [35]	Bridge improvement cost 240000 Roadway impr	rovement cost 24000								
Length of structure improvement 132.3 m = 434.1 ft Total project cost 360000										
	Year of improvement cost estimate 2013									
	Border bridge - state Bord	der bridge - percent responsibility of other state								
	Border bridge - structure number									

Inspection and Sufficiency										
Structure status Posted for loa	d [P]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]							
Condition ratings - superstructure	Good [7]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]							
Condition ratings - substructure	Good [7]	Appraisal ratings -	Meets minimum tolerable limits to be left in place as is [4]							
Condition ratings - deck	Good [7]	deck geometry								
Scour	Countermeasures have	ountermeasures have been installed to mitigate an existing problem with scour. [7]								
Channel and channel protection	Bank protection is in ne Banks and/or channel	eed of minor repairs. River cont have minor amounts of drift. [7]	rol devices and embankment protection have a little minor damage.							
Appraisal ratings - water adequacy	Equal to present desira	able criteria [8]	Status evaluation							
Pier or abutment protection			Sufficiency rating 46.2							
Culverts Not applicable. Used if structure is not a culvert. [N]										
Traffic safety features - railings	Inpect	ed feature meets currently acce	ptable standards. [1]							
Traffic safety features - transitions										
Traffic safety features - approach	guardrail Inpect	ed feature meets currently acce	ptable standards. [1]							
Traffic safety features - approach	guardrail ends Inpect	ed feature meets currently acce	ptable standards. [1]							
Inspection date October 2012	[1012] Designate	d inspection frequency 24	Months							
Underwater inspection L	Inknown [Y60]	Underwater inspec	August 2013 [0813]							
Fracture critical inspection	lot needed [N]	Fracture critical ins	spection date							
Other special inspection	lot needed [N]	Other special insp	ection date							

BRIDGE INSPECTION REPORT

Ver Date: 01/27/2014

Agency: SPOKANE

Status: Released Printed On: 09/30/20 Program Mgr: Roman G. Peralta

Bridge No. 533000802 Page: 1/3 Structure Type

Bridge Name GREENE ST OC SPOKANE R. Route 00802 Location 1.65 N OF I-90

Structure ID 08514600 MilePost 1.19 Intersecting SPOKANE RIV, UPRIVER DR

Inspector's Signature JEM IDent# G0608 Co-Inspector's Signature **Inspections Performed** Structural Adqcy Pier/Abut/Protect 4 (657)Ν (679)1955 Year Built (332)IT NT HRS **Date** Rep Type 4 **Deck Geometry** (658)7 Scour (680)1999 Year Rebuilt (336)Υ 24 8.0 10/17/2012 Routine 4 Underclearance (659)7 Retaining Walls (682)33 Oper Rating (551)Fract Crit 5 Operating Level (660)9 Pier Protection (683)20 Inv Rating (554)D 60 1.5 08/13/2013 Underwater Ρ 8 Alignment Adqcy (661)1 Bridge Rails Open Close (293)(684)Special 8 WaterwayAdqcy (662)0 Transition (685) 9999 Vert Over Deck (360)Interim 7 Deck Overall Guardrails 1402 Vert Under (663)1 (686)(374)Equipment 9 **Drains Condition** (664)1 Terminals (687)Н Vert Und Code (378)Damage 7 Superstructure (671)Ν Revise Rating (688)0.00 Asphalt Depth Safety Number Utilities 35 Speed Limit (675)Photos Flag (691)Short Span 4 Substructure (693)Total: 1.0 7 (676)Soundings Flag Chan/Protection 7 (677)Measure Clearance (694)9 Culvert (678)Suff Rating: 46.23 66.00

	BMS Elements										
Element	Element Description	Total	Units	State 1	State 2	State 3	State 4				
12	Concrete Deck	19219	SF	19179	40	0	0				
35	Concrete Deck Soffit	19219	SF	19219	0	0	0				
116	Concrete Stringer	1820	LF	1820	0	0	0				
144	Concrete Arch	1092	LF	1084	8	0	0				
205	Concrete Pile/Column	72	EA	63	8	1	0				
210	Concrete Pier Wall	102	LF	102	0	0	0				
215	Concrete Abutment	140	LF	132	8	0	0				
234	Concrete Pier Cap / Crossbeam	2193	LF	2143	50	0	0				
310	Elastomeric Bearing	42	EA	42	0	0	0				
321	Concrete Roadway Approach Slab	2	SF	0	2	0	0				
330	Metal Bridge Railing	728	LF	728	0	0	0				
331	Concrete Bridge Railing	728	LF	728	0	0	0				

BRIDGE INSPECTION REPORT

Ver Date: 01/27/2014

Agency: SPOKANE

Status: Released Printed On: 09/30/20 Program Mgr: Roman G. Peralta

Structure ID 08514600 MilePost 1.19 Intersecting SPOKANE RIV,UPRIVER DR	Bridge	No.	533000802	Page:	2/3	Stru	cture Type						
405 Compression Seal / Polymer Header 317 LF 317 0 0 0 0 417 Silicone Rubber Joint Filler 422 LF 422 0 0 0 0 803 Modified Concrete Overlay 19219 SF 19199 20 0 0 Notes The bridge is oriented from the south to the north. The temperature at the time of the inspection was 51 degrees. 9 The WSDOT BPO Dive Team performed the underwater inspection of the Greene Street Bridge, over Spokane River on August 13, 2013. Bridge is oriented south and north. Piers 2 and 3 are in the channel. Complete Final Dive report under the Files tab. 12 The deck is covered by a concrete overlay. 35 There are a few light cracks in the deck soffit near the pier caps. 16 The columns under the joints are water-stained and developing cracks. 210 215 The abutment joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. 224 There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. 310 321 The appproach slabs have some cracking, but the pavement surface remains smooth and even. 330 The grout is missing from under the bases of some of the posts on the pedestrian railing. 405 The compression seals are leaking and there is some cracking in the joint headers. 417 The poured rubber joints are beginning to leak	Bridge	Nar	ne Greene St oc spokane R.	Route	00802	Loca	ation	1.65 N OF I-90					
417 Silicone Rubber Joint Filler 422 LF 422 0 0 0 0 0 803 Modified Concrete Overlay 19219 SF 19199 20 0 0 0 0 Notes Notes 0 The bridge is oriented from the south to the north. The temperature at the time of the inspection was 51 degrees. 9 The WSDOT BPO Dive Team performed the underwater inspection of the Greene Street Bridge, over Spokane River on August 13, 2013. Bridge is oriented south and north. Piers 2 and 3 are in the channel. Complete Final Dive report under the Files tab. 12 The deck is covered by a concrete overlay. 35 There are a few light cracks in the deck soffit near the pier caps. 118 119 119 110 110 111 111 112 114 115 116 117 117 118 118 119 119 119 119	Structu	ıre I	D 08514600	MilePo	st 1.19	Intersecting SPOKANE RIV,I				,UPRIVER DR			
417 Silicone Rubber Joint Filler 422 LF 422 0 0 0 0 0 803 Modified Concrete Overlay 19219 SF 19199 20 0 0 0 0 Notes Notes 0 The bridge is oriented from the south to the north. The temperature at the time of the inspection was 51 degrees. 9 The WSDOT BPO Dive Team performed the underwater inspection of the Greene Street Bridge, over Spokane River on August 13, 2013. Bridge is oriented south and north. Piers 2 and 3 are in the channel. Complete Final Dive report under the Files tab. 12 The deck is covered by a concrete overlay. 35 There are a few light cracks in the deck soffit near the pier caps. 118 119 119 110 110 111 111 112 114 115 116 117 117 118 118 119 119 119 119					Ţ		T	Γ					
Notes Notes 19219 SF 19199 20 0 0 Notes 1 The bridge is oriented from the south to the north. The temperature at the time of the inspection was 51 degrees. 9 The WSDOT BPO Dive Team performed the underwater inspection of the Greene Street Bridge, over Spokane River on August 13, 2013. Bridge is oriented south and north. Piers 2 and 3 are in the channel. Complete Final Dive report under the Files tab. 12 The deck is covered by a concrete overlay. 35 There are a few light cracks in the deck soffit near the pier caps. 116 144 205 The columns under the joints are water-stained and developing cracks. 210 215 The abutment joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. 234 There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. 310 310 311 312 The appproach slabs have some cracking, but the pavement surface remains smooth and even. 330 The grout is missing from under the bases of some of the posts on the pedestrian railing. 331 405 The compression seals are leaking and there is some cracking in the joint headers. 417 The poured rubber joints are beginning to leak	4	405	Compression Seal / Polymer Header		317	LF	317	0	0	0			
Notes The bridge is oriented from the south to the north. The temperature at the time of the inspection was 51 degrees. The WSDOT BPO Dive Team performed the underwater inspection of the Greene Street Bridge, over Spokane River on August 13, 2013. Bridge is oriented south and north. Piers 2 and 3 are in the channel. Complete Final Dive report under the Files tab. The deck is covered by a concrete overlay. There are a few light cracks in the deck soffit near the pier caps. The columns under the joints are water-stained and developing cracks. The abutment joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. The grout is missing from under the bases of some of the posts on the pedestrian railing. The compression seals are leaking and there is some cracking in the joint headers. The poured rubber joints are beginning to leak	4	417	Silicone Rubber Joint Filler		422	LF	422	0	0	0			
The bridge is oriented from the south to the north. The temperature at the time of the inspection was 51 degrees. The WSDOT BPO Dive Team performed the underwater inspection of the Greene Street Bridge, over Spokane River on August 13, 2013. Bridge is oriented south and north. Piers 2 and 3 are in the channel. Complete Final Dive report under the Files tab. The deck is covered by a concrete overlay. There are a few light cracks in the deck soffit near the pier caps. The columns under the joints are water-stained and developing cracks. The columns under the joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. The appproach slabs have some cracking, but the pavement surface remains smooth and even. The grout is missing from under the bases of some of the posts on the pedestrian railling. The poured rubber joints are beginning to leak The poured rubber joints are beginning to leak	8	803	Modified Concrete Overlay	19199	20	0	0						
The WSDOT BPO Dive Team performed the underwater inspection of the Greene Street Bridge, over Spokane River on August 13, 2013. Bridge is oriented south and north. Piers 2 and 3 are in the channel. Complete Final Dive report under the Files tab. The deck is covered by a concrete overlay. There are a few light cracks in the deck soffit near the pier caps. There are a few light cracks in the deck soffit near the pier caps. The columns under the joints are water-stained and developing cracks. The abutment joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. The appproach slabs have some cracking, but the pavement surface remains smooth and even. The grout is missing from under the bases of some of the posts on the pedestrian railing. The poured rubber joints are beginning to leak The poured rubber joints are beginning to leak		Notes											
on August 13, 2013. Bridge is oriented south and north. Piers 2 and 3 are in the channel. Complete Final Dive report under the Files tab. 12 The deck is covered by a concrete overlay. 35 There are a few light cracks in the deck soffit near the pier caps. 116 144 205 The columns under the joints are water-stained and developing cracks. 210 215 The abutment joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. 234 There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. 310 321 The appproach slabs have some cracking, but the pavement surface remains smooth and even. 330 The grout is missing from under the bases of some of the posts on the pedestrian railing. 331 405 The compression seals are leaking and there is some cracking in the joint headers. 417 The poured rubber joints are beginning to leak	0	The bridge is oriented from the south to the north. The temperature at the time of the inspection was 51 degrees.											
There are a few light cracks in the deck soffit near the pier caps. There are a few light cracks in the deck soffit near the pier caps. The columns under the joints are water-stained and developing cracks. The abutment joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. The appproach slabs have some cracking, but the pavement surface remains smooth and even. The grout is missing from under the bases of some of the posts on the pedestrian railing. The compression seals are leaking and there is some cracking in the joint headers. The poured rubber joints are beginning to leak	9	on August 13, 2013. Bridge is oriented south and north. Piers 2 and 3 are in the channel. Complete Final Dive report											
116 144 205 The columns under the joints are water-stained and developing cracks. 210 215 The abutment joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. 234 There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. 310 321 The appproach slabs have some cracking, but the pavement surface remains smooth and even. 330 The grout is missing from under the bases of some of the posts on the pedestrian railing. 331 405 The compression seals are leaking and there is some cracking in the joint headers. 417 The poured rubber joints are beginning to leak	12	The	e deck is covered by a concrete overlay	·.									
144 205 The columns under the joints are water-stained and developing cracks. 210 215 The abutment joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. 234 There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. 310 321 The appproach slabs have some cracking, but the pavement surface remains smooth and even. 330 The grout is missing from under the bases of some of the posts on the pedestrian railing. 331 405 The compression seals are leaking and there is some cracking in the joint headers. 417 The poured rubber joints are beginning to leak	35												
The columns under the joints are water-stained and developing cracks. The abutment joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. The appproach slabs have some cracking, but the pavement surface remains smooth and even. The grout is missing from under the bases of some of the posts on the pedestrian railing. The compression seals are leaking and there is some cracking in the joint headers. The poured rubber joints are beginning to leak	116												
210 215 The abutment joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. 234 There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. 310 321 The appproach slabs have some cracking, but the pavement surface remains smooth and even. 330 The grout is missing from under the bases of some of the posts on the pedestrian railing. 331 405 The compression seals are leaking and there is some cracking in the joint headers. 417 The poured rubber joints are beginning to leak	144												
The abutment joints have been leaking, but no new spalling was noted. The open areas behind the abutment walls were inspected via an unused utility block-out. The water main is still shut down. There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. The appproach slabs have some cracking, but the pavement surface remains smooth and even. The grout is missing from under the bases of some of the posts on the pedestrian railing. The compression seals are leaking and there is some cracking in the joint headers. The poured rubber joints are beginning to leak	205	The	e columns under the joints are water-st	ained and	d developing	cracks							
were inspected via an unused utility block-out. The water main is still shut down. 234 There is a crack at the top of most pier caps at the apparent construction joint where the pier cap joins the deck. There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. 310 321 The appproach slabs have some cracking, but the pavement surface remains smooth and even. 330 The grout is missing from under the bases of some of the posts on the pedestrian railing. 331 405 The compression seals are leaking and there is some cracking in the joint headers. 417 The poured rubber joints are beginning to leak	210												
There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs, some of which are beginning to break up. 310 321 The appproach slabs have some cracking, but the pavement surface remains smooth and even. 330 The grout is missing from under the bases of some of the posts on the pedestrian railing. 331 405 The compression seals are leaking and there is some cracking in the joint headers. 417 The poured rubber joints are beginning to leak 681	215								d the abutn	ient walls			
The appproach slabs have some cracking, but the pavement surface remains smooth and even. The grout is missing from under the bases of some of the posts on the pedestrian railing. The compression seals are leaking and there is some cracking in the joint headers. The poured rubber joints are beginning to leak	234	There are vertical, hairline cracks in the pier caps at the columns. The pier caps at the joints have previous repairs,											
The grout is missing from under the bases of some of the posts on the pedestrian railing. The compression seals are leaking and there is some cracking in the joint headers. The poured rubber joints are beginning to leak 681	310												
331 405 The compression seals are leaking and there is some cracking in the joint headers. 417 The poured rubber joints are beginning to leak 681	321	The	e appproach slabs have some cracking,	but the p	oavement su	rface re	emains smoo	th and even	l.				
The compression seals are leaking and there is some cracking in the joint headers. The poured rubber joints are beginning to leak 681	330	The grout is missing from under the bases of some of the posts on the pedestrian railing.											
417 The poured rubber joints are beginning to leak 681	331												
681	405	The compression seals are leaking and there is some cracking in the joint headers.											
	417	The	e poured rubber joints are beginning to	leak									
803 Cracking in the overlay is beginning to form grid patterns	681												
	803	Cra	acking in the overlay is beginning to for	m grid pa	itterns								

Repairs

BRIDGE INSPECTION REPORT

Ver Date: 01/27/2014

Agency: SPOKANE

Status: Released Printed On: 09/30/20 Program Mgr: Roman G. Peralta

Bridge No. 533000802 Page: 3/3 Structure Type

Bridge Name GREENE ST OC SPOKANE R. Route 00802 Location 1.65 N OF I-90

Structure ID 08514600 MilePost 1.19 Intersecting SPOKANE RIV, UPRIVER DR

Repair No	Pr	R	Repair Description	Noted	Maint	Verified

		I	nspe	ection	ıs Pei	form	ned a	nd Res	sources Required
Report Type	<u>Date</u>	<u>IT</u>	<u>Frq</u>	<u>Hrs</u>	<u>Insp</u>	Ce	rtNo	Coinsp	<u>Note</u>
Routine	10/17/12		24	8.0	JEM	GC	809	LAM	Ubit used in 2010 inspection. 6.5 Hrs Next high cost 2012.
Resource	s		Use	Hour	Min	Req	Max	[Notes
UBIT			50	4.50					
Bucket									
Underwater	08/13/13	D	60	1.5	DON	GC	314	MBS	Underwater Inspection performed by WSDOT Dive Team.9/6/2013Entered only Inspection Date, Hours, Inspectors' Initials and any data modified by the inspector on the NBI or WB71 through WB75 panels (as indicated of the BPO WSBIS Inventory Report). BDJ
Resource	s		Use	Hour	Min	Req	Max	1	Notes
Informational	01/16/14			1.0	JEM	GC	0608		Greene St Bridge was strengthen for shear and moment with FRP in fall of 2013.
Resource	s		Use	Hour	Min	Req	Max	(Notes