

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

| | | | | | |
|---|--|--|------------------------------------|----------------------------|----------------------|
| Michigan [26] | Saginaw County [145] | Buena Vista [11560] | 0.3 MI N OF BECKER ROAD | 00-00-00 = 0.000000 | 000-00-00 = 0.000000 |
| 73200140000B010 | Highway agency district 4 | Owner County Highway Agency [02] | Maintenance responsibility | County Highway Agency [02] | |
| Route 7379 | PORTSMOUTH RD | Toll On free road [3] | Features intersected | CHEBOYGANING CREEK | |
| Design - main Concrete [1] | Design - approach Steel [3] | Kilometerpoint 0 km = 0.0 mi | Year built 1921 | Year reconstructed 1930 | |
| 1 Arch - Deck [11] | 1 Stringer/Multi-beam or girder [02] | Skew angle 30 | Structure Flared | | |
| | | Historical significance | Bridge is on the NRHP. [1] | | |
| Total length 38.1 m = 125.0 ft | Length of maximum span 21.3 m = 69.9 ft | Deck width, out-to-out 8.6 m = 28.2 ft | Bridge roadway width, curb-to-curb | 7.3 m = 24.0 ft | |
| Inventory Route, Total Horizontal Clearance 7.3 m = 24.0 ft | Curb or sidewalk width - left 0 m = 0.0 ft | Curb or sidewalk width - right | 0 m = 0.0 ft | | |
| Deck structure type | Concrete Cast-in-Place [1] | | | | |
| Type of wearing surface | Bituminous [6] | | | | |
| Deck protection | | | | | |
| Type of membrane/wearing surface | | | | | |

Weight Limits

| | | | | |
|---------------------------------------|--------------------------------------|--------------------------|-------------------|-----------------------------|
| Bypass, detour length 0.3 km = 0.2 mi | Method to determine inventory rating | Allowable Stress(AS) [2] | Inventory rating | 10.9 metric ton = 12.0 tons |
| | Method to determine operating rating | Allowable Stress(AS) [2] | Operating rating | 30.9 metric ton = 34.0 tons |
| Bridge posting | | Design Load | M 13.5 / H 15 [2] | |

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

| | | | |
|---|---|---------------------------------------|--|
| Structure status | Posted for load [P] | Appraisal ratings - structural | Basically intolerable requiring high priority of corrective action [3] |
| Condition ratings - superstructure | Fair [5] | Appraisal ratings - roadway alignment | Equal to present desirable criteria [8] |
| Condition ratings - substructure | Poor [4] | Appraisal ratings - deck geometry | Meets minimum tolerable limits to be left in place as is [4] |
| Condition ratings - deck | Fair [5] | | |
| Scour | Scour calculation/evaluation has not been made. [6] | | |
| Channel and channel protection | Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6] | | |
| Appraisal ratings - water adequacy | Basically intolerable requiring high priority of corrective action [3] | Status evaluation | Structurally deficient [1] |
| Pier or abutment protection | | Sufficiency rating | 14.9 |
| Culverts | Not applicable. Used if structure is not a culvert. [N] | | |
| Traffic safety features - railings | Inspected feature meets currently acceptable standards. [1] | | |
| Traffic safety features - transitions | Inspected feature meets currently acceptable standards. [1] | | |
| Traffic safety features - approach guardrail | Inspected feature meets currently acceptable standards. [1] | | |
| Traffic safety features - approach guardrail ends | | | |
| Inspection date | January 1998 [0198] | Designated inspection frequency | 24 Months |
| Underwater inspection | Unknown [N24] | Underwater inspection date | |
| Fracture critical inspection | Unknown [N24] | Fracture critical inspection date | |
| Other special inspection | Unknown [N24] | Other special inspection date | |