The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information							39-08-51 =	086-24-26 = -
Indiana [18] Monroe County [105]		Unknown [00000] 0.5 S of SR 46				39.147500	86.407222	
5300110 Highway agency district 5		Owner County Highway	Agency [02]	Maintenance	responsibility	County Highway A	Agency [02]	
Route 11 FRIENDSHIP Rd			Toll On fre	e road [3]	eatures intersed	ted STEPHENS	Creek	
Design - main Truss - Thru [7]	10]	Design - approach Other	[00]	Kilometerpoint 0 km Year built #Num! Skew angle 0 Historical significance	Structure F		not determinable at t	his time. [4]
Total length $30.5 \text{ m} = 1$	00.1 ft Leng	yth of maximum spa	29.9 m = 98.1 ft	Deck width, out-to-ou				curb 4.3 m = 14.1 ft
Inventory Route, Total Horizontal Clearance 4.3 m = 14.1 ft			Curb or sidewalk wi	Curb or sidewalk width - left 0 m = 0.0 ft Curb or side			walk width - right	0 m = 0.0 ft
Deck structure type Type of wearing surface	Ор	en Grating [3]						
Deck protection								
Type of membrane/weari	ing surface							
Weight Limits								
Bypass, detour length Method to determine inventory rating		Allowable Stress(AS)	[2] Inve	entory rating	17.1 metric ton =	= 18.8 tons		
1.4 km = 0.9 mi Method to determine operating rating			Allowable Stress(AS)) [2] Ope	erating rating	24.3 metric ton =	26.7 tons	
Bridge posting 10.0 - 19.9 % below [3]					sign Load		_	

Functional Details							
Average Daily Traffic 318 Average daily tr	uck traffi 5 % Year 2008 Future average daily traffic 428 Year 2028						
Road classification Local (Rural) [09]	Lanes on structure 1 Approach roadway width 3 m = 9.8 ft						
Type of service on bridge Highway [1]	Direction of traffic One lane bridge for 2 - way traffic [3] Bridge median						
Parallel structure designation No parallel structure	e exists. [N]						
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control						
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway 4.78 m = 15.7 ft							
Minimum lateral underclearance reference feature Feature not a highway or railroad [N]							
Minimum lateral underclearance on right 99.9 = Unlimited Minimum lateral underclearance on left 0 = N/A							
Minimum Vertical Underclearance 0 = N/A Minimum vertical underclearance reference feature Feature not a highway or railroad [N]							
Appraisal ratings - underclearances N/A [N]							
Danair and Danlagament Dlang							
Repair and Replacement Plans	W						
Type of work to be performed	Work done by Work to be done by contract [1]						
Replacement of bridge or other structure because of substandard load carrying capacity or substantial	Bridge improvement cost 275000 Roadway improvement cost 100000						
bridge roadway geometry. [31]	Length of structure improvement 38.7 m = 127.0 ft Total project cost 375000						
	Year of improvement cost estimate 2008						
	Border bridge - state Border bridge - percent responsibility of other state						
	Border bridge - structure number						

Inspection and Sufficiency									
Structure status Posted for lo	ad [P]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]						
Condition ratings - superstructur	Poor [4]	Appraisal ratings - roadway alignment	Basically intolerable requiring high priority of corrrective action [3]						
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings -	Basically intolerable requiring high priority of replacement [2]						
Condition ratings - deck	Very Good [8]	deck geometry							
Scour	Bridge with "unknown" founda	Bridge with "unknown" foundation that has not been evaluated for scour. [U]							
Channel and channel protection	Bank is beginning to slump. If minor stream bed movement	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]							
Appraisal ratings - water adequac	Meets minimum tolerable limi	Meets minimum tolerable limits to be left in place as is [4] Status evaluation							
Pier or abutment protection			Sufficiency rating 27.2						
Culverts Not applicable. Used	if structure is not a culvert. [N]								
Traffic safety features - railings									
Traffic safety features - transition	ns								
Traffic safety features - approach	n guardrail								
Traffic safety features - approach guardrail ends									
Inspection date March 2008 [0308] Designated inspection frequency 24 Months									
Underwater inspection	Not needed [N]	Underwater inspec	ection date						
Fracture critical inspection	Every two years [Y24]	Fracture critical in:	nspection date May 2008 [0508]						
Other special inspection	Not needed [N]	Other special insp	pection date						