

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Indiana [18]	Tippecanoe County [157]	Unknown [00000]	00.60 N OLD SR 25	40-29-43.87 = 40.495519	086-49-23.84 = -86.823289
29150	Highway agency district: 1	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 225	SR 225	Toll On free road [3]	Features intersected	WABASH RIVER	
Design - main	Steel [3]	Design - approach		Kilometerpoint	96.5 km = 59.8 mi
4	Truss - Thru [10]	0	Other [00]	Year built	1912
				Year reconstructed	1989
				Skew angle	0
				Structure Flared	
				Historical significance	Bridge is eligible for the NRHP. [2]
Total length	195.7 m = 642.1 ft	Length of maximum span	48.2 m = 158.1 ft	Deck width, out-to-out	4.7 m = 15.4 ft
Bridge roadway width, curb-to-curb	4.4 m = 14.4 ft	Inventory Route, Total Horizontal Clearance	4.4 m = 14.4 ft	Curb or sidewalk width - left	0.2 m = 0.7 ft
				Curb or sidewalk width - right	0.2 m = 0.7 ft
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Monolithic Concrete (concurrently placed with structural deck) [1]				
Deck protection	Epoxy Coated Reinforcing [1]				
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	19 metric ton = 20.9 tons
0.6 km = 0.4 mi	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	27.2 metric ton = 29.9 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	M 18 / H 20 [4]	

Functional Details

Average Daily Traffic	960	Average daily truck traffi	8 %	Year	2009	Future average daily traffic	1594	Year	2033
Road classification	Major Collector (Rural) [07]	Lanes on structure	1	Approach roadway width	5.5 m = 18.0 ft				
Type of service on bridge	Highway [1]	Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]								
Type of service under bridge	Waterway [5]	Lanes under structure	0	Navigation control					
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A					
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	4.57 m = 15.0 ft					
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]								
Minimum lateral underclearance on right	0 = N/A			Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]					
Appraisal ratings - underclearances	N/A [N]								

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]					
Bridge rehabilitation because of general structure deterioration or inadequate strength. [35]	Bridge improvement cost	1065000	Roadway improvement cost	0			
	Length of structure improvement	195.7 m = 642.1 ft	Total project cost	1065000			
	Year of improvement cost estimate						
	Border bridge - state		Border bridge - percent responsibility of other state				
	Border bridge - structure number						

Inspection and Sufficiency

Structure status	Posted for other load-capacity restriction [R]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - superstructure	Poor [4]	Appraisal ratings - roadway alignment	Basically intolerable requiring high priority of corrective action [3]
Condition ratings - substructure	Fair [5]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Good [7]		
Scour	Countermeasures have been installed to mitigate an existing problem with scour. [7]		
Channel and channel protection	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]		
Appraisal ratings - water adequacy	Better than present minimum criteria [7]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	32.8
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	May 2015 [0515]	Designated inspection frequency	12 Months
Underwater inspection	Unknown [Y60]	Underwater inspection date	April 2014 [0414]
Fracture critical inspection	Every year [Y12]	Fracture critical inspection date	May 2015 [0515]
Other special inspection	Not needed [N]	Other special inspection date	