

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26] Berrien County [021] Benton Harbor [07520] 5 BLKS NO. OF MAIN ST. 42-07-15 = 42.120833 086-27-16 = - 86.454444

114063000115B01 Highway agency district 5 Owner City or Municipal Highway Agency [04] Maintenance responsibility City or Municipal Highway Agency [04]

Route 2013 NO. SHORE DR Toll On free road [3] Features intersected OX CREEK

Design - main Concrete continuous [2] Design - approach Steel [3] Kilometerpoint 174.5 km = 108.2 mi

2 Culvert [19] 1 Culvert [19] Year built 1939 Year reconstructed N/A [0000]

Skew angle 0 Structure Flared

Historical significance Bridge is not eligible for the NRHP. [5]

Total length 7.6 m = 24.9 ft Length of maximum span 2.7 m = 8.9 ft Deck width, out-to-out 20.8 m = 68.2 ft Bridge roadway width, curb-to-curb 11 m = 36.1 ft

Inventory Route, Total Horizontal Clearance 10.9 m = 35.8 ft Curb or sidewalk width - left 1.5 m = 4.9 ft Curb or sidewalk width - right 1.5 m = 4.9 ft

Deck structure type Concrete Cast-in-Place [1]

Type of wearing surface Bituminous [6]

Deck protection

Type of membrane/wearing surface

Weight Limits

Bypass, detour length 0.2 km = 0.1 mi Method to determine inventory rating Load Factor(LF) [1] Inventory rating 26.4 metric ton = 29.0 tons

Method to determine operating rating Load Factor(LF) [1] Operating rating 42.7 metric ton = 47.0 tons

Bridge posting Equal to or above legal loads [5] Design Load M 18 / H 20 [4]

Functional Details

Average Daily Traffic	3900	Average daily truck traffi	4	%	Year	1984	Future average daily traffic	5000	Year	2011
Road classification	Collector (Urban) [17]	Lanes on structure	2		Approach roadway width	20.7 m = 67.9 ft				
Type of service on bridge	Highway-pedestrian [5]	Direction of traffic	2 - way traffic [2]		Bridge median					
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]	Lanes under structure	0		Navigation control					
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	147000	Roadway improvement cost							
	Length of structure improvement	9.1 m = 29.9 ft		Total project cost	150000					
	Year of improvement cost estimate									
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status

Open, no restriction [A]

Appraisal ratings -
structural

Somewhat better than minimum adequacy to tolerate being left in place as is [5]

Condition ratings - superstructure

Not Applicable [N]

Appraisal ratings -
roadway alignment

Equal to present desirable criteria [8]

Condition ratings - substructure

Not Applicable [N]

Appraisal ratings -
deck geometry

Somewhat better than minimum adequacy to tolerate being left in place as is [5]

Condition ratings - deck

Not Applicable [N]

Scour

Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]

Channel and channel protection

Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]

Appraisal ratings - water adequacy

Equal to present desirable criteria [8]

Status evaluation

Pier or abutment protection

Sufficiency rating

79.8

Culverts

Moderate to major deterioration or disintegration, extensive cracking and leaching or spalls on concrete or masonry walls and slabs. Minor settlement or misalignment. Noticeable scouring or erosion at curtain walls, wingwalls or pipes. Metal culverts have significant distortion and deflection in one section, significant corrosion or deep pitting. [5]

Traffic safety features - railings

Traffic safety features - transitions

Traffic safety features - approach guardrail

Traffic safety features - approach guardrail ends

Inspection date

February 2009 [0209]

Designated inspection frequency

24

Months

Underwater inspection

Not needed [N]

Underwater inspection date

Fracture critical inspection

Not needed [N]

Fracture critical inspection date

Other special inspection

Not needed [N]

Other special inspection date