

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26]	Genesee County [049]	Atlas [04000]	INTERS OF PERRY & VASSAR	42-55-57 = 42.932500	083-34-25 = - 83.573611
25200022000B010	Highway agency district 4	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 2534	PERRY ROAD	Toll On free road [3]	Features intersected	THREAD RIVER	
Design - main Steel [3]	Design - approach	Kilometerpoint 447.2 km = 277.3 mi	Year built 1928	Year reconstructed N/A [0000]	
1	Stringer/Multi-beam or girder [02]	0	Other [00]	Skew angle 30	Structure Flared
			Historical significance	Bridge is not eligible for the NRHP. [5]	
Total length 13.7 m = 44.9 ft	Length of maximum span 12.8 m = 42.0 ft	Deck width, out-to-out 12.2 m = 40.0 ft	Bridge roadway width, curb-to-curb	11 m = 36.1 ft	
Inventory Route, Total Horizontal Clearance 10.9 m = 35.8 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft		
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 1.4 km = 0.9 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	19.3 metric ton = 21.2 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	47.9 metric ton = 52.7 tons
Bridge posting	10.0 - 19.9 % below [3]	Design Load	MS 18+Mod / HS 20+Mod [6]	

Functional Details

Average Daily Traffic	5927	Average daily truck traffi	5	%	Year	1998	Future average daily traffic	10400	Year	2018
Road classification	Minor Arterial (Urban) [16]		Lanes on structure	2		Approach roadway width	6.1 m = 20.0 ft			
Type of service on bridge	Highway [1]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by		Work to be done by contract [1]	
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	108000	Roadway improvement cost	11000
	Length of structure improvement	13.7 m = 44.9 ft	Total project cost	135000
	Year of improvement cost estimate			
	Border bridge - state		Border bridge - percent responsibility of other state	
	Border bridge - structure number			

Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Basically intolerable requiring high priority of corrective action [3]
Condition ratings - superstructure	Serious [3]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]
Condition ratings - substructure	Fair [5]	Appraisal ratings - deck geometry	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - deck	Fair [5]		
Scour	Bridge is scour critical; bridge foundations determined to be unstable. [3]		
Channel and channel protection	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]		
Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	23.6
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - transitions	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	December 2009 [1209]	Designated inspection frequency	12 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	