

# Sewalls Falls Bridge 2012 In-Depth Inspection



Prepared for the  
**CITY of CONCORD, NEW HAMPSHIRE**  
**ENGINEERING SERVICES DIVISION**

March 2012

---

---

## **TABLE OF CONTENTS**

### **REPORT**

<b>INTRODUCTION.....</b>	<b>1</b>
<b>INSPECTION CONVENTIONS .....</b>	<b>2</b>
<b>DESCRIPTION OF TRUSS SPANS .....</b>	<b>2</b>
<b>INSPECTION &amp; MEASUREMENT METHODS .....</b>	<b>4</b>
<b>SUMMARY OF FINDINGS.....</b>	<b>6</b>
Upper Trusses & Bracing .....	6
Vehicular Impact Damage.....	6
Lower Trusses – Truss Members.....	7
Lower Trusses – Truss Gusset Plates .....	7
Stringers .....	9
Floorbeams.....	9

### **DATA TABLES**

<b>TABLE 1: OBSERVED IMPACT DAMAGE LOCATIONS &amp; MEASUREMENTS .....</b>	<b>1</b>
<b>TABLE 2: TRUSS MEMBER SECTION LOSSES.....</b>	<b>3</b>
<b>TABLE 3: STRINGER CONDITIONS .....</b>	<b>5</b>
<b>TABLE 4: FLOORBEAM CONDITIONS .....</b>	<b>6</b>
<b>DIAGRAM: FLOOR SYSTEM FRAMING .....</b>	<b>7</b>

### **CONDITION PHOTOS**

### **SECTION LOSS CALCULATIONS**

### **FIELD NOTES**

### **SELECTED RECORD DRAWINGS**

## **SEWALLS FALLS BRIDGE** **2012 IN-DEPTH INSPECTION**

### **INTRODUCTION:**

CHA conducted an in-depth structural inspection, truss spans only, of the Sewalls Falls Bridge, which carries Sewalls Falls Road over the Merrimack River in the City of Concord, NH. Performed in conjunction with a load rating analysis of the structure, the purpose of this evaluation is to establish a baseline for the City to judge the feasibility of repair, re-use, modification or replacement options for the bridge. The inspection was performed during the week of March 5<sup>th</sup> through 9<sup>th</sup> of 2012, by the CHA Bridge Inspection Team of Carl Snyder and Joe Albert, with traffic control assistance provided by Greg Meagher, Construction Inspector with the City of Concord's Engineering Services Division.



**Figure 1: Bridge from north shore, left (upstream) side**

The inspection was limited to the two truss spans, superstructure elements only. Numerous existing bridge components are already contemplated for complete removal, abandonment, or replacement under the various bridge rehab/replacement schemes presently under consideration. The existing multi-girder approach spans forming the elevated southern approach to the two main truss spans are expected to be replaced by a filled-earth causeway; the existing concrete and masonry pier and abutments are expected to be replaced with new substructures to accommodate the rehabilitated existing structure and a new, parallel bridge constructed immediately upstream; the existing floor system and bearings are known to be in generally poor condition, and are expected to need replacement even if the existing trusses

remain in service; the existing bridge railing system exhibits serious impact damage and corrosion, and has many generations of patchwork and welding repairs. Therefore, the following elements were NOT given a detailed, in-depth inspection: the multi-girder approach spans; existing substructures; existing truss and stringer bearings; existing steel open-grating deck; existing steel floor system framing (stringers and floorbeams); existing lower (under-deck) horizontal lateral bracing; and the existing bridge railing system.

Pursuant to the agreed scope of services, the existing truss-span floor system (stringers and floorbeams) was given a casual inspection, using visual assessment and physical probing (with metal bar) to the extent possible through the open-grating deck.

By pre-arrangement with the City and Concord, the bridge was closed from 7 a.m. to 5 p.m. daily, to all but emergency use during the inspection. Access to the upper trusses and bracing was made by various ladders. Access to the truss lower chords was made by climbing over or through the bridge railing system. All work was performed in compliance with OSHA requirements for worker safety and fall protection.


### **INSPECTION CONVENTIONS:**

For identification and location purposes, the bridge is considered to be oriented from the south-southwest to the north-northeast, or nominally south to north. Ignoring the approach spans, the southern truss span is considered Span 1 and the northern one is Span 2. Bridge elements (e.g., truss panel points) are numbered in this order longitudinally. "Left" and "Right" designations are based on the observer looking north from the south end of the bridge. Thus the Merrimack River flows left to right with respect to the bridge.

Unless otherwise specified, elevation views are shown looking westward, or from the right side, and plan views are shown with west up. Truss panel points are numbered from 0 (zero) at the south end of each span, and 9 (nine) at the north. Note to site visitors: there are field markings on various bridge components which are both consistent AND inconsistent with this convention.

### **DESCRIPTION OF TRUSS SPANS:**

The truss-span portion of Sewalls Falls Bridge is a 338-foot-long, 2-span steel structure built circa 1915 on pre-existing stone-masonry substructures. Design plans dated 1936 show the addition of an elevated structure at the south approach, comprised of 10 steel multi-girder spans (not inspected), which replaced an earth-filled causeway. The two truss spans have nine panels in a parallel-chord, Pratt-truss configuration,



**Figure 2: Sewalls Falls Bridge truss schematic**



with diagonal counters forming an "X" in the 3 center panels (Fig. 2). As is common in the Pratt design, the first and last interior panel points (U1L1 & U8L8) have a vertical member serving primarily as a floorbeam hanger. Trusses are comprised of riveted, built-up members connected by riveted gusset plates at all panel points. Top chords are channel-box sections comprised of 2 rolled channel sections with outward-facing flanges with a single top plate; these sections are open on the bottom to receive the panel-point gusset plates. Truss verticals and diagonals are single-angle pairs or double-angle pairs. Truss bottom chords are double-angle pairs, supplemented with a single pair of outer side plates in the central 5 panels of the truss.

The two circa-1915 truss spans differ in length by 2 feet, presumably to fit the pre-existing pier and abutment layout. This difference is made up solely in the lengths of the first and last panels of the spans, which results in different slopes in the truss end-posts.

Intermediate panel lengths and *all* corresponding member cross-sections (including those in the differing end panels) are the same in both spans. The standard intermediate panel length is 18'-6½". Record drawings indicate center-to-center bearing dimensions of 166'-10½" for Span 1 (south span); and 164'-10½" for Span 2 (north span). Field measurements are consistent with these dimensions. All truss members and floorbeams are of built-up riveted fabrication of the original 1915 construction. With regard to rolling tolerances, we frequently encountered thickness measurements 5 to 10 percent in excess of the nominal thickness in angle legs.




Figure 3: Excerpt from 1915 shop drawings



Figure 4: Typical floor framing - Span 2 Panel 9

The Stringers are rolled beams; their date of origin was not determined, but they have the same staggered holes in the top flanges (for fastening timber nailers), as shown in the 1915 shop drawings. Floorbeams are built-up riveted sections with separate web plates and flange angles. Both the stringers and the floorbeams have been extensively modified; they have welded flange cover plates and web repair plates, possibly from multiple generations of rehabs and retrofit construction. Truss members are all original sections, with a very few localized welded and bolted repairs.

Without exception, truss dimensions and member sizes appear to be consistent with the 1915 record drawings.

### **INSPECTION & MEASUREMENT METHODS:**

All primary truss members received a hands-on, close-up inspection for alignment, straightness, localized impact damage, corrosion, and potential cracking (no cracks were observed). Plan verification measurements were typically made with bow calipers and a stick rule.

Impact damage resulting in the misalignment of a member as a whole was measured off a tensioned string line. The string line was positioned as close to as practicable to the member's original alignment at the panel points at each end of the member. A stick rule was then used to measure the maximum displacement perpendicular to the axis of the member, in both longitudinal and transverse planes. Axial twist was documented with and measured off digital imagery. Photos were sighted down the length of the member, and composed with an original reference plane in view. Zoom settings were maximized to mitigate perspective and lens effects. Localized impact damage, such as bent or dented angle legs or channel flanges, was documented with a straightedge and stick rule.



**Figure 5: Documentation of impact damage**

Each truss member was visually assessed to identify the location for the worst overall (gross) section loss for the member, based primarily on build-up of crevice corrosion or "pack rust". Many bottom chord members exhibit similar-looking deterioration intermittently throughout their length. This occasionally required taking measurements at additional locations per member to ascertain the worst instance.

Truss member section losses were almost exclusively measured by ultrasonic ("d-meter") means, because the worst corrosion is typically between closely spaced or mated surfaces. In most cases, the accessible sides of the components were free of pitting or corrosion, requiring minimal surface preparation for testing. Truss gusset plates, which are typically too large to permit



**Figure 6: Measuring section loss on a truss vertical**

mechanical measurement, were similarly measured by d-meter (very few plates have significant section losses). Over 900 d-meter readings were recorded.

Floorbeams and stringers were evaluated visually and by probing with a piece of rebar through the open grating steel deck, as prescribed in the project scope. The primary focus was on beam flanges near their mid-length, and beam webs near their supports. Efforts were concentrated at areas with already-visible holes, material loss, or very heavy rust scale. These locations were forcibly pounded to remove additional rust and determine if there was obvious additional loss or hole-enlargement. A rough estimate was then made of the apparent magnitude of section loss.


\* \* \*



## **SUMMARY OF FINDINGS:**

### **Upper Trusses & Bracing:**

Above the travelway, no deficiencies were observed in any upper truss panel point gusset plates or member connections; however, the top chords of the truss exhibit minor deterioration in their top plates due to crevice corrosion ("pack rust"). This corrosion is typically present between the horizontal bracing gusset plates and the top plates of the upper chords at each panel point (see Fig. 7). These were not accessible for direct measurement, but pitting is typically visible along and just under the edges of the horizontal gusset plates. Based on what is visible, a conservative estimate of 33% section loss in the top plates of the upper chords is recommended for load rating purposes. Because this loss typically occurs over very short lengths along the member ( $<1"$ ), it applies only to local bearing/compression stress, and not to slenderness or buckling modes of analysis. No losses were evident in the channel components of the chords, so the resulting weighted maximum effect of the top plate losses on the gross section is 12% for the section with the lightest channels (chord members U1U2 and U7U8). See Photos 1 through 4.



**Figure 7: Typical horizontal gusset plates along upper chord (Span 1 Right Truss shown)**

Also above the travelway, the upper lateral (horizontal-plane) and sway (vertical-plane) bracing exhibit only minor pack rust and no significant distortions. No rivet failures were observed on the bridge, including those near to and clearly stressed by pack rust prying forces.

### **Vehicular Impact Damage:**

Along the travelway envelope, numerous truss members exhibit impact damage in the form of large-scale twisting and out-of-plane deformations in numerous truss diagonals (Fig. 8).



**Figure 8: Truss member impact damage**

Much of the worst structural damage coincides with bridge railing damage, and appears consistent with typical impact damage from a snowplow blade. Also, there are numerous small dents and localized bends in various projecting member legs and flanges. No cracks or tears were observed in any truss component. See Table 1 for a detailed summary of observed impact damage to truss members, with photo references.

Along the bridge centerline there is evidence of impact damage resulting from an over-height vehicle or load hitting the lower chord of the transverse sway bracing (Fig. 9). No impact damage was observed at the "portal" bracing at each end of each of the truss spans. At the intermediate



sway bracing, several low chords exhibit minor to moderate bends, with little effect on other components, including connections to the corresponding truss verticals. No cracks or tears were observed in any of these components. See Table 2 for a summary of maximum longitudinal displacements of these chords, with photo references.

### Lower Trusses – Truss Members:

Where vertical and diagonal truss members intersect gusset plates at the lower-chord panel points, there is minor to moderate crevice corrosion and localized loss of cross-sectional area ("section loss") in most truss members. Section losses are typically greater at the inboard sides of the connections, i.e., at the gusset plates closest to the travelway. The greatest section losses found among all truss verticals was 15% on Span 1 Right Truss member U3L3. The greatest section losses found among all truss diagonals was 9% on Span 2 Left Truss member U1L2. See Table 2.

Along the truss bottom chords, there is intermittent crevice corrosion and section loss in each truss panel (Fig. 10). Some panels have their worst losses at the panel point gusset plates, others occur between panel points. The greatest section losses found among all truss bottom chords was 27% on Span 1 Right Truss member L0L1. Similar losses were encountered at Span 1 Left Truss member L6L7 (26% SL); and Span 2 Left Truss member L2L3 (26% SL). See Table 2.

### Lower Trusses – Truss Gusset Plates:

Truss gusset plates are typically in good condition throughout, with generally minor and/or localized non-critical corrosion and section loss. Most have minor distortions along the upper edges due to pack rust at the truss verticals and diagonals, and in some cases due to



Figure 9: Typical lower chord gusset plate conditions (Span 2 Left Truss at L3).




Figure 9: Damaged sway-bracing chords



Figure 10: Typical truss bottom chord

distortions carried into the plates from the most severely impact-damaged diagonals. If the trusses are to remain in service, removal of selected distortions should be considered. Most of these locations are where the degree of pack rust and/or impact damage would already warrant disassembly and cleaning of the connection.

In a few locations, gusset plates have light pitting along horizontal lines just above the upper angles of the bottom chords – most of this is minor and predates the current paint system. Since the lower

panel point gusset plates are attached on the outsides of the members, this pitting is typically on the interior surfaces of the gusset plates. Ultrasonic thickness measurements were taken at a few plates appearing to have the most pronounced and continuous lines of pitting anywhere on the bridge. Locations and section loss (SL) were as follows:

1. Span 2 Left Truss at Panel Point L3:
  - a. Left (outboard) plate: Begin and End halves: 0% SL (despite pitting).
  - b. Right (inboard) plate: Begin half: 0% SL; End half: 12% SL.
2. Span 2 Right Truss at Panel Point L6:
  - a. Left (inboard) plate: Begin half: 3% SL; End half: 2% SL.
  - b. Right (outboard) plate: Begin half: 3% SL; End half: 10% SL.

Also along the bottom chord, most inboard truss gusset plates have a line of deep pitting and active corrosion just above the intersection with the horizontal gusset plates for the lower lateral (under-deck) bracing. This is located in a horizontal plane corresponding to the centerline of the intersecting bottom chord members, with connecting rivets above and below the pitting - so that the chord member itself effectively knits the gusset plate across the pitted zone. This condition is considered as not seriously compromising the truss. Similar localized pitting occurs where the tops of the floorbeams intersects the inboard plates. In these locations, the truss verticals similarly knit the gusset plate across the pitted regions. See Figure 12.



Figure 10: Typical pitting lines, from top



Figure 11: Utility brackets welded to gusset plates (Left side shown, Right side similar)

Finally, almost all bottom chord gusset plates have utility support brackets welded to the outboard plate, along both sides of the bridge. These brackets support a municipal sewer line along the left (upstream) side of the bridge, and a natural gas main on the other. Each bracket has a vertical leg welded directly to the outboard truss gusset plate with intermittent field-made fillet welds. No cracked or broken welds were observed in these connections; however, these welds compromise the gusset plates, the truss, and thus each entire span by creating points of stress concentration, introducing potential point sources for propagation of fatigue cracks, and altering the old gusset plates metallurgically due to the heat of welding. If the existing trusses are to remain in service, removal and post-removal testing of these welds should be considered as part of any superstructure repair scheme.

\*(The exception is at Span 1 panel point L0 in the left and right trusses).

### Stringers:

Stringer beams typically exhibit moderate to serious deterioration throughout the bridge, with few instances of severe deterioration (Fig 14). All 144 stringers were assessed on a binary basis to distinguish between members with or without relatively obvious severe deterioration. As these members were inspected through the open grating deck rather than hands-on, our assessment is mostly qualitative, with only a rough and not necessarily complete estimation of the magnitude of deterioration. See Table 3 for a summary of findings.



Figure 12: Stringer deterioration (from 2011 NHDOT (Draft) Inspection Report, Image No, D077-28)

### Floorbeams:

Floorbeams typically exhibit moderate to serious deterioration throughout the bridge, with few instances of severe deterioration (Fig 15). All 16 floorbeams were assessed on a binary basis to distinguish between members with or without relatively obvious severe deterioration. As these members were inspected through the open grating deck rather than hands-on, our assessment is mostly qualitative, with only a rough and not necessarily complete estimation of the magnitude of deterioration. See Table 4 for a summary of findings.



Figure 13: Floorbeam deterioration (from 2011 NHDOT (Draft) Inspection Report, Image No, D077-62)

\* \* \* \* \*



# Sewalls Falls Bridge 2012 In-Depth Inspection DATA TABLES







Table 1:


# OBSERVED IMPACT DAMAGE LOCATIONS & MEASUREMENTS



Span	Truss	Member	Deformations at Apparent Point of Impact (APOI)			Distance from APOI to Nearest Panel Point	Photo No. <filenames>
			Longitudinal Offset	Transverse Offset	Approximate Axial Rotation <sup>1,2</sup>		
1	Left	L0U1	Local damage only: Bottom flange of inboard channel bent up 1¾" over 15" length, and adjoining web slightly distorted; Top plate edge bent up ½" over 9" length.			13.4' to L0	Photos 5, 6 <12-0003, 04>
1	Left	U2L2	None	None	3° CCW	Forces from lower sway bracing	Photos 7, 8 <12-0008, 09>
1	Left	L4U5	2¼"	¾"	8° CW	5.3' to L4	Photos 9, 10 <12-0016, 19>
1	Left	U4L5	¼"	¼"	None noted	6.5' to L5	(None) <12-0020, 29>
1	Left	U5L6 Inboard Member	2¼"	1"	1° CCW	5.5' to L6	Photo 11 <12-0024a>
1	Left	U5L6 Outboard Member	¼"	¼"			
1	Left	L5U6 Inboard Member	4⅛"	1⅛"	15° CCW	5.5' to L5	Photos 12-14 <12-0030-32>
1	Left	L5U6 Outboard Member	¼"	1⅝"			
1	Left	L6U7	Localized damage only: Bottom inboard angle leg is bent 1" over a 5" length.			5.5' to L6	(None)
1	Right	L1U1	Local damage only: Inboard railing bracket is detached and the angle leg is bent ½" over 6" length.			At rail post connections.	(None)
1	Right	L3U4 Inboard Member	5¼"	2¼"	21° CCW	4.5' to L3	Photos 15, 16 <12-0047a, 48>
1	Right	L3U4 Outboard Member	⅜"	1⅜"			

Table 1:

# OBSERVED IMPACT DAMAGE LOCATIONS & MEASUREMENTS




Span	Truss	Member	Deformations at Apparent Point of Impact (APOI)			Distance from APOI to Nearest Panel Point	Photo No. <filenames>
			Longitudinal Offset	Transverse Offset	Approximate Axial Rotation <sup>1,2</sup>		
1	Right	U4L5 Inboard Member	6"	2¾"	18° CCW	6.8' to L5	Photos 17, 18 <12-0053a, 55>
1	Right	U4L5 Outboard Member	⅝"	1½"			
1	Right	U5L6 Inboard Member	⅝"	0"	None	8.7' to L6	(None) <12-0060>
2	Left	U5L6 Inboard Member	3¾"	1¾"	2° CCW	5' to L6	Photos 19, 20 <12-0071a, 72>
2	Left	U5L6 Outboard Member	¾"	1½"			
2	Right	U5L6	½"	¼"	None	10.8' to L6	(None) <12-0102, 103>

Table 1 Notes:

1. This is an estimation of the maximum amount of axial twist of the whole member section at the apparent point of impact (APOI).
2. CW & CCW indicate clockwise and counter-clockwise, respectively, in plan view (looking from upper end to lower end of member).

Table 2:


## TRUSS MEMBER SECTION LOSSES<sup>1</sup>



Member	Type	Size <sup>2</sup>	Span 1 Left Truss	Span 1 Right Truss	Span 2 Left Truss	Span 2 Right Truss
L0U1 & U8L9	End Posts	2-C12 x 25 plus plate 18 x $\frac{3}{8}$ "	No significant section loss (NSSL), or impact damage			
U1 through U8	Top Chords	2-C12 x 20.5 or 35 plus plate 18 x $\frac{3}{8}$ "				
L0L1 & L1L2	Bottom Chord	4-L5 x 3 x $\frac{5}{16}$ "	4%	<b>27%</b> Photo 21, 22	3%	3%
L2L3	Bottom Chord	4-L5 x 3½ x $\frac{5}{16}$ " plus 2-Pl. 11 x $\frac{5}{16}$ "	17%	15%	<b>26%</b> Photo 23, 24	16%
L3L4	Bottom Chord	4-L5 x 3½ x $\frac{7}{16}$ " plus 2-Pl. 11 x $\frac{3}{8}$ "	5%	10%	10%	<b>11%</b> Photo 25, 26
L4L5	Bottom Chord	4-L5 x 3½ x $\frac{1}{2}$ " plus 2-Pl. 11 x $\frac{3}{8}$ "	NSSL	NSSL	≤5%	<b>5%</b> Photo 27, 28
L5L6	Bottom Chord	4-L5 x 3½ x $\frac{7}{16}$ " plus 2-Pl. 11 x $\frac{3}{8}$ "	<b>18%</b> Photo 29, 30	9%	8%	10%
L6L7	Bottom Chord	4-L5 x 3½ x $\frac{5}{16}$ " plus 2-Pl. 11 x $\frac{5}{16}$ "	<b>26%</b> Photo 31, 32	24%	10%	18%
L7L8 & L8L9	Bottom Chord	4-L5 x 3 x $\frac{5}{16}$ "	NSSL	1%	<b>13%</b>	9%
U1L1	FB Hanger	4-L3 x 3 x $\frac{5}{16}$ "	NSSL			
U2L2	Vertical	4-L5 x 3½ x $\frac{3}{8}$ "	NSSL	NSSL	NSSL	NSSL
U3L3	Vertical	4-L5 x 3 x $\frac{5}{16}$ "	7%	<b>15%</b> Photo 33, 34	10%	6%
U4L4	Vertical		NSSL	9%	<b>13%</b> Photo 35, 36	9%
U5L5	Vertical		<b>9%</b>	7%	*≤5%	*≤5%
U6L6	Vertical		NSSL	<b>10%</b> Photo 37, 38	*≤6%	9%
U7L7	Vertical	4-L5 x 3½ x $\frac{3}{8}$ "	NSSL	*≤4%	*≤2%	<b>*≤5%</b>
U8L8	FB Hanger	4-L3 x 3 x $\frac{5}{16}$ "	NSSL			
U1L2	Diagonal	4-L4 x 3 x $\frac{7}{16}$ "	NSSL	NSSL	≤1%	<b>5%</b> Photo 39, 40

Table 2:

## TRUSS MEMBER SECTION LOSSES<sup>1</sup>



Member	Type	Size <sup>2</sup>	Span 1 Left Truss	Span 1 Right Truss	Span 2 Left Truss	Span 2 Right Truss
U2L3	Diagonal	4-L4 x 3 x 5/16"	NSSL	3%	3%	<b>5%</b> <b>Photo 41, 42</b>
U3L4	Diagonal	2-L5 x 3 x 5/16"	NSSL	<b>7%</b>	4%	4%
L3U4	Counter	2-L3 x 3 x 5/16"	NSSL	<b>6%</b> <b>Photo 43, 44</b>	3%	4%
U4L5	Counter		NSSL			
L4U5	Counter		NSSL			
U5L6	Counter		1%	2%	*≤4%	<b>6%</b>
L5U6	Diagonal	2-L5 x 3 x 5/16"	<b>9%</b> <b>Photo 45, 46</b>	5%	3%	<b>12%</b> <b>Photo 47, 48</b>
L6U7	Diagonal	4-L4 x 3 x 5/16"	1%	*≤5%	4%	<b>8%</b> <b>Photo 49, 50</b>
L7U8	Diagonal	4-L4 x 3 x 7/16"	NSSL	*≤5%	*1%	NSSL

### Table 2 Notes:

1. Section Loss = percentage of material lost through corrosion compared to the original cross sectional area. Numbers presented as "≤" are calculated from visually-estimated losses. Numbers in **bold text** indicate losses which control among all symmetrically equivalent members.
2. Member Size is that shown on the 1915 shop drawings. Field checks indicate the 1915 shop drawings are accurate.
3. \* indicates member also has significant impact damage.



Table 3:

## STRINGER CONDITIONS<sup>1</sup>

Span	Floor Panel	Stringer #	Description of Losses <sup>2</sup>
1	1	4	9.5' from the Begin approach, Top Flange Cover Plate :30% SL, Web 50% SL
		5 & 6	8.0' from the Begin approach, Top Flange Cover Plate 100% SL 7.5' from the Begin approach, Bottom Flange: 30% SL
	2	5	9.0' from Floorbeam 1, Web: 50% loss, Top Flange: 20% SL
	3	3	5' from Floorbeam 2, Web: 30% SL
		6	2' from Floorbeam 3: Web: 80% SL over a 2' length
		7	2' from Floorbeam 3: Web: 20% SL
	4	4	2' from Floorbeam 3, Web: 45% SL
		5	2' from Floorbeam 4, Web: 30% SL
		6	2' from Floorbeam 4, Web: 60% SL
		7	2' from Floorbeam 4, Web: 90% SL, approximately 8"x4" hole in the web.
	5	3	2' from Floorbeam 4, Web: 40% SL
		5	2' from Floorbeam 5, Web: 20% SL
	8	6	2' from Floorbeam 7, Web:60% SL, approximately 4"x4" hole in web
	9	4	3' from Floorbeam 8, Web: 30% SL
		5	2' from Floorbeam 8, Web: 30% SL
		6	2.5' from Floorbeam 8, Web: 25% SL, Top Flange Cover Plate: 20% SL 10.8' from Floorbeam 8, Web 45% SL over a 1' length, Top Flange Cover Plate 35% SL, Top Flange 10% SL
		7	0.5' from Floorbeam 8, Web: 40% SL, 2.5' from Floorbeam 8, Web: 30% SL
2	1	2	0.5' From Floorbeam 0, Web: 35%SL
		3	1.0' from Floorbeam 0, Top Flange: 30% SL
		5	0.5' from Floorbeam 1, Web: 25% SL
		7	1.0' from Floorbeam 1, Web: 30% SL
	2	4	2.0' from Floorbeam 2, Web: 20% SL
		5	1.0' from Floorbeam 2, Web: 30% SL
		6	1.0' from Floorbeam 2, Web: 40% SL
	3	3	2.0' from Floorbeam 2, Web: 50% SL
		5	2.0' from Floorbeam 2, Web: 25% SL
	7	5	9.3' from Floorbeam 6, Top Flange: 15% SL over 8" length
	8	5	5.0' from Floorbeam 7, Top Flange: 30% SL over 8" length 1.0' from Floorbeam 8, Top Flange: 35% SL over 3" length
	9	3	10.0' from Floorbeam 8, Bottom Flange: 40% SL
		5	An average of 40% SL along entire Top Flange, with a maximum of 70% SL at two locations; 1.0' from Floorbeam 8 and 11.1' from Floorbeam 8

1.) Stringers are numbered from left to right looking NNE

2.) SL= Section Loss

**Table 4:**

## **FLOORBEAM CONDITIONS<sup>1</sup>**

<b>Span</b>	<b>Floorbeam #</b>	<b>Description of Losses<sup>2</sup></b>
1	1	Begin side bottom flange, holes between Stringers 3-6. 80% SL between Stringers 3 and 4, 30% SL between Stringers 4 and 5, and 50 % SL between Stringers 5 and 6
	4	Begin side bottom flange, multiple holes in between stringers 4 and 6, maximum SL of 50%. End side bottom flange, holes between Stringers 3 and 4 (60% SL) and Stringers 5 and 6 (35% SL) End side bottom flange, holes 6"-8" in length under stringer 6, maximum SL of 70%.
	6	Begin side bottom flange, holes between Stringers 3 and 4, 90% SL
	7	End side bottom flange, gauges between Stringers 5 and 6, 25% SL
	8	Begin side bottom flange, between Stringers 4 and 6, maximum SL of 60%
2	1	End side bottom flange, holes between Stringers 5 and 6, maximum SL of 70%
	2	Begin side bottom flange, holes between Stringers 5 and 6, 70% SL
	4	Begin side bottom flange, holes between Stringers 3 and 4, 30% SL
	6	End side bottom flange, holes between Stringers 2 and 3, 80% SL
	7	End side bottom flange, holes over a length of 18" between Stringers 2 and 3, 50% SL

1.) Floorbeam 0 is the southernmost Floorbeam


2.) SL= Section Loss; Stringers are numbered from left to right looking NNE.

## FLOOR SYSTEM FRAMING

(Locations of Observed Serious Section Losses in Tables 3 & 4)

● STRINGER LOSS

▼ FLOORBEAM LOSS



# Sewalls Falls Bridge 2012 In-Depth Inspection CONDITION PHOTOS








Photo 1: Span 1 Right Truss at U1: Pack rust at top chord and bracing gusset plate <12-0042>



Photo 2: Span 1 Left Truss at U6: Pack rust at top chord and bracing gusset plate <12-0033>



Photo 3: Span 2 Left Truss at U1: Pack rust at top chord and bracing gusset plate. <12-0066a>



Photo 4: Span 2 Right Truss at U7: Pack rust at top chord and bracing gusset plate. <12-0105>



Photo 5: Span 1 Left Truss at L0U1: Localized impact damage <12-0003>



Photo 6: Span 1 Left Truss at L0U1: Localized impact damage <12-0004>





Photo 7: Span 1 Left Truss at U2L2 (Begin side looking up): Impact damage: axial rotation <12-0008>



Photo 8: Span 1 Left Truss at U2L2 (Right side looking up): Impact damage: axial rotation <12-0009>




Photo 9: Span 1 Left Truss - L1U2: Impact damage. <12-0016a>



Photo 10: Span 1 Left Truss - L1U2: Impact damage. <12-0019>



Photo 11: Span 1 Left Truss at U5L6: Impact damage in lower half, looking from U5 <12-0024a>



Photo 12: Span 1 Left Truss - L5U6: Impact damage <12-0030>





Photo 13: Span 1 Left Truss – L5U6: Impact damage in lower half of member <12-0031>



Photo 14: Span 1 Left Truss – L5U6: Impact damage looking back from U6 <12-0032a>




Photo 15: Span 1 Right Truss - L3U4: Impact damage <12-0047a>



Photo 16: Span 1 Right Truss – L3U4: Impact damage in lower half, looking toward L3 <12-0048>



Photo 17: Span 1 Right Truss – U4L5: Impact damage <12-0053a>



Photo 18: Span 1 Right Truss – U4L5: Impact damage, looking toward L5 <12-0055>





Photo 19: Span 2 Left Truss - U5L6: Impact damage.  
<12-0071a>



Photo 20: Span 2 Left Truss - U5L6: Impact damage,  
looking toward L6. <12-0072>



Photo 21: Span 1 Right Truss - L0L1 at L0, from  
Right: Section loss <12-0202a>



Photo 22: Span 1 Right Truss - L0L1 at L0, looking  
into L0: Section loss <12-0203>



Photo 23: Span 2 Left Truss - L2L3 looking from L2:  
Section loss <12-0314>



Photo 24: Span 2 Left Truss - L2L3 at 5<sup>th</sup> tie plate:  
Section loss <12-0315>





Photo 25: Span 2 Right Truss - L3L4 looking toward panel point L4: Section loss <12-0413>



Photo 26: Span 2 Right Truss - L3L4 between tie plates #2 & #3: Section loss <12-0413>



Photo 27: Span 2 Right Truss - L4L5 looking toward panel point L5: Section loss <12-0423>



Photo 28: Span 2 Right Truss - L4L5 looking back at panel point L4: Section loss <12-0424>



Photo 29: Span 1 Left Truss - L5L6 at tie plate #5 (near L6): Section loss <12-0169>



Photo 30: Span 1 Left Truss - L5L6 at tie plate #5, underside: Section loss <12-0172a>





Photo 31: Span 1 Left Truss - L6L7 at tie plate #3 (mid-panel): Section loss <12-0182>



Photo 32: Span 1 Left Truss - L6L7 at tie plate #3, underside: Section loss <12-0184>



Photo 33: Span 1 Right Truss - U3L3 at L3: Section loss <12-0227>



Photo 34: Span 1 Right Truss - U3L3 at L3: Section loss <12-0229>



Photo 35: Span 2 Left Truss - U4L4 at L4: Section loss <12-0333>



Photo 36: Span 2 Left Truss - U4L4 at L4: Section loss <12-0334>





**Photo 37: Span 1 Right Truss – U6L6 at L6: Section loss <12-0264>**



**Photo 38: Span 1 Right Truss – U6L6 at L6: Section loss <12-0267>**



**Photo 39: Span 2 Right Truss - U1L2 at L2: Section loss <12-0396>**



**Photo 40: Span 2 Right Truss - U1L2 at L2: Section loss <12-0397>**



**Photo 41: Span 2 Right Truss - U2L3 at L3: Section loss <12-0406>**



**Photo 42: Span 2 Right Truss - U2L3 at L3: Section loss <12-0407>**





**Photo 43: Span 1 Right Truss - L3U4 at L3: Section loss <12-0230>**



**Photo 44: Span 1 Right Truss - L3U4 at L3: Section loss <12-0232>**



**Photo 45: Span 1 Left Truss - L5U6 at L5: Section loss <12-0166>**



**Photo 46: Span 1 Left Truss - L5U6 at L5: Section loss <12-0167>**



**Photo 47: Span 2 Right Truss - L5U6 at L5: Section loss. <12-0431>**



**Photo 48: Span 2 Right Truss - L5U6 at L5: Section loss. <12-0432>**




**Photo 49: Span 2 Right Truss – L6U7 at L6: Section loss. <12-0443>**



**Photo 50: Span 2 Right Truss - L6U7 at L6: Section loss. <12-0445>**



# Sewalls Falls Bridge 2012 In-Depth Inspection SECTION LOSS CALCS





CHA Project # 23968


Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF

\*\*\*Book dimensions were used when d-meter readings exceed the nominal thickness of the member.



Section Loss Summary- Span 1 Truss 1

L1L2 @ L1

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.306			0.313	0.317	0.297	0.313	0.286		
	0.310			0.313	0.278	0.312	0.250	0.266		
	0.313			0.313	0.261			0.313		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.310	0.313	0.313	0.313	0.285	0.305	0.281	0.288		
Section Loss (%)	1%	0%	0%	0%	9%	3%	10%	8%	-	-
Gross Loss	4%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 1 Truss 1**

**L2L3 @ Tie Plate 1**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)					0.264	0.241	0.139	0.274	0.167	0.157
					0.271	0.291	0.224	0.284	0.281	0.280
					0.279			0.279	0.280	0.293
									0.224	0.299
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.313	0.313	0.313	0.313	0.271	0.266	0.182	0.279	0.238	0.257
Section Loss (%)	0%	0%	0%	0%	13%	15%	42%	11%	24%	18%
Gross Loss	14%									

Member	L5x3-1/2 x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0.3125
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	2.56
Original Area of Steel (in <sup>2</sup> )	17.11
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 1**

**L2L3 @ Tie Plate 3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.304			0.285	0.245	0.193	0.201	0.275	0.132	0.181
	0.293			0.278	0.258	0.225	0.226	0.277	0.231	0.283
	0.291			0.287	0.268			0.266	0.281	0.299
									0.274	0.241
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.296	0.313	0.313	0.283	0.257	0.209	0.214	0.273	0.230	0.251
Section Loss (%)	5%	0%	0%	9%	18%	33%	32%	13%	27%	20%
Gross Loss	17%									

Member	L5x3-1/2 x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0.3125
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	2.56
Original Area of Steel (in <sup>2</sup> )	17.11
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 1 Truss 1**

**U3L3 @ L3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.318		0.226	0.297	0.305		0.234	0.292		
	0.311		0.219	0.298	0.300		0.209	0.294		
	0.312			0.302	0.312			0.304		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.314	0.313	0.223	0.299	0.306	0.313	0.222	0.297		
Section Loss (%)	0%	0%	29%	4%	2%	0%	29%	5%	-	-
Gross Loss	7%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 1 Truss 1**

**L3L4 @ L4**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)						0.279	0.271			
						0.333	0.246			
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.438	0.438	0.438	0.438	0.438	0.306	0.259	0.438	0.375	0.375
Section Loss (%)	0%	0%	0%	0%	0%	30%	41%	0%	0%	0%
Gross Loss	5%									

Member	L5x3-1/2 x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0.375
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	3.53
Original Area of Steel (in <sup>2</sup> )	22.36
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 1 Truss 1**

**U5L5 @ L5**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)		0.310	0.212			0.253	0.230	0.285		
		0.246	0.233			0.311	0.242	0.266		
								0.295		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.313	0.278	0.223	0.313	0.313	0.282	0.236	0.282		
Section Loss (%)	0%	11%	29%	0%	0%	10%	24%	10%	-	-
Gross Loss	9%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



Section Loss Summary- Span 1 Truss 1

L5U6 @ L5

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.291			0.233						
	0.293			0.228						
	0.297			0.246						
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.294	0.313	0.313	0.236	0.000	0.000	0.000	0.000		
Section Loss (%)	6%	0%	0%	25%	0%	0%	0%	0%	-	-
Gross Loss	9%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	4.80
Rivet Hole (in)	0.81
# of Angles	2


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 1 Truss 1**

**L5L6 @ Tie Plate 5**

Leg	A	*B	*C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.428	0.361	0.291	0.424	0.367	0.362	0.274	0.395	0.320	0.331
	0.417			0.415	0.370	0.360	0.307	0.390	0.325	0.324
					0.376			0.227	0.320	0.319
									0.190	0.312
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.423	0.361	0.291	0.420	0.371	0.361	0.291	0.337	0.289	0.322
Section Loss (%)	3%	17%	33%	4%	15%	17%	34%	23%	23%	14%
Gross Loss	18%									

Member	L5x3-1/2 x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0.375
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	3.53
Original Area of Steel (in <sup>2</sup> )	22.36
Rivet Hole (in)	0.81
# of Angles	4

\*Values not taken at these legs, visually similar section losses to opposite member.




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



Section Loss Summary- Span 1 Truss 1

U5L6 @ L6

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)					0.313			0.285		
					0.313			0.302		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.000	0.000	0.000	0.000	0.313	0.313	0.313	0.294		
Section Loss (%)	0%	0%	0%	0%	0%	0%	0%	6%	-	-
Gross Loss	1%									

Member	L3x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	3.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	1.78
Original Area of Steel (in <sup>2</sup> )	3.55
Rivet Hole (in)	0.81
# of Angles	2


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 1 Truss 1**

**L6U7 @ L6**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.313			0.306	0.313			0.310		
	0.313			0.288	0.313			0.313		
	0.313			0.289						
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.313	0.313	0.313	0.294	0.313	0.313	0.313	0.311		
Section Loss (%)	0%	0%	0%	6%	0%	0%	0%	0%	-	-
Gross Loss	1%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 1 Truss 1**

**L6L7 @ Tie Plate 3**

Leg	A	* B	* C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.272	0.203	0.173	0.257	0.259	0.181	0.180	0.288	0.162	0.192
	0.275			0.256	0.288	0.224	0.162	0.257	0.295	0.295
					0.295		0.177	0.246	0.280	0.271
									0.185	0.141
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.274	0.203	0.173	0.257	0.281	0.203	0.173	0.264	0.231	0.225
Section Loss (%)	12%	35%	45%	18%	10%	35%	45%	16%	26%	28%
Gross Loss	26%									

Member	L5x3-1/2 x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0.3125
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	2.56
Original Area of Steel (in <sup>2</sup> )	17.11
Rivet Hole (in)	0.81
# of Angles	4

\*Values not taken at these legs, visually similar section losses to opposite member.

CHA Project # 23968


Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF

\*\*\*Book dimensions were used when d-meter readings exceed the nominal thickness of the member.



Section Loss Summary- Span 1 Truss 2

L0L1 @ L0

Leg	*A	*B	*C	*D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.296	0.185	0.214	0.210	0.310	0.134	0.220	0.202		
					0.303	0.203	0.207	0.200		
					0.276	0.217		0.227		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.296	0.185	0.214	0.210	0.296	0.185	0.214	0.210		
Section Loss (%)	5%	41%	32%	33%	5%	41%	32%	33%	-	-
Gross Loss	26%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4

\*Values not taken at these legs, visually similar section losses to opposite member.


**CHA Project # 23968**

**Location: Concord, New Hampshire**

**Bridge: Sewalls Falls Road over the Merrimack River**

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**L0L1 @ L1**

Leg	A	* B	* C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.240	0.163	0.179	0.313	0.275	0.151	0.125	0.323		
	0.312			0.226	0.284	0.139	0.171	0.212		
	0.313			0.207	0.204	0.198	0.242	0.279		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.288	0.163	0.179	0.249	0.254	0.163	0.179	0.271		
Section Loss (%)	8%	48%	43%	20%	19%	48%	43%	13%	-	-
Gross Loss	27%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4

\*Values not taken at these legs, visually similar section losses to opposite member.




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**L2L3 @ L3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.289			0.253	0.284	0.206	0.141	0.313	0.264	0.263
	0.292			0.264	0.279	0.193	0.202	0.293	0.298	0.304
				0.286	0.285	0.160	0.209	0.302	0.293	0.290
									0.275	0.111
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.291	0.313	0.313	0.268	0.283	0.186	0.184	0.303	0.283	0.242
Section Loss (%)	7%	0%	0%	14%	10%	40%	41%	3%	10%	23%
Gross Loss	15%									

Member	L5x 3-1/2 x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0.3125
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	2.56
Original Area of Steel (in <sup>2</sup> )	17.11
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**U2L3 @L3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.313			0.312	0.252			0.293		
	0.309			0.313	0.277			0.298		
	0.277			0.313	0.297			0.301		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.300	0.313	0.313	0.312	0.275	0.313	0.313	0.297		
Section Loss (%)	4%	0%	0%	0%	12%	0%	0%	5%	-	-
Gross Loss	3%									

Member	L4x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	4.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.09
Original Area of Steel (in <sup>2</sup> )	8.36
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**U3L3 @ L3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.291	0.203	0.313	0.311	0.304	0.292	0.313	0.271		
	0.279	0.218	0.293	0.261	0.278	0.212	0.299	0.272		
	0.266			0.260	0.274	0.000		0.291		
Wane						0.313				
In Plane Rivet Hole										
Average Section Remaining	0.279	0.211	0.303	0.277	0.285	0.168	0.306	0.278		
Section Loss (%)	11%	33%	3%	11%	9%	46%	2%	11%	-	-
Gross Loss	15%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**L3U4 @ L3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.271			0.272						
	0.266			0.269						
	0.261			0.288						
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.266	0.313	0.313	0.276	0.000	0.000	0.000	0.000		
Section Loss (%)	15%	0%	0%	12%	0%	0%	0%	0%	-	-
Gross Loss	6%									

Member	L3x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	3.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	1.78
Original Area of Steel (in <sup>2</sup> )	3.55
Rivet Hole (in)	0.81
# of Angles	2


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**L3L4 @ 8.2' From L3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.393			0.406	0.419	0.330	0.309	0.420	0.295	0.338
	0.381			0.396	0.402	0.422	0.346	0.402	0.367	0.364
					0.411			0.415	0.258	0.353
									0.335	0.319
Wane									0.125	
In Plane Rivet Hole										
Average Section Remaining	0.387	0.438	0.438	0.401	0.411	0.376	0.328	0.412	0.314	0.344
Section Loss (%)	12%	0%	0%	8%	6%	14%	25%	6%	16%	8%
Gross Loss	10%									

Member	L5x3-1/2x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0.375
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	3.53
Original Area of Steel (in <sup>2</sup> )	22.36
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**U3L4 @ L4**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)					0.271			0.313		
					0.255			0.298		
					0.244			0.289		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.000	0.000	0.000	0.000	0.257	0.313	0.313	0.300		
Section Loss (%)	0%	0%	0%	0%	18%	0%	0%	4%	-	-
Gross Loss	7%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	4.80
Rivet Hole (in)	0.81
# of Angles	2




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**U4L4 @ L4**

Leg	A	B	C	D	E	*F	*G	H	Left Plate	Right Plate
Measured Thickness (in)	0.271	0.230	0.304	0.299	0.303	0.236	0.298			
	0.259	0.242	0.292	0.297						
	0.269			0.313						
Wane		0.188								
In Plane Rivet Hole										
Average Section Remaining	0.266	0.236	0.298	0.303	0.303	0.236	0.298	0.313		
Section Loss (%)	15%	24%	5%	3%	3%	24%	5%	0%	-	-
Gross Loss	9%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4

\*Values not taken at these legs, visually similar section losses to opposite member.


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**U5L5 @ L5**

Leg	A	B	C	D	E	*F	*G	*H	Left Plate	Right Plate
Measured Thickness (in)	0.297	0.232	0.297	0.301		0.229	0.307	0.307		
	0.288	0.225	0.313	0.306						
	0.294			0.313						
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.293	0.229	0.305	0.307	0.313	0.229	0.307	0.307		
Section Loss (%)	6%	27%	2%	2%	0%	27%	2%	2%	-	-
Gross Loss	7%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4

\*Values not taken at these legs, visually similar section losses to opposite member.


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



Section Loss Summary- Span 1 Truss 2

L5U6 @ L5

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.302			0.274						
	0.313			0.272						
	0.308			0.248						
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.308	0.313	0.313	0.265	0.000	0.000	0.000	0.000		
Section Loss (%)	2%	0%	0%	15%	0%	0%	0%	0%	-	-
Gross Loss	5%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	4.80
Rivet Hole (in)	0.81
# of Angles	2


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**L5L6 @ Tie Plate 2**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.430	0.352	0.357	0.429	0.436	0.351	0.312	0.427	0.373	0.344
	0.422	0.342	0.332	0.419	0.420	0.338	0.308	0.418	0.365	0.366
					0.418			0.428	0.364	0.362
									0.359	0.297
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.426	0.347	0.345	0.424	0.425	0.345	0.310	0.424	0.365	0.342
Section Loss (%)	3%	21%	21%	3%	3%	21%	29%	3%	3%	9%
Gross Loss	9%									

Member	L5x 3-1/2 x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0.375
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	3.53
Original Area of Steel (in <sup>2</sup> )	22.36
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**U5L6 @ L6**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)					0.313			0.293		
					0.284			0.310		
					0.291			0.313		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.000	0.000	0.000	0.000	0.296	0.313	0.313	0.305		
Section Loss (%)	0%	0%	0%	0%	5%	0%	0%	2%	-	-
Gross Loss	2%									

Member	L3x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	3.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	1.78
Original Area of Steel (in <sup>2</sup> )	3.55
Rivet Hole (in)	0.81
# of Angles	2




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**U6L6 @ L6**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.296	0.272		0.292	0.307	0.191	0.305	0.287		
	0.281	0.246		0.279	0.265	0.235	0.313	0.285		
	0.277			0.313	0.253	0.201		0.311		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.285	0.259	0.313	0.295	0.275	0.209	0.309	0.294		
Section Loss (%)	9%	17%	0%	6%	12%	33%	1%	6%	-	-
Gross Loss	10%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**L6U7 @ L6**

Leg	**A	B	C	** D	** E	F	G	**H	Left Plate	Right Plate
Measured Thickness (in)	0.297			0.281	0.297			0.281		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.297	0.313	0.313	0.281	0.297	0.313	0.313	0.281		
Section Loss (%)	5%	0%	0%	10%	5%	0%	0%	10%	-	-
Gross Loss	5%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4

\*\*Values visually estimated.


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**L6L7 @ Tie Plate 1**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.266	0.254	0.216	0.268	0.275	0.289	0.211	0.294	0.247	0.235
	0.281	0.304	0.152	0.265	0.284	0.308	0.229	0.277	0.300	0.305
	0.271			0.293	0.282		0.281	0.271	0.307	0.275
									0.147	0.195
Wane		0.188							0.250	
In Plane Rivet Hole										
Average Section Remaining	0.273	0.279	0.184	0.275	0.280	0.299	0.240	0.281	0.250	0.253
Section Loss (%)	13%	11%	41%	12%	10%	4%	23%	10%	33%	33%
Gross Loss	24%									

Member	L5x 3-1/2 x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0.375
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	2.56
Original Area of Steel (in <sup>2</sup> )	18.48
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**U7L7 @ L7**

Leg	**A	** B	** C	D	** E	**F	**G	H	Left Plate	Right Plate
Measured Thickness (in)	0.297	0.281	0.297		0.297	0.281	0.297			
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.297	0.281	0.297	0.313	0.297	0.281	0.297	0.313		
Section Loss (%)	5%	10%	5%	0%	5%	10%	5%	0%	-	-
Gross Loss	4%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4

\*\*Values visually estimated.


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 1 Truss 2**

**L7U8 @ L7**

Leg	**A	B	C	** D	** E	F	G	**H	Left Plate	Right Plate
Measured Thickness (in)	0.394			0.416	0.394			0.394		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.394	0.438	0.438	0.416	0.394	0.438	0.438	0.394		
Section Loss (%)	10%	0%	0%	5%	10%	0%	0%	10%	-	-
Gross Loss	5%									

Member	L4x3x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	4.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.87
Original Area of Steel (in <sup>2</sup> )	11.48
Rivet Hole (in)	0.81
# of Angles	4

\*\*Values visually estimated.




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



Section Loss Summary- Span 1 Truss 2

L7L8 @ L8

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.293			0.313	0.304			0.313		
	0.310			0.309	0.308			0.297		
				0.313	0.313			0.293		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.302	0.313	0.313	0.311	0.308	0.313	0.313	0.301		
Section Loss (%)	4%	0%	0%	0%	1%	0%	0%	4%	-	-
Gross Loss	1%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4

CHA Project # 23968


Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF

\*\*\*Book dimensions were used when d-meter readings exceed the nominal thickness of the member.



Section Loss Summary- Span 2 Truss 1

L1L2 @ L1

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.312			0.310	0.282			0.301		
	0.303			0.312	0.287			0.288		
					0.283			0.297		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.308	0.313	0.313	0.311	0.284	0.313	0.313	0.295		
Section Loss (%)	2%	0%	0%	0%	9%	0%	0%	5%	-	-
Gross Loss	3%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



Section Loss Summary- Span 2 Truss 1

U2L2 @ L2

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)		0.352	0.274			0.350	0.293			
		0.353	0.236			0.364	0.319			
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.375	0.353	0.255	0.375	0.375	0.357	0.306	0.375		
Section Loss (%)	0%	6%	32%	0%	0%	5%	18%	0%	-	-
Gross Loss	6%									

Member	L5x3x3/8
Nominal Member Thickness (in)	0.3750
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.86
Original Area of Steel (in <sup>2</sup> )	11.44
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**U1L2 @ L2**

Leg	**A	B	C	**D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.416			0.416						
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.416	0.438	0.438	0.416	0.438	0.438	0.438	0.438		
Section Loss (%)	5%	0%	0%	5%	0%	0%	0%	0%	-	-
Gross Loss	1%									

Member	L4x3x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	4.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.87
Original Area of Steel (in <sup>2</sup> )	11.48
Rivet Hole (in)	0.81
# of Angles	4

\*\*Values were estimated visually




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**L2L3 @ Tie Plate 5**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.285	0.312	0.278	0.272	0.174	0.224	0.292	0.293	0.081	0.195
	0.276		0.287	0.283	0.178	0.276	0.225	0.276	0.234	0.301
	0.290			0.291	0.205	0.312	0.173	0.267	0.187	0.290
									0.066	0.086
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.284	0.312	0.283	0.282	0.186	0.271	0.230	0.279	0.142	0.218
Section Loss (%)	9%	0%	10%	10%	41%	13%	26%	11%	55%	30%
Gross Loss	26%									

Member	L5x 3-1/2 x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0.3125
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	2.56
Original Area of Steel (in <sup>2</sup> )	17.11
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**U2L3 @ L3**

Leg	**A	B	C	**D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.297			0.297	0.313			0.280		
					0.303			0.287		
								0.299		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.297	0.313	0.313	0.297	0.308	0.313	0.313	0.289		
Section Loss (%)	5%	0%	0%	5%	2%	0%	0%	8%	-	-
Gross Loss	3%									

Member	L4x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	4.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.09
Original Area of Steel (in <sup>2</sup> )	8.36
Rivet Hole (in)	0.81
# of Angles	4

\*\*Values were estimated visually


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



Section Loss Summary- Span 2 Truss 1

U3L3 @ L3

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.303		0.231	0.299	0.266	0.310	0.221	0.292		
	0.296		0.246	0.264	0.297	0.313	0.236	0.280		
	0.292		0.265	0.285	0.305	0.313	0.209	0.287		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.297	0.313	0.247	0.283	0.289	0.312	0.222	0.286		
Section Loss (%)	5%	0%	21%	10%	7%	0%	29%	8%	-	-
Gross Loss	10%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



Section Loss Summary- Span 2 Truss 1

L3U4 @ L3

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.303			0.305						
	0.284			0.266						
	0.292			0.298						
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.293	0.313	0.313	0.290	0.000	0.000	0.000	0.000		
Section Loss (%)	6%	0%	0%	7%	0%	0%	0%	0%	-	-
Gross Loss	3%									

Member	L3x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	3.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	1.78
Original Area of Steel (in <sup>2</sup> )	3.55
Rivet Hole (in)	0.81
# of Angles	2




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**L3L4 @ Mid of Tie Plates 1 and 2**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.428	0.406	0.409	0.422	0.394	0.390	0.386	0.383	0.278	0.302
	0.424	0.422	0.403	0.408	0.390		0.372	0.395	0.327	0.342
					0.395			0.387	0.326	0.353
									0.338	0.318
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.426	0.414	0.406	0.415	0.393	0.390	0.379	0.388	0.317	0.329
Section Loss (%)	3%	5%	7%	5%	10%	11%	13%	11%	15%	12%
Gross Loss	10%									

Member	L5x 3-1/2 x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0.375
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	3.53
Original Area of Steel (in <sup>2</sup> )	22.36
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**U3L4 @ L4**

Leg	A	B	C	D	**E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)					0.297			0.265		
								0.273		
								0.311		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.000	0.000	0.000	0.000	0.297	0.313	0.313	0.283		
Section Loss (%)	0%	0%	0%	0%	5%	0%	0%	9%	-	-
Gross Loss	4%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	4.80
Rivet Hole (in)	0.81
# of Angles	2

\*\*Values were estimated visually


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



Section Loss Summary- Span 2 Truss 1

U4L4 @ L4

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.310	0.306	0.179	0.281	0.297	0.295	0.186	0.283		
	0.292	0.292	0.201	0.258	0.287		0.182	0.286		
	0.286		0.255	0.273	0.292		0.225			
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.296	0.299	0.212	0.271	0.292	0.295	0.198	0.285		
Section Loss (%)	5%	4%	32%	13%	7%	6%	37%	9%	-	-
Gross Loss	13%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**U5L5 @ L5**

Leg	**A	** B	**C	**D	** E	**F	**G	**H	Left Plate	Right Plate
Measured Thickness (in)	0.297	0.297	0.297	0.297	0.297	0.297	0.297	0.297		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.297	0.297	0.297	0.297	0.297	0.297	0.297	0.297		
Section Loss (%)	5%	5%	5%	5%	5%	5%	5%	5%	-	-
Gross Loss	5%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4

\*\*Values were estimated visually


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



Section Loss Summary- Span 2 Truss 1

L5U6 @ L5

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)				0.313						
				0.275						
				0.272						
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.313	0.313	0.313	0.287	0.000	0.000	0.000	0.000		
Section Loss (%)	0%	0%	0%	8%	0%	0%	0%	0%	-	-
Gross Loss	3%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	4.80
Rivet Hole (in)	0.81
# of Angles	2




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**L5L6 Between Tie Plates 2 and 3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.427	0.413	0.323	0.423	0.412	0.342	0.415	0.419	0.303	0.337
	0.412	0.410	0.318	0.417	0.402	0.422	0.333	0.406	0.361	0.372
					0.416			0.412	0.352	0.359
									0.352	0.367
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.420	0.412	0.321	0.420	0.410	0.382	0.374	0.412	0.342	0.359
Section Loss (%)	4%	6%	27%	4%	6%	13%	15%	6%	9%	4%
Gross Loss	8%									

Member	L5x 3-1/2 x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0.375
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	3.53
Original Area of Steel (in <sup>2</sup> )	22.36
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**U5L6 @ L6**

Leg	A	B	C	D	**E	F	G	**H	Left Plate	Right Plate
Measured Thickness (in)					0.281			0.297		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.000	0.000	0.000	0.000	0.281	0.313	0.313	0.297		
Section Loss (%)	0%	0%	0%	0%	10%	0%	0%	5%	-	-
Gross Loss	4%									

Member	L3x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	3.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	1.78
Original Area of Steel (in <sup>2</sup> )	3.55
Rivet Hole (in)	0.81
# of Angles	2

\*\*Values were estimated visually


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**U6L6 @ L6**

Leg	**A	** B	** C	D	** E	**F	**G	H	Left Plate	Right Plate
Measured Thickness (in)	0.281	0.297	0.281		0.281	0.297	0.281			
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.281	0.297	0.281	0.313	0.281	0.297	0.281	0.313		
Section Loss (%)	10%	5%	10%	0%	10%	5%	10%	0%	-	-
Gross Loss	6%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4

\*\*Values were estimated visually


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**L6U7 @ L6**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.313	0.310	0.307	0.284	0.313	0.305	0.301	0.272		
	0.313	0.302	0.293	0.282	0.313			0.276		
	0.288			0.313	0.313					
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.304	0.306	0.300	0.293	0.313	0.305	0.301	0.274		
Section Loss (%)	3%	2%	4%	6%	0%	2%	4%	12%	-	-
Gross Loss	4%									

Member	L4x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	4.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	
Area of Angle (in <sup>2</sup> )	2.09
Original Area of Steel (in <sup>2</sup> )	8.36
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**L6L7 Between Tie Plates 2 and 3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.305	0.286	0.303	0.293	0.275	0.223	0.275	0.286	0.243	0.281
	0.310	0.305	0.271	0.288	0.295	0.261	0.295	0.293	0.293	0.290
				0.290	0.310	0.311	0.313	0.305	0.287	0.288
									0.230	0.191
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.308	0.296	0.287	0.290	0.293	0.265	0.294	0.295	0.263	0.263
Section Loss (%)	2%	5%	8%	7%	6%	15%	6%	6%	16%	16%
Gross Loss	10%									

Member	L5x 3-1/2 x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0.3125
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	2.56
Original Area of Steel (in <sup>2</sup> )	17.11
Rivet Hole (in)	0.81
# of Angles	4




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



Section Loss Summary- Span 2 Truss 1

U7L7 @ L7

Leg	**A	B	C	**D	**E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.356			0.356	0.356					
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.356	0.375	0.375	0.356	0.356	0.375	0.375	0.375		
Section Loss (%)	5%	0%	0%	5%	5%	0%	0%	0%	-	-
Gross Loss	2%									

Member	L5x3x3/8
Nominal Member Thickness (in)	0.3750
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.86
Original Area of Steel (in <sup>2</sup> )	11.44
Rivet Hole (in)	0.81
# of Angles	4

\*\*Values were estimated visually


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**L7U8 @ L7**

Leg	A	B	C	**D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)				0.356	0.375			0.375		
					0.375			0.375		
					0.375					
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.375	0.375	0.375	0.356	0.375	0.375	0.375	0.375		
Section Loss (%)	0%	0%	0%	5%	0%	0%	0%	0%	-	-
Gross Loss	1%									

Member	L4x3x3/8
Nominal Member Thickness (in)	0.3750
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	4.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.48
Original Area of Steel (in <sup>2</sup> )	9.94
Rivet Hole (in)	0.81
# of Angles	4

\*\*Values were estimated visually


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 1**

**L8L9 @L8**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.313	0.308	0.159	0.328	0.313	0.154	0.199	0.304		
	0.312	0.304	0.205	0.273	0.313	0.265	0.158	0.300		
	0.313			0.313	0.310		0.140	0.313		
Wane			0.250							
In Plane Rivet Hole										
Average Section Remaining	0.312	0.306	0.182	0.305	0.312	0.210	0.166	0.306		
Section Loss (%)	0%	2%	42%	3%	0%	33%	47%	2%	-	-
Gross Loss	13%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4

CHA Project # 23968


Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF

\*\*\*Book dimensions were used when d-meter readings exceed the nominal thickness of the member.



Section Loss Summary- Span 2 Truss 2

L0L1 @ L0

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.296	0.303	0.313	0.313	0.308	0.299	0.311	0.302		
	0.292	0.299	0.294	0.312	0.306	0.312	0.291	0.309		
	0.293			0.312	0.282			0.313		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.294	0.301	0.304	0.312	0.299	0.306	0.301	0.308		
Section Loss (%)	6%	4%	3%	0%	4%	2%	4%	1%	-	-
Gross Loss	3%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**U1L2 @ L2**

Leg	A	B	C	D	** E	F	G	**H	Left Plate	Right Plate
Measured Thickness (in)	0.289			0.437	0.416			0.416		
	0.192			0.438						
	0.432									
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.304	0.438	0.438	0.437	0.416	0.438	0.438	0.416		
Section Loss (%)	30%	0%	0%	0%	5%	0%	0%	5%	-	-
Gross Loss	5%									

Member	L4x3x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	4.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.87
Original Area of Steel (in <sup>2</sup> )	11.48
Rivet Hole (in)	0.81
# of Angles	4

\*\*Values were estiamted visually


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**L2L3 @ Tie Plate 3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.284	0.260	0.310	0.283	0.269	0.208	0.313	0.297	0.237	0.132
	0.288	0.234	0.304	0.298	0.295	0.198	0.207	0.289	0.313	0.301
	0.302			0.308	0.295		0.204	0.277	0.282	0.277
									0.247	0.208
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.291	0.247	0.307	0.296	0.286	0.203	0.241	0.288	0.270	0.230
Section Loss (%)	7%	21%	2%	5%	8%	35%	23%	8%	14%	27%
Gross Loss	16%									

Member	L5x 3-1/2 x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0.3125
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	2.56
Original Area of Steel (in <sup>2</sup> )	17.11
Rivet Hole (in)	0.81
# of Angles	4




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**U2L3 @ L3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.313			0.282	0.278			0.247		
	0.308			0.313	0.281			0.313		
					0.307			0.190		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.310	0.313	0.313	0.297	0.289	0.313	0.313	0.250		
Section Loss (%)	1%	0%	0%	5%	8%	0%	0%	20%	-	-
Gross Loss	5%									

Member	L4x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	4.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.09
Original Area of Steel (in <sup>2</sup> )	8.36
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**U3L3 @ L3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.311	0.293	0.313	0.283	0.294	0.294	0.295	0.290		
	0.287	0.305	0.292	0.307	0.300	0.313	0.295	0.258		
	0.291			0.297	0.312			0.269		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.296	0.299	0.303	0.296	0.302	0.304	0.295	0.272		
Section Loss (%)	5%	4%	3%	5%	3%	3%	6%	13%	-	-
Gross Loss	6%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**L3U4 @ L3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.299			0.269						
	0.274			0.283						
	0.275			0.307						
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.283	0.313	0.313	0.286	0.000	0.000	0.000	0.000		
Section Loss (%)	10%	0%	0%	8%	0%	0%	0%	0%	-	-
Gross Loss	4%									

Member	L3x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	3.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	1.78
Original Area of Steel (in <sup>2</sup> )	3.55
Rivet Hole (in)	0.81
# of Angles	2


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**L3L4 Between Tie Plates 2 and 3**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.413	0.400	0.266	0.420	0.397	0.322	0.402	0.418	0.297	0.327
	0.399	0.397	0.401	0.410	0.390	0.331	0.334	0.382	0.355	0.353
	0.436		0.409	0.415	0.413	0.438	0.312	0.397	0.353	0.348
									0.307	0.334
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.416	0.399	0.359	0.415	0.400	0.364	0.349	0.399	0.328	0.341
Section Loss (%)	5%	9%	18%	5%	9%	17%	20%	9%	13%	9%
Gross Loss	11%									

Member	L5x 3-1/2 x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0.375
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	3.53
Original Area of Steel (in <sup>2</sup> )	22.36
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**U3L4 @ L4**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)					0.283			0.292		
					0.281			0.304		
					0.308					
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.000	0.000	0.000	0.000	0.291	0.313	0.313	0.298		
Section Loss (%)	0%	0%	0%	0%	7%	0%	0%	5%	-	-
Gross Loss	4%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	4.80
Rivet Hole (in)	0.81
# of Angles	2


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**U4L4 @L4**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)		0.262	0.313	0.278	0.299	0.258	0.313	0.270		
		0.252	0.304	0.294	0.297	0.221	0.295	0.273		
		0.188		0.303				0.304		
Wane		0.188				0.188				
In Plane Rivet Hole										
Average Section Remaining	0.313	0.234	0.308	0.292	0.298	0.240	0.304	0.282		
Section Loss (%)	0%	25%	1%	7%	5%	23%	3%	10%	-	-
Gross Loss	9%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**L4L5 @ Tie Plate 1**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)		0.335	0.301			0.404	0.282			
		0.284	0.361			0.355	0.385			
						0.293	0.438			
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.438	0.310	0.331	0.438	0.438	0.351	0.368	0.438	0.375	0.375
Section Loss (%)	0%	29%	24%	0%	0%	20%	16%	0%	0%	0%
Gross Loss	5%									

Member	L5x3x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0.375
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	3.31
Original Area of Steel (in <sup>2</sup> )	21.48
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**L5U6 @ L5**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.222			0.262						
	0.210			0.280						
	0.207			0.320						
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.213	0.313	0.313	0.287	0.000	0.000	0.000	0.000		
Section Loss (%)	32%	0%	0%	8%	0%	0%	0%	0%	-	-
Gross Loss	12%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	4.80
Rivet Hole (in)	0.81
# of Angles	2


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 2**

**L5L6 Between Tie Plates 4 and 5**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.436	0.371	0.367	0.410	0.424	0.309	0.425	0.433	0.356	0.333
	0.404	0.348	0.356	0.415	0.421	0.326	0.314	0.404	0.359	0.372
					0.413	0.406	0.297	0.393	0.354	0.359
									0.312	0.335
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.420	0.360	0.362	0.413	0.419	0.347	0.345	0.410	0.345	0.350
Section Loss (%)	4%	18%	17%	6%	4%	21%	21%	6%	8%	7%
Gross Loss	10%									

Member	L5x 3-1/2 x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0.375
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	3.53
Original Area of Steel (in <sup>2</sup> )	22.36
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**U5L6 @ L6**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)					0.295			0.252		
					0.284			0.260		
					0.274			0.279		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.000	0.000	0.000	0.000	0.284	0.313	0.313	0.264		
Section Loss (%)	0%	0%	0%	0%	9%	0%	0%	16%	-	-
Gross Loss	6%									

Member	L3x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	3.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	1.78
Original Area of Steel (in <sup>2</sup> )	3.55
Rivet Hole (in)	0.81
# of Angles	2


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**U6L6 @ L6**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.310	0.199	0.313	0.306	0.313	0.261	0.313	0.298		
	0.288	0.187	0.307	0.288	0.291	0.233	0.307	0.301		
	0.270		0.298	0.330	0.287			0.310		
Wane		0.188				0.125				
In Plane Rivet Hole										
Average Section Remaining	0.289	0.193	0.306	0.308	0.297	0.247	0.310	0.303		
Section Loss (%)	7%	38%	2%	1%	5%	21%	1%	3%	-	-
Gross Loss	9%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**L6U7 @ L6**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.313			0.297	0.304			0.295		
	0.310			0.293	0.313			0.313		
	0.302			0.271						
Wane										
In Plane Rivet Hole				0.813				0.8125		
Average Section Remaining	0.308	0.313	0.313	0.287	0.308	0.313	0.313	0.304		
Section Loss (%)	1%	0%	0%	8%	1%	0%	0%	3%	-	-
Gross Loss	8%									

Member	L4x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	4.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.09
Original Area of Steel (in <sup>2</sup> )	8.36
Rivet Hole (in)	0.81
# of Angles	4




CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**L6L7 @ Tie Plate 1**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.267	0.221	0.210	0.274	0.305	0.179	0.185	0.293	0.288	0.264
	0.270	0.230	0.205	0.277	0.295	0.158	0.197	0.299	0.291	0.304
	0.287			0.295	0.303			0.301	0.296	0.288
									0.208	0.223
Wane						0.125	0.250			
In Plane Rivet Hole										
Average Section Remaining	0.275	0.226	0.208	0.282	0.301	0.169	0.191	0.298	0.271	0.270
Section Loss (%)	12%	28%	34%	10%	4%	46%	39%	5%	13%	14%
Gross Loss	18%									

Member	L5x 3-1/2 x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0.3125
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	2.56
Original Area of Steel (in <sup>2</sup> )	17.11
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: JPA

Checked By: JMF



**Section Loss Summary- Span 2 Truss 2**

**L6L7 @ Tie Plate 2**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)					0.313	0.222	0.309	0.340	0.249	0.207
					0.313	0.286	0.224	0.327	0.309	0.307
					0.313			0.254	0.301	0.305
									0.247	0.237
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.313	0.313	0.313	0.313	0.313	0.254	0.267	0.307	0.277	0.264
Section Loss (%)	0%	0%	0%	0%	0%	19%	15%	2%	12%	16%
Gross Loss	8%									

Member	L5x 3-1/2 x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0.3125
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.50
Length of Plate (in)	11
Area of Angle (in <sup>2</sup> )	2.56
Original Area of Steel (in <sup>2</sup> )	17.11
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**U7L7 @ L7**

Leg	**A	B	C	**D	** E	F	G	**H	Left Plate	Right Plate
Measured Thickness (in)	0.338			0.356	0.338			0.356		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.338	0.375	0.375	0.356	0.338	0.375	0.375	0.356		
Section Loss (%)	10%	0%	0%	5%	10%	0%	0%	5%	-	-
Gross Loss	5%									

Member	L5x3x3/8
Nominal Member Thickness (in)	0.3750
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.86
Original Area of Steel (in <sup>2</sup> )	11.44
Rivet Hole (in)	0.81
# of Angles	4

\*\*Values were estiamted visually


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**L7U8 @ L7**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.438			0.438	0.438			0.438		
					0.421			0.438		
					0.435			0.438		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.438	0.438	0.438	0.438	0.431	0.438	0.438	0.438		
Section Loss (%)	0%	0%	0%	0%	1%	0%	0%	0%	-	-
Gross Loss	0%									

Member	L4x3x7/16
Nominal Member Thickness (in)	0.4375
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	4.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.87
Original Area of Steel (in <sup>2</sup> )	11.48
Rivet Hole (in)	0.81
# of Angles	4


CHA Project # 23968

Location: Concord, New Hampshire

Bridge: Sewalls Falls Road over the Merrimack River

Input By: \_\_\_\_\_ JPA

Checked By: \_\_\_\_\_ JMF



**Section Loss Summary- Span 2 Truss 2**

**L8L9 @ L9**

Leg	A	B	C	D	E	F	G	H	Left Plate	Right Plate
Measured Thickness (in)	0.313	0.301	0.302	0.313	0.313	0.14	0.213	0.310		
	0.297	0.233	0.313	0.306	0.308	0.181	0.304	0.294		
	0.313			0.277	0.279	0.264	0.320	0.276		
Wane										
In Plane Rivet Hole										
Average Section Remaining	0.307	0.267	0.307	0.299	0.300	0.195	0.279	0.293		
Section Loss (%)	2%	15%	2%	4%	4%	38%	11%	6%	-	-
Gross Loss	9%									

Member	L5x3x5/16
Nominal Member Thickness (in)	0.3125
Nominal Plate Thickness (in)	0
Nominal Long Leg Length (in)	5.00
Nominal Short Leg Length (in)	3.00
Length of Plate (in)	0
Area of Angle (in <sup>2</sup> )	2.40
Original Area of Steel (in <sup>2</sup> )	9.61
Rivet Hole (in)	0.81
# of Angles	4

# Sewalls Falls Bridge 2012 In-Depth Inspection FIELD NOTES



Also @ 2' A/D Bottom flg bent to Begin 1" over 15"

<114115>

ABUTMENTS		WINGWALLS		STREAM CHANNEL		APPROACHES		Field Note Sheet	STANDARD PHOTOS	BIN	CITY	Cross	D.O.	Date
22 23 Joint with Deck	30 31 Stem	40 41 Walls	48 49 Erosion / Scour	53 Drainage	54 Embankment	55 Settlement	56 Erosion	A/D = above deck ①	Load Posting Approach Begin Approach End Feature Crossed Left Feature Crossed Right Abutment Begin Abutment End Elevation Left Right Span 1 Framing Framing Span 1 etc Trussing Floor Truss Pier 1 etc Utility -1 -2 etc Special emphasis -1 -2 etc.	114 070/117	Sewells Falls	Merrimack R	NE	3/5/2012
24 25 Brgs, AB's & Pads	32 33 Erosion / Scour	42 43 Footings	50 Waterway Opening	57 Pavement	58 Guiding	Span "A"	Span "A"							
26 27 Br Seat & Pedestals	34 35 Footings	44 45 Erosion / Scour	51 Bank Protection	59 Footings	60 Erosion / Scour	61 Piles	62 Pier Columns	UTILITIES						
28 29 Backwall	36 37 Piles	46 47 Piles	52 Stem Solid Pier	63 Pier Columns	64 Sign Structure	65 Utilities & Supports								
Span "A"	Span "A"	Span "A"	Span "A"	Span "A"	Span "A"	Span "A"	Span "A"							

✓ Span Item Photo Location / Description / ○ Rating / (Overall Summary, or Other Elements Summary) Photo ✓

1	28	1T1-LOU1	End post imp damage @ 7'-10" A/D: Bott channel flange bent up 1 3/4" over 15 (Pacing panel) [ web also slightly distorted over bottom 1/2". Else OK Top RL (only, not channel flg) bent up 1/2" over 9"	002
				3
				4
				5
1	28	1T1-U1L1	no I.D.	
1	28	1T1-U1L2	" "	
1	28	1T1 @ U1	Gen Config.	006
1	28	1T1-U2L2	appears twisted CCW 3° ± axially and out legs flared on Begin, pinched on End side. prob due ID 11" b to b 7 9" b to b to sway BC	007, 8, 9, 10, 11, 13, 14, 15
			Overall member not o.o.p. noticeably. No I.D.	
1	28	1T1 @ U2	Top HGRL for bracing: 1/8" p.r. @ edges	0012
1	28	1T1-L4(M)U5	Bent to Begin @ 5.3' from PPLA. 2 1/4" to End and 3/4" Left	0016, 17, 18, 19, 21 #, 22
1	28	1T1-U4(M)L5	Sight down; Elev:	20 # 29
1	28	1T1-U5(M)L6	Sight down	23, 24, 25
1	28	1T1 @ U5	Top HGRL for bracing: 1/16 - 3/32" p.r. @ Begin edge	26, 27, 28
1	28	1T1-L5(M)U6	Elev; Sight downs from (M)	30; 31, 32, 34
1	28	1T1 @ U6	Top HGRL for bracing up to 3/8" p.r. @ Beg edge	33
1	28	1T1-U5L6	Elev; Sight downs from (M)	35; 36, 37
1	28	1T1 @ U7	Top HGRL for bracing up to 1/2" p.r. Beg & End edges	38
1	28	1T1-U8L8	from U8: slight bow to End 1/4" ± @ mid-height.	40
1T1	1	28	1T1 Top Chord from U8	39
1T2	1	28	1T2 @ U1 - gen config; p.r. @ cap RL	41, 42
	1	28	1T2-U2U1 from U2 gen config; also U3+ from U2	43; 44, 45
	1	28	1T2 @ U3 = p.r. @ top HGRL, Beg Rt cor.	46
	1	28	1T2-L3U4 Elev; Sight downs	47; 48, 49, 50
	1	28	1T2 @ U4 = p.r. @ top HGRL	51



ABUTMENTS		WINGWALLS		STREAM CHANNEL		APPROACHES		Field Note Sheet		STANDARD PHOTOS		NH 070/117	
22 23 Joint with Deck	30 31 Stem	40 41 Wall	42 43 Footings	48 Alignment	49 Erosion / Scour	53 Drainage	54 Embankment	②	Load/Testing	Approach/Begin	Feature/Crossed/Left	Abutment/Begin	BIN
24 25 Brgs, AB's, & Pads	32 33 Erosion / Scour	44 45 Erosion / Scour	46 47 Piles	50 Waterway Opening	51 Bank Protection	55 Settlement	56 Erosion		Feature/Crossed/Right	Abutment/End	Elevation/Left/Right/Span/1 etc	Framing/Floor/Truss	Carry
26 27 Br Seat & Pedestals	34 35 Footings	48 Alignment	49 Erosion / Scour	53 Drainage	54 Embankment	55 Settlement	56 Erosion		Abutment/End	Elevation/Left/Right/Span/1 etc	Framing/Floor/Truss	Pier/1 etc	Cross
28 29 Backwall	36 37 Piles	40 41 Wall	42 43 Footings	48 Alignment	49 Erosion / Scour	53 Drainage	54 Embankment		Abutment/End	Elevation/Left/Right/Span/1 etc	Framing/Floor/Truss	Pier/1 etc	D.O.
Span "A"	Span "A"	Span "A"	Span "A"	Span "A"	Span "A"	Span "A"	Span "A"		Utilities	43 Light Sids & Fixtures	44 Sign Structure	45 Utilities & Supports	Dates
DECK ELEMENTS		SUPERSTRUCTURE		PIER		UTILITIES							
19 Wearing Surface	23 Scuppers	27 Deck	33 Brgs, AB's, & Pads	38 Pier Columns	43 Light Sids & Fixtures	44 Sign Structure	45 Utilities & Supports						
20 Curbs	24 Gratings	28 Primary	34 Pedestals	39 Footings	40 Erosion / Scour	41 Piles							
21 Sidewalks & Fascias	25 Median	29 Secondary	35 Top of Cap or Beam	40 Erosion / Scour									
22 Railings & Parapets	26 Mono Deck Surface	30 Paint	36 Stem Solid Pier	41 Piles									
		31 Joints	37 Cap Beam										

✓	Span	Item	Photo Location / Description / ○ Rating / (Overall Summary, or Other Elements Summary)	Photo	✓
	1	28	1T2-U4L5 Elevs (52,53); Sight-downs	0052,53; 54,55,56,57	
	1	28	1T2@U5 = gen config typ condition (good)	58,59	
	1	28	1T2-U5L6 look down from U5	60	
	1	28	1T2@U7: p.r. @ top HGR = U6U7 top R pitting up to 1/8" deep, max	61	
			so 33% SL for 3/8 R (conservative)		
3/5					
3/6	2	28/29	2T1@U1: up to 3/8" p.r. @ cap R. Trough of SL to 1/8" mark.	65,66	
	2	28	2T1-L0U1@ 7.7' above deck = I.D. to lower chan flg 4" long x 1/4" flg only	67,68	
	2	28	2T1-U5(M)L6 from U5: I.D. sight down	69,70	
			elev & sight down from M:	71,72,73	
	2	28/29	2T1@U6: p.r. @ top HGR (typ.)	74	
			plan view	75,76	
	2	28	2T1-U8L8: slight I.D. @ bottom rail bracket = End Rt L lungit	77,78	
			leg bent out 5/16" over 5" length @ 4.8' from L8		
	1	28	Top chord panel point photo survey - gen config	Span 1 (79) (80-87)	
				Span 2 (88-95)	
	2	28	2T2-L0U1@ 8.0' A/D: dent in edge top R 3" long x 3/16"	96,97	
	2	28	2T2-U2U3 p.r. scallops < 1/8", intermittent, infreq, from U2 (typ.)	98	
	2	28	2T2-U5(M)L6 lower half bowed inbd (left): Elev; look downs from M	101,102,103	
	2	28	2T2@U5 - typ condition inside PP (upper)	99,100	
	2	28	2T2-U8L9 @ A/D = ID to chan BF 7/8 x 15", Top R 5/8 x 8"	106,107	
	2	28	2T2@U7: p.r. @ HGR	104,105	
	1	29	Portal BC's @ U1#U8 - No I.D. evid.		
	1	29	Sway brace BC @ pp2: 1 1/2" to Begin	110, 108, 109	
	1	29	" " " @ pp3: 2" to Begin	111, 112	
	1	29	" " " pp4: 1 1/4" ± " (est.)	No Photo	
	1	29	" " " pp5: NS Def; pp6: 1/2" ± to Begin; pp7: 3/8" to Begin	" "	
	2	29	Portal BC @ U1#U8 No I.D. evid		
	2	29	Sway brace BC @ pp2: 1/4" ± to Begin		
			pp3: NS Def; pp4: 1/8" ± to Beg; pp5: 3/4" to Beg.		
			pp6: 1/2" to Beg. pp7 NS Def.		



## CHA COMPUTATION PAD



COMPLETED BY: Tue Albert  
CHECKED BY: C. Snyder  
PROJECT NAME: Sewalls Falls BI  
PROJECT LOCATION: Concord, NH

PROJECT: 23968 PHASE: 1000 ORG:   
SHEET #: 1 OF 2  
DATE: 3/5/2012  
SUBJECT: Truss impact damage SP1

(3)

### Impact damages - Primary Members

- (inboard) SP1 T1 L4(M)U5 @ 5.3' From PP4 measured along member, bent  $2\frac{1}{4}"$   $\perp$  Long.  $5/8"$  Transverse  
Outboard & Leg bent  $\approx \frac{1}{2}"$  Longitudinally  $\perp$ , minimal transverse bending if any.
- (inboard) SP1 T1 L5(M)U6 @ 5.5' From PP5 measured along member, bent  $4\frac{1}{8}"$  Longitudinally  $\perp$   
inboard  $\approx 1\frac{1}{8}"$  Transverse  
outboard  $\frac{1}{4}" \times 1\frac{5}{8}"$   $L^{\perp} \times T$
- SP1 T1 L5(M)U4 @ 6.5' From PP5 measured along member, bent  $\approx \frac{1}{4}" \times \frac{1}{4}"$   $L^{\perp} \times T$
- SP1 T1 U5(M)L6 @ 5.5' From PP6 M.A.M bent  $2\frac{1}{4}" \times 1"$   $L^{\perp} \times T$  (inboard) Max  
 $\frac{1}{4}" \times \frac{1}{4}"$   $L^{\perp} \times T$  (outboard)
- SP1 T1 L6U7 localized impact of inboard bottom & leg 5.5' From PP6  $5\frac{1}{8}"$  long  $1"$  in
- SP1 T2 L1U1 Begin site inboard & leg @ rail supports & leg bent downstream max of  $\frac{1}{2}"$  at bottom two rail supports.
- SP1 T2 L3(M)U4 inboard @ 4.5' From PP3  $5\frac{1}{4}" \times 2\frac{1}{4}"$   $L^{\perp} \times T$  twisted downstream  
outboard @ 4.5' " "  $3\frac{1}{8}" \times 1\frac{3}{8}"$   $L^{\perp} \times T$  bent toward d/s.
- SP1 T2 L5(M)U4 inboard @ 6.8' From PP5  $6" \times 2\frac{3}{4}"$   $L^{\perp} \times T$  twisted upstream  
outboard @ 6.8' From PP5  $5\frac{1}{8}" \times 1\frac{1}{2}"$   $L^{\perp} \times T$  twisted upstream
- SP1 T2 L6(M)U5 inboard @ 8.7' From PP6  $5\frac{1}{8}" \times 0"$   $L^{\perp} \times T$  bowed toward begin



→  
see back  
for descriptive sketch





## CHA COMPUTATION PAD

COMPLETED BY: Joe Albert  
CHECKED BY: C. Snyder  
PROJECT NAME: Sewalls Falls Bridge Inspection  
PROJECT LOCATION: Concord, New Hampshire

PROJECT: 23968 PHASE: 1000 ORG: —

SHEET #: 2 OF 2

DATE: 3/6/2012

SUBJECT: Impact damages span 2

④

Impact damage

Span 2

T1 L6(M)U5 inboard @ 5.0' from PP6  $3\frac{3}{4}" \times 1\frac{3}{4}"$  L<sup>+</sup>XT twisted upstream  
outboard @ 5.0' from PP6  $3\frac{3}{4}" \times 1\frac{1}{2}"$  L<sup>+</sup>XT twisted upstream

T2 L6(M)U5 inboard @ 10.8' from PP6  $1\frac{1}{2}" \times 1\frac{1}{4}"$  L<sup>+</sup>XT bent upstream


## CHA COMPUTATION PAD

COMPLETED BY: JPA /  
CHECKED BY: CDS  
PROJECT NAME: Sewalls Falls bridge inspection  
PROJECT LOCATION: Concord, New Hampshire

PROJECT: 239681000 PHASE: ORG:   
 SHEET #: 1 OF 1 DATE: 3/6/2012 SUBJECT: Field Verification of dimensions

⑤

File 3998-05.TIF



## Field Measurements


4 Bridge

Span 1 161'-2" edge  $\pi$  to edge  $\pi$  129'-10"  
Span 2 159'-2" " " 129'-9 1/4"



✓	Span	T#	Member ID (L, U, M) Member Build (4L...)	Leg A	Leg B	Leg C	Leg D	Leg E	Leg F	Leg G	Leg H	Comments / R's	Photo
1	T1	L1L2@L1	.306	N/A	N/A	.314	.317	.297	.314	.286			
		4L5x3x5/16	.310			.316	.278	.312	.250	.266			
			.315			.325	.261			.316			
			.310 1%	~leg F	~leg G	0%	.285 9%	.305 3%	.282 10%	.289 8%			
1	T1	L0L1@L1	similar but less SL than L1L2@L1										
1	T1	L2L3@	.304			.285	.264	.241	.139	.274	L R		
		Tie R #1	.293			.278	.271	.291	.224	.284	.167	R R	
		4L5x3 1/2 x 5/16	.291			.287	.279			.279	.281	.157	
		+ 2R11x5/16								.280	.280		
										.224	.293		
			5%			9%	13%	15%	42%	11%	24%	18%	
1	T1	L2L3@	.304			.285	.245	.193	.201	.275	L R		
		Tie R #3	.293			.278	.258	.225	.226	.277	.132	R R	
		(same as above)	.291			.287	.268			.266	.231	.181	
			5%			9%	18%	33%	25%	13%	27%	20%	
										32%			
1	T1	U3L3@L3	.318	NSSL	.226	.297	.305	NSSL	.234	.292			
		4L5x3x5/16	.311		.219	.298	.300		.209	.294			
			.312			.302	.312			.304			
			-		29%	4%	2%		29%	5%			
1	T1	L3L4@L4	NSSL	——	NSSL	NSSL	.279	.271	NSSL	Loca, inside panel			
		4L5x3 1/2 x 7/16 (.430)					.333	.246		point, obvious not			
		+ 2R11x7/8 (.372)					30%	41%		Control; for info only			

%SL	3/16"	1/4"	5/16"	3/8"	7/16"	1/2"	9/16"	3/4"
0	0.1875	0.250	0.3125	0.375	0.4375	0.500	0.5625	0.750
15	0.159	0.213	0.266	0.319	0.372	0.425	0.478	0.638
25	0.141	0.188	0.234	0.281	0.328	0.375	0.422	0.563
33.33	0.125	0.167	0.208	0.250	0.292	0.333	0.375	0.500
50	0.094	0.125	0.156	0.188	0.219	0.250	0.281	0.375
66.66	0.063	0.083	0.104	0.125	0.146	0.167	0.188	0.250
75	0.047	0.063	0.078	0.094	0.109	0.125	0.141	0.188
85	0.019	0.025	0.031	0.036	0.042	0.048	0.054	0.072
95	0.009	0.013	0.016	0.019	0.022	0.025	0.028	0.038



### ISEC Member Section Losses

Legend:  
k or Ok: knife edge  
w or wane: width loss  
p or perf: perforation  
SL: section loss  
GSL or SLG: gross SL  
Units: inch UON

(171)

(7)

BIN **NH 070/117**  
Carry **Sewells Falls Road**  
Cross **Merrimack River**  
D.O. **Northeast**  
Date **3/7/2012**

✓	Span	T#	Member ID (L, U, M) Member Build (4L...)	Leg A	Leg B	Leg C	Leg D	Leg E	Leg F	Leg G	Leg H	Comments	Photo	✓
	1	T1	U5L5@L5	NSSL	.310	.212	NSSL	NSSL	.253	.230	.285			
			4L5x3x5/16		.246	.233			.311	.242	.266			
					11%	29%			10%	24%	.295			
											10%			
			(1 T1 U6L6 sim.)											
	1	T1	L5U6@L5	.291	NSSL	NSSL	.233							
			2L5x3x5/16	.293			.228							
				.297			.246							
				6%			25%							
	1	T1	L5L6@tie	.428	—	—	.424	.367	.362	.274	.395	LPE RPE .320 .331		
			tie #5	.417	Sim to legs F&G		.415	.370	.360	.307	.390	.325 .324		
			4L5x3 1/2 x 5/16					.376			.227	.320 .319		
			+ 2R 11x3/8	3%			4%	15%	17%	34%	23%	.190 .312		
												23% 14%		
	1	T1	U5L6@L6					.324	NSSL	NSSL	.285			
			2L3x3x5/16					.313			.302			
								—			6%			
	1	T1	L6U7@L6	.328	NSSL	NSSL	.306	.318	NSSL	NSSL	.310			
			4L5x3x5/16	.314			.288	.314			.315			
				.313			.289							
				—			6%	—			—			
	1	T1	L6L7	.272	—	—	.257	.259	.181	.180	.288	LPE RPE .162 .192		
			@tie tie #3	.275	Sim to F&G		.256	.288	.224	.162	.257	.295 .295		
			4L5x3 1/2 x 5/16	12%			16%	.295		.177	.246	.280 .271		
			+ 2R 11x5/16					10%	35%	45%	16%	.185 .141		
												26% 28%		



%SL	3/16"	1/4"	5/16"	3/8"	7/16"	1/2"	9/16"	3/4"
0	0.1875	0.250	0.3125	0.375	0.4375	0.500	0.5625	0.750
15	0.159	0.213	0.266	0.319	0.372	0.425	0.478	0.638
25	0.141	0.188	0.234	0.281	0.328	0.375	0.422	0.563
33.33	0.125	0.167	0.208	0.250	0.292	0.333	0.375	0.500
50	0.094	0.125	0.156	0.188	0.219	0.250	0.281	0.375
66.66	0.063	0.083	0.104	0.125	0.146	0.167	0.188	0.250
75	0.047	0.063	0.078	0.094	0.109	0.125	0.141	0.188
85	0.019	0.025	0.031	0.036	0.042	0.048	0.054	0.071
95	0.009	0.013	0.016	0.019	0.022	0.025	0.028	0.038

**ISEC Member Section Losses**

Legend:  
k or Ok: knife edge  
w or wane: width loss  
p or perf: perforation  
SL: section loss  
GSL or SLG: gross SL  
Units: inch UON

1 T2

8

BIN: **NH 070/117**

Carry: **Sewells Falls Road**

Cross: **Merrimack River**


D.O.: **Northeast**

Date: **3/7/2012**

Span	T#	Member ID (L, U, M) Member Build (4L...)	Leg A	Leg B	Leg C	Leg D	Leg E	Leg F	Leg G	Leg H	Comments	Photo	
✓	1	T2 L0L1@L0 4L5x3x5/16	No better than Leg E	No better than F#G	No better than Leg H	.310 .303 .276	.134 .203 .217	.220 .207 .227	.202 .200			<202,34,5,6>	
							5%	41%	32%	33%			
	1	T2 L0L1@L1 (same as above)	.240 .312 .331 6%	— No better than F#G	— 226 207	.325 .284 .204	.275 .139 .198	.151 .171 .242	.125 .212 .279	.323		<207,08>	
							19%	19%	48%	43%	13%		
	1	T2 L2L3@L3 4L5x3 1/2 x 5/16 +2R	.289 .292	— —	— —	.253 .264 .286	.284 .279 .285	.206 .193 .160	.141 .202 .209	.313 .293 .302	LFE .264 .298 .293 .275	RFE .263 .304 .290 .111	<218,19,20,21,22>
			7%			14%	10%	40%	41%	3%	25%	35%	
	1	T2 U2L3@L3 4L4x3x3/16	.320 .309 .277 3%	NSSL	NSSL	.312 .317 .314	.252 .277 .297	NSSL	NSSL	.293 .298 .301		<223,24,25,26>	
							12%			5			
	1	T2 U3L3@L3 4L5x3x5/16	.291 .279 .266 11%	.203 .218 33%	.314 .293 3%	.311 .261 .260 11%	.304 .278 .274 9%	.292 .212 Ok w 5/16	.314 .299	.271 .272 .291		<227,28,29>	
							46%	2%	11%				
	1	T2 L3U4@L3 2L3x3x5/16	.271 .266 .261 15%	NSSL	NSSL	.272 .269 .288 12%	N/A					<230,31,32>	



%SL	3/16"	1/4"	5/16"	3/8"	7/16"	1/2"	9/16"	3/4"
0	0.1875	0.250	0.3125	0.375	0.4375	0.500	0.5625	0.750
15	0.159	0.213	0.266	0.319	0.372	0.425	0.478	0.638
25	0.141	0.188	0.234	0.281	0.328	0.375	0.422	0.563
33.33	0.125	0.167	0.208	0.250	0.292	0.333	0.375	0.500
50	0.094	0.125	0.156	0.188	0.219	0.250	0.281	0.375
66.66	0.063	0.083	0.104	0.125	0.146	0.167	0.188	0.250
75	0.047	0.063	0.078	0.094	0.109	0.125	0.141	0.188
85	0.019	0.025	0.031	0.036	0.042	0.048	0.054	0.072
95	0.009	0.013	0.016	0.019	0.022	0.025	0.028	0.038



# ISEC Member Section Losses

Legend:  
k or Ok: knife edge  
w or wane: width loss  
p or perf: perforation  
SL: section loss  
GSL or SLG: gross SL  
Units: inch UON

BIN **NH 070/117**

Carry **Sewells Falls Road**

Cross **Merrimack River**

D.O. **Northeast**

Date **3/7/2012**

**3/8/2012**

✓	Span	T#	Member ID (L, U, M) Member Build (4L...)	Leg A	Leg B	Leg C	Leg D	Leg E	Leg F	Leg G	Leg H	Comments	Photo	✓
	1	T2	L3L4	.393	—	—	.406	.419	.330	.309	.420	LR .295 .338	<233, 34, 35>	
			@ 8.2' from L3	.381			.396	.402	.422	.346	.402	.367 .364	36, 37, 38 >	
			4L5x3 1/2 x 7/16"	12%			8%	6%	14%	25%	.415 .258 .335	.353 .319		
			+ 2R11 x 3/8"								W 1/8"			
											16%	8%		
3/7														
18	1	T2	U3L4 @ L4					.271	NSSL	NSSL	.323		<239, 40, 41>	
			2L5x3x5/16"					.255			.298			
								.244			.289			
								18%			3%			
	1	T2	U4L4 @ L4	.271	W 3/16"	.304	.299						<242, 43, 44>	
			4L5x3x5/16"	.259	.230	.292	.297						45>	
				.269	.242		.314							
				15%	29%	5%	3%	3%±	29%±	5%	NSSL			
	1	T2	U5L5 @ L5	.297	.232	.297	.301						<252, 53, 54, 55>	
			4L5x3x5/16"	.288	.225	.316	.306							
				.294			.314							
				6%	27%	2%	2%	NSSL	27%±	2%	2%			
	1	T2	L5U6 @ L5	.302	NSSL	NSSL	.274						<256, 57>	
			2L5x3x5/16"	.313			.272							
				.308			.248							
				21			15%							
	1	T2	L5L6	.430	.352	.357	.429	.436	.351	.312	.427	LR .373 .344	<258, 58, 60>	
			@ Tie R #2	.422	.342	.332	.419	.420	.338	.308	.418	.365 .366		
			4L5x3 1/2 x 7/16"					.418			.428	.364 .359	.362 .297	
			+ 2R11 x 3/8"											
				3%	21%	21%	3%	3%	21%	29%	3%	3%	9%	

%SL	3/16"	1/4"	5/16"	3/8"	7/16"	1/2"	9/16"	3/4"
0	0.1875	0.250	0.3125	0.375	0.4375	0.500	0.5625	0.750
15	0.159	0.213	0.266	0.319	0.372	0.425	0.478	0.638
25	0.141	0.188	0.234	0.281	0.328	0.375	0.422	0.563
33.33	0.125	0.167	0.208	0.250	0.292	0.333	0.375	0.500
50	0.094	0.125	0.156	0.188	0.219	0.250	0.281	0.375
66.66	0.063	0.083	0.104	0.125	0.146	0.167	0.188	0.250
75	0.047	0.063	0.078	0.094	0.109	0.125	0.141	0.188
85	0.019	0.025	0.031	0.036	0.046	0.055	0.064	0.112
95	0.009	0.013	0.016	0.019	0.022	0.025	0.028	0.038

End (or BC Top) Side  
Begin (or BC Bottom) Side

**ISEC Member Section Losses**

**Legend:**  
k or OK: knife edge  
w or wane: width loss  
p or perf: perforation  
SL: section loss  
GSL or SLG: gross SL  
Units: inch UON

**NH 070/117**  
**Sewells Falls Road**  
**Merrimack River**  
**Northeast**  
**3/8/2012**

✓	Span	T#	Member ID (L, U, M) Member Build (4L...)	Leg A	Leg B	Leg C	Leg D	Leg E	Leg F	Leg G	Leg H	Comments	Photo	✓
	1	T2	U5L6@L6					.313	NSSL	NSSL	.293			
			2L3X3X5/16"		N/A			.284			.310			
								.291			.319			
								5%			2%			
	1	T2	U6L6	.296	.272	NSSL	.292	.307	.191	.305	.287			
			4L5X3X5/16"	.281	.246		.279	.265	.235	.320	.285			
				.277			.314	.253	.201		.311			
				9%	17%		6%	12%	33%	-	6%			
	1	T2	L6U7	5%±	0%	0%	10%	5%	0%	0%	10%±			
			4L5X3X5/16"											
	1	T2	L6L7	.266	w 3/16"	.216	.268	.275	.289	.241	.294	L#	R#	
			@ Tie #1	.281	.254	.152	.265	.284	.308	.229	.277	.247	.235	
			4L5X3X5/16"	.271	.304		.293	.282		.281	.271	.300	.305	
			+2#11x"	13%	11%	61%	12%	10%	4%	23%	10%	.147	.195	
						41%						33%	33%	
	1	T2	U7L7@L7	5%	10%	5%	NSSL	5%	10%	5%	NSSL			
			4L5X3X5/16"											
	1	T2	L7U8@L7	10%	0%	0%	5%	10%	0%	0%	10%			
			4L4X3X7/16"											
	1	T2	L7L8@L8	.293	NSSL	NSSL	.314	.304	NSSL	NSSL	.323			
			(worst of L7-L9)	.372			.309	.308			.297			
			4L5X3X5/16"	.310			.317	.314			.293			
				4%			-	1%			3%			



%SL	3/16"	1/4"	5/16"	3/8"	7/16"	1/2"	9/16"	3/4"
0	0.1875	0.250	0.3125	0.375	0.4375	0.500	0.5625	0.750
15	0.159	0.213	0.266	0.319	0.372	0.425	0.478	0.638
25	0.141	0.188	0.234	0.281	0.328	0.375	0.422	0.563
33.33	0.125	0.167	0.208	0.250	0.292	0.333	0.375	0.500
50	0.094	0.125	0.156	0.188	0.219	0.250	0.281	0.375
66.66	0.063	0.083	0.104	0.125	0.146	0.167	0.188	0.250
75	0.047	0.063	0.078	0.094	0.109	0.125	0.141	0.188
85	0.019	0.025	0.031	0.036	0.042	0.047	0.054	0.071
95	0.009	0.013	0.016	0.019	0.022	0.025	0.028	0.038

End (or BC Top) Side

Begin (or BC Bottom) Side

**ISEC Member Section Losses**

Legend:  
k or ok: knife edge  
w or wane: width loss  
p or perf: perforation  
SL: section loss  
GSL or SLG: gross SL  
Units: inch UON

2T1

11

**NH 070/117**

Carry: **Sewells Falls Road**


Cross: **Merrimack River**

D.O.: **Northeast**

Date: **3/8/2012**

Span	T#	Member ID (L, U, M)	Member Build (4L...)	Leg A	Leg B	Leg C	Leg D	Leg E	Leg F	Leg G	Leg H	Comments	Photo	✓
✓	2	T1	L1L2@L1	.312	N	N	.310	.282	N	N	.301			
			4L5x3x5/16"	.303			.312	.287			.288			
								.283			.297			
				2%			-	9%			5%			
			(2 T1 L0L1)										<302>	
7	2	T1	U2L2@L2	N	.352	.274	N	N	.350	.293	N		<312, 13>	
			12" below top of		.353	.236			.364	.319				
#			PP Gusset Pls		6%				5%	18%				
			5x3x3/8		6%	.321								
	2	T1	U1L2@L2	5%±	0%	0%	5%±	0%	0%	0%	0%		<309, 10, 11>	
	2	T1	L2L3	.285	.312	.278	.272	.174	.224	.292	.293	LPE RPE	<314, 15, 16, 17>	
			@ Tie #5	.276		.287	.283	.178	.276	.225	.276	.234	.301	
			4L5x3x5/16"	.290			.291	.205	.312	.173	.267	.187	.290	
				9%	-	10%	10%	41%	13%	26%	11%	.066	.086	
												62%	42%	
	2	T1	U2L3@L3	5%±	0%	0%	5%±	.318	0%	0%	.280		<318, 19, 20>	
			4L4x3x5/16" w					.303			.287			
											.299			
								1%			8%			
	2	T1	U3L3@L3	.303	NSSL	.231	.299	.266	.310	.221	.292		<321, 22>	
			4L5x3x5/16"	.296		.246	.264	.297	.315	.236	.280			
				.292		.265	.285	.305	.318	.209	.287			
				5%		21%	10%	7%	-	29%	8%			
	2	T1	L3U4@L3	.303	NSSL	NSSL	.305						<323, 24, 25>	
			2L3x3x5/16	.284			.266							
				.292			.298							
				6%			7%							



%SL	3/16"	1/4"	5/16"	3/8"	7/16"	1/2"	9/16"	3/4"	End (or BC Top) Side		ISEC Member Section Losses		BIN	NH 070/117						
0	0.1875	0.250	0.3125	0.375	0.4375	0.500	0.5625	0.750			<b>Legend:</b> k or Ok: knife edge w or wane: width loss p or perf: perforation SL: section loss GSL or SLG: gross SL Units: inch UON		Carry	Sewells Falls Road						
15	0.159	0.213	0.266	0.319	0.372	0.425	0.478	0.638			<b>Legend:</b> k or Ok: knife edge w or wane: width loss p or perf: perforation SL: section loss GSL or SLG: gross SL Units: inch UON		Cross	Merrimack River						
25	0.141	0.188	0.234	0.281	0.328	0.375	0.422	0.563					D.O.	Northeast						
33.33	0.125	0.167	0.208	0.250	0.292	0.333	0.375	0.500			<b>Legend:</b> k or Ok: knife edge w or wane: width loss p or perf: perforation SL: section loss GSL or SLG: gross SL Units: inch UON		Date	3/8/2012						
50	0.094	0.125	0.156	0.188	0.219	0.250	0.281	0.375							<b>Legend:</b> k or Ok: knife edge w or wane: width loss p or perf: perforation SL: section loss GSL or SLG: gross SL Units: inch UON					
66.66	0.063	0.083	0.104	0.125	0.146	0.167	0.188	0.250			<b>Legend:</b> k or Ok: knife edge w or wane: width loss p or perf: perforation SL: section loss GSL or SLG: gross SL Units: inch UON									
75	0.047	0.063	0.078	0.094	0.109	0.125	0.141	0.188												
85	0.019	0.025	0.031	0.036	0.042	0.048	0.054	0.071							<b>Legend:</b> k or Ok: knife edge w or wane: width loss p or perf: perforation SL: section loss GSL or SLG: gross SL Units: inch UON					
95	0.009	0.013	0.016	0.019	0.022	0.025	0.028	0.038			<b>Legend:</b> k or Ok: knife edge w or wane: width loss p or perf: perforation SL: section loss GSL or SLG: gross SL Units: inch UON									

Span	T#	Member ID (L, U, M) Member Build (4L...)	Leg A	Leg B	Leg C	Leg D	Leg E	Leg F	Leg G	Leg H	Comments	Photo	✓
2 T1	L3L4@		.428	.406	.409	.422	.394	.390	.386	.383	LTP .278 RTP .302	<326, 27, 28, 29	
	btwn Tie P's #1 & #2		.424	.422	.403	.408	.390		.372	.395	.327 .342		
	4L5x3/2x7/16						.395			.387	.326 .353		
	+2P11x3/8		3%	5%	7%	5%	10%	11%	13%	11%	.338 .318		
											27% 12%		
2 T1	U3L4@L4		N/A				5%	0%	0%	.265		<330, 31, 32>	
	2L5x3x5/16									.273			
										.311			
										9%			
2 T1	U4L4@L4		.310	.306	.179	.281	.297	.295	.186	.283		<333, 34, 35>	
	4L5x3x5/16		.292	.292	.201	.258	.287		.182	.286			
			.286		.255	.273	.292		.225				
			5%	4%	32%	13%	7%	6%	37%	9%			
2 T1	L4U5@L4		NSSL									<336, 37>	
	2L3x3x5/16												
2 T1	L4L5 all		<5%						<5%		<5% LTP <5% RTP	<338>	
	4L5x3/2x1/2												
2 T1	U4L5@L5		N/A				NSSL					<339, 40>	
	2L3x3x5/16												
2 T1	U5L5@L5		5%	5%	10%	5%	5%	5%	10%	5%		<341, 42>	
	4L5x3x5/16												
2 T1	L5U6@L5		0%	0%	0%	.322	N/A					<343, 44, 45>	
	2L5x3x5/16"					.275							
						.272							
						7%							
2 T1	L5L6@		.427	.413	.323	.423	.412	.342	.415	.419	LTP .303 RTP .337	<346, 47, 48, 49>	
	btwn Tie P's #2 & #3		.412	.410	.318	.417	.402	.422	.333	.406	.361 .372		
	4L5x3/2x7/16						.416			.412	.352 .359		
			4%	6%	27%	4%	6%	13%	15%	6%	.352 .367		
											9% 4%		



BR-NOTE-~~Times-Gazette~~ Plateau-B8.doc

%SL	3/16"	1/4"	5/16"	3/8"	7/16"	1/2"	9/16"	3/4"	End (or BC Top) Side		ISEC Member Section Losses		NH 070/117		
0	0.1875	0.250	0.3125	0.375	0.4375	0.500	0.5625	0.750			Legend: k or 0k: knife edge w or wane: width loss p or perf: perforation SL: section loss GSL or SLG: gross SL Units: inch UON		Carry: Sewells Falls Road Cross: Merrimack River D.O. Northeast Date: 3/9/2012		
15	0.159	0.213	0.266	0.319	0.372	0.425	0.478	0.638							
25	0.141	0.188	0.234	0.281	0.328	0.375	0.422	0.563							
33.33	0.125	0.167	0.208	0.250	0.292	0.333	0.375	0.500							
50	0.094	0.125	0.156	0.188	0.219	0.250	0.281	0.375							
66.66	0.063	0.083	0.104	0.125	0.146	0.167	0.188	0.250							
75	0.047	0.063	0.078	0.094	0.109	0.125	0.141	0.188							
85	0.019	0.025	0.031	0.056	0.066	0.075	0.084	0.112							
95	0.009	0.013	0.016	0.019	0.022	0.025	0.028	0.038							
									Begin (or BC Bottom) Side						
Span	T#	Member ID (L, U, M)	Member Build (4L...)	Leg A	Leg B	Leg C	Leg D	Leg E	Leg F	Leg G	Leg H	Comments	Photo	✓	
✓		2 T2 L0L1 @ L0		.296	.303	.313	.316	.308	.299	.311	.302		<388, 88.90, 91>		
		4 L5 x 3 x 5/16"		.292	.299	.294	.312	.306	.312	.291	.309		<394>		
				.293			.312	.282			.316		L1L2		
				6%	4%	3%	0	4%	2%	4%	1%				
✓		2 T2 U1L2 @ L2		.289	0%	0%	.442	5%	0%	0%	5%		<395, 96, 97, 98>		
		4 L4 x 3 x 7/16		.192			.440								
				.432											
				31%			-								
✓		2 T2 L2L3 @		.284	.260	.310	.283	.269	.208	.314	.297	LTP .237	RTP .132	<401, 02, 03, 04>	
		Tie R #3		.288	.234	.304	.298	.295	.198	.207	.289	.313	.301		
		4 L5 x 3 1/2 x 5/16"		.302			.308	.295		.204	.277	.282	.277		
		+ 2 #11 x 5/16"									.247	.208			
				7%	21%	2%	5%	8%	35%	23%	8%	4%	27%		
✓		2 T2 U2L3 @ L3		.319	0%	0%	.282	.278	0%	0%	.247		<405, 06, 07>		
		4 L4 x 3 x 5/16" (fat)		.308			.324	.281			.324				
								.307			.190				
				-			3%	8%			19%				
✓		2 T2 U3L3 @ L3		.311	.293	.313	.283	.294	.294	.295	.290		<408, 09>		
		4 L5 x 3 x 5/16"		.287	.305	.292	.307	.300	.313	.295	.258				
				.291			.297	.312			.269				
				5%	4%	3%	5%	3%	3%	6%	13%				
✓		2 T2 L3U4 @ L3		.299	0%	0%	.269	N/A					<410, 11>		
		2 L3 x 3 x 7/16		.274			.283								
				.275			.307								
				10%			8%								



%SL	3/16"	1/4"	5/16"	3/8"	7/16"	1/2"	9/16"	3/4"
0	0.1875	0.250	0.3125	0.375	0.4375	0.500	0.5625	0.750
15	0.159	0.213	0.266	0.319	0.372	0.425	0.478	0.638
25	0.141	0.188	0.234	0.281	0.328	0.375	0.422	0.563
33.33	0.125	0.167	0.208	0.250	0.292	0.333	0.375	0.500
50	0.094	0.125	0.156	0.188	0.219	0.250	0.281	0.375
66.66	0.063	0.083	0.104	0.125	0.146	0.167	0.188	0.250
75	0.047	0.063	0.078	0.094	0.109	0.125	0.141	0.188
85	0.019	0.025	0.031	0.036	0.042	0.048	0.054	0.072
95	0.009	0.013	0.016	0.019	0.022	0.025	0.028	0.038

**ISEC Member Section Losses**

**Legend:**  
k or Ok: knife edge  
w or wane: width loss  
p or perf: perforation  
SL: section loss  
GSL or SLG: gross SL  
Units: inch UON

2T2

15

BIN: **NH 070/117**  
Crry: **Sewells Falls Road**  
Crrs: **Merrimack River**  
D.O.: **Northeast**  
Date: **3/9/2012**

Span	T#	Member ID (L, U, M)	Member Build (4L...)	Leg A	Leg B	Leg C	Leg D	Leg E	Leg F	Leg G	Leg H	Comments	Photo	
✓	2 T2	L3L4 @ 2	btwn Tie Pls 2#3	.397	.322	.402	.418	.413	.400	.266	.420	LP .297	RP .327	<412, 13, 14, 15, 16>
		4L5x3x7/16"		.413	.442	.312	.397	.436		.409	.415	.353	.348	
		+2 Pl 11x3/8		51%	91%	181%	51%	91%	171%	251%	91%	.307	.334	
				51%	91%	181%	51%	91%	171%	201%	91%	131%	91%	
✓	2 T2	U3L4 @ L4	2L5x3x5/16"	N/A				.283	0%	0%	.292		<417, 18, 19>	
								.281			.304			
								.308						
								71%			51%			
✓	2 T2	U4L4 @ L4	4L5x3x5/16"	0%	.262	.318	.278	.299	.258	.314	.270			<420, 21>
					.252	.304	.294	.297	.221	.295	.273			
					.188		.303		w 3/16		.304			
					w 3/16									
					251%	-	71%	51%	231%	31%	101%			
✓	2 T2	L4U5 @ L4	2L3x3x5/16"	NSSL				N/A					<422>	
✓	2 T2	L4L5 @	Tie Pl #1	0%	.335	.301	0%	0%	.404	.282	0%	LP 0%	RP 0%	<423, 24, 25, 26>
		4L5x3x7/16"			.284	.361			.355	.385				
		+2 Pl 11x3/8			291%	241%			201%	161%				
✓	2 T2	U4L5 @ L5	2L3x3x5/16"	N/A				NSSL					<427, 28>	
✓	2 T2	U5L5 @ L5	4L5x3x5/16"	≤5%				≤5%					<429, 30>	
✓	2 T2	L5U6 @ L5		.222	0%	0%	.262	N/A					<431, 32>	
				.710			.280							
				.207			.320							
				321%			81%							

BR-NOTE-~~Truss Gussset Plates-B~~0.doc



%SL	3/16"	1/4"	5/16"	3/8"	7/16"	1/2"	9/16"	3/4"
0	0.1875	0.250	0.3125	0.375	0.4375	0.500	0.5625	0.750
15	0.159	0.213	0.266	0.319	0.372	0.425	0.478	0.638
25	0.141	0.188	0.234	0.281	0.328	0.375	0.422	0.563
33.33	0.125	0.167	0.208	0.250	0.292	0.333	0.375	0.500
50	0.094	0.125	0.156	0.188	0.219	0.250	0.281	0.375
66.66	0.063	0.083	0.104	0.125	0.146	0.167	0.188	0.250
75	0.047	0.063	0.078	0.094	0.109	0.125	0.141	0.188
85	0.019	0.025	0.031	0.036	0.042	0.048	0.054	0.072
95	0.009	0.013	0.016	0.019	0.022	0.025	0.028	0.038

End (or BC Top) Side

Begin (or BC Bottom) Side

**ISEC Member Section Losses**

Legend:  
k or Ok: knife edge  
w or W: width loss  
p or P: perforation  
SL: section loss  
GSL or SLG: gross SL  
Units: inch UON

2T2

17

**NH 070/117**

Carry: **Sewells Falls Road**

Cross: **Merrimack River**

D.O. **Northeast**

Date: **3/9/2012**

Span	T#	Member ID (L, U, M)	Member Build (4L...)	Leg A	Leg B	Leg C	Leg D	Leg E	Leg F	Leg G	Leg H	Comments	Photo
✓	2 T2	U7L7@L7	4L5x3x3/8"✓	10%	0%	0%	5%	10%	0%	0%	5%	<454,55>	
→	2 T2	L7U8	4L4x3x7/16"	.450	0%	0%	.443	.442	0%	0%	.441	<456,457,58>	
				0%				.421			.456		
								.435			.466		
								1%			-		
→	2 T2	L7L8	≤ 5% SL (all); See L8L9										<459>
→	2 T2	U8L8@L8	NSSL										<460,61>
→	2 T2	L8L9@L9	4L5x3x5/16"	.327	.301	.302	.323	.334	.140	.213	.310	<462,63,64,65,66>	
				.297	.233	.315	.306	.308	.181	.304	.294		
				.320			.277	.279	.264	.320	.276		
				-	15%	1%	3%	2%	38%	11%	6%		

ABUTMENTS		WINGWALLS		STREAM CHANNEL		APPROACHES		Field Note Sheet		STANDARD PHOTOS		BIN	
22 23 Joint with Deck	30 31 Stem	40 41 Walls	48 Alignment	53 Drainage	18		Span "A"		Load/Post Approach/Begin Feature/Crossed/Left Feature/Crossed/Right Abutment/Begin Abutment/End Elevation/Left/Right/Span/1 Framing/Framing/Span/1 etc Framing/Framing/Truss Pier/1 etc Utility -1 -2 etc Special/Emphasis -1 -2 etc.		NH 070/116		
24 25 Brgs, Affs, & Pads	32 33 Erosion / Scour	42 43 Footings	49 Erosion / Scour	54 Embankment							Sewalls Falls Rd		
26 27 Br Seat & Pedestals	34 35 Footings	44 45 Erosion / Scour	50 Waterway Opening	55 Settlement					Merrimack R.		D.O. NNE		
28 29 Backwall	36 37 Piles	46 47 Piles	51 Bank Protection	56 Erosion							Dates 3/8/2012		
Span "A"		Span "A"		Span "A"		Span "A"		Span "A"					
DECK ELEMENTS		SUPERSTRUCTURE		PIER		UTILITIES							
19 Wearing Surface	23 Souders	27 Deck	33 Brgs, Affs, & Pads	38 Pier Columns	43 Light Sds & Fixtures								
20 Curbs	24 Gratings	28 Primary	34 Pedestals	39 Footings	44 Sign Structure								
21 Sidewalks & Fencings	25 Median	29 Secondary	35 Top of Cap or Beam	40 Erosion / Scour	45 Utilities & Supports								
22 Railings & Parapets	26 Mono Deck Surface	30 Paint	36 Stem Solid Pier	41 Piles									
		31 Joints	37 Cap Beam										
✓	Span	Item	Photo Location / Description / Rating / (Overall Summary, or Other Elements Summary)						Photo	✓			
	1	T1 L1 U1							<124>				
	1	T1 U1 L2							<128, 29, 30, 31>				
	1	T1 U2 L2							<132, 33>				
	1	T1 U2 L3	Est. 5% ± SL						<140, 41>				
	1	T1 L3 U4							<145, 46, 47, 48>				
	1	T1 U3 L4	NSSL						<153, 54>				
	1	T1 U4 L4	NSSL						<155, 56>				
	1	T1 L4 U5	NSSL						<157, 58>				
	1	T1 L4 L5	Est. 5% ± SL						<159>				
	1	T1 U4 L5	NSSL						<160, 61>				
	1	T1 U7 L7	NSSL						<185, 86, 87, 88>				
	1	T1 L7 U8	Est. 5% ± SL						<189, 190>				
	1	T1 L7 L8	Vertical legs = 5% SL, horizontal legs NSSL						<191, 92, 93>				
	1	T1 U8 L8	NSSL						<194, 95>				
	1	T1 L8 L9	NSSL						<196>				
	1	T2 U1 L1	NSSL						<209, 10>				
	1	T2 L1 L2 @ L1	Similar not as bad as L2 L1						<211, 12>				
	1	T2 U1 L2	≤ 5% SL						<213, 14, 15>				
	1	T2 U2 L2	NSSL						<216, 17>				
	1	T2 L4 U5	NSSL						<246, 47>				
	1	T2 L4 L5	≤ 5% SL						<248, 49>				
	1	T2 U4 L5	≤ 5% SL						<250, 51>				
	1	T2 L8 U8	NSSL						<286, 87, 88>				
	2	T1 L1 U1	NSSL						<303, 304>				
	2	T2 U1 L1	NSSL						<392, 93>				
	2	T2 U2 L2							<399> 400				
	2	T2 L8							<483>				
	1	T1 PPL1-L8							<467-474>				
	1	T2 L1							<475, 76, 77>				
	1	T2 L8							<478>				
	2	T1 L1							<479>				
	2	T2 L1							<480>				
	2	T2 L7							<481, 82>				




✓	Span	Item	Photo Location / Description / ○Rating / (Overall Summary, or Other Elements Summary)	Photo	✓
---	------	------	---	-------	---

## Panel Point Schematic

Right Plate K116


Panel Point Schematic (HOL1)[illegible]




[illegible]

%SL	3 / 8"	7 / 16"	1 / 2"	9 / 16"	5 / 8"	11 / 16"	3 / 4"	7 / 8"	Gusset Plate Section Losses  <div>(21)</div>	Span: <div>2</div> <div>T1 T2</div> PP: <div>L3</div>	BIN <div>NH 070/117</div> Corry <div>Sewells Falls Road</div> Cross <div>Merrimack River</div> D.O. <div>Northeast</div> Date <div>3/8/2012</div>
0	0.375	0.4375	0.500	0.5625	0.625	0.6875	0.750	0.875			
15	0.319	0.372	0.425	0.478	0.531	0.584	0.638	0.744			
25	0.281	0.328	0.375	0.422	0.469	0.516	0.563	0.656			
33.33	0.250	0.292	0.333	0.375	0.417	0.458	0.500	0.583			
50	0.188	0.219	0.250	0.281	0.313	0.344	0.375	0.438			
66.66	0.125	0.146	0.167	0.188	0.208	0.229	0.250	0.292			
75	0.094	0.109	0.125	0.141	0.156	0.172	0.188	0.219			
85	0.056	0.066	0.075	0.084	0.094	0.103	0.112	0.131			
95	0.019	0.022	0.025	0.028	0.031	0.034	0.038	0.044			

✓ Span Item Photo Location / Description / ○ Rating / (Overall Summary, or Other Elements Summary) Photo ✓



Line AB	Line BC	Line GH	Line H	Line HI	Line DE	Line EF	Line JK	Line K	Line KL
← NSSL →						.377			
						.361			
						.382			
						0.1			



Line AB	Line BC	Line GH	Line H	Line HI	Line DE	Line EF	Line JK	Line K	Line KL
← NSSL →						.286			
						.275			
						.344			
						.375			
						.361			
						12.1			

%SL	3/8"	7/16"	1/2"	9/16"	5/8"	11/16"	3/4"	7/8"	Gusset Plate Section Losses	Span: 2 T1 (T2) PP: L6	BIN NH 070/117 Covr. Sewells Falls Road Cross. Merrimack River D.O. Northeast Date 3/9/2012
0	0.375	0.4375	0.500	0.5625	0.625	0.6875	0.750	0.875			
15	0.319	0.372	0.425	0.478	0.531	0.584	0.638	0.744			
25	0.281	0.328	0.375	0.422	0.469	0.516	0.563	0.656			
33.33	0.250	0.292	0.333	0.375	0.417	0.458	0.500	0.583			
50	0.188	0.219	0.250	0.281	0.313	0.344	0.375	0.438			
66.66	0.125	0.146	0.167	0.188	0.208	0.229	0.250	0.292	(22)	PP: L6	
75	0.094	0.109	0.125	0.141	0.156	0.172	0.188	0.219			
85	0.056	0.066	0.075	0.084	0.094	0.103	0.112	0.131			
95	0.019	0.022	0.025	0.028	0.031	0.034	0.038	0.044			

✓	Span	Item	Photo Location / Description / Rating / (Overall Summary, or Other Elements Summary)	Photo	✓
---	------	------	--	-------	---

				<b>Left Plate</b> Plate Size: Meas. Thickness: (fat) 3/8" + Nominal Thickness: 3/8"	
←(SSW) Begin				End (NNE)→	

Panel Point Schematic

Line AB	Line BC	Line GH	Line H	Line HI	Line DE	Line EF	Line JK	Line K	Line KL
.373						.369			
.354						.365			
.362						0% SL			
3%						2%			

				<b>Right Plate</b> Plate Size: Meas. Thickness: (fat) 3/8" + Nominal Thickness: 3/8"	
←(SSW) Begin				End (NNE)→	

Panel Point Schematic

Line AB	Line BC	Line GH	Line H	Line HI	Line DE	Line EF	Line JK	Line K	Line KL
.351						.347			
.363						.279			
.372						.387 (fat)			
3%						10%			





## CHA COMPUTATION PAD

COMPLETED BY: Joe Albert  
CHECKED BY: C. Snyder  
PROJECT NAME: Sewalls Falls  
PROJECT LOCATION: Concord, New Hampshire

PROJECT: 23968 PHASE: 1000 ORG:   
SHEET #: 1 OF 2 (23)  
DATE: 3/6/2012  
SUBJECT: Stringer Section Loss

StringersSpan 1, Floor panel 1 (FB0-FB1)

S4 @ 9.5' from Begin approach Top Cover P: 30%  
Web: 50%

S5 & S6 @ 8.0' from Begin approach Top Cover P: 100%  
7.5' " " BF: 35%

Span 1, Floor Panel 2 (FB1-FB2)

S5 @ 9.0' from FB1 Web: 50% 3 drilled bolt holes deteriorating  
TF: 20% 1 " " "

Floor Panel 3 (FB2-FB3)

S3 @ 5' from FB2 Web 30%

P → S6 @ FB3 - 2' Web: shot, 80% + over length of 2' P High shear zone  
S7 " " " Web: 20% (high shear zone)

Floor Panel 4 (FB3-FB4)

P	S4 @ 2' from FB3	Web: 45% (High shear zone)	P
P	S5 @ 2' from FB4	Web: 30% " " "	P
P	S6 " " "	Web: 60% " " "	P
P	S7 " " "	Web: 90% " " "	P

≈ 8" x 4" hole in web

Floor Panel 5 (FB4-FB5)

P S3 @ 2' from FB4 Web: 40% P  
S5 @ 2' from FB5 Web: 20% small hole in web

Floor Panel 8 (FB7-FB8)

P S6 @ 2' from FB7 Web: 60% 4" x 4" hole in web P

Floor Panel 9 (FB8-FB9)

S4 @ 3' from FB8 Web: 30%  
S5 " 2' Web: 30%  
S6 " 2.5' " Web: 25% TF cover P: 20%  
S7 " 5.5' " " Web: 10% & 20% respectively



## CHA COMPUTATION PAD

COMPLETED BY: Joe Albert  
CHECKED BY: C. Snyder  
PROJECT NAME: Sewalls Falls Bridge Inspection  
PROJECT LOCATION: Concord, New Hampshire

PROJECT: 23968 PHASE: 1000 ORG:   
SHEET #: 2 OF 2 (24)  
DATE: 3/6/2012  
SUBJECT: Stringer Section Loss

Stringers:

Span 1: Floor Panel 9 (FB8-FB9) ctd.

S6 @ 10.8' From FB8

Web: 45% over 1' length

TF cover P: 35%

TF: 10%

★ S2, 3, 4 over FB9 30% loss of bearing area ★  
(over pier)

Span 2: Floor Panel 1 (FB0-FB1)

S3 @ 0.5' From FB0

Web: 35%

S5 @ 1.0' From FB0

TF: 30%

S2 @ 0.5' From FB1

Web: 25%

S7 @ 1.0' " FB1

Web: 30%

Floor Panel 2 (FB1-FB2)

S4 @ 2.0' From FB2

Web: 20%

S5 @ 1.0' From FB2

Web: 30%

▲ S6 @ 1.0' From FB2

Web: 40% ▲

Floor Panel 3 (FB2-FB3)

▲ S3 & S5 @ 2' From FB2

Web: 50% & 25% respectively

Floor Panel 7 (FB6-FB7)

S5 @ 9.3' From FB6

TF: 15% over 8" length (near mid panel)

Floor Panel 8 (FB7-FB8)

S5 @ 5.0' From FB7

TF: 30% over 8" length (1/3 span)

S5 @ 1.0' from FB8

TF: 35% over 3" length

Floor Panel 9 (FB8-FB9)

S5 (functional) @ 10' From FB8

BF: 40% (hook in flange)

entire →  
stringer

S3 all along Top Flange, average of 40% loss w/ max of 70% in 2 locations

1 @ 7.0' from FB8 and another @ 11.1' from FB8 ▲





## CHA COMPUTATION PAD

COMPLETED BY: Joe Albert  
CHECKED BY: C. Snyder  
PROJECT NAME: Sewalls Falls BI  
PROJECT LOCATION: Concord, New Hampshire

PROJECT				PHASE				ORG			
2	3	9	6	8	1	0	0	0			

SHEET #: 1 OF 1 (25)  
DATE: 3/5/2012 - 3/6/2012  
SUBJECT: Floor beam Section Loss

Flow beams (SL through X section)

Span 1 FB1 Begin side bottom flange 3 locations of chunks of steel missing in between stringers 3-6 S3-S4 (80%)<sup>P</sup>, S4-S5 (30%), S5-S6 (50%)

End side holes between S3-S4 & S5-S6 (50%)<sup>P</sup>

Span 1 FB4 Begin side bottom flange multiple holes in between stringers 4-6 (50% max)  
End side " " holes between S3-S4 & S5-S6 (35%)  
(55%)<sup>P</sup>

Span 1 FB6 End side bottom flange holes 6"-8" in length under S6 (70% max)<sup>P</sup>

SP 1 FB7 Begin side bottom flange holes between S3-S4 (90%)<sup>P</sup>

Span 1 FB8 End side bottom flange gouges between S5-S6 (25%)

Span 2

FB1 between stringers 4-6 begin side, gashes in BF (60% max)

FB2 End side between S5-S6 holes in BF (70% max)

FB4 Begin side between S3-S4 holes in BF (30% max)

FB6 End side between S2-S3 holes in BF (80% max)

FB7 End side between S2-S3 holes in BF over a length of 78" (50% max)  
(90% avg)