The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Inf	ormation									40-38-07 =	074-54-43 = -
New Jersey [34]		Hunterdon County [019]		Clinton [1	Clinton [13750]		0.1 MI WEST OF LEIGH ST			40.635278	74.911944
10XX0N1		Highway agency district 2		Owner	Owner County Highway Agency [02]		2]	Maintenance responsibility		County Highway Agency [02]	
Route 0 MAIN STREET				Toll On free road [3] Features intersected SOUTH BR			RARITAN RIVER				
Design - main	main Iron [9] approach		Kilometerpoint 0 km = 0.0 mi Year built 1870 Year reconstructed N/A [er [00] Skew angle 24 Structure Flared Historical significance Bridge is on the NRHP. [1					[0000]			
Total length 51.8 m = 170.0 ft Length of maximum span 25.9 m = 85.0 ft Deck width, out-to-out 5.1 m = 16.7 ft Bridge roadway width, curb-to-curb 4.8 m = 15.7 ft											
Inventory Route, Total Horizontal Clearance 4.8 m = 15.7 ft Deck structure type Open Grating [3] Type of wearing surface				Cı	Curb or sidewalk width - left 1.6 m = 5.2 ft Curb or sidewalk					ewalk width - right	1.6 m = 5.2 ft
Deck prot		earing surface									
Weight L	imits										
Bypass, detour length Method to determine inventory rating			ng Loa	Load Factor(LF) [1]		Inv	entory rating	12.7 metric ton	= 14.0 tons		
0.2 km = 0.1 mi Method to determine opera			ne operating ratir	rating Load Factor(LF) [1]			Ор	Operating rating 21.8 metric to		i = 24.0 tons	
		Bridge posting	30.0 - 39.9 % b∈	elow [1]			Des	sign Load			

Functional Details								
Average Daily Traffic 350 Average daily tr	uck traffi 0 % Year 2009 Future average daily traffic 450 Year 2029							
Road classification Local (Urban) [19]	Lanes on structure 1 Approach roadway width 6.4 m = 21.0 ft							
Type of service on bridge Highway-pedestrian [5]	Direction of traffic 1 - way traffic [1] Bridge median							
Parallel structure designation No parallel structure exists. [N]								
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control							
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A							
Minimum navigation vertical clearance, vertical lift bri	Minimum vertical clearance over bridge roadway 99.99 m = 328.1 ft							
Minimum lateral underclearance reference feature Feature not a highway or railroad [N]								
Minimum lateral underclearance on right 0 = N/A Minimum lateral underclearance on left 0 = N/A								
Minimum Vertical Underclearance 0 = N/A Minimum vertical underclearance reference feature Feature not a highway or railroad [N]								
Appraisal ratings - underclearances N/A [N]								
Densir and Denlessment Dlane								
Repair and Replacement Plans								
Type of work to be performed	Work done by Work to be done by contract [1]							
Replacement of bridge or other structure because of substandard load carrying capacity or substantial	Bridge improvement cost 3050000 Roadway improvement cost 40000							
bridge roadway geometry. [31]	Length of structure improvement 67.1 m = 220.2 ft Total project cost 3925000							
	Year of improvement cost estimate 2009							
	Border bridge - state Border bridge - percent responsibility of other state							
	Border bridge - structure number							

Inspection and Sufficiency									
Structure status Posted for lo	ad [P]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]						
Condition ratings - superstructur	Poor [4]	Appraisal ratings - roadway alignment Appraisal ratings - deck geometry	Meets minimum tolerable limits to be left in place as is [4]						
Condition ratings - substructure	Fair [5]		Basically intolerable requiring	high priority of corrrective action [3]					
Condition ratings - deck	Fair [5]								
Scour	Countermeasures have been	Countermeasures have been installed to mitigate an existing problem with scour. [7]							
Channel and channel protection	Bank is beginning to slump. I minor stream bed movement	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]							
Appraisal ratings - water adequac	y Better than present minimum	criteria [7]	Status evaluation	Status evaluation Structurally deficient [1]					
Pier or abutment protection			Sufficiency rating	23.5					
Culverts Not applicable. Used	if structure is not a culvert. [N]								
Traffic safety features - railings									
Traffic safety features - transition	S								
Traffic safety features - approach guardrail									
Traffic safety features - approach guardrail ends									
Inspection date									
	Not needed [N]	Underwater inspection date							
·	Every two years [Y24]	Fracture critical ins							
Other special inspection	Every year [Y12]	Other special insp	June 2009 [06	09]					