

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

New Jersey [34] Monmouth County [025] Upper Freehold [74900] 5 MI NW RT 539 & RT 537 40-07-59 = 40.133056 074-33-37 = - 74.560278

1300U47 Highway agency district 2 Owner County Highway Agency [02] Maintenance responsibility County Highway Agency [02]

Route 0 WALNS MILL ROAD Toll On free road [3] Features intersected CROSSWICKS CREEK

Design - main Wood or timber [7] Design - approach Other [00] Kilometerpoint 0 km = 0.0 mi

4 Stringer/Multi-beam or girder [02] 0 Other [00] Year built #Num! Year reconstructed 1948

Skew angle 0 Structure Flared

Historical significance Bridge is eligible for the NRHP. [2]

Total length 18.9 m = 62.0 ft Length of maximum span 5.2 m = 17.1 ft Deck width, out-to-out 4.6 m = 15.1 ft Bridge roadway width, curb-to-curb 4.5 m = 14.8 ft

Inventory Route, Total Horizontal Clearance 4.5 m = 14.8 ft Curb or sidewalk width - left 0.2 m = 0.7 ft Curb or sidewalk width - right 0.2 m = 0.7 ft

Deck structure type Wood or Timber [8]

Type of wearing surface Bituminous [6]

Deck protection

Type of membrane/wearing surface

Weight Limits

Bypass, detour length 0.5 km = 0.3 mi Method to determine inventory rating Allowable Stress(AS) [2] Inventory rating 22.7 metric ton = 25.0 tons

Method to determine operating rating Allowable Stress(AS) [2] Operating rating 31.8 metric ton = 35.0 tons

Bridge posting Equal to or above legal loads [5] Design Load

Functional Details

Average Daily Traffic	250	Average daily truck traffi	3	%	Year	2009	Future average daily traffic	310	Year	2029
Road classification	Local (Rural) [09]		Lanes on structure	1		Approach roadway width	4.6 m = 15.1 ft			
Type of service on bridge	Highway [1]		Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge	0 m = 0.0 ft			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft					
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	1188000	Roadway improvement cost	100000						
	Length of structure improvement	35.4 m = 116.1 ft		Total project cost	1785000					
	Year of improvement cost estimate	2006								
	Border bridge - state		Border bridge - percent responsibility of other state							
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - superstructure	Satisfactory [6]	Appraisal ratings - roadway alignment	Somewhat better than minimum adequacy to tolerate being left in place as is [5]
Condition ratings - substructure	Poor [4]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Satisfactory [6]		
Scour	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]		
Channel and channel protection	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]		
Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	45.5
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	June 2011 [0611]	Designated inspection frequency	24 Months
Underwater inspection	Unknown [Y48]	Underwater inspection date	July 2011 [0711]
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	June 2011 [0611]
Other special inspection	Not needed [N]	Other special inspection date	