

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

New York [36] Tompkins County [109] Dryden [20962] 1.6 MI SW OF MCLEAN 42-32-01 = 42.533611 076-18-39 = - 76.310833

3209780 Highway agency district 36 Owner County Highway Agency [02] Maintenance responsibility County Highway Agency [02]

Route 0 W MALLORYVILLE RD Toll On free road [3] Features intersected FALL CREEK

Design - main Aluminum, Wrought Iron or Cast Iron [9] Design - approach Other [00] Kilometerpoint 0 km = 0.0 mi

1 Truss - Thru [10] 0 Other [00] Year built 1915 Year reconstructed 1973

Skew angle 20 Structure Flared

Historical significance Bridge is eligible for the NRHP. [2]

Total length 20.7 m = 67.9 ft Length of maximum span 19.5 m = 64.0 ft Deck width, out-to-out 4.9 m = 16.1 ft Bridge roadway width, curb-to-curb 4.7 m = 15.4 ft

Inventory Route, Total Horizontal Clearance 4.7 m = 15.4 ft Curb or sidewalk width - left 0 m = 0.0 ft Curb or sidewalk width - right 0 m = 0.0 ft

Deck structure type Concrete Cast-in-Place [1]

Type of wearing surface Integral Concrete (separate non-modified layer of concrete added to structural deck) [2]

Deck protection

Type of membrane/wearing surface

**Weight Limits**

Bypass, detour length 0.1 km = 0.1 mi Method to determine inventory rating Allowable Stress(AS) [2] Inventory rating 17.2 metric ton = 18.9 tons

Method to determine operating rating Allowable Stress(AS) [2] Operating rating 26.3 metric ton = 28.9 tons

Bridge posting 10.0 - 19.9 % below [3] Design Load

### Functional Details

Average Daily Traffic	239	Average daily truck traffi	6	%	Year	2009	Future average daily traffic	300	Year	2029
Road classification	Local (Rural) [09]		Lanes on structure	1		Approach roadway width	4.2 m = 13.8 ft			
Type of service on bridge	Highway [1]		Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

### Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Widening of existing bridge with deck rehabilitation or replacement. [34]	Bridge improvement cost	256000	Roadway improvement cost	153000						
	Length of structure improvement	20.7 m = 67.9 ft		Total project cost	409000					
	Year of improvement cost estimate	2009								
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

## Inspection and Sufficiency

Structure status

Posted for load [P]

Appraisal ratings - structural

Meets minimum tolerable limits to be left in place as is [4]

Condition ratings - superstructure

Poor [4]

Appraisal ratings - roadway alignment

Somewhat better than minimum adequacy to tolerate being left in place as is [5]

Condition ratings - substructure

Poor [4]

Appraisal ratings - deck geometry

Basically intolerable requiring high priority of replacement [2]

Condition ratings - deck

Fair [5]

Scour

Bridge is scour critical; field review indicates that extensive scour has occurred at bridge foundations. [2]

Channel and channel protection

Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]

Appraisal ratings - water adequacy

Meets minimum tolerable limits to be left in place as is [4]

Status evaluation

Structurally deficient [1]

Pier or abutment protection

Sufficiency rating

35.7

Culverts

Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings

Traffic safety features - transitions

Traffic safety features - approach guardrail

Traffic safety features - approach guardrail ends

Inspection date

August 2009 [0809]

Designated inspection frequency

12

Months

Underwater inspection

Not needed [N]

Underwater inspection date

Fracture critical inspection

Every year [Y12]

Fracture critical inspection date

August 2009 [0809]

Other special inspection

Not needed [N]

Other special inspection date