The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information					43-26-27 =	075-12-25 = -
New York [36]	Oneida County [065]		Forestport [26627]	1.5 MI W FORESTPORT STA.	43.440833	75.206944
2205760 Highway agency district 26		Owner Town or Township Highway Agency [03] Maintenance responsibility		nance responsibility Town or Townsh	nip Highway Agency [03]	
Route 0	RIVER ROAD		Toll On free road [3] Features intersected BLACK RIV		tersected BLACK RIVER	
Design - Steel [3] main Truss - Thr	u [10]	Design - approach 0 Other	r [00]	Skew angle 0 Struc	ear reconstructed N/A [0000] ture Flared idge is eligible for the NRHP. [2]	
Total length 18.2 m	= 59.7 ft L	ength of maximum sp	an 17.6 m = 57.7 ft	Deck width, out-to-out 4.9 m =	= 16.1 ft Bridge roadway width, curb-to	o-curb 4.7 m = 15.4 ft
Inventory Route, Total Horizontal Clearance 4.7 m = 15.4 ft		Curb or sidewalk w	Curb or sidewalk width - left 1.6 m = 5.2 ft Curb		0 m = 0.0 ft	
Deck structure type		Wood or Timber [8]				
Type of wearing surface Wood or Timber [7]						
Deck protection						
Type of membrane/w	earing surface					
Weight Limits						
Bypass, detour length Method to determine inventory rating		Load Factor(LF) [1]	Inventory rat	ing 4.5 metric ton = 5.0 tons		
0.1 km = 0.1 mi Method to determine operation		rmine operating rating	Load Factor(LF) [1]	Operating ra	8.2 metric ton = 9.0 tons	
	Bridge posting	30.0 - 39.9 % beld	ow [1]	Design Load		

Functional Details									
Average Daily Traffic 684 Average daily tr	uck traffi 6 % Year 2009 Future average daily traffic 848 Year 2029								
Road classification Local (Rural) [09]	Lanes on structure 1 Approach roadway width 4.5 m = 14.8 ft								
Type of service on bridge Highway-pedestrian [5]	Direction of traffic One lane bridge for 2 - way traffic [3] Bridge median								
Parallel structure designation No parallel structure	e exists. [N]								
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control								
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A								
Minimum navigation vertical clearance, vertical lift brid	Minimum vertical clearance over bridge roadway 99.99 m = 328.1 ft								
Minimum lateral underclearance reference feature Fe	eature not a highway or railroad [N]								
Minimum lateral underclearance on right 99.9 = Unlimited Minimum lateral underclearance on left 0 = N/A									
Minimum Vertical Underclearance 0 = N/A	Minimum vertical underclearance reference feature Feature not a highway or railroad [N]								
Appraisal ratings - underclearances N/A [N]									
Danair and Danlagament Dlang									
Repair and Replacement Plans	West days by West to be days by contract [4]								
Type of work to be performed	Work done by Work to be done by contract [1]								
Widening of existing bridge with deck rehabilitation or replacement. [34]	Bridge improvement cost 203000 Roadway improvement cost 121000								
,	Length of structure improvement 18.2 m = 59.7 ft Total project cost 324000								
	Year of improvement cost estimate 2009								
	Border bridge - state Border bridge - percent responsibility of other state								
	Border bridge - structure number								

Inspection and Sufficiency								
Structure status Bridge close	ed to all traffic [K]	Appraisal ratings - structural						
Condition ratings - superstructur	Serious [3]	Appraisal ratings - roadway alignment	Somewhat better than minimum adequacy to tolerate being left in place as is [5]					
Condition ratings - substructure	Poor [4]	Appraisal ratings -						
Condition ratings - deck	Serious [3]	deck geometry						
Scour	required. [4]	Bridge foundations determined to be stable for assessed or calculated scour conditions; field review indicates action is required. [4]						
Channel and channel protection	Bank is beginning to slump. I minor stream bed movement	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]						
Appraisal ratings - water adequa	Meets minimum tolerable lim	its to be left in place as is	[4] Status ev	aluation Structurally deficient [1]				
Pier or abutment protection			Sufficienc	cy rating 21.6				
Culverts Not applicable. Used	I if structure is not a culvert. [N]							
Traffic safety features - railings								
Traffic safety features - transition	ns							
Traffic safety features - approac	ch guardrail							
Traffic safety features - approac	ch guardrail ends							
Inspection date August 200	9 [0809] Designated inspe	ection frequency 12	Months					
Underwater inspection Not needed [N]		Underwater inspec	ction date					
Fracture critical inspection	Every year [Y12]	Fracture critical ins	spection date Augu	ıst 2009 [0809]				
Other special inspection	Not needed [N]	Other special inspe	ection date					