

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

| | | | | | |
|---|--------------------------------|---------------------------------|----------------------------|-------------------------------------|--|
| New York [36] | Chemung County [015] | Wellsburg [79081] | 0.5 MI S JCT RTS 367 +427 | 42-00-33.08 = 42.009189 | 076-43-45.38 = -76.729272 |
| 1046800 | Highway agency district: 62 | Owner State Highway Agency [01] | Maintenance responsibility | State Highway Agency [01] | |
| Route 367 | RTE 367 | Toll On free road [3] | Features intersected | BENTLEY CREEK | |
| Design - main 1 | Steel [3] Truss - Thru [10] | Design - approach 0 | Other [00] | Kilometerpoint 85.3 km = 52.9 mi | Year built 1940 Year reconstructed 1999 |
| | | | | Skew angle 27 | Structure Flared |
| | | | | Historical significance | Bridge is not eligible for the NRHP. [5] |
| Total length | 44.2 m = 145.0 ft | Length of maximum span | 42.6 m = 139.8 ft | Deck width, out-to-out | 8 m = 26.2 ft |
| | | | | Bridge roadway width, curb-to-curb | 7.4 m = 24.3 ft |
| Inventory Route, Total Horizontal Clearance | 7.3 m = 24.0 ft | Curb or sidewalk width - left | 0 m = 0.0 ft | Curb or sidewalk width - right | 1.7 m = 5.6 ft |
| Deck structure type | Other [9] | | | | |
| Type of wearing surface | Epoxy Overlay [5] | | | | |
| Deck protection | Unknown [8] | | | | |
| Type of membrane/wearing surface | | | | | |

Weight Limits

| | | | | |
|-----------------------|--------------------------------------|---------------------|------------------|-----------------------------|
| Bypass, detour length | Method to determine inventory rating | Load Factor(LF) [1] | Inventory rating | 33.5 metric ton = 36.9 tons |
| 0.4 km = 0.2 mi | Method to determine operating rating | Load Factor(LF) [1] | Operating rating | 56.3 metric ton = 61.9 tons |
| Bridge posting | Equal to or above legal loads [5] | | Design Load | MS 18 / HS 20 [5] |

Functional Details

| | | | | | | | | | | |
|---|---------------------------------------|----------------------------|---|---------------------------------------|--|------------------------|------------------------------|------|------|------|
| Average Daily Traffic | 3230 | Average daily truck traffi | 8 | % | Year | 2018 | Future average daily traffic | 3262 | Year | 2038 |
| Road classification | Collector (Urban) [17] | | Lanes on structure | 2 | | Approach roadway width | 11.6 m = 38.1 ft | | | |
| Type of service on bridge | Highway-pedestrian [5] | | Direction of traffic | 2 - way traffic [2] | | Bridge median | | | | |
| Parallel structure designation | No parallel structure exists. [N] | | | | | | | | | |
| Type of service under bridge | Waterway [5] | | Lanes under structure | 0 | | Navigation control | | | | |
| Navigation vertical clearanc | 0 = N/A | | Navigation horizontal clearance | 0 = N/A | | | | | | |
| Minimum navigation vertical clearance, vertical lift bridge | | | Minimum vertical clearance over bridge roadway | 99.99 m = 328.1 ft | | | | | | |
| Minimum lateral underclearance reference feature | Feature not a highway or railroad [N] | | | | | | | | | |
| Minimum lateral underclearance on right | 0 = N/A | | | | Minimum lateral underclearance on left | 0 = N/A | | | | |
| Minimum Vertical Underclearance | 0 = N/A | | Minimum vertical underclearance reference feature | Feature not a highway or railroad [N] | | | | | | |
| Appraisal ratings - underclearances | N/A [N] | | | | | | | | | |

Repair and Replacement Plans

| | | | | | | | | | | |
|---|-----------------------------------|---------------------------------|--------------------------|--------------------|---|--|--|--|--|--|
| Type of work to be performed | Work done by | Work to be done by contract [1] | | | | | | | | |
| Widening of existing bridge with deck rehabilitation or replacement. [34] | Bridge improvement cost | 3026000 | Roadway improvement cost | 1772000 | | | | | | |
| | Length of structure improvement | 44.1 m = 144.7 ft | | Total project cost | 4798000 | | | | | |
| | Year of improvement cost estimate | 2018 | | | | | | | | |
| | Border bridge - state | | | | Border bridge - percent responsibility of other state | | | | | |
| | Border bridge - structure number | | | | | | | | | |

Inspection and Sufficiency

| | | | |
|---|---|---------------------------------------|---|
| Structure status | Posted for other load-capacity restriction [R] | Appraisal ratings - structural | Somewhat better than minimum adequacy to tolerate being left in place as is [5] |
| Condition ratings - superstructure | Fair [5] | Appraisal ratings - roadway alignment | Equal to present desirable criteria [8] |
| Condition ratings - substructure | Fair [5] | Appraisal ratings - deck geometry | Basically intolerable requiring high priority of replacement [2] |
| Condition ratings - deck | Poor [4] | | |
| Scour | Bridge foundations determined to be stable for assessed or calculated scour conditions; field review indicates action is required. [4] | | |
| Channel and channel protection | Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6] | | |
| Appraisal ratings - water adequacy | Meets minimum tolerable limits to be left in place as is [4] | Status evaluation | Structurally deficient [1] |
| Pier or abutment protection | | Sufficiency rating | 58 |
| Culverts | Not applicable. Used if structure is not a culvert. [N] | | |
| Traffic safety features - railings | Inspected feature meets currently acceptable standards. [1] | | |
| Traffic safety features - transitions | | | |
| Traffic safety features - approach guardrail | Inspected feature meets currently acceptable standards. [1] | | |
| Traffic safety features - approach guardrail ends | | | |
| Inspection date | September 2017 [0917] | Designated inspection frequency | 24 Months |
| Underwater inspection | Not needed [N] | Underwater inspection date | |
| Fracture critical inspection | Every two years [Y24] | Fracture critical inspection date | September 2017 [0917] |
| Other special inspection | Not needed [N] | Other special inspection date | |