

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Ohio [39]	Lorain County [093]	Lorain [44856]	0.1 MILE EAST OF SR 57	41-28-07 = 41.468611	082-10-39 = - 82.177500
4700813	Highway agency district 3	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 6	STATE ROUTE 6	Toll On free road [3]	Features intersected OVER CSX RR & BLACK RIVE		
Design - main Steel [3]	Design - approach Steel [3]	Kilometerpoint 1557 km = 965.3 mi	Year built 1939	Year reconstructed 1988	
1	Movable - Bascule [16]	11	Girder and floorbeam system [03]	Skew angle 0	Structure Flared
		Historical significance Bridge is eligible for the NRHP. [2]			
Total length 321 m = 1053.2 ft	Length of maximum span 100.6 m = 330.1 ft	Deck width, out-to-out 18.9 m = 62.0 ft	Bridge roadway width, curb-to-curb 14.3 m = 46.9 ft		
Inventory Route, Total Horizontal Clearance 6.8 m = 22.3 ft	Curb or sidewalk width - left 1.9 m = 6.2 ft	Curb or sidewalk width - right 1.9 m = 6.2 ft			
Deck structure type	Open Grating [3]				
Type of wearing surface	Other [9]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.2 km = 0.1 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	14.3 metric ton = 15.7 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	19.8 metric ton = 21.8 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	MS 13.5 / HS 15 [3]	

Functional Details

Average Daily Traffic	13580	Average daily truck traffi	3	%	Year	2011	Future average daily traffic	15976	Year	2033
Road classification	Other Principal Arterial (Urban) [14]		Lanes on structure	4	Approach roadway width	14.3 m = 46.9 ft				
Type of service on bridge	Highway [1]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Highway-waterway-railroad [Lanes under structure	2	Navigation control	Navigation control on waterway (bridge permit required). [1]				
Navigation vertical clearanc	10.1 m = 33.1 ft		Navigation horizontal clearance	89.9 m = 295.0 ft						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft						
Minimum lateral underclearance reference feature	Railroad beneath structure [R]									
Minimum lateral underclearance on right	2.1 m = 6.9 ft				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	4.34 m = 14.2 ft		Minimum vertical underclearance reference feature	Railroad beneath structure [R]						
Appraisal ratings - underclearances	Basically intolerable requiring high priority of corrective action [3]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Bridge rehabilitation because of general structure deterioration or inadequate strength. [35]	Bridge improvement cost	\$4,619,000	Roadway improvement cost	\$462,000						
	Length of structure improvement	399.9 m = 1312.1 ft		Total project cost	\$5,297,000					
	Year of improvement cost estimate	2005								
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Basically intolerable requiring high priority of corrective action [3]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present minimum criteria [6]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - deck	<input type="text" value="Fair [5]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]"/>		
Channel and channel protection	<input type="text" value="Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>	Status evaluation	<input type="text" value="Functionally obsolete [2]"/>
Pier or abutment protection	<input type="text" value="In place and functioning [2]"/>	Sufficiency rating	<input type="text" value="32"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="October 2012 [1012]"/>	Designated inspection frequency	<input type="text" value="12"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Every two years [Y24]"/>	Fracture critical inspection date	<input type="text" value="October 2012 [1012]"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>

Unit of Measure: **English**
Structure File Number **4700813**
Sufficiency Rating: **32.0 fo**

Bridge Inventory Information
Inventory Bridge Number: **LOR 00006 0967**
ON OVER CSX RR & BLACK RIVER

Report Date **12/12/2014** BM-191 Page: 1 of 2
BR. Type STEEL / TRUSS / MOVABLE - BASC
Date of Last Inventory Update: **03/28/2014**

District: **03** County **LORAIN** (101) Location: **0.1 MILE EAST OF SR 57** (102) Facility Carried: **STATE ROUTE 6**
(2) FIPS Code: **LORAIN** (103) Route On Bridge: **STATE (ODOT)** (104) Route Under Bridge: **MUNICIPAL**
(9) Direction of Traffic: **2-WAY TRAFFIC** (10) Temporary: **N** (11) Truck Network: **N** (12) Parallel: **N**
(95) Insp: **OHIO TRAN DEPT** (96) Maint: **OHIO TRAN DEPT** (97) Routine: **CITY/LOC** (100) Type Serv: (On): **HIGHWAY** (Under): **HIGHWAY/WATERWAY/RAI**

Inventory Route Data

(3) Route On/Under: **ON** Hwy Sys: **U.S. NUMBERED HIGHWAY**
Route No.: **00006** Dir: Des: **MAINLINE** Pref:
(4) Feature Intersected: **OVER CSX RR & BLACK RIVER**
(5) County: **LOR** Mileage: **0967** Special Desig:
(6) Avg. Daily Traffic(ADT): **13,580** (7) ADT Year: **2011**
(8) Truck Traf: **440** (14) NHS: **YES - N** (15) Corridor: **N**
(16) Functional Class: **OTHER PRINCIPAL ARTERIAL-URBAN** (19) Strahnt: **Not Applicable**

(63) Main Spans Number: **1** Type: **STEEL / TRUSS / MOVABLE - BASC**
Approach Spans Number: **11** Type: **STEEL / GIRDER / DECK**
Total Spans: **12** (65) Max Span: **330 Ft** (66) Overall Leng: **1053 Ft**

Intersected Route Data

(22) Route On/Under: **UNDER** Hwy Sys: **MUNICIPAL STREET**
Route No.: **RVFRT** Dir: Des: **8** Pref:
(23) Feature Intersected: **UNDER LOR-6-0967(ERIE AV)**
(24) County: **LOR** Mileage: **PLCE** Special Desig:
(25) Avg. Daily Traffic(ADT): **400** (26) ADT Year: **1900**
(27) Truck Traf: **0** (28) NHS: **NO - X** (29) Corridor: **N**
(30) Functional Class: **LOCAL ROAD-URBAN** (36) Strahnt: **Not Applicable**

(70) Substructure (71) Foundation and Scour Information
Abut-Rear Matl: **CONCRETE** Type: **GRAVITY** Fnd: **SPREAD FOOTING**
Abut-Fwd Matl: **CONCRETE** Type: **GRAVITY** Fnd: **SPREAD FOOTING**
Pier-Pred Matl: **STEEL** Type: **CAPPED COLUMN** Fnd: **CIP REINF CONCRETE PILES(OTHER DIAMETER)**
Pier-Other Matl: **STONE** Type: **OTHER** Fnd: **CIP REINF CONCRETE PILES(OTHER DIAMETER)**
Pier-Other Matl: **CONCRETE** Type: **STUB GRAVITY** Fnd: **CIP REINF CONCRETE PILES(OTHER DIAMETER)**
No of Piers Predominate: **05** Other: **02** Other: **04**
(86) Stream Velocity: **UUU** (74) Scour: **STABLE: EVAL SCOUR ABOVE TOP OF FOOTING**
(189) Dive: **N Freq: 0** Probe: **N Freq: 0** (75) Chan Prot: **SHEET PILING**
(189) Date of last Dive Insp: (152) Drainage Area: **UUU Sq Mi**

Clearance Under the Bridge

(154) Min Hriz on Bridge: NC: **22.3 Ft** Card: **22.3 Ft**
(155) Prac Max Vert On Brg: **9999.9 Ft**
(67) Min Vrt Clr On Brg: NC: **0.0 Ft** Card: **9999.9 Ft**
(80) Min Latl Clr: NC: **0.0 / 0.0 Ft** Card: **0.0 / 0.0 Ft**
(81) Vrt Clr Lft: **0.0 Ft**

(156) Min. Horiz Under Clear: NC: **0.0 Ft** Card: **24.0 Ft**
(157) Prac Max Vrt Under Clear: **14.2 Ft**
(77) Min Vert Under Clear: NC: **0.0 Ft** Card: **14.2 Ft**
(78) Min Lat Under Clear: NC: **0.0 / 0.0 Ft** Card: **0.0 / 7.0 Ft**

Load Rating Information

(88-89) Appraisal

(38) Bypass Length: **01 Miles**
(39) Latitude: **41 Deg 28.1 Min** Longitude: **82 Deg 10.7 Min**
(40) Toll: **ON FREE ROAD**
(41) Date Built: **07/01/1939** (42) Major Rehabilitation: **01/01/1988**
(43) No. Lanes On: **4** No. Lanes Under: **2**
(44) Horiz Curve: **05 Deg. D00M Min.** (45) Skew: **0 Deg**
(49) App. Rdw Width: **47 Ft** (50) Brg. Rdw Width: **47.0 Ft**
(51) Deck Width: **62.0 Ft** Deck Area: **65284 Sq. Ft**

(48) Design Load: **HS/15** (Including calculated Items)
(83) Operating: **22 Ton**
Inventory: **16 Ton**
Ohio Percent of Legal Load **125** (88) Waterway Adequacy **5**
Year of Rating: **1988** (89) Approach Alignment **6**
(84) Analysis: **COMBINATION OF METHODS** Calc Gen Appraisal: **3**
(85) Rate Soft: **NO SOFTWARE USED** Analyzed by: Calc Deck Geometry: **2**
Analysis on Bars: **NOT ON BARS [DEFAULT]** Calc Underclearance: **3**

Approach Information

(52) Median Type: **NONE / NON BARRIE / NO JOINT**
(53) Bridge Median: **NO MEDIAN**
(54) Sidewalks: (left) **6 Ft** (right) **6 Ft**
(55) Type Curb or Sidewalks:
(Left) Matl: **OTHER** Type: **OTHER**
(Right) Matl: **OTHER** Type: **OTHER**
(56) Flared: **N** (57) Composite:
(58) Railing: **STEEL POST & STEEL PANEL (DECORATIVE)**
(59) Deck Drainage: **SCUPPERS & DWNSPTS**
(60) Deck Type: **STEEL GRID - OPEN**
(61) Deck Protection: External: **NONE**
Internal: **NONE**
(62) Wearing Surface: **SUPERPLASTICIZED DENSE CONCRETE (SDC) OV**
Thickness: **1.0 in** (119) Date of Wearing Surface: **08/23/1988**
Slope Protection: **?? OTHER ??**

(109) Approach Guardrail: **STEEL BEAM**
(110) Approach Pavement: **BITUMINOUS** (111) Grade: **FAIR**

Culvert Information

(131) Culvert Type: **NONE/NOT APPLICBLE** (127) Length: **0.0 Ft**
(129) Depth of Fill: **0.0 Ft** (130) Headwalls: **NONE**

General Information

(121) Main Member **RIVETED BUILT-UP STEEL** (122) Moment Plate: **NONE**
(169) Expansion Joint: **SLIDING METAL PLATE ANGLE**
(124) Bearing Devices: **ROCKERS/NONE**
(126) Navigation: **Control- Y** Vert Clr: **33.0 Ft** Horiz Clear: **295.0 Ft**
(193) Spec Insp: **N** Freq: **0** Date:
(188) Fracture Critical Insp: **Y** Freq: **24** Date: **2013-10-15**
(138) Long Member: **THREE OR MORE TRUSSES (WELDED)** (135) Hinges: **PINS, PIN PLATES**
(141) Structural Steel Memb: **UNKNOWN** (139) Framing: **NONE**
Railing: **UNKNOWN**
Paint: **PAINT SYSTEM OZEU**
Pay Wt: **0 pounds** Prime Loc: **UNKNOWN**
Bridge Dedicated Name: **CHARLES BERRY**

Unit of Measure: **English**
 Structure File Number **4700813**
 Sufficiency Rating: **32.0 fo**

Bridge Inventory Information
 Inventory Bridge Number: **LOR 00006 0967**
ON OVER CSX RR & BLACK RIVER

Report Date **12/12/2014 BM-191 Page: 2 of 2**
 BR. Type **STEEL/TRUSS/MOVABLE - BASCULE**
 Date of Last Inventory Update: **03/28/2014**

General Information (Continued)				Original Plans Information			
(---) Hist Significance: NON-REGISTERED HISTORIC BRIDGE		(69) NBIS: Y		(142) Fabricator:			
(---) Hist Builder: WILBUR WATSON & ASSOCIATES		Hist Build Year: 1939		(143) Contractor:			
(69) Hist Type:				(144) Ohio Original Construction Project No.:			
(161) Special Features (see below):				(---) Microfilm Reel:			
(105) Border Bridge State: Resp % (106) SFN:				(151) Standard Drawing:			
Proposed Improvements		Programming Info		Aperture Cards: Orig: Y Repair: Y Fabr: N			
(90) Type Work: 35 - BRG REHAB--GEN DECLINE/INADEQ STRENGTH		PID Number: 15837		Plan Information Available: 1PLAN INFORMATION AVAILABLE			
(90) Length: Ft		PID Status: PROGRAM		(153) Repair Projects			
(90) Bridge Cost (\$1000s): 0		PID Date: 02/04/1999		1. / 020	2. 860897 / 004	3. / MMM	
(90) Roadway Cost (\$1000s): 0				4. / 020	5. /	6. / 022	
(90) Total Project Cost (\$1000s): 0		(90) Year:		7. / 020	8. / 008	9. / 011	
(91) Future ADT (On Bridge): 0		(92) Year of Future ADT: 2033		10. / 011			
Inspection Summary		(I-69) Survey Items		Utilities		Special Features	
(I-8) Deck: 5	Railings: 0 DOES NOT MEET CURRENT STANDARDS	(I-32) Superstructure: 5	Transitions: 0 DOES NOT MEET CURRENT STANDARDS	(46) Electric: U	(161) Lighting: N		
(I-42) Substructure: 5	Guardrail: 0 DOES NOT MEET CURRENT STANDARDS	(I-50) Culvert: 5	Rail Ends: 0 DOES NOT MEET CURRENT STANDARDS	Gas: U	Fencing: N		
(I-54) Channel: 7	In Depth: 1 MEETS CURRENT STANDARDS	(I-60) Approaches: 6	Fracture Critical: 0 DOES NOT MEET CURRENT STANDARDS	Sanitary Sewer: U	Glare-Screen: N		
(I-66) General Appraisal: 5	Scour Critical: N NONE N/A	(I-66) Operational Status: A	Critical Findings: N NONE N/A	Telephone: U	Splash-Guard: N		
Inspection Date: 10/10/2013	Insp. Update Date: 12/11/2013	(94) Desig Insp Freq: 12 Months		TV Cable: U	Catwalks: N		
				Water: U	Other-Feat: U		
				Other: U	(184) Signs-on: Y		
					Signs-Under: Y		
					(162) Fence-Ht: 0.0 Ft		
					(163) Noise Barr: N		
SFNs Replacing this retired bridge: -							
SFNs That where replaced by this bridge: -							
This bridge was retired and copied to:							
The bridge was copied from:				INV Field Bridge Marker:		LOR-00006-0967 -	
				INT Field Bridge Marker:		LOR-RVFRT-PLCE -	

PONTIS CoRe elements and Condition States

Elem No.	CoRe Element Description	Total Quantity	Unit Meas.	Condition State Percents(*)				
				1	2	3	4	5
28	STEEL DECK - OPEN GRID	1	EA	0	0	0	0	0
215	REINFORCED CONC ABUTMENT	124	LF	0	0	0	0	0
304	OPEN EXPANSION JOINT	124	LF	0	0	0	0	0
321	REINFORCED CONCRETE APPROACH SLAB	2	EA	0	0	0	0	0
330	METAL BRIDGE RAILING	2104	LF	0	0	0	0	0

(*) Percentages Should add to 100%

STATE OF OHIO DEPARTMENT OF TRANSPORTATION
BRIDGE INSPECTION REPORT

BR-86 REV 02-95

4	7	0	0	8	1	3
---	---	---	---	---	---	---

Bridge Number **LOR 00006 0967**
CO ROUTE UNIT

LORAIN

Date Built **07/01/1939 - 1988**

1 Structure File Number 7

District **03** Bridge Type **STEEL/TRUSS/MOVABLE - BASC**

Type Service **1 18 OVER CSX RR & BLACK RIVER**

LOR

DECK		Out/Out 62.0	2	THCK = 1.0		2
1. Floor	5-STEEL GRID - OPEN	8	2	2. Wearing Surface	A-SUPERPLASTICIZED DENSE	41
		0-OTHER	2	W.S. Date = 08/23/1988		1
3. Curbs, Sidewalks, Walkways	0-OTHER	9	2	4. Median		42
5. Railing	6-STEEL POST & STEEL PAN	10	2	6. Drainage	3-SCUPPERS & DWNSPTS	43
7. Expansion Joints	2-SLIDING METAL PLATE AN	11	2	8. Summary		44
SUPERSTRUCTURE		MAX.SPAN=330	1			2
9. Alignment		12	1	10. Beams/Girders/Slab	2-RIVETED BUILT-UP STEEL	45
		TOT.LGTH=1053	1			2
11. Diaphragms or Crossframes		13	1	12. Joists/Stringers		46
13. Floor Beams		14	3	14. Floor Beam Connections		47
15. Verticals		15	2	16. Diagonals		48
17. End Posts		16		18. Top Chord		49
19. Lower Chord		17	2	20. Lower Lateral Bracing		50
21. Top Lateral Bracing		18		22. Sway Bracing		51
23. Portals		19		24. Bearing Devices	2-ROCKERS N-NONE	52
25. Arch		20		26. Arch Columns or Hangers		53
27. Spandrel Walls		21		28. Protective Coating System	TYPE = 5-PAINT SYSTEM OZEU DATE = 01/01/1989	54
29. Pins/Hangers/Hinges		22	1	30. Fatigue Prone Connections		55
31. Live Load Response		23	S	32. Summary		56
SUBSTRUCTURE		2-CONCRETE	2	PIERS=11 SPANS = 1		1
33. Abutments	2-CONCRETE	24	2	34. Abutment Seats		57
35. Piers	TYPE = 5-STEEL	25	3	36. Pier Seats		58
37. Backwalls		26	1	38. Wingwalls	ABUTMENT:=SPREAD / SPREAD	59
39. Fenders and Dolphins		27	1	40. Scour	8-STABLE: EVAL SCOUR ABO	60
41. Slope Protection	0-OTHER	28	2	42. Summary		62
				DIVE DT=N/A		
CULVERTS						
43. General		29		44. Alignment		63
45. Shape		30		46. Seams		64
47. Headwalls or Endwalls		31		48. Scour		65
49.		32		50. Summary		66
CHANNEL				3-SHEET PILING		1
51. Alignment		33	1	52. Protection		67
53. Waterway Adequacy		34	1	54. Summary		68
APPROACHES						
55. Pavement	2-BITUMINOUS	35	2	56. Approach Slabs		69
57. Guardrail	1-STEEL BEAM	36		58. Relief Joints		70
59. Embankment	BRDG.WIDTH=47.0	37	1	60. Summary		71
				PCT.LEGAL=125		
GENERAL				ROUTINE.RESP: 4-CITY/LOCAL		1
61. Navigation Lights		38	2	62. Warning Signs	MAINT.RESP: 1-OHIO TRAN DEPT	72
63. Sign Supports	MVC ON=9999 UND=0000	39	1	64. Utilities		73
65. Vertical Clearance		40	1	66. General Appraisal & Operational Status		74
						COND 5 STAT A

67. INSPECTED BY

68. REVIEWED BY

SIGNED

7	7	5	2	7
---	---	---	---	---

76 PE

P	A
---	---

78 INITIALS

SIGNED

6	9	9	9	1
---	---	---	---	---

81 PE

W	W
---	---

83 INITIALS

DOT 2852

DECK AREA 65,284

Date

1	0	1	0	1	3
---	---	---	---	---	---

86

91

Date

0	0	0	0	1	0	N	N
---	---	---	---	---	---	---	---

92

69 Survey

99

Date

1	2	0	6	1	3
---	---	---	---	---	---

100

105

STATE OF OHIO DEPARTMENT OF TRANSPORTATION
BRIDGE INSPECTION REPORT

BR-86 REV 02-95

4	7	0	0	8	1	3
---	---	---	---	---	---	---

1 Structure File Number 7

Bridge Number **LOR 00006 0967**
 CO ROUTE UNIT

Date Built 07/01/1939 - 1988

District **03** Bridge Type **STEEL/TRUSS/MOVABLE - BASC**

Type Service **1 18**

OVER CSX RR & BLACK RIVER

- Deck 1. MIN.GROWTH OF DELAMS,SPALLS IN APPR.SPANS.MODERATE
- Deck CORROSION OF STEEL GRID AT RIVER PIER SPANS.
- Deck 2. APPROX.15% SURFACE SCALING OFF,ISOLATED AREAS OF SCALING
- Deck AREA GROWTH AT PATCHES.
- Deck 3. SHALLOW SPALLING ON SIDEWALK SURFACES, SCRAPES AT THE
- Deck STEEL CURB PLATE.
- Deck 5. ISOLATED IMPACT DEFORMATION OF TRAFFIC RAIL POSTS.
- Deck ISOLATED HOLED THROUGH LOCATIONS AT BOTTOM PED RAILS.
- Deck 6. N.DRAIN PIPES INSIDE W.RIVER PIER LEAK RAINWATER ONTO
- Deck STEEL.PIER 3 TROUGH FRACTURED. PIER 2 CB UNDERMINED.
- Deck 7. UP TO 3/8" VERTICAL DIFFERENTIAL @ BASCULE FINGER JT. @
- Deck EB LANES.
- Superstructure 10. AREAS OF MODERATE LOSSES(ISOLATED ADVANCED LOSSES),
- Superstructure ACTIVE RUSTING AND IMPACTED RUST.
- Superstructure 12. AREAS OF MODERATE TO ADVANCED PITTING, ESPECIALLY AT
- Superstructure RIVER PIER JOINT LOCATIONS AND SIDEWALK FASCIAS.
- Superstructure 13. BASCULE FLOORBEAM TRUSSES EXHIBIT ADVANCED SECTION
- Superstructure LOSSES WITH ISOLATED WELDED STEEL REPAIRS. THERE ARE HOLED
- Superstructure THROUGH AREAS IN THE VERTICAL STIFFENERS ON FLOORBEAMS 3W,3E
- Superstructure AND 5E AND ON THE JOINT SIDE OF BOTH RIVER PIERS.FLOORBEAMS.
- Superstructure THE WEST ABUTMENT SOUTH FLOORBEAM COPE CRACK IS 1-1/8" LONG.
- Superstructure SHOWS NO GROWTH SINCE 2007.
- Superstructure 15. SCATTERED 1/8" PITTING(ISOLATED AREAS UP TO 1/4")ALONG
- Superstructure TOP OF GUSSET PLATES AND LOWER CHORD INTERFACES, AND BEHIND
- Superstructure FILL PLATES. NO NOTICEABLE CHANGE SINCE 2011.
- Superstructure 16. SCATTERED 1/8" PITTING(ISOLATED AREAS UP TO 1/4")ALONG
- Superstructure TOP OF GUSSET PLATES AND LOWER CHORD INTERFACES, AND BEHIND
- Superstructure FILL PLATES. NO NOTICEABLE CHANGE SINCE 2012.
- Superstructure 19. SCATTERED 1/8" PITTING, TYPICAL IMPACTED RUST BETWEEN
- Superstructure BUILT-UP SECTIONS.NO NOTICEABLE CHANGE SINCE 2011.
- Superstructure 20. UP TO 1/8" PITTING & SECTION LOSS, TYPICALLY ALONG TRUSS
- Superstructure MEMBERS.NO NOTICEABLE CHANGE SINCE 2012.
- Superstructure 21. TYPICAL 1/8" PITTING TO LOWER LATERAL BRACING,ISOLATED
- Superstructure HOLED THROUGH AREAS.
- Superstructure 24. 1/16" TO 1/8" PITTING ON BEARING SURFACES & ISOLATED
- Superstructure LOCATIONS OF BACKED OFF NUTS OR TILTED ANCHORS.
- Superstructure 28. APPROX.15% OF AREA EXHIBITS DETERIORATION AND SURFACE
- Superstructure RUST,BUT NOT PREVALENT.
- Substructure 33. TYPICAL FULL HEIGHT,HAIRLINE TO 1/16" VERTICAL CRACKS
- Substructure W/MINOR EFFL..NO NOTICEABLE CHANGE SINCE 2012.
- Substructure 35. THE STEEL FRAMES OF THE BASCULE PIERS EXHIBIT ADVANCED
- Substructure SECTION LOSS W/HOLED THROUGH AREAS ALONG THE INTERFACES
- Substructure BETWEEN THE STEEL & CONCRETE. NO NOTICEABLE CHANGE SINCE
- Substructure 2012.
- Substructure 38. NORTHWEST WINGWALL FRACTURED & DELAMINATED ABOUT 12 SF.
- Substructure NO NOTICEABLE CHANGE SINCE 2012.
- Substructure 39. CONCRETE BRIDGE PROTECTION CAP BEAM IN GOOD CONDITION,
- Substructure BUT SOME BOLTS ANCHORING SOME OF THE RUBBER DOCK FENDERS ARE
- Substructure BROKEN.NO NOTICEABLE CHANGE SINCE 2012.
- Approaches 55. ASPHALT PAV'T TRANS.& LONG.CRACKS W/MINOR DEPRESSIONS @
- Approaches APPR.SLAB.NO NOTICABLE CHANGE SINCE 2012.
- Approaches 56. WEST SLAB EXHIBITS A 3 SF SPALL PATCHED WITH ASPHALT. NO
- Approaches NOTICEABLE CHANGE SINCE 2012.
- General MOVABLE BRIDGES
- General GEARS: ABRASIVE WEAR,CROSS BEARING,GRIT IN LUBE ON SOME GEAR
- General SETS.CORROSION HAS LED TO THE FAILURE OF GEAR COVERS LEAVING
- General SOME HIGH SPEED GEARING EXPOSED.
- General BEARINGS: CORROSION,MISALIGNMENT,BOLTS NOT FULLY SEATED ON
- General SOME BEARINGS.
- General ELECTRIC MOTORS: OPERATIONAL,WITH SIGNS OF DETERIORATION:
- General CORROSION TO HOUSINGS AND WEAR TO FEEDER CABLES.
- General CENTER LOCKS: CORROSION,MODERATE LEAKAGE FROM ENCLOSED
- General REDUCERS.MOTOR BRAKE LIMIT SWITCHES AND SPACE HEATERS ARE NO

General WIRED.

General TAIL LOCKS: SEVERE CORROSION AND SECTION LOSS TO THE CRANK

General FRAME,MODERATE TO SEVERE CORROSION TO HOUSINGS,MODERATE

General CORROSION TO OPEN GEARING.INSUFFICIENT CLEARANCE AROUND THE

General ELECTRICAL EQUIPEMENT.

General SPAN BALANCE: STRAIN GAGE BALANCE TESTING WAS PERFORMED AS

General PART OF THE INSPECTION:BOTH SPANS ARE WELL BALANCED FOR THIS

General SIZE AND TYPE OF BRIDGE, THE OPERATING LOADS ARE WITHIN THE

General CAPACITY OF THE SPAN DRIVE MOTORS.

General BUFFERS: ALL AIR BUFFERS ARE EFFECTIVELY NON-FUNCTIONAL.(SW

General BUFFER PISTON DOESN'T DESCEND,NO AIR FLOW AT THE OTHERS).

General BRAKES: CRITICAL BOLTED CONNECTIONS FOR MOTOR BRAKES-POORLY

General FORMED HOLES AND NO TIGHT FIT.

General LIMIT SWITCHES: MOST ARE FUNCTIONAL,SOME ARE NOT CONNECTED

General TO THE BRIDGE CONTROL SYSTEM.

General TRAFFIC GATES: MISSING DOOR LIMIT SWITCH FOR INTERLOCK,

General ROTARY CAM LIMIT SWITCHES EXHIBIT SIGNS OF CORROSION AS THEY

General ARE NOT PROVIDED WITH PROTECTIVE COVERS,AND LIGHTS INSIDE

General THE GATE HOUSING IS BROKEN.

General LUBRICATION: SOME BEARINGS HAVE INSUFFICIENT LUBE.

General (FRACTURE CRITICAL PLAN ON FILE mlw)
