

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Ohio [39]	Erie County [043]	Vermilion [79716]	.60 MI W LOR. CO. LINE	41-25-19 = 41.421944	082-21-32 = - 82.358889
2202344	Highway agency district 3	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 6	US 6	Toll On free road [3]	Features intersected	VERMILION RIVER	
Design - main 1	Steel [3] Truss - Thru [10]	Design - approach 0	Other [00]	Kilometerpoint 4643 km = 2878.7 mi	Year built 1928 Year reconstructed 1986
				Skew angle 0	Structure Flared
				Historical significance Bridge is not eligible for the NRHP. [5]	
Total length	75 m = 246.1 ft	Length of maximum span	73.2 m = 240.2 ft	Deck width, out-to-out	12.3 m = 40.4 ft
Inventory Route, Total Horizontal Clearance	10.7 m = 35.1 ft	Curb or sidewalk width - left	1.8 m = 5.9 ft	Curb or sidewalk width - right	1.8 m = 5.9 ft
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Integral Concrete (separate non-modified layer of concrete added to structural deck) [2]				
Deck protection	Epoxy Coated Reinforcing [1]				
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	21.1 metric ton = 23.2 tons
2.6 km = 1.6 mi	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	36 metric ton = 39.6 tons
Bridge posting	Equal to or above legal loads [5]	Design Load	MS 18 / HS 20 [5]	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present minimum criteria [6]"/>
Condition ratings - substructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - deck	<input type="text" value="Satisfactory [6]"/>		
Scour	<input type="text" value="Bridge foundations (including piles) on dry land well above flood water elevations. [9]"/>		
Channel and channel protection	<input type="text" value="Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present desirable criteria [8]"/>	Status evaluation	<input type="text" value="Functionally obsolete [2]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="40.6"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - transitions	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="February 2012 [0212]"/>	Designated inspection frequency	<input type="text" value="12"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Every two years [Y24]"/>	Fracture critical inspection date	<input type="text" value="February 2012 [0212]"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>

Unit of Measure: **English**
Structure File Number **2202344**
Sufficiency Rating: **47.6 fo**

Bridge Inventory Information
Inventory Bridge Number: **ERI 00006 2884**
ON VERMILION RIVER

Report Date **12/12/2014** BM-191 Page: 1 of 2
BR. Type STEEL / TRUSS / THRU
Date of Last Inventory Update: **03/27/2014**

District: **03** County **ERIE** (101) Location: **.60 MI W LOR. CO. LINE** (102) Facility Carried: **US 6**
(2) FIPS Code: **VERMILION** (103) Route On Bridge: **STATE (ODOT)** (104) Route Under Bridge: **NON-HIGHWAY**
(9) Direction of Traffic: **2-WAY TRAFFIC** (10) Temporary: **N** (11) Truck Network: **N** (12) Parallel: **N**
(95) Insp: **OHIO TRAN DEPT** (96) Maint: **OHIO TRAN DEPT** (97) Routine: **CITY/LOC** (100) Type Serv: (On): **HIGHWAY/PEDESTRIAN** (Under): **WATERWAY**

Inventory Route Data

(3) Route On/Under: **ON** Hwy Sys: **U.S. NUMBERED HIGHWAY** (63) Main Spans Number: 1 Type: **STEEL / TRUSS / THRU**
Route No.: **00006** Dir: Des: **MAINLINE** Pref: Total Spans: 1 Type: **NONE / NONE / NONE**
(65) Max Span: **240 Ft** (66) Overall Leng: **246 Ft**

(4) Feature Intersected: **VERMILION RIVER** (70) Substructure (71) Foundation and Scour Information
(5) County: **ERI** Mileage: **2884** Special Desig: Abut-Rear Matl: **CONCRETE** Type: **CANTILEVER** Fnd: **TIMBER PILES**
(6) Avg. Daily Traffic(ADT): **14,140** (7) ADT Year: **2010** Abut-Fwd Matl: **CONCRETE** Type: **CANTILEVER** Fnd: **TIMBER PILES**
(8) Truck Traf: **480** (14) NHS: **YES - N** (15) Corridor: **N** Pier-Pred Matl: **NONE** Type: **NONE** Fnd: **NONE/NOT APPLICABLE (SUCH AS CULVERTS)**
(16) Functional Class: **OTHER PRINCIPAL ARTERIAL-URBAN** (19) Strahnt: **Not Applicable** Pier-Other Matl: **NONE** Type: **NONE** Fnd: **NONE/NOT APPLICABLE (SUCH AS CULVERTS)**
Pier-Other Matl: **NONE** Type: **NONE** Fnd: **NONE/NOT APPLICABLE (SUCH AS CULVERTS)**

Intersected Route Data

(22) Route On/Under: Hwy Sys: No of Piers Predominate: **NN** Other: **NN** Other: **NN**
Route No.: Dir: Des: Pref: (86) Stream Velocity: **UUU** (74) Scour: **FND/PILES ABOVE FLOOD WATER ELEVATIONS**
(23) Feature Intersected: (189) Dive: **N Freq: 0** Probe: **N Freq: 0** (75) Chan Prot: **SHEET PILING**
(24) County: Mileage: Special Desig: (189) Date of last Dive Insp: (152) Drainage Area: **UUU Sq Mi**

(25) Avg. Daily Traffic(ADT): **0** (26) ADT Year: (189) Date of last Dive Insp: (152) Drainage Area: **UUU Sq Mi**
(27) Truck Traf: **0** (28) NHS: - (29) Corridor: (156) Min. Horiz Under Clear: NC: **0.0 Ft** Card: **0.0 Ft**
(30) Functional Class: (36) Strahnt: **Not Applicable** (157) Prac Max Vrt Under Clear: **0.0 Ft**
(77) Min Vert Under Clear: NC: **0.0 Ft** Card: **0.0 Ft**
(78) Min Lat Under Clear: NC: **0.0 / 0.0 Ft** Card: **0.0 / 0.0 Ft**

Clearance On the Bridge

(154) Min Hriz on Bridge: NC: **0.0 Ft** Card: **35.2 Ft**
(155) Prac Max Vert On Brg: **15.9 Ft**
(67) Min Vrt Clr On Brg: NC: **0.0 Ft** Card: **15.9 Ft**
(80) Min Latl Clr: NC: **0.0 / 0.0 Ft** Card: **0.0 / 0.0 Ft**
(81) Vrt Clr Lft: **0.0 Ft**

Structure Information

(38) Bypass Length: **16 Miles**
(39) Latitude: **41 Deg 25.3 Min** Longitude: **82 Deg 21.5 Min**
(40) Toll: **ON FREE ROAD**
(41) Date Built: **07/01/1928** (42) Major Rehabilitation: **01/01/1986**
(43) No. Lanes On: **3** No. Lanes Under: **0**
(44) Horiz Curve: **Deg. Min.** (45) Skew: **0 Deg**
(49) App. Rdw Width: **40 Ft** (50) Brg. Rdw Width: **35.0 Ft**
(51) Deck Width: **40.4 Ft** Deck Area: **9946 Sq. Ft**

(52) Median Type: **NONE / NON BARRIE / NO JOINT**
(53) Bridge Median: **NO MEDIAN**
(54) Sidewalks: (left) **6 Ft** (right) **6 Ft**
(55) Type Curb or Sidewalks: (Left) Matl: **CONCRETE** Type: **SIDEWALK(>2')**
(Right) Matl: **CONCRETE** Type: **SIDEWALK(>2')**
(56) Flared: **N** (57) Composite: **non-composite**

Clearance Under the Bridge

(156) Min. Horiz Under Clear: NC: **0.0 Ft** Card: **0.0 Ft**
(157) Prac Max Vrt Under Clear: **0.0 Ft**
(77) Min Vert Under Clear: NC: **0.0 Ft** Card: **0.0 Ft**
(78) Min Lat Under Clear: NC: **0.0 / 0.0 Ft** Card: **0.0 / 0.0 Ft**

Load Rating Information (88-89) Appraisal

(48) Design Load: **HS/20** (Including calculated Items)
(83) Operating: **40 Ton**
Inventory: **28 Ton**
Ohio Percent of Legal Load **135** (88) Waterway Adequacy **8**
Year of Rating: **2010** (89) Approach Alignment **6**
(84) Analysis: **ALLOWABLE STRESS OR WORKING STRESS** Calc Gen Appraisal: **5**
(85) Rate Soft: **BARS** Analyzed by: **WSA** Calc Deck Geometry: **2**
Analysis on Bars: **WRKG STRESS ANALYSIS** Calc Underclearance: **N**

Approach Information

(109) Approach Guardrail: **STEEL BEAM**
(110) Approach Pavement: **BITUMINOUS** (111) Grade: **GOOD**

Culvert Information

(131) Culvert Type: **NONE/NOT APPLICBLE** (127) Length: **0.0 Ft**
(129) Depth of Fill: **0.0 Ft** (130) Headwalls: **NONE**

General Information

(121) Main Member **N/A (CULVERTS, TRUSSES, ETC.)** (122) Moment Plate: **NOT APPLICABLE**
(169) Expansion Joint: **ELASTOMERIC STRIP SEAL**
(124) Bearing Devices: **ROCKERS/ELASTOMERIC (LAMIN.)**
(126) Navigation: **Control- N** Vert Clr: **0.0 Ft** Horiz Clear: **0.0 Ft**
(193) Spec Insp: **N** Freq: **0** Date: **2012-02-01**
(188) Fracture Critical Insp: **Y** Freq: **24** Date: **2012-02-01**
(138) Long Member: **TWO TRUSSES (RIVETED)** (135) Hinges: **NOT APPLICABLE**
(141) Structural Steel Memb: **UNKNOWN** (139) Framing: **NONE**
Railing: **UNKNOWN**
Paint: **RED LEAD**
Pay Wt: **0 pounds** Prime Loc: **UNKNOWN**
Bridge Dedicated Name:

Unit of Measure: **English**
 Structure File Number **2202344**
 Sufficiency Rating: **47.6 fo**

Bridge Inventory Information
 Inventory Bridge Number: **ERI 00006 2884**
ON VERMILION RIVER

Report Date **12/12/2014** **BM-191** Page: 2 of 2
BR. Type STEEL/TRUSS/THRU
 Date of Last Inventory Update: **03/27/2014**

General Information (Continued)				Original Plans Information			
(---) Hist Significance: NOT HISTORIC		(69) NBIS: Y		(142) Fabricator:			
(---) Hist Builder: OHIO STATE HIGHWAY DEPARTMENT		Hist Build Year: 1928		(143) Contractor:			
(69) Hist Type: PENNSYLVANIA (RIVETED)				(144) Ohio Original Construction Project No.: 000228			
(161) Special Features (see below):				(---) Microfilm Reel: ERI001			
(105) Border Bridge State: Resp % (106) SFN:				(151) Standard Drawing:			
				Aperture Cards: Orig: Y Repair: Y Fabr: Y			
Proposed Improvements		Programming Info		Plan Information Available: 1PLAN INFORMATION AVAILABLE			
(90) Type Work: 35 - BRG REHAB--GEN DECLINE/INADEQ STRENGTH		PID Number:		(153) Repair Projects			
(90) Length: Ft		PID Status:		1. / 020	2. / MMM	3. 860010 / 004	
(90) Bridge Cost (\$1000s): 0		PID Date:		4. / 020	5. / 044	6.	
(90) Roadway Cost (\$1000s): 0				7.	8.	9.	
(90) Total Project Cost (\$1000s): 0		(90) Year:		10.			
(91) Future ADT (On Bridge): 0		(92) Year of Future ADT: 2033					
Inspection Summary		(I-69) Survey Items		Utilities		Special Features	
(I-8) Deck: 6	Railings: 1 MEETS CURRENT STANDARDS	(46) Electric: Y		(161) Lighting: Y			
(I-32) Superstructure: 6	Transitions: 1 MEETS CURRENT STANDARDS	Gas: N		Fencing: N			
(I-42) Substructure: 6	Guardrail: 1 MEETS CURRENT STANDARDS	Sanitary Sewer: N		Glare-Screen: N			
(I-50) Culvert:	Rail Ends: 1 MEETS CURRENT STANDARDS	Telephone: N		Splash-Guard: N			
(I-54) Channel: 7	In Depth: N NONE N/A	TV Cable: N		Catwalks: N			
(I-60) Approaches: 7	Fracture Critical: 1 MEETS CURRENT STANDARDS	Water: N		Other-Feat: N			
(I-66) General Appraisal: 6	Scour Critical: N NONE N/A	Other: N		(184) Signs-on: Y			
(I-66) Operational Status: A	Critical Findings: N NONE N/A			Signs-Under: N			
Inspection Date: 05/14/2013	Insp. Update Date: 05/31/2013			(162) Fence-Ht: 0.0 Ft			
(94) Desig Insp Freq: 12 Months				(163) Noise Barr: N			
SFNs Replacing this retired bridge: -				INV Field Bridge Marker: ERI-00006-2884 -			
SFNs That where replaced by this bridge: -				INT Field Bridge Marker: ---			
This bridge was retired and copied to:							
The bridge was copied from:							

PONTIS CoRe elements and Condition States

Elem No.	CoRe Element Description	Total Quantity	Unit Meas.	Condition State Percents(*)				
				1	2	3	4	5
26	CONCRETE DECK - PROTECTED W/COATED BARS	1	EA	0	0	0	0	0
121	PAINTED STEEL BOTTOM CHORD THROUGH TRUSS	490	LF	0	0	0	0	0
126	PAINTED STEEL THRU TRUSS(EXCL BOT CHORD)	490	LF	0	0	0	0	0
215	REINFORCED CONC ABUTMENT	81	LF	0	0	0	0	0
300	STRIP SEAL EXPANSION JOINT	81	LF	0	0	0	0	0
321	REINFORCED CONCRETE APPROACH SLAB	2	EA	0	0	0	0	0

(*) Percentages Should add to 100%

STATE OF OHIO DEPARTMENT OF TRANSPORTATION
BRIDGE INSPECTION REPORT

BR-86 REV 02-95

2	2	0	2	3	4	4
---	---	---	---	---	---	---

1 Structure File Number 7

Bridge Number **ERI 00006 2884**
CO ROUTE UNIT

VERMILION

Date Built **07/01/1928 - 1986**

District **03** Bridge Type **STEEL/TRUSS/THRU**

Type Service **1 55 VERMILION RIVER**

ERI

DECK		Out/Out 40.4			THCK = 1.2	
1. Floor	1-REINF CONCRT (PRESTRSD	8	2	2. Wearing Surface	2-INTEGRAL CONCRETE (MON	41
	1-CONCRETE				W.S. Date = 01/01/1986	
3. Curbs, Sidewalks, Walkways	1-CONCRETE	9	1	4. Median		42
5. Railing	A-TUBULAR BACKUP	10	1	6. Drainage	3-SCUPPERS & DWNSPTS	43
7. Expansion Joints	8-ELASTOMERIC STRIP SEAL	11	2	8. Summary		44
SUPERSTRUCTURE		MAX.SPAN=240				
9. Alignment		12	1	10. Beams/Girders/Slab	N-N/A (CULVERTS, TRUSSES	45
11. Diaphragms or Crossframes	TOT.LGTH=246	13		12. Joists/Stringers		46
13. Floor Beams		14	2	14. Floor Beam Connections		47
15. Verticals		15	2	16. Diagonals		48
17. End Posts		16	2	18. Top Chord		49
19. Lower Chord		17	2	20. Lower Lateral Bracing		50
21. Top Lateral Bracing		18		22. Sway Bracing		51
23. Portals		19	2	24. Bearing Devices	2-ROCKERS C-ELASTOMERIC (LAMIN.)	52
25. Arch		20		26. Arch Columns or Hangers		53
27. Spandrel Walls		21		28. Protective Coating System	TYPE = 1-RED LEAD DATE = 09/01/2012	54
29. Pins/Hangers/Hinges		22		30. Fatigue Prone Connections		55
31. Live Load Response		23	S	32. Summary		56
SUBSTRUCTURE		2-CONCRETE		PIERS=0	SPANS = 1	
33. Abutments	2-CONCRETE	24	2	34. Abutment Seats		57
35. Piers	TYPE = N-NONE	25		36. Pier Seats		58
37. Backwalls		26	2	38. Wingwalls	ABUTMENT:=TIMBER / TIMBER	59
39. Fenders and Dolphins		27		40. Scour	9-FND/PILES ABOVE FLOOD	60
41. Slope Protection	S-PROBLEM	28	1	42. Summary	DIVE DT=N/A	62
CULVERTS						
43. General		29		44. Alignment		63
45. Shape		30		46. Seams		64
47. Headwalls or Endwalls		31		48. Scour		65
49.		32		50. Summary		66
CHANNEL					3-SHEET PILING	
51. Alignment		33	1	52. Protection		67
53. Waterway Adequacy		34	1	54. Summary		68
APPROACHES						
55. Pavement	2-BITUMINOUS	35	1	56. Approach Slabs		69
57. Guardrail	1-STEEL BEAM	36	1	58. Relief Joints		70
59. Embankment	BRDG.WIDTH=35.0	37	2	60. Summary	PCT.LEGAL=135	71
GENERAL					ROUTINE.RESP: 4-CITY/LOCAL MAINT.RESP: 1-OHIO TRAN DEPT	
61. Navigation Lights		38		62. Warning Signs	ELEC/	72
63. Sign Supports	MVC ON=15.9 UND=0000	39	2	64. Utilities		73
65. Vertical Clearance		40	1	66. General Appraisal & Operational Status		74

67. INSPECTED BY

68. REVIEWED BY

_____ SIGNED _____ 76 PE _____ A T _____ SIGNED _____ 81 PE _____ M W _____ 83 INITIALS

DOT 2852

DECK AREA 9,946

Date 0 5 1 4 1 3
86 91

1 1 1 1 N 1 N N
92 69 Survey 99

Date 0 5 2 1 1 3
100 105

STATE OF OHIO DEPARTMENT OF TRANSPORTATION
BRIDGE INSPECTION REPORT

BR-86 REV 02-95

2	2	0	2	3	4	4
---	---	---	---	---	---	---

1 Structure File Number 7

Bridge Number **ERI 00006 2884**
 CO ROUTE UNIT

Date Built 07/01/1928 - 1986

District **03** Bridge Type **STEEL/TRUSS/THRU**

Type Service **1 55**

VERMILION RIVER

Deck 61. DECK BOTTOM HAS TRANS.HAIRLINES/CRACKS W/EFFL.(SOME WET)
 Deck THE CRACKS ARE SPACED @ 20-30 FT. THE PART OF THE DECK CLOSE
 Deck TO THE FWD.ABUT IS WORSE THAN THAT CLOSE TO REAR ABUT.THERE
 Deck ARE SOME SPALLED AREAS ALONG EXTERIOR STRINGER'S TOP FLANGES
 Deck & DECK EDGES.THE SPALLED AREA IS LESS THAN 10% OF THE TOTAL
 Deck DECK AREA.
 Deck 2.DECK WEARING SURFACE HAS MANY TRANS.HAIRLINES(TIGHT)W/A
 Deck FEW SPALLS.THE CRACKS ARE LESS THAN 1/16TH IN.WIDE.THE
 Deck SPALLED AREA IS LESS THAN 10% OF OF THE TOTAL DECK AREA.MOST
 Deck GROOVING WORN AWAY(SMOOTH). SEALED WITH PROJECT 2009(HMWM).
 Deck 3.THERE ARE HAIRLINE CRACKS ON SIDEWALK.FWD.LT.,FWD.RT.&
 Deck REAR LT.ENDS OF SIDEWALK OFF THE BRIDGE HAVE LARGE LONG.
 Deck CRACKS (1/2"-1" MAX WIDTH.)W/SOME SETTLEMENTS (2"-3" MAX.)
 Deck THERE ARE A FEW SPALLED AREAS ALONG CURBS.FWD.RT.END OF
 Deck SIDEWALK HAS ABOUT 4' OF CURB CRACKED & BROKEN. SEALED WITH
 Deck PROJECT 2009.UNDER SIDEWALK BOTH SIDES TRANS.HAIRLINES WITH
 Deck EFFL.& SPACING OF 1'- 3'(±)FULL LENGTH BOTH. 2013; NEW
 Deck SDIEWALK AND CURB WITH 2012 PROJECT REAR LEFT, FWD. LT, AND
 Deck RT.
 Deck 5.PED.HAND RAIL HAS SCATTERED AREAS OF PAINT FAILURE & MINOR
 Deck COLLISION DAMAGE @ FWD.RT.END.ANCHORAGE SPLICE PLATES HAVE
 Deck SOME PACK RUST.HAND RAIL BOTH SIDES ARE LINED W/FLOWER
 Deck PLANTERS & RUBBER SPRINKLER HOSE.CLEAR SPACING OF VERTICAL
 Deck PICKETS IS 5". TOP RAIL CONNECTION PLATES ARE CRACKED @ L3,
 Deck L4,L9 LT.SIDE,LO,L4,& L9 RT.SIDE.POST TOP CAPS ARE LOOSE @
 Deck L2 LT.SIDE,L6 & L7 RT.SIDE.RAIL FWD.& REAR + RAIL ENDS HAVE
 Deck MINOR COLLISION DAMAGE. 2013; RAIL REPAIRS COMPLETED WITH
 Deck 2012 PROJECT.
 Deck 6. TWO OF THE 12 SCUPPERS ARE 30-50% BLOCKED W/DEBRIS &
 Deck VEGETATION.THEY ARE LOCATED ON THE RIGHT SIDE.1 SCUPPER TUBE
 Deck BROKEN FWD.RT. + DIRTY ALONG BOTH CURBS.
 Deck 7. THE FWD.COMP.SEAL HAS MINOR CUT FROM SNOWPLOW.SIDE STRIP
 Deck SEAL IS TORN W/EVIDENCE OF LEAKING.THE EXP.JOINT @ REAR IS
 Deck ALMOST TOTALLY CLOSED 1/18"-1/16"(±) @ 84 DEGREES.
 Superstructure 12. THERE IS MINOR RUST & CHIPPED/PEELING PAINT ALONG
 Superstructure EXTERIOR STRINGER.EXTERIOR STRINGER END @ CONNECTION TO
 Superstructure FLOOR BEAM HAS HEAVY RUST. 2013; NEW PCS WITH 2012 PROJECT.
 Superstructure 13. FLOOR BEAM WEB @ CONNECTION TO LOWER CHORD HAS PITTING
 Superstructure PACK RUST & MINOR SECTION LOSS.
 Superstructure 14. FLOOR BEAM CONNECTION ANGLES HAVE PACK RUST FORMING,
 Superstructure MINOR SECTION LOSS,& AREAS OF PAINT PEELING.
 Superstructure 15. TRUSS VERTICALS HAVE PITTING & SECTION LOSS IN SPLASH
 Superstructure ZONE FROM ROAD SALTS.(LESS THAN 10% OF WEB AREA).THERE IS
 Superstructure PACK RUST & SECTION LOSS AT CONNECTION TO FLOOR BEAMS &
 Superstructure SIDEWALK LEVEL.
 Superstructure 16.TRUSS DIAGONALS HAVE SECTION LOSS,PITTING IN SPLASH ZONE
 Superstructure (LESS THAN 10% OF TOTAL WEB AREA.)DIAGONALS OF(SOUTH)
 Superstructure UPSTREAM TRUSS @ L3 & L4 HAVE DEEP PITTING & TWO SMALL 1/2"
 Superstructure TO 1" DIAMETER RUST HOLES
 Superstructure 17.CROSS BRACING & ALL 4 END POSTS HAVE SECTION LOSS & RUST
 Superstructure THROUGH HOLES + SOME RUST BETWEEN FLANGES & DEBRIS.
 Superstructure 18.TOP CHORD HAS A FEW AREAS OF LOCALIZED DENTS FROM
 Superstructure ORIGINAL CONSTRUCTION APPEARS TO BE IN SATISFACTORY
 Superstructure CONDITION.
 Superstructure 19. LOWER CHORD HAS PACK RUST,PITTING & MINOR SECTION LOSS.
 Superstructure (10-20% OF WEB AREA).THERE IS HEAVY RUST PACK (3/8"MAX)
 Superstructure BETWEEN THE THIN EXTERIOR WEB PLATE & ADJACENT THICK WEB
 Superstructure PLATE W/RUST THROUGH PLATES ALONG LOWER CHORD BETWEEN L3 &
 Superstructure L6 ON BOTH SIDES.
 Superstructure 20.).THE LOWER GUSSET PLATES L4, L5,& L6 ON THE UPSTREAM
 Superstructure (SOUTH)TRUSS HAVE SIGNIFICANT PAST SECTION
 Superstructure LOSS OF UP TO 50%(1/4")OVER 30-50% OF THE PLATE AREA. THESE
 Superstructure PLATES WERE PAINTED OVER IN 1986.THERE IS NOW ACTIVE

Superstructure CORROSION AGAIN ON THE LOWER GUSSET PLATES ALONG VERTICAL &
Superstructure DIAGONAL MEMBER EDGES. RUST HOLES VARYING FROM 1" TO 2"
Superstructure DIAMETER WERE FOUND ON GUSSET PLATES L4,L5,AND L6.L6 IS IN
Superstructure THE WORST CONDITION. NO WARPING OR CRACKING WERE OBSERVED IN
Superstructure THE GUSSET PLATES.THE RATING OF THE GUSSET PLATES IS
Superstructure INCLUDED W/ THE DIAGONAL MEMBER.DIAGONAL MEMBERS.
Superstructure GUSSET PLATES ARE RATED FAIR(2)BASED ON THE STRUCTURAL
Superstructure ANALYSIS & SATISFACTORY LOAD RATING RESULTS.LOAD & GUSSET
Superstructure PLATE ANALYSIS DATED DEC. 2009. 2013; REHAB OF PLAN SPECIFIE
Superstructure GUSSET PLATES COMPLETED WITH 2012 PROJECT.
Superstructure 21.)LOWER LATERAL BRACING HAS SOME MINOR SURFACE RUST &
Superstructure IMPACT DAMAGE ON TWO TENSION RODS IN BAYS 3 & 7.
Superstructure TOP LATERAL BRACING HAS SOME MINOR RUST. LATERAL
Superstructure CONNECTIONS HAVE SOME PACK RUST & MINOR DEFORMATION FROM
Superstructure PACK RUST OF PLATES @ CONNECTIONS + CONNECTIONS RUSTY.
Superstructure 24. ROCKER BEARINGS @ REAR ABUT.TIPPED TOWARD BACKWALL.THE
Superstructure CONTACT AREA FALLS INSIDE THE MIDDLE THIRD OF ROCKER BASE,SO
Superstructure THE ROCKER IS NOT FALLING OFF IT'S BASE.ELASTOMERIC PAD
Superstructure UNDER THE ROCKERS DEFORMED 1" IN SAME DIRECTION.FWD.ABUT.IS
Superstructure FIXED W/BOLSTERS.ALL BEARINGS HAVE RUST + FWD.RT.BEARING
Superstructure PLATE NUT NOT COMPLETELY THREADED. NO CHANGE FROM PREVIOUS
Superstructure INSPECTIONS.
Superstructure 28.THE PROTECTIVE COATING EXHIBITS SCATTERED RUSTY AREAS
Superstructure WITHIN SPLASH ZONE & @ FLOOR BEAM CONNECTIONS.THERE IS ALSO
Superstructure SOME PEELING PAINT,AREAS OF PACK RUST & AREAS OF ACTIVE
Superstructure CORROSION. ABOUT 10-15% OF TOTAL PCS IS FAILED.2013; NEW
Superstructure ROYAL BLUE PCS WITH 2012 PROJECT. OVERALL GOOD COVERAGE, AS
Superstructure NOTED FROM GROUND LEVEL INSPECTION. MINOR OVERSPRAY AREAS.
Superstructure 32. *SEE #13,#14,#15,#16 AND #19.*NOTE; 2013 INSPECTION IS
Superstructure ROUTINE. WORK COMPLETED ON GUSSET PLATES, AND OTHER OTHER
Superstructure AREAS COMPLETED WITH PROJECT 2012 WILL BE VERIFIED WITH A
Superstructure CONSULTANT INSPECTION. 2013 INSPECTION AT GROUND LEVEL.
Substructure 33.THERE ARE SOME CRACKS WITH EFFL. SMALL DELAMINATED AREAS
Substructure AND MINOR SPALLS. THE DELAMINATED AREAS ARE LESS THAN 5% OF
Substructure TOTAL CONCRETE AREAS.REAR IS WORSE THAN FORWARD ABUTMENT.A
Substructure COUPLE SPALLS HAVE RESTEEL. ABUTMENT SEATS CLEANED AND SEALE
Substructure WITH 2012 PROJ.
Substructure 34. THE REAR ABUT.SEAT IS WET W/DEBRIS UP TO 6" THICK.FWD.
Substructure ABUT.IS DRY W/LESS THAN 5% AREAS THAT SOUND HOLLOW.THE
Substructure HOLLOW SOUNDING AREAS ARE IN THE MIDDLE PORTION OF THE
Substructure ABUT.SEAT,& DO NOT AFFECT BEARING.
Substructure 37.THE BACKWALLS HAVE MINOR CRACKS BOTH VERT.& HORZ.W/EFFL.,
Substructure EVIDENCE OF MINOR LEAKAGE OVER 10%.
Substructure 38.WINGWALLS HAVE CRACKS,EFFL.& DELAM..OVER 10% OF SURFACE.
Substructure FWD.RT.WINGWALL IS PAINTED W/MURAL.OUTLET DRAIN,DRAIN
Substructure WASHING OUT SOME DIRT & CREATED SMALL PUDDLE @ REAR
Substructure RT.WINGWALL.
Substructure 40. ABUTS.ARE BEHIND SHEET PILING.NO EVIDENCE OF SCOUR IS
Substructure NOTED @ ABUTMENTS.NOT IN WATER 2012.
Substructure 41. NO REPAIRS NECESSARY.
Substructure 42. *SEE #33,#34 AND #37.
Channel 52.THERE IS SHEET PILING ALONG CHANNEL @ BOTH FWD.& REAR
Channel ABUTS.TOP OF SHEET PILING @ REAR ABUT.HAS 6" TO 8" GAP IN A
Channel COUPLE AREAS BEHIND THE SHEETING.SHEET PILING @
Channel FWD.ABUT.INCLINED 1:40 TOWARDS WATER. NO GAP OR SEPARATION
Channel BEHIND FWD.SHEET PILING IS NOTED.
Approaches 55. NEW ASPHALT W/PROJ.2009 + @ JCT.W/APPR.SLABS-TRANS.
Approaches CRACKS & RAVELING + A FEW OTHER HAIRLINES/CRACKS.
Approaches 56.THERE ARE SOME SPALLED AREAS ALONG JTS.W/NO SETTLEMENT OF
Approaches APPR.SLABS FWD.IS WORSE.
Approaches 57. COLLISION DAMAGE IS NOTED @ REAR RT.,& FWD.LT.& RT.G/R
Approaches ENDS. NEW GR ENDS WITH POSTS, ECT AT ALL FOR CORNERS, PROJEC
Approaches 2012.
Approaches 59. TWO GROUNDHOG HOLES NEAR REAR RT.WINGWALL NOTED.FWD.LT.
Approaches END OF WINGWALL HAS MINOR EMBANKMENT EROSION(ABOUT 5' WIDE
Approaches 1' DEEP)FROM TOP TO BOTTTOM OF SLOPE.
General 63. SIGN SUPPORTS HAVE MINOR RUST BUT NO SECTION LOSS NOTED.
General CHECKED 2012.
General 64. THERE IS A SMALL SECTION OF EXPOSED CABLE @ RT.END OF
General REAR ABUT.DUE TO SPLIT CONDUIT.CHECKED STREET LIGHT ATTACHED

General TO LT.SIDE NEAR TOP OF TRUSS-CONNECTION APPEARS STABLE-2013.
General 2013 LIGHT IS WORKING.
General 66. *SEE #32 AND #42.
General NOTES;
General *NBIS QAR 2011 03-03 FWD.RT.FLOOR BEAM #3 RT.WEB 1'(+/-)FROM
General END ABOVE ABUT..
General FCM 02-01-12 M. WENGERD,BOB VALENTINE, ANDREA TESCHLER.
General DARYLL SHANNON, MATT STEIFIC, USED SNOOPER TRUCK.
General *NOTE REPAIR WORK TO GUSSET PLATES,STRUCTURAL STEEL PAINTING
General RAIL REPAIR, AND SIDEWALK REPAIR COMPLETED WITH PROJECT 513-
General 11. 2013 IS A ROUTINE INSPECTION FROM GROUND LEVEL. 2014 IS
General SCHEDULED FCM INSPECTION.
