The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information							42-06-36 =	084-14-44 = -
Michigan [26]	ackson County [0	75]	Brooklyn [11000]	1000] 0.10 MI E OF M50			42-06-36 = 42.110000	84.245556
384093200038B01 Highway agency district 6		Owner City or Municipal Highway Agency [04] Maintenance responsibility		City or Municipal Highway Agency [04]				
Route 1404	ee road [3]	eatures intersec	ted SO BRANCI	H RAISIN RIVER				
Design - main Masonry [8] Design - approach Arch - Deck [11] 0 Other			Kilometerpoint 19 km = 11.8 mi Year built 1925 Year reconstructed 198 [00] Skew angle 25 Structure Flared					
				Historical significance	Bridge is	on the NRHP. [1]	
Total length 10.6 m = 34.8 ft Length of maximum span 2.4 m = 7.9 ft Deck width, out-to-out 7.8 m = 25.6 ft Bridge roadway width, curb-to-curb 6.7 m = 22.0 ft								
Inventory Route, Total H	idth - left $0 \text{ m} = 0.0 \text{ f}$	t	Curb or side	walk width - right	0 m = 0.0 ft			
Deck structure type Not applicable [N]								
Type of wearing surface Bituminous [6]								
Deck protection Not applicable (applied			es only to structures with no deck) [N]					
Type of membrane/wearing surface Not applicable (applie			es only to structures with no deck) [N]					
Weight Limits								
Bypass, detour length	Wethou to determine inventory rating			erformed [5] Inve	entory rating	19.6 metric ton =	21.6 tons	
1.4 km = 0.9 mi Method to determine ope		rmine operating rating	No rating analysis p	erformed [5] Ope	erating rating	32.7 metric ton =	36.0 tons	
Bridge posting Equal to or above legal loads [5]					sign Load M 1	3.5 / H 15 [2]		

Functional Details								
Average Daily Traffic 600 Average daily tr	ruck traffi 10 % Year 1986 Future average daily traffic 1100 Year 2010							
Road classification Minor Collector (Rural) [08]	Lanes on structure 2 Approach roadway width 8.5 m = 27.9 ft							
Type of service on bridge Highway [1]	Direction of traffic 2 - way traffic [2] Bridge median							
Parallel structure designation No parallel structure	e exists. [N]							
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control							
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A							
Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway 99.99 m = 328.1 ft								
Minimum lateral underclearance reference feature F	eature not a highway or railroad [N]							
Minimum lateral underclearance on right 99.9 = Unlimited Minimum lateral underclearance on left 0 = N/A								
Minimum Vertical Underclearance 0 = N/A	Minimum vertical underclearance reference feature Feature not a highway or railroad [N]							
Appraisal ratings - underclearances N/A [N]								
Repair and Replacement Plans								
Type of work to be performed	Work done by							
	Bridge improvement cost Roadway improvement cost							
	Length of structure improvement Total project cost							
	Year of improvement cost estimate							
	Border bridge - state Border bridge - percent responsibility of other state							
	Border bridge - structure number							

Inspection and Sufficiency									
Structure status Open, no res	striction [A]	Appraisal ratings - structural	Somewhat better than minimum adequacy to tolerate being left in place as is [5] Equal to present minimum criteria [6]						
Condition ratings - superstructur	Satisfactory [6]	Appraisal ratings - roadway alignment							
Condition ratings - substructure	Fair [5]	Appraisal ratings - deck geometry	Meets minimum tolerable limits to be left in place as is [4]						
Condition ratings - deck	Not Applicable [N]								
Scour	Bridge foundations determine	Bridge foundations determined to be stable for assessed or calculated scour condition. [5]							
Channel and channel protection	Bank is beginning to slump. Finding stream bed movement	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]							
Appraisal ratings - water adequac	Better than present minimum	criteria [7]	Status evaluation						
Pier or abutment protection			Sufficiency rating 53.3						
Culverts Not applicable. Used	if structure is not a culvert. [N]								
Traffic safety features - railings									
Traffic safety features - transition	ns								
Traffic safety features - approach	n guardrail								
Traffic safety features - approach guardrail ends									
Inspection date May 2008 [0	Months								
Underwater inspection	Not needed [N]	Underwater inspec	ction date						
Fracture critical inspection Not needed [N]		Fracture critical inspection date							
Other special inspection Not needed [N] Other special inspection date									