The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information										40-15-23 =	075-25-48 = -
Pennsylvania [42]	nia [42] Montgomery County [091]			Lower S	Lower Salford [45096] BERGEYS MILL RD.			14G09		40.256389	75.430000
467046021001460 Highway agency district: 6			Owner	Owner County Highway Agency [02] Maintenance responsibility			County Highway	Agency [02]			
Route 0 BERGEYS MILL ROAD)	Toll On free road [3] Features intersected ESAT BR.P					PERKIOMEN CREE	K
Design - main Steel [3] Design - approach Truss - Thru [10] 0		approach	ther [00]		Kilometerpoint 0 km = 0.0 mi Year built 1893 Year reconstructed 1985 Skew angle 15 Structure Flared Historical significance Bridge is not eligible for the						
Total length 59.7 m = 195.9 ft Length of maximum span 28.7 m = 94.2 ft Deck width, out-to-out 4.8 m = 15.7 ft Bridge roadway width, curb-to-curb 4.6 m = 15.1 ft Inventory Route, Total Horizontal Clearance 4.6 m = 15.1 ft Curb or sidewalk width - left 0 m = 0.0 ft Curb or sidewalk width - right 0 m = 0.0 ft											
Deck structure type Closed Grating [4]										<i>y</i>	
Type of wearing surface Bituminous [6]											
Deck protection											
Type of membrane/wearing surface											
Weight Limits											
3.	Bypass, detour length Method to detern			ng Lo	Load Factor(LF) [1]		Inv	entory rating	5.4 metric ton =	= 5.9 tons	
0.6 km = 0.4 mi	Metho	Method to determine operating rating			Load Factor(LF) [1]		Ор	erating rating	9.1 metric ton =	= 10.0 tons	
Bridge posting							De	sign Load M	13.5 / H 15 [2]		

Functional Details										
Average Daily Traffic 175 Average daily truc	k traffi % Year 1977 Future average daily traffic 245 Year 2023									
Road classification Minor Collector (Rural) [08]	Lanes on structure 1 Approach roadway width 6.1 m = 20.0 ft									
Type of service on bridge Highway [1]	Direction of traffic One lane bridge for 2 - way traffic [3] Bridge median									
Parallel structure designation No parallel structure e	exists. [N]									
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control									
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A									
Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway 3 m = 9.8 ft										
Minimum lateral underclearance reference feature Feature not a highway or railroad [N]										
Minimum lateral underclearance on right $0 = N/A$	Minimum lateral underclearance on left 0 = N/A									
Minimum Vertical Underclearance 0 = N/A Minimum vertical underclearance reference feature Feature not a highway or railroad [N]										
Appraisal ratings - underclearances N/A [N]										
D : 10 1 10										
Repair and Replacement Plans										
Type of work to be performed	Work done by Work to be done by contract [1]									
Replacement of bridge or other structure because of substandard load carrying capacity or substantial	Bridge improvement cost 0 Roadway improvement cost 0									
	Length of structure improvement 61 m = 200.1 ft Total project cost 1000									
	Year of improvement cost estimate									
	Border bridge - state Border bridge - percent responsibility of other state									
	Border bridge - structure number									

Inspection and Sufficiency									
Structure status Posted for lo	Appraisal ratings - structural								
Condition ratings - superstructure	Appraisal ratings - roadway alignment								
Condition ratings - substructure	Poor [4]	Appraisal ratings -	Basically into						
Condition ratings - deck	Poor [4]	deck geometry							
Scour	Bridge foundations determine required. [4]	Bridge foundations determined to be stable for assessed or calculated scour conditions; field review indicates action is required. [4]							
Channel and channel protection	Bank is beginning to slump. minor stream bed movement	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]							
Appraisal ratings - water adequac	Equal to present desirable cr	iteria [8]	Status evaluation Structurally deficient [1]						
Pier or abutment protection			Sı	ufficiency rating	11.8				
Culverts Not applicable. Used	if structure is not a culvert. [N]		,						
Traffic safety features - railings									
Traffic safety features - transition	ns								
Traffic safety features - approach	n guardrail								
Traffic safety features - approach	n guardrail ends								
Inspection date July 2009 [0709] Designated inspection frequency 24 Months									
Underwater inspection	Every two years [Y24]	Underwater inspec	ction date	July 2009 [0709]				
Fracture critical inspection	Every two years [Y24]	Fracture critical in:	spection date	July 2009 [0709]				
Other special inspection	Every year [Y12]	Other special insp	ection date	December 2000	[1200]				