HistoricBridges.org - National Bridge Inventory Data Sheet

The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information						39-59-41.30 =	076-12-15.18
Pennsylvania [42]	Lancaster County	[071]	West Lampeter [83256]	Wheatland Mills		39.994806	= -76.204217
21571	Highway age	ency district 8	Owner State Highway	Agency [01]	Maintenance responsibility	State Highway Age	ency [01]
Route 0	Str	asburg Pike	Toll On fre	ee road [3] Fe	atures intersected Pequea	Creek	
Design - Concrete [main Arch - Dec		Design - approach 0 Other	· [00]	Year built 1926 Skew angle 0	km = 512.7 mi Year reconstructed N Structure Flared		
Total length 24.4 m Inventory Route, Total		Length of maximum sponce 6.1 m = 20.0 ft	an 24.4 m = 80.1 ft Curb or sidewalk w	Historical significance Deck width, out-to-out idth - left 0 m = 0.0 ft		or the NRHP. [5] roadway width, curb-to-c sidewalk width - right	urb 6.1 m = 20.0 ft 0 m = 0.0 ft
Deck structure type Type of wearing surfa	ice	Not applicable [N] Not applicable (applie)	es only to structures with no	deck) [N]			
Deck protection		Not applicable (applie	es only to structures with no	deck) [N]			
Type of membrane/w	earing surface	Not applicable (applie	es only to structures with no	deck) [N]			
Weight Limits Bypass, detour lengt 1.1 km = 0.7 mi	Wicthod to dete	ermine inventory rating ermine operating rating Equal to or above I		Ope	ntory rating 32.7 metric trating rating 49 metric torign Load	on = 36.0 tons n = 53.9 tons	

Functional Details									
Average Daily Traffic 6577 Average daily to	ruck traffi 6 % Year 2012 Future average da	aily traffic 8668 Year 2032							
Road classification Collector (Urban) [17]	Lanes on structure 2	Approach roadway width 6.7 m = 22.0 ft							
Type of service on bridge Highway [1]	Direction of traffic 2 - way traffic [2]	Bridge median							
Parallel structure designation No parallel structu	re exists. [N]								
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation	control							
Navigation vertical clearance 0 = N/A Navigation horizontal clearance 0 = N/A									
Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway 10 m = 32.8 ft									
Minimum lateral underclearance reference feature Feature not a highway or railroad [N]									
Minimum lateral underclearance on right 0 = N/A Minimum lateral underclearance on left 0 = N/A									
Minimum Vertical Underclearance 0 = N/A Minimum vertical underclearance reference feature Feature not a highway or railroad [N]									
Appraisal ratings - underclearances N/A [N]									
Repair and Replacement Plans									
	Work done by Work to be done by contract [1]								
Type of work to be performed	Work done by Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial	Bridge improvement cost 0 Ro	padway improvement cost 0							
bridge roadway geometry. [31]	Length of structure improvement 38 m = 124.7 ft	Total project cost 1000							
	Year of improvement cost estimate								
	Border bridge - state	Border bridge - percent responsibility of other state							
	Border bridge - structure number								

Inspection and Sufficiency								
Structure status Open, no res	striction [A]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4] Equal to present desirable criteria [8]					
Condition ratings - superstructur	Poor [4]	Appraisal ratings - roadway alignment						
Condition ratings - substructure	Poor [4]	Appraisal ratings -	Basically intolerable requiring high priority of replacement [2]					
Condition ratings - deck	Not Applicable [N]	deck geometry						
Scour	Bridge is scour critical; bridge	Bridge is scour critical; bridge foundations determined to be unstable. [3]						
Channel and channel protection		Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]						
Appraisal ratings - water adequac	Superior to present desirable	Superior to present desirable criteria [9]		Status evaluation	Structurally deficient [1]			
Pier or abutment protection				Sufficiency rating	46.6			
Culverts Not applicable. Used	if structure is not a culvert. [N]							
Traffic safety features - railings								
Traffic safety features - transition	ns							
Traffic safety features - approach	n guardrail							
Traffic safety features - approach	n guardrail ends							
Inspection date April 2012 [0412] Designated inspection frequency 24 Months								
Underwater inspection Unknown [N00]		Underwater inspec						
Fracture critical inspection	Unknown [N00]	wn [N00] Fracture critical inspection						
Other special inspection	Unknown [N00]	wn [N00] Other special inspection date						