

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Virginia [51]	Albemarle County [003]	Unknown [00000]	0.3FR 663 & 0.4 GREENE CL	38-13-29.59 = 38.224886	078-31-15.04 = -78.520844
645	Highway agency district: 7	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 603	PLUNKETT RD	Toll On free road [3]	Features intersected	LYNCH RIVER	
Design - main Steel [3]	Design - approach Steel [3]	Kilometerpoint 48.3 km = 29.9 mi	Year built 1917	Year reconstructed N/A [0000]	
1 Truss - Thru [10]	1 Stringer/Multi-beam or girder [02]	Skew angle 0	Structure Flared		
		Historical significance	Bridge is not eligible for the NRHP. [5]		
Total length 25.6 m = 84.0 ft	Length of maximum span 16.5 m = 54.1 ft	Deck width, out-to-out 4.3 m = 14.1 ft	Bridge roadway width, curb-to-curb 4 m = 13.1 ft		
Inventory Route, Total Horizontal Clearance 3.4 m = 11.2 ft	Curb or sidewalk width - left 0.2 m = 0.7 ft	Curb or sidewalk width - right 0.2 m = 0.7 ft			
Deck structure type	Wood or Timber [8]				
Type of wearing surface					
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 1 km = 0.6 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	6.9 metric ton = 7.6 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	11.6 metric ton = 12.8 tons
Bridge posting		Design Load		

Functional Details

Average Daily Traffic	340	Average daily truck traffi	0	%	Year	2014	Future average daily traffic	498	Year	2035
Road classification	Local (Rural) [09]		Lanes on structure	1		Approach roadway width	5.5 m = 18.0 ft			
Type of service on bridge	Highway [1]		Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	150000	Roadway improvement cost	30000						
	Length of structure improvement	24.4 m = 80.1 ft		Total project cost	205000					
	Year of improvement cost estimate									
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status

Posted for load [P]

Appraisal ratings -
structural

Basically intolerable requiring high priority of replacement [2]

Condition ratings - superstructure

Poor [4]

Appraisal ratings -
roadway alignment

Basically intolerable requiring high priority of corrective action [3]

Condition ratings - substructure

Fair [5]

Appraisal ratings -
deck geometry

Basically intolerable requiring high priority of replacement [2]

Condition ratings - deck

Good [7]

Scour

Bridge foundations determined to be stable for assessed or calculated scour condition. [5]

Channel and channel protection

Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]

Appraisal ratings - water adequacy

Better than present minimum criteria [7]

Status evaluation

Structurally deficient [1]

Pier or abutment protection

Sufficiency rating

13.5

Culverts

Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings

Traffic safety features - transitions

Traffic safety features - approach guardrail

Traffic safety features - approach guardrail ends

Inspection date

November 2015 [1115]

Designated inspection frequency

6

Months

Underwater inspection

Not needed [N]

Underwater inspection date

Fracture critical inspection

Unknown [Y06]

Fracture critical inspection date

November 2015 [1115]

Other special inspection

Not needed [N]

Other special inspection date