

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Washington [53]	Spokane County [063]	Spokane [67000]	2.0 W OF SR 395	47-39-15.90 = 47.654417	117-27-15.65 = -117.454347
85426000000000	Highway agency district 6	Owner City or Municipal Highway Agency [04]	Maintenance responsibility	City or Municipal Highway Agency [04]	
Route 825	RIVERSIDE AVENUE	Toll On free road [3]	Features intersected	LATAH CREEK	
Design - main Concrete [1]	Design - approach	Kilometerpoint 32 km = 19.8 mi	Year built 1920	Year reconstructed N/A [0000]	
1 Culvert [19]	0 Other [00]	Skew angle 5	Structure Flared		
		Historical significance	Bridge is not eligible for the NRHP. [5]		
Total length 33.5 m = 109.9 ft	Length of maximum span 33.5 m = 109.9 ft	Deck width, out-to-out 11.6 m = 38.1 ft	Bridge roadway width, curb-to-curb	10.4 m = 34.1 ft	
Inventory Route, Total Horizontal Clearance 10.4 m = 34.1 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft		
Deck structure type	Not applicable [N]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.5 km = 0.3 mi	Method to determine inventory rating	No rating analysis or evaluation perfor	Inventory rating	32.4 metric ton = 35.6 tons
	Method to determine operating rating	No rating analysis or evaluation perfor	Operating rating	43.2 metric ton = 47.5 tons
Bridge posting	Equal to or above legal loads [5]	Design Load		

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Better than present minimum criteria [7]"/>
Condition ratings - superstructure	<input type="text" value="Not Applicable [N]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Basically intolerable requiring high priority of corrective action [3]"/>
Condition ratings - substructure	<input type="text" value="Not Applicable [N]"/>	Appraisal ratings - deck geometry	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - deck	<input type="text" value="Not Applicable [N]"/>		
Scour	<input type="text" value="Countermeasures have been installed to mitigate an existing problem with scour. [7]"/>		
Channel and channel protection	<input type="text" value="Banks are protected or well vegetated. River control devices such as spur dikes and embankment protection are not required or are in a stable condition. [8]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present desirable criteria [8]"/>	Status evaluation	<input type="text" value="Functionally obsolete [2]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="93.4"/>
Culverts	<input type="text" value="Shrinkage cracks, light scaling and insignificant spalling which does not expose reinforcing steel. Insignificant damage caused by drift with no misalignment and not requiring corrective action. Some minor scouring has occurred near curtain walls, wingwa"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="June 2013 [0613]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>

BRIDGE INSPECTION REPORT

Ver Date: 06/27/2013

Agency: SPOKANE

Status: Released

Printed On: 09/30/20

Program Mgr: Roman G. Peralta

Bridge No. 288800825

Page: 1/2

Structure Type

Bridge Name MARNE BRIDGE

Route 00825

Location 2.0 W OF SR 395

Structure ID 08542600

MilePost 0.20

Intersecting LATAH CREEK

Inspector's Signature JEM

IDent# G0608

Co-Inspector's Signature LAM

										Inspections Performed					
7		Structural Adqcy (657)	N		Pier/Abut/Protect (679)	1920	Year Built (332)			IT	NT	HRS	Date	Rep	Type
5		Deck Geometry (658)	7		Scour (680)	0	Year Rebuilt (336)			Y	24	2.5	06/05/2013	Routine	
9		Underclearance (659)	6		Retaining Walls (682)	48	Oper Rating (551)								Fract Crit
5		Operating Level (660)	9		Pier Protection (683)	36	Inv Rating (554)								Underwater
3		Alignment Adqcy (661)	0		Bridge Rails (684)	A	Open Close (293)								Special
8		WaterwayAdqcy (662)	0		Transition (685)	9999	Vert Over Deck (360)								Interim
9		Deck Overall (663)	1		Guardrails (686)	0000	Vert Under (374)								Equipment
9		Drains Condition (664)	1		Terminals (687)	N	Vert Und Code (378)								Damage
9		Superstructure (671)	N		Revise Rating (688)	0.00	Asphalt Depth								Safety
0		Number Utilities (675)			Photos Flag (691)		Speed Limit								Short Span
9		Substructure (676)			Soundings Flag (693)										
8		Chan/Protection (677)			Measure Clearance (694)										
7		Culvert (678)													
											Total: 2.5				
											Suff Rating: 93.45 FO		93.41 FO		

BMS Elements

Element	Element Description	Total	Units	State 1	State 2	State 3	State 4
145	Earth Filled Concrete Arch	110	LF	0	110	0	0
215	Concrete Abutment	75	LF	0	75	0	0
331	Concrete Bridge Railing	220	LF	-20	220	20	0
361	Scour	2	EA	0	2	0	0
800	Asphaltic Concrete (AC) Overlay	3740	SF	0	0	3740	0

Notes

0	The bridge is oriented from the south to the north with wide shoulders on either side that are used by pedestrians. The temperature at the time of the inspection was 79 degrees.
145	There is a longitudinal crack running the length of the arch at the center which has been epoxy injected. There is a small spall on the west side at the south end of the arch near the abutment measuring 4" x 6". There are some vertical cracks on the west side of the arch at the north and south ends next to the abutments. The ornamental edges of the arch are spalling.
215	The north abutment has one vertical, hairline crack and some light, disorganized cracking on the west side. The south abutment has vertical cracks, 2 to 3 feet apart across the face of the abutment. One of these cracks has been epoxy injected and the rest range in size from hairline to 0.16. There is also a horizontal crack about mid-height in the south abutment. There are light cracks in the retaining walls on both ends of the bridge, and some small spalls at the tops of the joints.

BRIDGE INSPECTION REPORT

Ver Date: 06/27/2013

Agency: SPOKANE

Status: Released

Printed On: 09/30/20

Program Mgr: Roman G. Peralta

Bridge No. 288800825	Page: 2/2	Structure Type
Bridge Name MARNE BRIDGE	Route 00825	Location 2.0 W OF SR 395
Structure ID 08542600	MilePost 0.20	Intersecting LATAH CREEK

331	The railing consists of Jersey-type barriers with metal hand rails embedded in the top, placed on a concrete curb along both sides of the bridge. These barriers are held in place by steel retaining plates bolted to the outside of the curb. The railing shows signs of numerous vehicle collisions. The barriers have scrapes, paint marks and chips and many of the retaining plates are bent. In spite of the impacts, the system is in place and remains functional.
361	At the south abutment, there is riprap filled with soil covering the footing with light vegetation growing around and under the bridge. The water's edge was about 7' from the south abutment at the time of the inspection. On the north end, the riprap and fill material reach almost to the spring line and there is brush and vegetation around and under the bridge. The channel is well defined in this area.
800	The asphalt overlay on the bridge has numerous cracks, most of which have been sealed with tar. There is a slightly sunken area at the southeast corner measuring 4' in diameter.

Repairs

Repair No	Pr	R	Repair Description	Noted	Maint	Verified

Inspections Performed and Resources Required

Report Type	Date	IT	Frq	Hrs	Insp	CertNo	Coinsp	Note
Routine	06/05/13		24	2.5	JEM	G0608	LAM	Soundings and wade are done with the routine inspection but not always on the same day.
Resources			Use	Hour	Min	Req	Max	Notes
UBIT			50	3.00				