

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Washington [53]	Spokane County [063]	Spokane [67000]	1.74 W OF US 2	47-38-57.08 = 47.649189	117-26-59.62 = -117.449894
85428000000000	Highway agency district 6	Owner City or Municipal Highway Agency [04]	Maintenance responsibility	City or Municipal Highway Agency [04]	
Route 824	SUNSET BOULEVARD	Toll On free road [3]	Features intersected	LATAH CREEK	
Design - main Concrete continuous [2]	Design - approach Concrete [1]	Kilometerpoint 1126 km = 698.1 mi	Year built 1913	Year reconstructed N/A [0000]	
7	Arch - Deck [11]	2	Girder and floorbeam system [03]	Skew angle 0	Structure Flared
				Historical significance Bridge is on the NRHP. [1]	
Total length 326.1 m = 1069.9 ft	Length of maximum span 45.7 m = 149.9 ft	Deck width, out-to-out 19.4 m = 63.7 ft	Bridge roadway width, curb-to-curb 13.7 m = 44.9 ft		
Inventory Route, Total Horizontal Clearance 13.7 m = 44.9 ft	Curb or sidewalk width - left 1.7 m = 5.6 ft	Curb or sidewalk width - right 1.7 m = 5.6 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.6 km = 0.4 mi	Method to determine inventory rating Load and Resistance Factor(LRFR) [3]	Inventory rating 32.4 metric ton = 35.6 tons
	Method to determine operating rating Load and Resistance Factor(LRFR) [3]	Operating rating 43.2 metric ton = 47.5 tons
Bridge posting 00.1 - 09.9 % below [4]	Design Load MS 18 / HS 20 [5]	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status

Posted for other load-capacity restriction [R]

Appraisal ratings -
structural

Somewhat better than minimum adequacy to tolerate being left in place as is [5]

Condition ratings - superstructure

Fair [5]

Appraisal ratings -
roadway alignment

Equal to present minimum criteria [6]

Condition ratings - substructure

Fair [5]

Appraisal ratings -
deck geometry

Superior to present desirable criteria [9]

Condition ratings - deck

Satisfactory [6]

Scour

Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]

Channel and channel protection

Banks are protected or well vegetated. River control devices such as spur dikes and embankment protection are not required or are in a stable condition. [8]

Appraisal ratings - water adequacy

Equal to present desirable criteria [8]

Status evaluation

Pier or abutment protection

Sufficiency rating

82.1

Culverts

Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings

Traffic safety features - transitions

Traffic safety features - approach guardrail

Traffic safety features - approach guardrail ends

Inspection date

September 2011 [0911]

Designated inspection frequency

24

Months

Underwater inspection

Not needed [N]

Underwater inspection date

Fracture critical inspection

Not needed [N]

Fracture critical inspection date

Other special inspection

Not needed [N]

Other special inspection date

BRIDGE INSPECTION REPORT

Ver Date: 11/12/2013

Agency: SPOKANE

Status: Released

Printed On: 09/30/20

Program Mgr: Roman G. Peralta

Bridge No. 288000824

Page: 1/3

Structure Type

Bridge Name LATAH BRIDGE (HIGH BR)

Route 00824

Location 1.74 W OF US 2

Structure ID 08542800

MilePost 7.00

Intersecting LATAH CREEK

Inspector's Signature JEM

IDent# G0608

Co-Inspector's Signature LAM

										Inspections Performed			
5		Structural Adqcy (657)	N		Pier/Abut/Protect (679)	1913	Year Built (332)	IT	NT	HRS	Date	Rep	Type
8		Deck Geometry (658)	8		Scour (680)	0	Year Rebuilt (336)	Y	24	14.5	09/10/2013	Routine	
8		Underclearance (659)	9		Retaining Walls (682)	48	Oper Rating (551)					Fract Crit	
4	5	Operating Level (660)	9		Pier Protection (683)	36	Inv Rating (554)					Underwater	
6		Alignment Adqcy (661)	0		Bridge Rails (684)	R	A Open Close (293)					Special	
8		WaterwayAdqcy (662)	0		Transition (685)	9999	Vert Over Deck (360)					Interim	
6		Deck Overall (663)	0		Guardrails (686)	8000	Vert Under (374)					Equipment	
5	4	Drains Condition (664)	0		Terminals (687)	H	Vert Und Code (378)					Damage	
5		Superstructure (671)	N		Revise Rating (688)	0.00	Asphalt Depth					Safety	
3		Number Utilities (675)			Photos Flag (691)		Speed Limit					Short Span	
5		Substructure (676)			Soundings Flag (693)								
8		Chan/Protection (677)			Measure Clearance (694)								
9		Culvert (678)											
											Total: 14.5		
											Suff Rating: 82.09		81.61

BMS Elements

Element	Element Description	Total	Units	State 1	State 2	State 3	State 4
12	Concrete Deck	48150	SF	38790	9000	360	0
35	Concrete Deck Soffit	48150	SF	38790	9000	360	0
110	Concrete Girder	3335	LF	0	2675	660	0
116	Concrete Stringer	2307	LF	1617	240	240	210
144	Concrete Arch	3160	LF	0	2850	310	0
150	Concrete Column on Spandrel Arch	51	EA	0	39	12	0
155	Concrete Floor Beam	8101	LF	7831	150	120	0
210	Concrete Pier Wall	387	LF	0	387	0	0
215	Concrete Abutment	168	LF	0	130	38	0
331	Concrete Bridge Railing	1880	LF	100	1200	480	100
361	Scour	2	EA	2	0	0	0
801	AC Overlay with Waterproofing Membrane	46859	SF	23000	22800	1059	0

BRIDGE INSPECTION REPORT

Ver Date: 11/12/2013

Agency: SPOKANE

Status: Released

Printed On: 09/30/20

Program Mgr: Roman G. Peralta

Bridge No. 288000824

Page: 2/3

Structure Type

Bridge Name LATAH BRIDGE (HIGH BR)

Route 00824

Location 1.74 W OF US 2

Structure ID 08542800

MilePost 7.00

Intersecting LATAH CREEK

Notes

0	The bridge is oriented from the west to the east. The outside lanes have been closed to traffic. The temperature on the first day of inspection was 93 degrees.
12	The deck has been overlaid with asphalt. The new overlay has helped slow water seeping through by removing cracks and tighing up the joint areas.
35	The deck soffit in the piers is severely deteriorated in the areas around the drains, around the manholes and along the girders supporting the curbs. Rebar section loss in these localized areas ranges from 50% to 100% of the bottom mat. There are also shallow spalls with exposed rebar along the interior pier walls. In the areas outside the piers the deck is spalled along the pier walls under the joints. Some rebar is exposed, but the section loss in these areas is minimal.
110	
116	In the south piers, the stringers supporting the curbs have deteriorated badly. In the girders where the bottom steel is exposed, the section loss in the longitudinal steel ranges from 40% to 70%. The stirrups have rusted through on the bottom face of the girders in the area adjacent to the drains, and the vertical legs of these stirrups have a section loss of approximately 30%. In the north piers the girders supporting the curbs are also cracked and spalling, although it is difficult to estimate section loss in these girders because not as much of the rebar is exposed.
144	The arches are generally in good condition with some efflorescence at the construction joints and water staining at the juncture with the piers. Arch 6 northeast inside edge there is a eight foot edge spall about two feet wide.
150	The columns on the exterior spandrel arches are spalled at the corners and on the ornamental collars.
155) The floor beams in the center section of the bridge are generally in good condition, but in the exterior sections of the bridge the floor beams under the joints are badly spalled with section loss up to 45% in the exposed sections of the rebar.
210	The exterior pier faces have numerous shallow spalls under the joints. Inside the piers there are large, diagonal cracks under the sidewalks, running from the curb girder down towards the outside wall of the pier, with heavy efflorescence and water staining. All of the piers are holding water and mud below the elevation of the drains.
215	The abutment faces are water stained with some light spalling along the top under the joints. Above the south arches in pier 8 or east abutment there is heavy spalling in floor beam. Pic ture(101)
331	A jersey-style guardrail has been placed down both sides of the bridge at the curb to provide a traffic barrier and separate the pedestrians from the traffic lanes. The exterior pedestrian railings have numerous cracks, spalls and repairs. There is almost always something on the pedestrian railing in need of repair.
361	The high-water level is clearly defined by grass, chaff and other debris on the sides of channel. There is no evidence of scour at the bridge piers. In the summer months transients live in the trees and brush under bridge mostly down by the water, to hide them. While they live there they move the rip rap to make their areas to stay.
801	The asphalt surface on the bridge deck was ground and overlaid in 2009.

Repairs

Repair No	Pr	R	Repair Description	Noted	Maint	Verified
1	2	B		11/23/05		

BRIDGE INSPECTION REPORT

Ver Date: 11/12/2013

Agency: SPOKANE

Status: Released

Printed On: 09/30/20

Program Mgr: Roman G. Peralta

Bridge No. 288000824

Page: 3/3

Structure Type

Bridge Name LATAH BRIDGE (HIGH BR)

Route 00824

Location 1.74 W OF US 2

Structure ID 08542800

MilePost 7.00

Intersecting LATAH CREEK

2 2 B

11/23/05

Inspections Performed and Resources Required

<u>Report Type</u>	<u>Date</u>	<u>IT</u>	<u>Frq</u>	<u>Hrs</u>	<u>Insp</u>	<u>CertNo</u>	<u>Coinsp</u>	<u>Note</u>
Routine	09/10/13		24	14.5	JEM	G0608	LAM	The scour soundings and wade inspection are part of the routine inspection but are conducted at a time of low water flow.
Resources			Use Hour	Min	Req	Max		Notes
UBIT								
Bucket								