

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

Alabama [01]	St. Clair County [115]	Riverside [64920]	@ ST CLAIR/TALLADEGA CL	33-36-06.78 = 33.601883	086-11-47.82 = -86.196617
10641	Highway agency district: 3	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 78	US 78	Toll On free road [3]	Features intersected	COOSA RIVER	
Design - main	Steel [3]	Design - approach	Steel [3]	Kilometerpoint	22289.4 km = 13819.4 mi
4	Truss - Thru [10]	12	Stringer/Multi-beam or girder [02]	Year built	1930
				Year reconstructed	1972
				Skew angle	0
				Structure Flared	
				Historical significance	Bridge is not eligible for the NRHP. [5]
Total length	279.5 m = 917.0 ft	Length of maximum span	70.7 m = 232.0 ft	Deck width, out-to-out	7.1 m = 23.3 ft
				Bridge roadway width, curb-to-curb	6 m = 19.7 ft
Inventory Route, Total Horizontal Clearance	6.4 m = 21.0 ft	Curb or sidewalk width - left	0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Monolithic Concrete (concurrently placed with structural deck) [1]				
Deck protection					
Type of membrane/wearing surface					

**Weight Limits**

Bypass, detour length	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	28.6 metric ton = 31.5 tons
0.2 km = 0.1 mi	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	47.6 metric ton = 52.4 tons
	Bridge posting	Equal to or above legal loads [5]	Design Load	M 13.5 / H 15 [2]

### Functional Details

Average Daily Traffic  Average daily truck traffi  % Year  Future average daily traffic  Year

Road classification  Lanes on structure  Approach roadway width

Type of service on bridge  Direction of traffic  Bridge median

Parallel structure designation

Type of service under bridge  Lanes under structure  Navigation control

Navigation vertical clearanc  Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge  Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right  Minimum lateral underclearance on left

Minimum Vertical Underclearance  Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

### Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost  Roadway improvement cost

Length of structure improvement  Total project cost

Year of improvement cost estimate

Border bridge - state  Border bridge - percent responsibility of other state

Border bridge - structure number

## Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - superstructure	Fair [5]	Appraisal ratings - roadway alignment	Equal to present minimum criteria [6]
Condition ratings - substructure	Poor [4]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Fair [5]		
Scour	Bridge is scour critical; bridge foundations determined to be unstable. [3]		
Channel and channel protection	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]		
Appraisal ratings - water adequacy	Superior to present desirable criteria [9]	Status evaluation	Structurally deficient [1]
Pier or abutment protection	Navigation protection not required [1]	Sufficiency rating	47.2
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	February 1999 [299]	Designated inspection frequency	24 Months
Underwater inspection	Every year [Y12]	Underwater inspection date	August 2018 [0818]
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	February 1999 [299]
Other special inspection	Every year [Y12]	Other special inspection date	February 1999 [299]