HistoricBridges.org - National Bridge Inventory Data Sheet

The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information					37-47-13 =	121-18-28 = -
California [06] San Joaquin County [077]			Lathrop [40704]	37.786944	121.307778	
29C0127 Highway agency district		agency district 10	Owner City or Municipal Highway Agency [04] Maintenance responsibility		e responsibility City or Municipal	Highway Agency [04]
Route 0		MANTHEY ROAD	Toll On free	road [3] Features interse	ected SAN JOAQUIN RIVER	
Design - Steel [3] main Truss - Th	ru [10]	Design - approach 9 Tee be	eam [04]	Skew angle 0 Structure	econstructed N/A [0000] Flared is not eligible for the NRHP. [5]	
Total length 164.3 r	n = 539.1 ft	Length of maximum spa	61 m = 200.1 ft	Deck width, out-to-out 10.2 m = 33	8.5 ft Bridge roadway width, curb-to-	curb 7.4 m = 24.3 ft
Inventory Route, Total Horizontal Clearance 7.4 m = 24.3 ft			Curb or sidewalk wid	th - left 0 m = 0.0 ft	Curb or sidewalk width - right	1.8 m = 5.9 ft
Deck structure type		Concrete Cast-in-Plac	e [1]			
Type of wearing surfa	ace					
Deck protection						
Type of membrane/w	earing surface					
Weight Limits						
Bypass, detour length 5.3 km = 3.3 mi Method to determine inventory rating Method to determine operating rating		Allowable Stress(AS)	[2] Inventory rating	20.8 metric ton = 22.9 tons		
		determine operating rating	Allowable Stress(AS)	[2] Operating rating	30.8 metric ton = 33.9 tons	
Bridge posting Equal to or above legal loa			gal loads [5]	Design Load		

Functional Details									
Average Daily Traffic 750 Average daily tr	uck traffi 5 % Year 1987 Future average daily traffic 627 Year 2028								
Road classification Local (Rural) [09]	Lanes on structure 2 Approach roadway width 10.4 m = 34.1 ft								
Type of service on bridge Highway-pedestrian [5]	Direction of traffic 2 - way traffic [2] Bridge median								
Parallel structure designation No parallel structure	e exists. [N]								
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control								
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A								
Minimum navigation vertical clearance, vertical lift brid	Minimum vertical clearance over bridge roadway 4.65 m = 15.3 ft								
Minimum lateral underclearance reference feature Feature not a highway or railroad [N]									
Minimum lateral underclearance on right 0 = N/A Minimum lateral underclearance on left 0 = N/A									
Minimum Vertical Underclearance 0 = N/A Minimum vertical underclearance reference feature Feature not a highway or railroad [N]									
Appraisal ratings - underclearances N/A [N]									
Repair and Replacement Plans									
Type of work to be performed	Work done by Work to be done by contract [1]								
Bridge deck rehabilitation with only incidental widening. [36]	Bridge improvement cost 3854000 Roadway improvement cost 770000								
widering, [50]	Length of structure improvement 164.3 m = 539.1 ft Total project cost 6476000								
	Year of improvement cost estimate 2010								
	Border bridge - state Border bridge - percent responsibility of other state								
	Border bridge - structure number								

Inspection and Sufficiency									
Structure status Open, no res	Appraisal ratings - structural	Basically intolerable requiring high priority of corrrective action [3]							
Condition ratings - superstructur	Serious [3]	Appraisal ratings - roadway alignment	Equal to pres	ual to present minimum criteria [6]					
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Meets minimum tolerable limits to be left in place as is [4]						
Condition ratings - deck	Serious [3]								
Scour	Bridge foundations determine	Bridge foundations determined to be stable for assessed or calculated scour condition. [5]							
Channel and channel protection	Bank protection is being erod channel. [5]	Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]							
Appraisal ratings - water adequac	Superior to present desirable	Superior to present desirable criteria [9]			Structurally deficient [1]				
Pier or abutment protection				sufficiency rating	7.1				
Culverts Not applicable. Used	if structure is not a culvert. [N]								
Traffic safety features - railings									
Traffic safety features - transition	ns								
Traffic safety features - approach	h guardrail								
Traffic safety features - approach	h guardrail ends								
Inspection date August 2010 [0810] Designated inspection frequency 24 Months									
Underwater inspection	Unknown [Y60]	Underwater inspec	Underwater inspection date		9 [0909]				
Fracture critical inspection	Every two years [Y24]	Fracture critical ins	Fracture critical inspection date		1]				
Other special inspection	Not needed [N]	ded [N] Other special inspec							