

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

Florida [12]	Pasco County [101]	Unknown [00000]	1.5MI S OF CHANCEY RD.	28-11-08.90 = 28.185806	082-11-02.53 = -82.184036
144002	Highway agency district: 7	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0	CRYSTAL SPRINGS	Toll On free road [3]	Features intersected	HILLSBOROUGH RIVER	
Design - main Concrete [1]	Design - approach Other [00]	Kilometerpoint 327.2 km = 202.9 mi	Year built 1923	Year reconstructed N/A [0000]	
4	Arch - Deck [11]	Skew angle 0	Structure Flared		
		Historical significance	Bridge is possibly eligible for the NRHP. [3]		
Total length 48.8 m = 160.1 ft	Length of maximum span 13.2 m = 43.3 ft	Deck width, out-to-out 6.4 m = 21.0 ft	Bridge roadway width, curb-to-curb 5.7 m = 18.7 ft		
Inventory Route, Total Horizontal Clearance 5.7 m = 18.7 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Not applicable [N]				
Type of wearing surface	Not applicable (applies only to structures with no deck) [N]				
Deck protection	Not applicable (applies only to structures with no deck) [N]				
Type of membrane/wearing surface	Not applicable (applies only to structures with no deck) [N]				

**Weight Limits**

Bypass, detour length 0.8 km = 0.5 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	45.1 metric ton = 49.6 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	67.3 metric ton = 74.0 tons
Bridge posting	Equal to or above legal loads [5]	Design Load		

### Functional Details

Average Daily Traffic	2090	Average daily truck traffi	2	%	Year	2018	Future average daily traffic	2612	Year	2039
Road classification	Major Collector (Rural) [07]	Lanes on structure	2		Approach roadway width	5.7 m = 18.7 ft				
Type of service on bridge	Highway [1]	Direction of traffic	2 - way traffic [2]			Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]	Lanes under structure	0		Navigation control					
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge	0 m = 0.0 ft			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft					
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

### Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	466000	Roadway improvement cost	47000						
	Length of structure improvement	50 m = 164.1 ft		Total project cost	513000					
	Year of improvement cost estimate									
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

## Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Somewhat better than minimum adequacy to tolerate being left in place as is [5]
Condition ratings - superstructure	Fair [5]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Not Applicable [N]		
Scour	Bridge foundations determined to be stable for assessed or calculated scour conditions; field review indicates action is required. [4]		
Channel and channel protection	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]		
Appraisal ratings - water adequacy	Equal to present minimum criteria [6]	Status evaluation	Functionally obsolete [2]
Pier or abutment protection		Sufficiency rating	65.8
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	February 2018 [0218]	Designated inspection frequency	24 Months
Underwater inspection	Every two years [Y24]	Underwater inspection date	January 2018 [0118]
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	