

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

Florida [12]	Sarasota County [115]	Siesta Key [66000]	1.73 MI W OF US-41	27-18-06.97 = 27.301936	082-33-18.17 = -82.555047
170060	Highway agency district: 1	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 758	SR-758 (SIESTA DR)	Toll On free road [3]	Features intersected	HANSON BAYOU	
Design - main Concrete [1]	Design - approach Tee beam [04]	Other [00]	Kilometerpoint 642.5 km = 398.4 mi	Year built 1928	Year reconstructed N/A [0000]
3			Skew angle 0	Structure Flared	
			Historical significance	Bridge is possibly eligible for the NRHP. [3]	
Total length 29.3 m = 96.1 ft	Length of maximum span 9.8 m = 32.2 ft	Deck width, out-to-out 10.4 m = 34.1 ft	Bridge roadway width, curb-to-curb 7.1 m = 23.3 ft		
Inventory Route, Total Horizontal Clearance 9.6 m = 31.5 ft	Curb or sidewalk width - left 1.2 m = 3.9 ft	Curb or sidewalk width - right 1.2 m = 3.9 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

**Weight Limits**

Bypass, detour length 0.3 km = 0.2 mi	Method to determine inventory rating Load Testing [4]	Inventory rating 24.5 metric ton = 27.0 tons
	Method to determine operating rating Load Testing [4]	Operating rating 40.8 metric ton = 44.9 tons
Bridge posting Equal to or above legal loads [5]	Design Load M 13.5 / H 15 [2]	

### Functional Details

Average Daily Traffic  Average daily truck traffi  % Year  Future average daily traffic  Year

Road classification  Lanes on structure  Approach roadway width

Type of service on bridge  Direction of traffic  Bridge median

Parallel structure designation

Type of service under bridge  Lanes under structure  Navigation control

Navigation vertical clearanc  Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge  Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right  Minimum lateral underclearance on left

Minimum Vertical Underclearance  Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

### Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost  Roadway improvement cost

Length of structure improvement  Total project cost

Year of improvement cost estimate

Border bridge - state  Border bridge - percent responsibility of other state

Border bridge - structure number

## Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Equal to present minimum criteria [6]
Condition ratings - superstructure	Satisfactory [6]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Satisfactory [6]		
Scour	Countermeasures have been installed to mitigate an existing problem with scour. [7]		
Channel and channel protection	Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]		
Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	Functionally obsolete [2]
Pier or abutment protection		Sufficiency rating	67.4
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	January 1999 [199]	Designated inspection frequency	24 Months
Underwater inspection	Every two years [Y24]	Underwater inspection date	December 2018 [1218]
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	