

HistoricBridges.org - National Bridge Inventory Data Sheet

2009 Inventory

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Indiana [18]	Putnam County [133]	Unknown [00000]	0.3 km S of CR 125N	39-40-34 = 39.676111	086-49-52 = - 86.831111
6700122	Highway agency district 1	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 55		ROAD 100 EAST	Toll On free road [3]	Features intersected BIG WALNUT Cr	
Design - main	Steel [3]	Design - approach		Kilometerpoint	0 km = 0.0 mi
1	Truss - Thru [10]	0	Other [00]	Year built	1902
				Year reconstructed	#Num!
				Skew angle	0
				Structure Flared	
				Historical significance	Bridge is possibly eligible for the NRHP. [3]
Total length	36.8 m = 120.7 ft	Length of maximum span	36.3 m = 119.1 ft	Deck width, out-to-out	4.9 m = 16.1 ft
Inventory Route, Total Horizontal Clearance	4.7 m = 15.4 ft	Curb or sidewalk width - left	0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft
Deck structure type	Wood or Timber [8]				
Type of wearing surface	Wood or Timber [7]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length	Method to determine inventory rating	No rating analysis performed [5]	Inventory rating	4.5 metric ton = 5.0 tons
0.5 km = 0.3 mi	Method to determine operating rating	No rating analysis performed [5]	Operating rating	9 metric ton = 9.9 tons
	Bridge posting	20.0 - 29.9 % below [2]	Design Load	

Functional Details

Average Daily Traffic	450	Average daily truck traffi	0	%	Year	2007	Future average daily traffic	800	Year	2027
Road classification	Local (Rural) [09]		Lanes on structure	1		Approach roadway width	4.8 m = 15.7 ft			
Type of service on bridge	Highway [1]		Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge	0 m = 0.0 ft					Minimum vertical clearance over bridge roadway	4.36 m = 14.3 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]		
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	700000	Roadway improvement cost	700000
	Length of structure improvement	45.7 m = 149.9 ft	Total project cost	1400000
	Year of improvement cost estimate	2007		
	Border bridge - state		Border bridge - percent responsibility of other state	
	Border bridge - structure number			

Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Basically intolerable requiring high priority of replacement [2]
Condition ratings - superstructure	Serious [3]	Appraisal ratings - roadway alignment	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - substructure	Serious [3]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Satisfactory [6]		
Scour	Bridge foundations determined to be stable for assessed or calculated scour conditions; field review indicates action is required. [4]		
Channel and channel protection	Bank and embankment protection is severely undermined. River control devices have severe damage. Large deposits of debris are in the channel. [4]		
Appraisal ratings - water adequacy	Somewhat better than minimum adequacy to tolerate being left in place as is [5]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	23
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	March 2007 [0307]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	March 2007 [0307]
Other special inspection	Every year [Y12]	Other special inspection date	March 2005 [0305]