Tab L. Sculpture

1. Consulting Conservator's Report

KENT SEVERSON

Conservator

74 The Fenway, #43
Boston, Massachusetts 02115-3750
617-267-9093
KJPSever@aol.com

Consulting Conservator's Report

Memorial Bridge Rehabilitation Portsmouth-Kittery 13678: US1 over Piscataqua River

Description of the Memorial

General

The main memorial on the Portsmouth-Kittery Bridge (Plaque 1) consists of a rectangular inscription over the roadway at the New Hampshire entrance to the bridge. The inscription, in raised, gilded letters, reads: "Memorial to the sailors and soldiers of New Hampshire who participated in the World War, 1917-1919." The inscription is framed by a simple molding, with an additional molded horizontal element above, supported by two small shields. There are two identical small shields at the bottom edge of the inscription with a larger shield, with bundles of laurel leaves at either side. At either side of the inscription are roundels: one with a military eagle in relief and the other with the shield and motto of the State of New Hampshire. The roundels are ornamented with scrolls at four points and framed with moldings. The roundels sit in clusters of openwork oak and pine branches, decorated on the west with an anchor and on the east with a cannon, that wrap around to the sides at the vertical trusses forming the entrance to the bridge. Beneath the clusters of leaves, a decorative molded band extends across the span between the trusses, supported at either end with brackets decorated with oak clusters. There is a flat trim panel beneath the molded span masking the ironwork beneath. The entire memorial is surmounted at the uppermost truss above the assemblage by an eagle with outspread wings, clutching laurel leaves, arrows and a fasces.

Plaques 2 and 3 consist of identical rectangular bronze inscriptions in raised letters, framed with simple moldings, commemorating the construction of the bridge. On the Portsmouth side, the plaque is attached to the east truss and on the Kittery side on the west.

Plaque 4 is an iron plaque on a vertical column at the Portsmouth side of the lift, on the east side of the bridge. The inscription, in raised letters, commemorates the patents associated with the design of the bridge.

Plaque 5 is a bronze inscription in raised letters, commemorating the construction of the approach to the bridge, mounted horizontally in a block of granite in a small traffic island in the roadway on the Portsmouth side of the bridge.

Construction

The main memorial and other plaques were inspected on 11 March 2008; the overhead materials were accessed by man lift, kindly provided by NHDOT through Gene Popien and his team, and the remaining pieces accessed by foot. This cursory inspection did not answer every question pertaining to how the memorial was constructed. Based on that inspection, the following notes are provided on the construction and condition of the memorial.

Plaque 1

The bronze ornament spanning the entrance at the New Hampshire approach to the bridge is an assemblage of at least 47 precisely-fit elements (and probably more), held together and to the structural members of the bridge by mechanical fasteners. The eagle appears to have been cast in a single piece with the *fasces*; the eagle was cast open at the back but is now covered with a bronze plate, fastened by small screws around the perimeter. The eagle was reported to have been removed for repair and re-mounted six or seven years ago (Gene Popien, NHDOT, by verbal communication). The eagle is currently mounted on two or three steel brackets that extend into the box formed by the plate in back at the bottom; these appear to be fixed to the sides of the box with new flathead machine screws at the sides of the box, and with stainless steel hex-head screws visible at the back (square holes in the back plate are presumably from cutting out old fasteners in the remounting). There is also an external strut in steel angle, extending from the back of the eagle to the girder below; the strut is attached to the eagle with a single hex-head stainless screw.

The central inscription is a box-like structure, cast in two sections with a seam down the middle, and enclosed in back with a two plates of bronze or brass, attached with small screws around the perimeter. It is unclear whether the moldings and sides of the inscription are separate pieces, but it is likely that they were cast as one with the inscription. The molding above the inscription was cast in two pieces, as was the rectangular box in the center above the molding, with flat head machine screws visible on the top of the box along the center seam. The molding is also enclosed in the back with plates held by small screws at the perimeter.

The small shields in front, at the top and bottom, were cast separately, as was the central shield and the clusters of leaves at either side. The shields mask three vertical iron supports running inside the main inscription. These are secured at the top with (nearly) horizontal braces in angled steel. The connections between the horizontal and vertical supports are visible in the space between the upper molding and the inscription in back. The bottom sections of the vertical supports are masked in back by small boxes in bronze sheet, fastened with small screws. The large sections of the inscription are almost certainly attached to the vertical supports, probably with machine screws or bolts, passing through cast-in lugs on the interior of the casting.

The roundels at either side appear to have been cast in one unit consisting of the sides, scrolls, and decoration in front. The open casts are enclosed in the back with round plates, fastened with small screws around the perimeter. It seems likely that there are vertical iron angle supports inside the roundels and that the roundels are fixed to these supports with machine screws through cast-in lugs. At the bottom in back the spaces between the elements below and the roundels are enclosed in truncated pyramidal boxes, held with small screws around the perimeter. There are light-weight brass or bronze bars connecting the outer perimeter of the roundels to the upper portion of the brackets in back; the bars are fastened with hex-head screws, presumably in bronze.

It is unclear whether the oak and pine ornaments at either side of the roundels were cast in one or two pieces, but the sections wrapping around the corners are a single cast along with the cannon and the anchor. It is also unclear how these elements are attached to the bridge or each other at the bottom, as visibility is masked by the covers on the surrounding ornaments; however, where the ornament is connected to the truss in back, the heads of hex-head bolts; are visible at the bottom of the leaves inside.

The long horizontal molding beneath the main inscription was cast in at least three pieces and perhaps more. Like the other elements above, it is enclosed in back with a cover consisting of three rectangular sheets, fastened around the perimeter with small screws. The brackets at

either side of the molding were cast in two sections and are presumed to be fastened internally. The brackets are fixed to the trusses on the outside with large hex-head nuts, with the bolts visible on the underside of the truss.

The lower trim on the underside of the span is a complex structure consisting primarily of three rectangular cast bronze plates forming the south face and a series of smaller plates forming the west face. The plates on the east side are joined internally at cast-in flanges with iron bolts and the assembly suspended by "T" shaped hangers from the iron truss above. There are also iron straps running inside the assembly, presumably for attachment of the plates on the west side. Much of this assembly is obscured on the inside by accumulated debris.

A summary of each of these parts is, along with estimated weights of selected elements is provided in the table in **Attachment 1**.

Plaque 2

The inscription was cast in one piece. The plaque is attached to the truss with four hexhead machine screws, bolted in back.

Plaque 3

The inscription was cast in one piece. The plaque is attached to the truss with four hexhead machine screws, bolted in back.

Plaque 4

The inscription was cast in one piece. The plaque is attached to the column with four very large, modern hex-head machine screws.

Plaque 5

The inscription was cast in one piece. The plaque is attached to the stone with four hexhead machine screws.

Conditions

Plaque 1

With a few exceptions, the bronze elements of the Memorial Bridge are in good condition. The bronze exhibits typical green corrosion of bronzes in an outdoor environment, particularly on the uppermost surfaces. The green, primarily copper carbonates and sulfates but along with some chlorides, is a symptom of exposure to acid precipitation in conjunction to the somewhat salty precipitation of a marine environment. On outdoor bronzes where corrosion is severe, the metal is deeply pitted and etched; however, the surface of the bronze on the Memorial Bridge is evenly and light. In fact, much of the surface is well preserved with large areas of original reddish brown patination and gilding on the letters of the inscription still intact. There is also some darkening in well protected areas. These corrosion products are mostly copper sulfides, caused by sulfur in the atmosphere and are also typical of outdoor bronzes in the modern industrial environment.

While the surface of the bronze is in relatively good condition, at many points of contact with the bridge and with internal supports, the steel is severely rusting. This is dramatically illustrated at the point where the center support, at the top and in the back of the main inscription is attached and in the surface of the trusses beneath the brackets in the front. This is likely to be at least partially due to galvanic (bimetallic) corrosion.

The most problematic area in the assembly is the lower trim plates where the "v" shaped configuration in back has allowed deep accumulation of organic debris. Sufficient material has accumulated to support tree growth through the front of the memorial. In addition, moisture in the organic debris is likely responsible for severe corrosion of the steel support bands connecting

the bronze elements of this assembly. The back plates, particularly on the east side, are buckled slightly, either from expanding rust, frost jacking, or both. Several of the "T" hangers that support the plates in front are broken and failing and the remaining hangers are clearly overstressed. There is a gap between the front and back plates and this prompted NHDOT to install the cables around these elements that we see today. (These cables do not currently support the panels and were installed as a safety precaution, as related by Gene Popien). There are many traces of old, iron fasteners and holes in these plates, probably from the attachment of traffic signs and signals in the past.

The fasteners used to reinstall the eagle appear to be stainless steel and are in good condition. Many of the small screws holding the cover plates to the back of the inscription, roundels, and other features appear to have been replaced with stainless steel. There are a few missing screws. Other exposed bronze fasteners, such as the screws in horizontal surface of the box at the top of the inscription and the screws visible at the top of the ornaments at either side of the shield at the bottom of the inscription, are slightly corroded but appear to be in good condition.

Plaque 2

The plaque is slightly corroded overall, with typical light green corrosion products. The plaque is in otherwise good condition.

Plaque 3

The plaque is slightly corroded overall, with typical light green corrosion products. The plaque is in otherwise good condition.

Plaque 4

The plaque is covered with many layers of paint. The paint is cracked and there is slight rusting around the perimeter. The bolts holding the plaque in place appear to be of non-corrosive metal and are in good condition.

Plaque 5

The plaque is somewhat more corroded that the other bronzes, probably due to its horizontal orientation. The surface is slightly pitted. The screws holding the plaque in place are out of plane and may not be securing the plaque. Although drainage channels have been cut in the stone at the sides of the plaque, grass and soil stand higher than the perimeter of the stone making the channels ineffectual.

Digital images prepared during inspection are submitted with this report.

Description of the Project

General

It is understood that de-installation of the bronze elements from the bridge is necessary to facilitate repair, replacement of some steel, and repainting. De-installation of these elements will require close cooperation between several teams of specialists, including: a sculpture conservator, an art-handling and transportation firm, riggers and crane operators, with occasional input from a structural engineer. During de-installation, the art-handling firm will be responsible for detaching the elements, safely lowering them from the bridge (working with a rigger and crane operator), and packing the pieces appropriately for transport. The conservation team will be responsible for documenting the de-installation, labeling the elements, collecting the fasteners and interfacing with the art handling team on appropriate handling and packing.

Memorial Bridge Historic Structures Report

Treatment of the bronze elements will be undertaken by the conservation team and will occur off-site. Treatment will include cleaning, repair, repatination and application of protective coatings. Prior to re-installation, the input of a structural engineer will likely be needed to determine the extent and design of new supports, fasteners and attachments. Fabrication of the new supports will be undertaken by the general contractor.

As with de-installation, re-installation will be a complex operation, requiring close cooperation between team members, with the art-handling team working closely with the riggers, crane operator, and conservator.

Specifications

Draft specifications for the work on Plaques 1-5 are submitted with this report.

Budget

A budget sketch for de-installation, treatment and re-installation is submitted in **Attachment 2**. The \$323,500 figure is considerably higher than the \$30,000 estimate presented elsewhere, but considering the complexity of the project, it is not unrealistic. This estimate is something of a "worst case" scenario, where de-installation and re-installation go slowly and require a great deal of trouble shooting. The previously presented figure of \$5,000 for Plaques 2-4 is realistic; this sketch includes all plaques in the de-installation and re-installation.

This sketch does not include the cost of the crane and operator as it seems likely that suitable equipment will be available as part of other work. Likewise, it may be that an on-hand rigging crew could be used for this part of the project. This sketch does not include the cost of transport/trucking, nor does it include a figure for rental of space or security after removal and during conservation treatment. This budget does not include the cost of participation by a structural engineer.

This project will almost certainly require staging under the span to provide a safe working platform during extraction of fasteners and lowering of many of the elements. Therefore, the de-installation and re-installation will need to be done after road closing and before re-opening. This program fits with both Construction Schedule Options. Conservation treatment should take from six to eight weeks and would likewise fit into either of these Options.

Qualifications of Team Members

Following are some recommendations for qualifying of the conservation and art handling teams:

Conservator:

- The successful bidder will include as head of the team a Professional Associate of the American Institute for Conservation of Artistic and Historic Works.
- The successful bidder will have at least ten years of experience in working with large scale outdoor bronzes.
- The successful bidder will have demonstrable experience in handling and relocating large-scale works of art.
- The successful bidding firm will be a well-established firm and will have been in business for at least five years.

The field of bidders for the conservation work could be further limited by requiring that the team include a Fellow of the American Institute for Conservation. A short list of potential

Memorial Bridge Historic Structures Report

local bidders is provided in **Attachment 3**. The list may be expanded through the American Institute for Conservation's referral service (http://aic.stanford.edu/public/select.html#two).

Art Handling Firms:

- The successful bidder will have at least ten years of demonstrable experience in handling and transporting large scale, complex works of art.
- The successful bidder will be a well-established firm and will have been in business for at least five years.
- The successful bidder will have demonstrable ability to work with rigging crews and crane operators.

Respectfully submitted,

22 March 2008

2. Draft Specifications

PLAQUE 1

1. De-installation.

- **1.1.** Documentation.
 - **1.1.1.** All elements will be documented in writing, photographically and graphically throughout the de-installation process to satisfactorily permit reinstallation in their original locations.
 - **1.1.2.** All elements will be clearly tagged or otherwise marked for identification during de-installation.
 - **1.1.2.1.** Painted identification marking may be applied on interior surfaces only.
 - **1.1.2.2.** Identification marking may not include etching, scratching or engraving metal.
 - **1.1.3.** The sequence of de-installation for each element will be recorded in the documentation.
 - **1.1.4.** Where elements of the bridge are to be replaced, a 1:1 scale template of the pattern of holes for fastening the bronze will be prepared as part of the documentation.
- **1.2.** Removal of fasteners.
 - **1.2.1.** To every extent possible, original bronze or brass fasteners (screws, bolts, etc.) will be backed out with the appropriate tools and retained.
 - **1.2.1.1.** Where fasteners are sound, they will be retained for use in reinstallation.
 - **1.2.1.2.** Where fasteners are rendered unusable by corrosion or other damage, they will be labeled and submitted to the New Hampshire Division of Historic Resources for archival storage.
 - **1.2.2.** Where fasteners cannot be backed out, they will be cut off with grinders, drilled out, or otherwise mechanically removed to minimize impact on the surrounding bronze.
 - **1.2.3.** At no time will torches be used to cut out old fasteners.
- **1.3.** Handling.
 - **1.3.1.** Nylon riggers straps and slings will be used to handle bronze elements at all times.
 - **1.3.2.** At no time will steel chains, cables or other metal come in contact with the bronze except at points where originally in contact with the supporting structure (internal flanges, lugs, lifting points, etc.).
 - **1.3.3.** Where necessary, timber framing, supports or other bracing may come in contact with the bronze.
 - **1.3.4.** Where necessary, framing, supports or bracing will be padded with high density expanded polyethylene foam (Ethafoam® or equivalent).
- **1.4.** Transportation and storage.
 - **1.4.1.** When removed from the bridge, each element will be either placed on a timber palette or in a purpose made timber box or skeleton crate.

- **1.4.1.1.** All elements on palettes will be secured with nylon straps for transport.
- **1.4.1.2.** All palettes and crates will be fitted with baffles and braces sufficient to prevent flexing or bending of the metal during transport. Bronze elements will be transported off-site to a location specified by the contractor.
- **1.4.2.** All elements will be kept in a secured area, building or other structure to prevent damage or theft from the time of de-installation, during conservation work and before re-installation.

2. Conservation of the Bronze Elements

- **2.1.** All treatment will be executed in accordance with the Code of Ethics and Guidelines for Practice of the American Institute for Conservation of Historic and Artistic Works.
- **2.2.** Cleaning.
 - **2.2.1.** Old organic resin residues (paint, caulk, etc.) will be removed with organic solvents or organic solvent based paint stripper, clearing with organic solvents.
 - **2.2.2.** Loose corrosion products will be removed by washing with Orvus® detergent (sodium lauryl sulfate) in water, using nylon pads, bronze wool or fine brass bristle brushes. Care will be taken during cleaning not to disturb surviving gilding on the letters of the main inscription.
 - **2.2.3.** All surfaces will be cleaned with low pressure water washing at 800 psi, using a fan-shaped nozzle, 12-14 inches from surface. If necessary, gilding on letters of the main inscription will be masked with soluble acrylic resin (such as Acryloid® B-72 in organic solvents) during washing.
- **2.3.** Repairs.
 - **2.3.1.** All residues of disused iron fasteners will be drilled out and the holes plugged with brass dowel, finished on the outside to match surrounding surfaces.
 - **2.3.2.** Loose or failing original joints and/or cracks will be reinforced internally with bronze mechanical joints.
- **2.4.** Re-patination and Re-gilding.
 - **2.4.1.** All external bronze surfaces will be re-patinated to approximate the reddish brown tone matching surviving areas of the original patination in the background of the main inscription or other protected areas.
 - **2.4.1.1.** Patination will be accomplished by heating the bronze with a clean gas torch (propane, Mapp® or equivalent) and application of chemical reagents, (such as potassium permanganate and/or ferric nitrate) diluted to achieve an appropriate tone.
 - **2.4.1.2.** Prior to overall repatination, three areas of sample colors will be applied and presented for approval by New Hampshire Division of Historical Resources.
 - **2.4.1.3.** All residual chemicals will be rinsed thoroughly with running water
 - **2.4.2.** Gilding on the lettering of the main inscription will by reintegrated by one of two methods:
 - **2.4.2.1.** Option 1: application of an appropriate, all-weather adhesive (gold size) to areas of loss and reapplication of gold leaf to those areas.
 - **2.4.2.1.1.** New gold leaf will be burnished to a high gloss.
 - **2.4.2.1.2.** New gold leaf may be toned with pigmented resin if necessary.

- **2.4.2.2.** Option 2: areas around the letters will be masked and the faces of the letters re-gilded with interference pigments in an appropriate tone, suspended in acrylic resin in organic solvents and applied by spray. In this option, original gilding may be coated with the reintegration material.
- **2.5.** Surface Coatings.
 - **2.5.1.** All bronze surfaces (inside and out) will be coated with Incralac acrylic resin (Acryloid® B-44 in organic solvents, containing benzotriazole and plasticizers, available from StanChem, Inc., 401 Berlin Street, East Berlin, CT 06023, Tel 860.828.0571), diluted 1:1 with toluene.
 - **2.5.1.1.** The bronze will be warmed with a gas torch (as above) above ambient temperature and the first coat of Incralac applied by brush.
 - **2.5.1.2.** A minimum of two subsequent coats will be applied by spray to achieve a layer of at least 1 mm in thickness.
 - **2.5.2.** After application of Incralac, exterior surfaces will be coated with hard paste wax (Butcher's Bowling Alley® or equivalent), applied cold by brush and buffed to a soft shine with bristle brushes followed by soft, clean cotton cloth.
 - **2.5.3.** At the completion of surface treatment, all work will be inspected for approval by New Hampshire Division of Historical Resources prior to reinstallation.
 - **2.5.4.** After re-installation, any scratches, abrasions or other defects in the surface coatings will be repaired by re-coating *in situ*.
- **2.6.** Documentation
 - **2.6.1.** All work will be documented in writing and photographically.
 - **2.6.1.1.** The written report will include a description of all materials and methods used in treatment.
 - **2.6.1.2.** The written report will include instructions for both routine (yearly) and long-term maintenance procedures.
 - **2.6.2.** Photographic documentation will be prepared in the format (digital or analog) as requested by the New Hampshire Division of Historical Research Photographic and will include before, during and after treatment photographs illustrating all stages of work.

3. Re-installation.

- **3.1.** Prior to re-installation.
 - **3.1.1.** A number of structural supporting elements will need to be replaced. New elements will be designed in consultation with a structural engineer and be fabricated from non-corrosive metal (stainless steel). These will likely include but are not limited to:
 - **3.1.1.1.** Vertical angles inside the main inscription.
 - **3.1.1.2.** Vertical supports (if any) inside the roundels.
 - **3.1.1.3.** Braces extending from the back of the eagle and (three) from the top of the main inscription.
 - **3.1.1.4.** "T" hangers supporting the horizontal trim plate at the bottom of the assemblage.
 - **3.1.1.5.** Internal straps supporting the back plate on the trim at the bottom of the assemblage.
 - **3.1.2.** Where new elements have been installed in the bridge, they will be drilled to receive fasteners, replicating the pattern and size of holes as indicated by deinstallation documentation.

- **3.1.3.** In consultation with the conservator, provision will be made to install flashing and drainage systems above and behind the lower trim plates in the back of the main inscription at the bottom.
- **3.2.** Handling.
 - **3.2.1.** Nylon riggers straps and slings will be used to handle bronze elements at all times.
 - **3.2.2.** At no time will steel chains, cables or other metal come in contact with the bronze except at points where originally in contact with the supporting structure (internal flanges, lugs, lifting points, etc.).
 - **3.2.3.** Where necessary, timber framing, supports or other bracing may come in contact with the bronze.
 - **3.2.4.** Where necessary, framing, supports or other bracing will be padded with high density expanded polyethylene foam (Ethafoam® or equivalent).
- **3.3.** Al-l elements will be reinstalled in their original locations on the bridge, following the documented sequence of de-installation.
 - **3.3.1.** Where original fasteners are unusable, new, non-corrosive stainless steel fasteners matching the original fasteners will be used.
 - **3.3.2.** Where possible, fasteners visible from the bridge deck (such as the bolts holding the brackets on the trusses) will be made of high tensile strength bronze; specification of these fasteners will be determined in consultation with the structural engineer. Bolt heads will be degreased and patinated and coated (as per bronze elements) or painted to match surrounding surfaces.
- **3.4.** Insulation.
 - **3.4.1.** In consultation with the structural engineer, points of contact between bronze and iron will be insulated with Teflon®, high density polyethylene, lead, or other non-conductive washers and gaskets.
 - **3.4.2.** If gaskets cannot be used for structural reasons, every effort will be made to make points of contact with bronze against stainless steel.
- **3.5.** Caulking.
 - **3.5.1.** After installation, upper and side joints between iron and bronze will be caulked with an approved caulk; lower joints will be left open to permit drainage of internal condensation.
 - **3.5.2.** Joints between bronze elements (back plates, etc.) will not be caulked.

PLAQUE 2

1. De-installation.

- **1.1.** Documentation.
 - **1.1.1.** The plaque will be documented in writing, photographically and graphically throughout the de-installation process to satisfactorily permit reinstallation in its original location.
 - **1.1.2.** If the supporting truss of the bridge is to be replaced, a 1:1 scale template of the pattern of holes for fastening the plaque will be prepared as part of the documentation.
- **1.2.** Removal of fasteners.
 - **1.2.1.** To every extent possible, original bronze or brass fasteners (screws, bolts, etc.) will be backed out with the appropriate tools and retained.
 - **1.2.1.1.** Where fasteners are sound, they will be retained for use in reinstallation
 - **1.2.1.2.** Where fasteners are rendered unusable by corrosion or other damage, they will be labeled and submitted to the New Hampshire Division of Historic Resources for archival storage.
 - **1.2.2.** Where fasteners cannot be backed out, they will be cut off with grinders, drilled out, or otherwise mechanically removed to minimize impact on the surrounding bronze.
 - **1.2.3.** At no time will torches be used to cut out corroded fasteners.
- **1.3.** Handling.
 - **1.3.1.** Nylon riggers straps and slings will be used to handle bronze elements at all times.
 - **1.3.2.** At no time will steel chains, cables or other metal come in contact with the bronze except at points where originally in contact with the supporting structure (internal flanges, lugs, lifting points, etc.).
 - **1.3.3.** Where necessary, timber framing, supports or other bracing may come in contact with the bronze.
 - **1.3.4.** Where necessary, framing and supports will be padded with high density expanded polyethylene foam (Ethafoam® or equivalent).
- **1.4.** Transportation and storage.
 - **1.4.1.** When removed from the bridge, the plaque will be placed either on a timber palette or in a purpose made timber box or skeleton crate.
 - **1.4.1.1.** The plaque will be secured with nylon straps for transport.
 - **1.4.1.2.** All palettes and crates will be fitted with supports and braces sufficient to prevent flexing or bending of the metal during transport.
 - **1.4.1.3.** The plaque will be transported off-site to a location specified by the contractor.
 - **1.4.2.** The plaque will be kept in a secured area, building or other structure to prevent damage or theft from the time of de-installation, during conservation work and before re-installation.

2. Conservation of the Plaque.

- **2.1.** All treatment will be executed in accordance with the Code of Ethics and Guidelines for Practice of the American Institute for Conservation of Historic and Artistic Works.
- **2.2.** Cleaning.

- **2.2.1.** Old organic resin residues (paint, caulk, etc.) will be removed with organic solvents or organic solvent based paint stripper, clearing with organic solvents.
- **2.2.2.** Loose corrosion products will be removed by washing with Orvus® detergent (sodium lauryl sulfate) in water, using nylon pads, bronze wool or fine brass bristle brushes. Care will be taken during cleaning not to disturb surviving gilding on the letters of the main inscription.
- **2.2.3.** The plaque will be cleaned with low pressure water washing at 800 psi, using a fan-shaped nozzle, 12-14 inches from surface.

2.3. Re-patination.

- **2.3.1.** The external surface will be re-patinated to approximate the reddish brown tone matching the re-patination of <u>Plaque 1</u>.
 - **2.3.1.1.** Patination will be accomplished by heating the bronze with a clean gas torch (propane, Mapp® or equivalent) and application of chemical reagents, such as potassium permanganate and/or ferric nitrate) diluted to achieve an appropriate tone.
 - **2.3.1.2.** All residual chemicals will be rinsed thoroughly with running water.

2.4. Surface Coatings.

- **2.4.1.** All surfaces (inside and out) will be coated with Incralac acrylic resin (Acryloid® B-44 in organic solvents, containing benzotriazole and plasticizers, available from StanChem, Inc., 401 Berlin Street, East Berlin, CT 06023, Tel 860.828.0571), diluted 1:1 with toluene.
 - **2.4.1.1.** The bronze will be warmed with a gas torch (as above) above ambient temperature and the first coat of Incralac applied by brush.
 - **2.4.1.2.** A minimum of two subsequent coats will be applied by spray to achieve a layer of at least 1 mm in thickness.
- **2.4.2.** After application of Incralac, exterior surfaces will be coated with hard paste wax (Butcher's Bowling Alley® or equivalent), applied cold by brush and buffed to a soft shine with bristle brushes followed by soft, clean cotton cloth.
- **2.4.3.** At the completion of surface treatment, the work will be inspected for approval by New Hampshire Division of Historical Resources prior to reinstallation.
- **2.4.4.** After re-installation, any scratches, abrasions or other defects in the surface coatings will be repaired by re-coating *in situ*.

2.5. Documentation

- **2.5.1.** All work will be documented in writing and photographically.
 - **2.5.1.1.** The written report will include a description of all materials and methods used in treatment.
 - **2.5.1.2.** The written report will include instructions for both routine (yearly) and long-term maintenance procedures.
- **2.5.2.** Photographic documentation will be prepared in the format (digital or analog) as requested by the New Hampshire Division of Historical Research Photographic and will include before, during and after treatment photographs illustrating all stages of work.

3. Re-installation.

3.1. Where new structural elements have been installed in the bridge, they will be drilled to receive fasteners, replicating the pattern and size of holes as indicated by deinstallation documentation.

3.2. Handling.

- **3.2.1.** Nylon riggers straps and slings will be used to handle bronze elements at all times.
- **3.2.2.** At no time will steel chains, cables or other metal come in contact with the bronze except at points where originally in contact with the supporting structure (internal flanges, lugs, lifting points, etc.).
- **3.2.3.** Where necessary, timber framing, supports or other bracing may come in contact with the bronze.
- **3.2.4.** Where necessary, baffles will be padded with high density expanded polyethylene foam (Ethafoam® or equivalent).
- **3.3.** The plaque will be reinstalled in their original locations on the bridge, following the documented sequence of de-installation.
 - **3.3.1.** Where original fasteners are unusable, new, non-corrosive stainless steel fasteners matching the original fasteners will be used.
 - **3.3.2.** Where possible, fasteners visible from the bridge deck will be made of high tensile strength bronze; specification of these fasteners will be determined in consultation with the structural engineer. Bolt heads will be degreased and patinated and coated (as per bronze elements) or painted to match surrounding surfaces.

3.4. Insulation.

- **3.4.1.** In consultation with the structural engineer, points of contact between bronze and iron will be insulated with Teflon®, high density polyethylene, lead, or other non-conductive washers and gaskets.
- **3.4.2.** If gaskets cannot be used for structural reasons, every effort will be made to make points of contact with bronze against stainless steel.

3.5. Caulking.

3.5.1. After installation, upper and side joints between iron and bronze will be caulked with an approved caulk; lower joints will be left open to permit drainage of internal condensation.

PLAQUE 3

1. De-installation.

- **1.1.** Documentation.
 - **1.1.1.** The plaque will be documented in writing, photographically and graphically throughout the de-installation process to satisfactorily permit reinstallation in its original location.
 - **1.1.2.** If the supporting truss of the bridge is to be replaced, a 1:1 scale template of the pattern of holes for fastening the plaque will be prepared as part of the documentation.
- **1.2.** Removal of fasteners.
 - **1.2.1.** To every extent possible, original bronze or brass fasteners (screws, bolts, etc.) will be backed out with the appropriate tools and retained.
 - **1.2.1.1.** Where fasteners are sound, they will be retained for use in reinstallation.
 - **1.2.1.2.** Where fasteners are rendered unusable by corrosion or other damage, they will be labeled and submitted to the New Hampshire Division of Historic Resources for archival storage.
 - **1.2.2.** Where fasteners cannot be backed out, they will be cut off with grinders, drilled out, or otherwise mechanically removed to minimize impact on the surrounding bronze.
 - **1.2.3.** At no time will torches be used to cut out corroded fasteners.
- **1.3.** Handling.
 - **1.3.1.** Nylon riggers straps and slings will be used to handle bronze elements at all times.
 - **1.3.2.** At no time will steel chains, cables or other metal come in contact with the bronze except at points where originally in contact with the supporting structure (internal flanges, lugs, lifting points, etc.).
 - **1.3.3.** Where necessary, timber framing, supports or other bracing may come in contact with the bronze.
 - **1.3.4.** Where necessary, framing and supports will be padded with high density expanded polyethylene foam (Ethafoam® or equivalent).
- **1.4.** Transportation and storage.
 - **1.4.1.** When removed from the bridge, the plaque will be placed either on a timber palette or in a purpose made timber box or skeleton crate.
 - **1.4.1.1.** The plaque will be secured with nylon straps for transport.
 - **1.4.1.2.** All palettes and crates will be fitted with supports and braces sufficient to prevent flexing or bending of the metal during transport.
 - **1.4.1.3.** The plaque will be transported off-site to a location specified by the contractor.
 - **1.4.2.** The plaque will be kept in a secured area, building or other structure to prevent damage or theft from the time of de-installation, during conservation work and before re-installation.

2. Conservation of the Plaque.

- **2.1.** All treatment will be executed in accordance with the Code of Ethics and Guidelines for Practice of the American Institute for Conservation of Historic and Artistic Works.
- **2.2.** Cleaning.

- **2.2.1.** Old organic resin residues (paint, caulk, etc.) will be removed with organic solvents or organic solvent based paint stripper, clearing with organic solvents.
- **2.2.2.** Loose corrosion products will be removed by washing with Orvus® detergent (sodium lauryl sulfate) in water, using nylon pads, bronze wool or fine brass bristle brushes. Care will be taken during cleaning not to disturb surviving gilding on the letters of the main inscription.
- **2.2.3.** The plaque will be cleaned with low pressure water washing at 800 psi, using a fan-shaped nozzle, 12-14 inches from surface.

2.3. Re-patination.

- **2.3.1.** The external surface will be re-patinated to approximate the reddish brown tone matching the re-patination of <u>Plaque 1</u>.
 - **2.3.1.1.** Patination will be accomplished by heating the bronze with a clean gas torch (propane, Mapp® or equivalent) and application of chemical reagents, (such as potassium permanganate and/or ferric nitrate) diluted to achieve an appropriate tone.
 - **2.3.1.2.** All residual chemicals will be rinsed thoroughly with running water.

2.4. Surface Coatings.

- **2.4.1.** All surfaces (inside and out) will be coated with Incralac acrylic resin (Acryloid® B-44 in organic solvents, containing benzotriazole and plasticizers, available from StanChem, Inc., 401 Berlin Street, East Berlin, CT 06023, Tel 860.828.0571), diluted 1:1 with toluene.
 - **2.4.1.1.** The bronze will be warmed with a gas torch (as above) above ambient temperature and the first coat of Incralac applied by brush.
 - **2.4.1.2.** A minimum of two subsequent coats will be applied by spray to achieve a layer of at least 1 mm in thickness.
- **2.4.2.** After application of Incralac, exterior surfaces will be coated with hard paste wax (Butcher's Bowling Alley® or equivalent), applied cold by brush and buffed to a soft shine with bristle brushes followed by soft, clean cotton cloth.
- **2.4.3.** At the completion of surface treatment, the work will be inspected for approval by New Hampshire Division of Historical Resources prior to reinstallation.
- **2.4.4.** After re-installation, any scratches, abrasions or other defects in the surface coatings will be repaired by re-coating *in situ*.

2.5. Documentation

- **2.5.1.** All work will be documented in writing and photographically.
 - **2.5.1.1.** The written report will include a description of all materials and methods used in treatment.
 - **2.5.1.2.** The written report will include instructions for both routine (yearly) and long-term maintenance procedures.
- **2.5.2.** Photographic documentation will be prepared in the format (digital or analog) as requested by the New Hampshire Division of Historical Research Photographic and will include before, during and after treatment photographs illustrating all stages of work.

3. Re-installation.

3.1. Where new structural elements have been installed in the bridge, they will be drilled to receive fasteners, replicating the pattern and size of holes as indicated by deinstallation documentation.

3.2. Handling.

- **3.2.1.** Nylon riggers straps and slings will be used to handle bronze elements at all times.
- **3.2.2.** At no time will steel chains, cables or other metal come in contact with the bronze except at points where originally in contact with the supporting structure (internal flanges, lugs, lifting points, etc.).
- **3.2.3.** Where necessary, timber framing, supports or other bracing may come in contact with the bronze.
- **3.2.4.** Where necessary, baffles will be padded with high density expanded polyethylene foam (Ethafoam® or equivalent).
- **3.3.** The plaque will be reinstalled in their original locations on the bridge, following the documented sequence of de-installation.
 - **3.3.1.** Where original fasteners are unusable, new, non-corrosive stainless steel fasteners matching the original fasteners will be used.
 - **3.3.2.** Where possible, fasteners visible from the bridge deck will be made of high tensile strength bronze; specification of these fasteners will be determined in consultation with the structural engineer. Bolt heads will be degreased and patinated and coated (as per bronze elements) or painted to match surrounding surfaces.

3.4. Insulation.

- **3.4.1.** In consultation with the structural engineer, points of contact between bronze and iron will be insulated with Teflon®, high density polyethylene, lead, or other non-conductive washers and gaskets.
- **3.4.2.** If gaskets cannot be used for structural reasons, every effort will be made to make points of contact with bronze against stainless steel.

3.5. Caulking.

3.5.1. After installation, upper and side joints between iron and bronze will be caulked with an approved caulk; lower joints will be left open to permit drainage of internal condensation.

PLAQUE 4

1. De-installation.

- **1.1.** The plaque will be documented in writing, photographically and graphically throughout the de-installation process to satisfactorily permit re-installation in its original location.
- **1.2.** Removal of fasteners.
 - **1.2.1.** To every extent possible the fasteners (screws, bolts, etc.) will be backed out with the appropriate tools and retained.
 - **1.2.2.** At no time will torches be used to cut out corroded fasteners.
- **1.3.** Handling.
 - **1.3.1.** Nylon riggers straps and slings will be used to handle the plaque at all times.
 - **1.3.2.** Where necessary, timber framing, supports or other bracing may come in contact with the plaque.
 - **1.3.3.** Where necessary, framing and supports will be padded with high density expanded polyethylene foam (Ethafoam® or equivalent).
- **1.4.** Transportation and storage.
 - **1.4.1.** When removed from the bridge, the plaque will be placed in a purpose made timber box or skeleton crate.
 - **1.4.1.1.** The plaque will be secured with nylon straps for transport.
 - **1.4.1.2.** The plaque will be transported off-site to a location specified by the contractor.
 - **1.4.2.** The plaque will be kept in a secured area, building or other structure to prevent damage or theft from the time of de-installation, during conservation work and before re-installation.

2. Conservation of the Plaque.

- **2.1.** All treatment will be executed in accordance with the Code of Ethics and Guidelines for Practice of the American Institute for Conservation of Historic and Artistic Works.
- **2.2.** Cleaning.
 - **2.2.1.** All paint will be removed with organic solvent based paint stripper, clearing residues with organic solvents.
 - **2.2.2.** Any corrosion products will be removed with small stainless steel brushes to gray metal
- **2.3.** Re-painting.
 - **2.3.1.** All surfaces will be degreased with organic solvents.
 - **2.3.2.** Two coats of high quality, high zinc primer will be applied to all surfaces (inside and out). The first coat will be applied by brush and the second coat will be applied by spray.
 - **2.3.3.** The external surface of the plaque will be painted with the same paint as the rest of the bridge in three coats.
 - **2.3.3.1.** The first coat will be applied by brush.
 - **2.3.3.2.** Subsequent coats will be applied by spray.
 - **2.3.4.** After re-installation, any scratches, abrasions or other defects in the surface coatings will be repaired by re-painting *in situ*.
- **2.4.** Documentation
 - **2.4.1.** All work will be documented in writing and photographically.

- **2.4.1.1.** The written report will include a description of all materials and methods used in treatment.
- **2.4.1.2.** The written report will include instructions for both routine (yearly) and long-term maintenance procedures.
- **2.4.2.** Photographic documentation will be prepared in the format (digital or analog) as requested by the New Hampshire Division of Historical Research Photographic and will include before, during and after treatment photographs illustrating all stages of work.

3. Re-installation.

- **3.1.** Where new structural elements have been installed in the bridge, they will be drilled to receive fasteners, replicating the pattern and size of holes as indicated by deinstallation documentation.
- **3.2.** Handling.
 - **3.2.1.** At no time will steel chains, cables or other metal come in contact with the plaque.
 - **3.2.2.** Where necessary, timber framing, supports or other bracing may come in contact with the plaque.
- **3.3.** The plaque will be reinstalled to an identical position on the closest fixed span member to the original location on the lift span of the bridge, following the documented sequence of de-installation. The old fasteners will be replaced with, new, non-corrosive stainless steel fasteners in a size as recommended by the New Hampshire Division of Historic Resources.
- **3.4.** Caulking.
 - **3.4.1.** After installation, upper and side joints between the plaque and column will be caulked with an approved caulk; the lower joint will be left open to permit drainage of internal condensation.

PLAQUE 5

1. De-installation.

- **1.1.** The plaque will be documented in writing, photographically and graphically throughout the de-installation process to satisfactorily permit re-installation in its original location.
- **1.2.** Removal of fasteners.
 - **1.2.1.** To every extent possible, the fasteners will be backed out with the appropriate tools.
 - **1.2.2.** Where fasteners cannot be backed out, they will be cut off with grinders, drilled out, or otherwise mechanically removed to minimize impact on the surrounding bronze.
 - **1.2.3.** At no time will torches be used to cut out corroded fasteners.
- **1.3.** Handling.
 - **1.3.1.** Nylon riggers straps and slings will be used to handle the plaque at all times.
 - **1.3.2.** At no time will steel chains, cables or other metal come in contact with the bronze.
 - **1.3.3.** Where necessary, timber framing, supports or other bracing may come in contact with the bronze.
 - **1.3.4.** Where necessary, framing and supports will be padded with high density expanded polyethylene foam (Ethafoam® or equivalent).
 - **1.3.5.** Contractor is advised that a survey monument is embedded in the granite plinth surrounding the plaque, and may be firmly anchored into place. Padding or timber framing will be installed over the granite plinth and the survey monument embedded in the stone to protect the stone in situ during construction. If the granite plinth and survey monument are to be removed, measures must be taken to protect the condition of the stone during de-installation and transport.
- **1.4.** Transportation and storage.
 - **1.4.1.** When removed from the granite plinth in Memorial Park, the plaque will be placed either on a timber palette or in a purpose made timber box or skeleton crate.
 - **1.4.1.1.** The plague will be secured with nylon straps for transport.
 - **1.4.1.2.** All palettes and crates will be fitted with supports and braces sufficient to prevent flexing or bending of the metal during transport.
 - **1.4.1.3.** The plaque will be transported off-site to a location specified by the contractor.
 - **1.4.2.** The plaque will be kept in a secured area, building or other structure to prevent damage or theft from the time of de-installation, during conservation work and before re-installation.

2. Conservation of the Plaque.

- **2.1.** All treatment will be executed in accordance with the Code of Ethics and Guidelines for Practice of the American Institute for Conservation of Historic and Artistic Works.
- **2.2.** Cleaning.
 - **2.2.1.** Old organic resin residues (paint, caulk, etc.) will be removed with organic solvents or organic solvent based paint stripper, clearing with organic solvents.

- **2.2.2.** Loose corrosion products will be removed by washing with Orvus® detergent (sodium lauryl sulfate) in water, using nylon pads, bronze wool or fine brass bristle brushes. Care will be taken during cleaning not to disturb surviving gilding on the letters of the main inscription.
- **2.2.3.** The plaque will be cleaned with low pressure water washing at 800 psi, using a fan-shaped nozzle, 12-14 inches from surface.
- **2.3.** Re-patination.
 - **2.3.1.** The external surface will be re-patinated to approximate the reddish brown tone matching the re-patination of <u>Plaque 1</u>.
 - **2.3.1.1.** Patination will be accomplished by heating the bronze with a clean gas torch (propane, Mapp® or equivalent) and application of chemical reagents, (such as potassium permanganate and/or ferric nitrate) diluted to achieve an appropriate tone.
 - **2.3.1.2.** All residual chemicals will be rinsed thoroughly with running water.
- **2.4.** Surface Coatings.
 - **2.4.1.** All surfaces (inside and out) will be coated with Incralac acrylic resin (Acryloid® B-44 in organic solvents, containing benzotriazole and plasticizers, available from StanChem, Inc., 401 Berlin Street, East Berlin, CT 06023, Tel 860.828.0571), diluted 1:1 with toluene.
 - **2.4.1.1.** The bronze will be warmed with a gas torch (as above) above ambient temperature and the first coat of Incralac applied by brush.
 - **2.4.1.2.** A minimum of two subsequent coats will be applied by spray to achieve a layer of at least 1 mm in thickness.
 - **2.4.2.** After application of Incralac, exterior surfaces will be coated with hard paste wax (Butcher's Bowling Alley® or equivalent), applied cold by brush and buffed to a soft shine with bristle brushes followed by soft, clean cotton cloth.
 - **2.4.3.** At the completion of surface treatment, the work will be inspected for approval by New Hampshire Division of Historical Resources prior to reinstallation.
 - **2.4.4.** After re-installation, any scratches, abrasions or other defects in the surface coatings will be repaired by re-coating *in situ*.
- **2.5.** The granite plinth will be cleaned with mild detergent and rinsed thoroughly with clear water prior to re-installation.
- **2.6.** Documentation
 - **2.6.1.** All work will be documented in writing and photographically.
 - **2.6.1.1.** The written report will include a description of all materials and methods used in treatment.
 - **2.6.1.2.** The written report will include instructions for both routine (yearly) and long-term maintenance procedures.
 - **2.6.2.** Photographic documentation will be prepared in the format (digital or analog) as requested by the New Hampshire Division of Historical Research Photographic and will include before, during and after treatment photographs illustrating all stages of work.

3. Re-installation.

- **3.1.** Handling.
 - **3.1.1.** Nylon riggers straps and slings will be used to handle bronze elements at all times.

- **3.1.2.** At no time will steel chains, cables or other metal come in contact with the bronze except at points where originally in contact with the supporting structure (internal flanges, lugs, lifting points, etc.).
- **3.1.3.** Where necessary, timber framing, supports or other bracing may come in contact with the bronze.
- **3.1.4.** Where necessary, braces will be padded with high density expanded polyethylene foam (Ethafoam® or equivalent).
- **3.2.** The plaque will be reinstalled in its original locations on the stone plinth.
 - **3.2.1.** Old anchors will be removed mechanically by drilling.
 - **3.2.2.** New stainless steel anchors, designed to accommodate machine screws, will be set in the stone with structural epoxy resin.
 - **3.2.3.** The plaque will be reinstalled using new stainless steel security machine screws. The screw heads will be scuffed, primed and painted to match the patinated bronze.

3. Budget

ATTACHMENT 1

Memorial Bridge Rehabilitation Portsmouth-Kittery 13678: US1 over Piscataqua River

Summary of Parts

Description		Estimated Weight	
Eagle and <i>fasces</i> (wingspan: ca. 6 ½')	of Units	per Unit (lbs.) 1,100 (measured)	
Cover of eagle (back)	1	1,100 (measured)	
Uppermost box (possibly fabricated in several pieces)	2		
Uppermost box cover (in back)	1		
Upper molding (front)	2		
Upper molding cover (back)	2		
Small shields with leaf ornaments	4		
Boxes around vertical supports behind lower shields (back)	2		
Central shield	1		
Oak ornament at sides of central shield	2		
Inscription (Height: 46", Width of each unit: 117" Depth: 11")	2	950	
Inscription cover (back)	2	600	
Inner oak and pine ornament around roundels (Width: 56",	2		
Height: 37")			
Outer oak and pine ornament around roundels and extending			
around the corners	2	350	
Roundels (front)	2	750	
Roundel covers (back, Diameter: 59", Depth: 8 1/4")	2	200	
Roundel support covers (back)	2		
Lower molding (possibly made in more parts)	3		
Cover on lower molding (back, possibly more)	3		
Moldings at top of brackets at ends of lower moldings	2		
Plates and ornament of brackets (possibly more)	2		
Lower trim plates	3		
Back of lower trim plates	3		

Memorial Bridge Historic Structures Report

ATTACHMENT 2

Memorial Bridge Rehabilitation Portsmouth-Kittery 13678: US1 over Piscataqua River

Budget Sketch

De-installation	Unit cost (per week where applicable)	Number of units	Cost	Sub-totals
			20,000,00	
Staging			20,000.00	
Art Handling Team*	16,800.00	2	33,600.00	
Conservation Team**	10,000.00	2	20,000.00	
Rigger***	7,500.00	2	15,000.00	
Palettes, Crates, Foam, etc.			12,000.00	
				100,600.00
ConservationTreatment (including all materials and costs)				
Plaque 1			75,000.00	75,000.00
Plaques 2-5	5,000.00	4	20,000.00	20,000.00
Re-installation				
Staging			20,000.00	
Fasteners			5,000.00	
Art Handling Team	16,800.00	3	50,400.00	
Conservation Team	10,000.00	3	30,000.00	
Rigger	7,500.00	3	22,500.00	127,900.00 \$
Total				\$ 323,500.00

ATTACHMENT 3

Conservators

Clifford Craine
Daedalus, Inc.
205-3 Arlington Street
Watertown, MA 02472
Tel: (617) 926-7590
Fax: (617) 926-7591
daedalusart@verizon.net

Type: Fellow

Rika Smith McNally, 59 Fountain Street, Box 55 4th Floor East, Studio 15 Framingham, MA 01702 Tel: (508) 620-2929 Fax: (508) 620-2904 rika.mcnally@verizon.net

Type: Fellow

Linda Merk-Gould Conservation Technical Associates 3 Meeker Road Westport, CT 06880 Tel: (203) 984-8000 Fax: (203) 222-2235 lgould@optonline.net

Type: Fellow

Nina Vinogradskaya 109 Webster Street #6 East Boston, MA 02128 Tel: (617) 567-7950 nina.vino@verizon.net Type: Professional Associate

Carol E. Snow 46 Hill Top Road Weston, MA 02493 Tel: (781) 642-0466 carolsnow@comcast.net Type: Professional Associate

Memorial Bridge Historic Structures Report

Art Handling Firms

Fine Arts Enterprises, Inc. 645 Summer Street Boston, MA 02210 Phone: 617-268-7200 Fax: 617-268-1818

Contact:

Larry Doherty, President

U.S. Art 66 Pacella Park Drive Randolph, MA 02368 Toll Free: 800 872-7826 Telephone: 781 986-6500

Fax: 781 986-5595

Contact: George Hagerty, National Special Projects Manager

www.usart.com

ARTEX Fine Art Services 200 Inner Belt Road Somerville, MA 02143 Telephone 617-776-0300 866-407-9660 (toll free) Fax 617-776-0330 http://www.artexfas.com