

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

New York [36]	Chenango County [017]	New Berlin [49957]	0.5 MI EAST OF HOLMESVILL	42-30-42 = 42.511667	075-23-42 = -75.395000
3351710	Highway agency district: 92	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0	DITCH ROAD TR 17	Toll On free road [3]	Features intersected	UNADILLA RIVER	
Design - main	Aluminum, Wrought Iron or Cast Iron [9]	Design - approach	Kilometerpoint		
2	Truss - Thru [10]	0	Other [00]	Year built #Num!	Year reconstructed N/A [0000]
			Skew angle 0	Structure Flared	
			Historical significance	Bridge is not eligible for the NRHP. [5]	
Total length	53.3 m = 174.9 ft	Length of maximum span	26.2 m = 86.0 ft	Deck width, out-to-out	4.3 m = 14.1 ft
Bridge roadway width, curb-to-curb	4.1 m = 13.5 ft	Inventory Route, Total Horizontal Clearance	4 m = 13.1 ft	Curb or sidewalk width - left	0 m = 0.0 ft
				Curb or sidewalk width - right	0 m = 0.0 ft
Deck structure type	Wood or Timber [8]				
Type of wearing surface	Wood or Timber [7]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length	Method to determine inventory rating		Inventory rating	3.6 metric ton = 4.0 tons
0.6 km = 0.4 mi	Method to determine operating rating		Operating rating	6.3 metric ton = 6.9 tons
Bridge posting	20.0 - 29.9 % below [2]		Design Load	

Functional Details

Average Daily Traffic	200	Average daily truck traffi	10	%	Year	1991	Future average daily traffic	2465	Year	2010
Road classification	Local (Rural) [09]		Lanes on structure	1		Approach roadway width	5.5 m = 18.0 ft			
Type of service on bridge	Highway [1]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	3.55 m = 11.6 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	662000	Roadway improvement cost	77000						
	Length of structure improvement	71.6 m = 234.9 ft		Total project cost	1155000					
	Year of improvement cost estimate									
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Basically intolerable requiring high priority of replacement [2]
Condition ratings - superstructure	Serious [3]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]
Condition ratings - substructure	Serious [3]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Serious [3]		
Scour	Scour calculation/evaluation has not been made. [6]		
Channel and channel protection	Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]		
Appraisal ratings - water adequacy	Meets minimum tolerable limits to be left in place as is [4]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	0
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - transitions	Not applicable or a safety feature is not required. [N]		
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	June 1991 [0691]	Designated inspection frequency	12 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	June 1991 [0691]
Other special inspection	Not needed [N]	Other special inspection date	