

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format. Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

New York [36] Steuben County [101] Lindley [42576] 0.1 MI N JCT RTE 15 + CL 42-00-06 = 42.001667 077-07-37 = - 77.126944

1011100 Highway agency district 64 Owner County Highway Agency [02] Maintenance responsibility County Highway Agency [02]

Route 0 CR 115 Toll On free road [3] Features intersected COWANESQUE RIVER

Design - main Steel [3] Design - approach Other [00] Kilometerpoint 0 km = 0.0 mi

1 Truss - Thru [10] 0 Other [00] Year built 1941 Year reconstructed N/A [0000]

Skew angle 15 Structure Flared

Historical significance Bridge is not eligible for the NRHP. [5]

Total length 53.3 m = 174.9 ft Length of maximum span 51.8 m = 170.0 ft Deck width, out-to-out 9 m = 29.5 ft Bridge roadway width, curb-to-curb 8.5 m = 27.9 ft

Inventory Route, Total Horizontal Clearance 8.5 m = 27.9 ft Curb or sidewalk width - left 1.5 m = 4.9 ft Curb or sidewalk width - right 0 m = 0.0 ft

Deck structure type Concrete Cast-in-Place [1]

Type of wearing surface Monolithic Concrete (concurrently placed with structural deck) [1]

Deck protection

Type of membrane/wearing surface

Weight Limits

Bypass, detour length 9.3 km = 5.8 mi Method to determine inventory rating Load Factor(LF) [1] Inventory rating 29.9 metric ton = 32.9 tons

Method to determine operating rating Load Factor(LF) [1] Operating rating 49.9 metric ton = 54.9 tons

Bridge posting Equal to or above legal loads [5] Design Load M 18 / H 20 [4]

Functional Details

Average Daily Traffic	4987	Average daily truck traffi	9	%	Year	2000	Future average daily traffic	6742	Year	2020
Road classification	Major Collector (Rural) [07]		Lanes on structure	2		Approach roadway width	12.1 m = 39.7 ft			
Type of service on bridge	Highway-pedestrian [5]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	4.57 m = 15.0 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Widening of existing bridge with deck rehabilitation or replacement. [34]	Bridge improvement cost	1088000	Roadway improvement cost	648000						
	Length of structure improvement	53.3 m = 174.9 ft		Total project cost	1736000					
	Year of improvement cost estimate	2009								
	Border bridge - state					Border bridge - percent responsibility of other state				
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - superstructure	Poor [4]	Appraisal ratings - roadway alignment	Equal to present minimum criteria [6]
Condition ratings - substructure	Fair [5]	Appraisal ratings - deck geometry	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - deck	Poor [4]		
Scour	Bridge foundations determined to be stable for assessed or calculated scour conditions; field review indicates action is required. [4]		
Channel and channel protection	Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]		
Appraisal ratings - water adequacy	Somewhat better than minimum adequacy to tolerate being left in place as is [5]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	33.7
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - transitions			
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	August 2009 [0809]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	August 2009 [0809]
Other special inspection	Not needed [N]	Other special inspection date	