The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information							41-11-23 =	076-39-13 = -	
Pennsylvania [42] Lycoming County [081]			Moreland [50936] 4 MI SW OF LAIRDSVILLE		DSVILLE		41.189722	76.653611	
412069002000000 Highway agency district: 3			Owner State Highway Agency [01] Maintenance responsibility		State Highway Age	ency [01]			
Route 0 SR 2069			Toll On free road [3] Features intersected OVER LITTI			E MUNCY CREEK			
Design - main Steel [3] Design - approach Truss - Thru [10] 0 Other		Kilometerpoint 86.3 km = 53.5 mi Year built 1904 Year reconstructed 1995 Skew angle 30 Structure Flared Historical significance Bridge is not eligible for the NRHP. [5]							
Total length 34.4 m = 112.9 ft Length of maximum span 33.5 m = 109.9 ft Deck width, out-to-out 4.9 m = 16.1 ft Bridge roadway width, curb-to-curb 4.6 m = 15.1 ft Inventory Route, Total Horizontal Clearance 4.6 m = 15.1 ft Curb or sidewalk width - left 0.2 m = 0.7 ft Curb or sidewalk width - right 0.2 m = 0.7 ft									
Deck structure type Wood or Timber [8]									
Type of wearing surface Wood or Timber [7]									
Deck protection									
Type of membrane/we	earing surface								
Weight Limits									
Bypass, detour length 0.6 km = 0.4 mi Method to determine inventory rating Method to determine operating rating		` ' '		Inventory rating Operating rating	10 metric ton = 1 17.2 metric ton =				
Bridge posting					Design Load M 1	3.5 / H 15 [2]			

Functional Details									
Average Daily Traffic 42 Average daily tr	uck traffi 9 % Year 2009 Future average daily traffic 65 Year 2031								
Road classification Local (Rural) [09]	Lanes on structure 1 Approach roadway width 3.7 m = 12.1 ft								
Type of service on bridge Highway [1]	Direction of traffic One lane bridge for 2 - way traffic [3] Bridge median								
Parallel structure designation No parallel structure	exists. [N]								
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control								
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A								
Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway 4 m = 13.1 ft									
Minimum lateral underclearance reference feature Feature not a highway or railroad [N]									
Minimum lateral underclearance on right $0 = N/A$	Minimum lateral underclearance on left 0 = N/A								
Minimum Vertical Underclearance 0 = N/A Minimum vertical underclearance reference feature Feature not a highway or railroad [N]									
Appraisal ratings - underclearances N/A [N]									
Repair and Replacement Plans									
Type of work to be performed	Work done by Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial	Bridge improvement cost 0 Roadway improvement cost 0								
bridge roadway geometry. [31]	Length of structure improvement 34 m = 111.6 ft Total project cost 1000								
	Year of improvement cost estimate								
	Border bridge - state Border bridge - percent responsibility of other state								
	Border bridge - structure number								

Inspection and Sufficiency									
Structure status Posted for lo	ad [P]	Appraisal ratings - structural	Basically intolerable requiring h	nigh priority of replacement [2]					
Condition ratings - superstructure Critical [2]		Appraisal ratings - roadway alignment	Meets minimum tolerable limits to be left in place as is [4]						
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]						
Condition ratings - deck	Satisfactory [6]								
Scour	Bridge foundations determine	Bridge foundations determined to be stable for assessed or calculated scour condition. [5]							
Channel and channel protection	Bank protection is being erode channel. [5]	Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]							
Appraisal ratings - water adequac	Equal to present minimum cri	iteria [6]	Status evaluation	Structurally deficient [1]					
Pier or abutment protection				21.6					
Culverts Not applicable. Used	if structure is not a culvert. [N]								
Traffic safety features - railings									
Traffic safety features - transition	ns								
Traffic safety features - approach guardrail									
Traffic safety features - approach guardrail ends									
Inspection date March 2009 [0309] Designated inspection frequency 12 Months									
Underwater inspection	Not needed [N]	Underwater inspec	ction date						
Fracture critical inspection	Not needed [N]	Fracture critical inspection date							
Other special inspection Unknown [Y00] Other special inspection date									