

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Pennsylvania [42] Bradford County [015] North Towanda [55448] 1 MI.N.OF TOWANDA BORO. 00-00-00 = 0.000000 000-00-00 = - 0.000000

83022010000000 Highway agency district 3 Owner State Highway Agency [01] Maintenance responsibility State Highway Agency [01]

Route 0 3022/CLOSED TRUSS Toll On free road [3] Features intersected SUGAR CREEK

Design - main Steel [3] Design - approach Kilometerpoint 0 km = 0.0 mi

1 Truss - Thru [10] 0 Other [00] Year built #Num! Year reconstructed N/A [0000]

Skew angle 0 Structure Flared

Historical significance Bridge is not eligible for the NRHP. [5]

Total length 47.5 m = 155.8 ft Length of maximum span 46.3 m = 151.9 ft Deck width, out-to-out 5.6 m = 18.4 ft Bridge roadway width, curb-to-curb 5.2 m = 17.1 ft

Inventory Route, Total Horizontal Clearance 5.2 m = 17.1 ft Curb or sidewalk width - left 0.2 m = 0.7 ft Curb or sidewalk width - right 0.2 m = 0.7 ft

Deck structure type Wood or Timber [8]

Type of wearing surface Bituminous [6]

Deck protection

Type of membrane/wearing surface

Weight Limits

Bypass, detour length 1.1 km = 0.7 mi Method to determine inventory rating No rating analysis performed [5] Inventory rating 32.4 metric ton = 35.6 tons

Method to determine operating rating No rating analysis performed [5] Operating rating 0 metric ton = 0.0 tons

Bridge posting Design Load

Functional Details

Average Daily Traffic	133	Average daily truck traffi	10	%	Year	2003	Future average daily traffic	301	Year	2024
Road classification	Local (Rural) [09]		Lanes on structure	2		Approach roadway width	5.5 m = 18.0 ft			
Type of service on bridge	Highway [1]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge	0 m = 0.0 ft				Minimum vertical clearance over bridge roadway	4.03 m = 13.2 ft				
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]		
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	200000	Roadway improvement cost	0
	Length of structure improvement	107.3 m = 352.1 ft	Total project cost	260000
	Year of improvement cost estimate			
	Border bridge - state		Border bridge - percent responsibility of other state	
	Border bridge - structure number			

Inspection and Sufficiency

Structure status	<input type="text" value="Bridge closed to all traffic [K]"/>	Appraisal ratings - structural	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - superstructure	<input type="text" value="Critical [2]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Basically intolerable requiring high priority of corrective action [3]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text"/>
Condition ratings - deck	<input type="text" value="Fair [5]"/>		
Scour	<input type="text" value="Scour calculation/evaluation has not been made. [6]"/>		
Channel and channel protection	<input type="text" value="Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Better than present minimum criteria [7]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="0"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="May 2002 [0502]"/>	Designated inspection frequency	<input type="text" value="12"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>