The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information							40-50-38 =	080-24-45 = -
Pennsylvania [42]	Beaver County [007]		Darlington [18200]	004017 YOUNG	017 YOUNG'S BRIDGE		40-30-36 = 40.843889	80.412500
047204067940170 Highway agency district 11			Owner County Highway Agency [02] Maintenance responsibility			County Highway A	gency [02]	
Route 0 SYLVANIA DR			Toll On free road [3] Features intersected LITTLE BEA			VER CREEK		
Design - Steel [3] main Truss - Thr	u [10]	Design - approach Other	[00]	Kilometerpoint Year built 1939 Skew angle 0 Historical signific	Structure F	constructed 2003 lared s possibly eligible		
Total length 29.9 m = 98.1 ft Length of maximum span 28 m = 91.9 ft Deck width, out-to-out 4.3 m = 14.1 ft Bridge roadway width, curb-to-curb 4 m = 13.1 ft Inventory Route, Total Horizontal Clearance 4 m = 13.1 ft Curb or sidewalk width - left 0.2 m = 0.7 ft 0.2 m = 0.7 ft								
Deck structure type Wood or Timber [8] Type of wearing surface Wood or Timber [7] Deck protection								
Type of membrane/wearing surface								
Weight Limits								
Bypass, detour lengtl 0.3 km = 0.2 mi	Method to determ	Method to determine inventory rating Method to determine operating rating			Inventory rating 4.5 metric ton = 5.0 tons Operating rating 5.4 metric ton = 5.9 tons			
Bridge posting					Design Load M 1	I3.5 / H 15 [2]		

Functional Details								
Average Daily Traffic 50 Average daily tr	uck traffi 0 % Year 2006 Future average daily traffic 55 Year 2025							
Road classification Local (Rural) [09]	Lanes on structure 1 Approach roadway width 3.7 m = 12.1 ft							
Type of service on bridge Highway [1]	Direction of traffic One lane bridge for 2 - way traffic [3] Bridge median							
Parallel structure designation No parallel structure exists. [N]								
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control							
Navigation vertical clearance 0 = N/A Navigation horizontal clearance 0 = N/A								
Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway 4 m = 13.1 ft								
Minimum lateral underclearance reference feature Feature not a highway or railroad [N]								
Minimum lateral underclearance on right 0 = N/A Minimum lateral underclearance on left 0 = N/A								
Minimum Vertical Underclearance 0 = N/A Minimum vertical underclearance reference feature Feature not a highway or railroad [N]								
Appraisal ratings - underclearances N/A [N]								
Densir and Danlessmant Dlane								
Repair and Replacement Plans								
Type of work to be performed	Work done by Work to be done by contract [1]							
Replacement of bridge or other structure because of substandard load carrying capacity or substantial	Bridge improvement cost 0 Roadway improvement cost 0							
bridge roadway geometry. [31]	Length of structure improvement 29 m = 95.1 ft Total project cost 1000							
	Year of improvement cost estimate							
	Border bridge - state Border bridge - percent responsibility of other state							
	Border bridge - structure number							

Inspection and Sufficiency									
Structure status Posted for lo	ad [P]	Appraisal ratings - structural	Basically intolerable requiring high priority of replacement [2]						
Condition ratings - superstructur Fair [5]		Appraisal ratings - roadway alignment	Meets minimum tolerable limits to be left in place as is [4]						
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]						
Condition ratings - deck	Satisfactory [6]								
Scour	Bridge foundations determine required. [4]	Bridge foundations determined to be stable for assessed or calculated scour conditions; field review indicates action is required. [4]							
Channel and channel protection	Bank protection is being erod channel. [5]	Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]							
Appraisal ratings - water adequac	Equal to present minimum cr	Equal to present minimum criteria [6] Status evaluation							
Pier or abutment protection			Sufficiency rating 17.8						
Culverts Not applicable. Used if structure is not a culvert. [N]									
Traffic safety features - railings									
Traffic safety features - transition	OS								
Traffic safety features - approach	n guardrail								
Traffic safety features - approach guardrail ends									
Inspection date March 2009 [0309] Designated inspection frequency 12 Months									
Underwater inspection	Not needed [N]	Underwater inspec	ction date						
L	Every year [Y12]	Fracture critical ins							
Other special inspection	Not needed [N]	Other special insp	ection date						