

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Indiana [18]	Elkhart County [039]	Elkhart [20728]	BEARDSLEY & JOHNSON C-10	41-41-30 = 41.691667	085-57-30 = - 85.958333
2000163	Highway agency district 2	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0	JOHNSON STREET	Toll On free road [3]	Features intersected	ST. JOSEPH RIVER	
Design - main Steel [3]	Design - approach	Kilometerpoint 0 km = 0.0 mi	Year built 1918	Year reconstructed 1981	
4 Truss - Deck [09]	0 Other [00]	Skew angle 0	Structure Flared	Historical significance Bridge is eligible for the NRHP. [2]	
Total length 118 m = 387.2 ft	Length of maximum span 30.5 m = 100.1 ft	Deck width, out-to-out 15.5 m = 50.9 ft	Bridge roadway width, curb-to-curb 13.4 m = 44.0 ft		
Inventory Route, Total Horizontal Clearance 13.4 m = 44.0 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 1.5 m = 4.9 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Monolithic Concrete (concurrently placed with structural deck) [1]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.2 km = 0.1 mi	Method to determine inventory rating	Inventory rating 32.4 metric ton = 35.6 tons
	Method to determine operating rating	Operating rating 41.4 metric ton = 45.5 tons
Bridge posting	Equal to or above legal loads [5]	Design Load MS 18 / HS 20 [5]

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Better than present minimum criteria [7]
Condition ratings - superstructure	Good [7]	Appraisal ratings - roadway alignment	Better than present minimum criteria [7]
Condition ratings - substructure	Good [7]	Appraisal ratings - deck geometry	Somewhat better than minimum adequacy to tolerate being left in place as is [5]
Condition ratings - deck	Satisfactory [6]		
Scour	Bridge foundations determined to be stable for assessed or calculated scour condition. [5]		
Channel and channel protection	Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]		
Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	
Pier or abutment protection		Sufficiency rating	80.6
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - transitions	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	September 1998 [0998]	Designated inspection frequency	24 Months
Underwater inspection	Unknown [Y48]	Underwater inspection date	September 1998 [0998]
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	August 1998 [0898]
Other special inspection	Not needed [N]	Other special inspection date	