HistoricBridges.org - National Bridge Inventory Data Sheet

2012 Inventory

The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.
Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Iowa [19]	Tama County [171]	Unknown [00000]	83162204	41-59-12 = 41.986667	092-42-01 = -92.700278

318400	Highway agency district 0	Owner: County Highway Agency [02]	Maintenance responsibility: County Highway Agency [02]		
Route: 0		IRR-LOCAL	Toll: On free road [3]	Features intersected: IOWA RIVER	

Design - main: Steel [3]		Design - approach: Steel [3]		Kilometerpoint: 0 km = 0.0 mi	
1	Truss - Thru [10]	2	Stringer/Multi-beam or girder [02]	Year built: 1938	Year reconstructed: N/A [0000]
				Skew angle: 0	Structure Flared:
				Historical significance: Bridge is possibly eligible for the NRHP. [3]	

Total length: 100.9 m = 331.1 ft	Length of maximum span: 48.8 m = 160.1 ft	Deck width, out-to-out: 6 m = 19.7 ft	Bridge roadway width, curb-to-curb: 5.7 m = 18.7 ft		
Inventory Route, Total Horizontal Clearance: 5.7 m = 18.7 ft	Curb or sidewalk width - left: 0 m = 0.0 ft	Curb or sidewalk width - right: 0 m = 0.0 ft			

Deck structure type	Concrete Cast-in-Place [1]
Type of wearing surface	Monolithic Concrete (concurrently placed with structural deck) [1]
Deck protection	
Type of membrane/wearing surface	

Weight Limits

Bypass, detour length: 0.6 km = 0.4 mi	Method to determine inventory rating: Allowable Stress(AS) [2]		Inventory rating: 4.5 metric ton = 5.0 tons		
	Method to determine operating rating: Allowable Stress(AS) [2]		Operating rating: 9.1 metric ton = 10.0 tons		
	Bridge posting:		Design Load: M 13.5 / H 15 [2]		

Functional Details

Average Daily Traffic	200	Average daily truck traffi	6 %	Year	2009	Future average daily traffic	222	Year	2030

Road classification	Local (Rural) [09]	Lanes on structure	2	Approach roadway width	8.5 m = 27.9 ft
Type of service on bridge	Highway [1]	Direction of traffic	2 - way traffic [2]	Bridge median	
Parallel structure designation	No parallel structure exists. [N]				
Type of service under bridge	Waterway [5]	Lanes under structure	0	Navigation control	
Navigation vertical clearanc	0 = N/A	Navigation horizontal clearance	0 = N/A		
Minimum navigation vertical clearance, vertical lift bridge	0 m = 0.0 ft	Minimum vertical clearance over bridge roadway	3.35 m = 11.0 ft		
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]				
Minimum lateral underclearance on right	0 = N/A	Minimum lateral underclearance on left	0 = N/A		
Minimum Vertical Underclearance	0 = N/A	Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]		
Appraisal ratings - underclearances	N/A [N]				

Repair and Replacement Plans

Type of work to be performed

Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]

Work done by	Work to be done by contract [1]		
Bridge improvement cost	1009000	Roadway improvement cost	100000
Length of structure improvement	354 m = 1161.5 ft	Total project cost	
Year of improvement cost estimate	2009		
Border bridge - state		Border bridge - percent responsibility of other state	
Border bridge - structure number			

Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Basically intolerable requiring high priority of replacement [2]
Condition ratings - superstructur	Poor [4]	Appraisal ratings - roadway alignment	Equal to present minimum criteria [6]
Condition ratings - substructure	Poor [4]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Poor [4]		

Scour	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]
Channel and channel protection	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]

Appraisal ratings - water adequacy	Equal to present minimum criteria [6]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	14.6

Culverts	Not applicable. Used if structure is not a culvert. [N]
Traffic safety features - railings	
Traffic safety features - transitions	
Traffic safety features - approach guardrail	
Traffic safety features - approach guardrail ends	

Inspection date	September 2010 [0910]	Designated inspection frequency	24	Months

Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	