HistoricBridges.org - National Bridge Inventory Data Sheet

2011 Inventory

The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.
Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Ohio [39]	Huron County [077]	Ridgefield [67006]	0.4 MI W OF PERU CENTER	41-13-02 = 41.217222	082-42-08 = -82.702222

3931072	Highway agency district 3	Owner: County Highway Agency [02]	Maintenance responsibility: County Highway Agency [02]		
Route: #Num!		STANDARDSBURG 90	Toll: On free road [3]	Features intersected: STANDRDSBRG/W BR HRN RVR	

Design - main: Steel [3]		Design - approach:		Kilometerpoint: 0 km = 0.0 mi	
1	Truss - Thru [10]	0	Other [00]	Year built: 1926	Year reconstructed: 1994
				Skew angle: 0	Structure Flared:
				Historical significance: Bridge is not eligible for the NRHP. [5]	

Total length: 39 m = 128.0 ft	Length of maximum span: 36 m = 118.1 ft	Deck width, out-to-out: 6.5 m = 21.3 ft	Bridge roadway width, curb-to-curb: 6 m = 19.7 ft		
Inventory Route, Total Horizontal Clearance: 6 m = 19.7 ft	Curb or sidewalk width - left: 0 m = 0.0 ft	Curb or sidewalk width - right: 0 m = 0.0 ft			

Deck structure type	Wood or Timber [8]
Type of wearing surface	Bituminous [6]
Deck protection	
Type of membrane/wearing surface	

Weight Limits

Bypass, detour length: 1.6 km = 1.0 mi	Method to determine inventory rating: No rating analysis performed [5]		Inventory rating: 32.4 metric ton = 35.6 tons		
	Method to determine operating rating: No rating analysis performed [5]		Operating rating: 40.5 metric ton = 44.6 tons		
	Bridge posting:		Design Load: MS 18 / HS 20 [5]		

Functional Details

Average Daily Traffic	354	Average daily truck traffi	5 %	Year	2004	Future average daily traffic	491
Year	2030						
Road classification	Local (Rural) [09]	Lanes on structure	2	Approach roadway width	9.8 m = 32.2 ft		
Type of service on bridge	Highway [1]	Direction of traffic	2 - way traffic [2]	Bridge median			
Parallel structure designation	No parallel structure exists. [N]						
Type of service under bridge	Waterway [5]	Lanes under structure	0	Navigation control	Not applicable, no waterway. [N]		
Navigation vertical clearanc	0 = N/A	Navigation horizontal clearance	0 = N/A				
Minimum navigation vertical clearance, vertical lift bridge		Minimum vertical clearance over bridge roadway	5.59 m = 18.3 ft				
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]						
Minimum lateral underclearance on right	0 = N/A	Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A	Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]				
Appraisal ratings - underclearances	N/A [N]						

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost

Roadway improvement cost

Length of structure improvement

Total project cost

Year of improvement cost estimate

Border bridge - state

Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Basically intolerable requiring high priority of corrrective action [3]
Condition ratings - superstructur	Serious [3]	Appraisal ratings - roadway alignment	Better than present minimum criteria [7]
Condition ratings - substructure	Fair [5]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of corrrective action [3]
Condition ratings - deck	Fair [5]		

Scour	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]
Channel and channel protection	Bank and embankment protection is severely undermined. River control devices have severe damage. Large deposits of debris are in the channel. [4]

Appraisal ratings - water adequacy	Superior to present desirable criteria [9]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	34.9

Culverts	Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings	Inpected feature meets currently acceptable standards. [1]
Traffic safety features - transitions	
Traffic safety features - approach guardrail	Inpected feature meets currently acceptable standards. [1]
Traffic safety features - approach guardrail ends	

Inspection date	December 2010 [1210]	Designated inspection frequency	12	Months

Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	December 2010 [1210]
Other special inspection	Not needed [N]	Other special inspection date	

District: **03** County **HURON** (101) Location: **0.4 MI W OF PERU CENTER** (102) Facility Carried: **STANDARDSBURG 90**
(2)FIPS Code: **RIDGEFIELD TWP** (103) Route On Bridge: **TOWNSHIP** (104) Route Under Bridge: **NON-HIGHWAY**
(9) Direction of Traffic: **2-WAY TRAFFIC** (10) Temporary: **N** (11)Truck Network: **N** (12)Parallel: **N**
(95) Insp: **COUNTY** (96) Maint: **COUNTY** (97) Routine: **COUNTY** (100) Type Serv: (On): **HIGHWAY** (Under): **WATERWAY**

Inventory Route Data

(3) Route On/Under: **ON** Hwy Sys: **COUNTY/TOWNSHIP HIGHWAY**
Route No.: **T0090** Dir: Des: **MAINLINE** Pref:
(4) Feature Intersected: **STANDRDSBRG/W BR HRN RVR**
(5) County: **RFT** Mileage: **0012** Special Desig:
(6) Avg. Daily Traffic(ADT): **354** (7) ADT Year: **2004**
(8) Truck Traf: **18** (14) NHS: **NO** - **X** (15) Corridor: **N**
(16) Functional Class: **LOCAL ROAD-RURAL** (19) Strahnt: **Not Applicable**

Intersected Route Data

(22) Route On/Under: Hwy Sys:
Route No.: Dir: Des: Pref:
(23) Feature Intersected:
(24) County: Mileage: Special Desig:
(25) Avg. Daily Traffic(ADT): **0** (26) ADT Year:
(27) Truck Traf: **0** (28) NHS: - (29) Corridor:
(30) Functional Class: (36) Strahnt: **Not Applicable**

Clearance On the Bridge

(154) Min Hriz on Bridge: NC: **0.0** Ft Card: **19.8** Ft
(155) Prac Max Vert On Brg: **18.4** Ft
(67) Min Vrt Clr On Brg: NC: **0.0** Ft Card: **18.3** Ft
(80) Min Latl Clr: NC: **0.0 / 0.0** Ft Card: **6.9 / 5.8** Ft
(81) Vrt Clr Lft: **0.0** Ft

Structure Information

(38) Bypass Length: **10** Miles
(39) Latitude: **41 Deg 13.0 Min** Longitude: **82 Deg 42.1 Min**
(40) Toll: **ON FREE ROAD**
(41) Date Built: **07/01/1926** (42) Major Rehabilitation: **01/01/1994**
(43) No. Lanes On: **2** No. Lanes Under: **0**
(44) Horiz Curve: **00 Deg. D00M Min.** (45) Skew: **0** Deg
(49) App. Rdw Width: **32** Ft (50) Brg. Rdw Width: **19.8** Ft
(51) Deck Width: **21.2** Ft Deck Area: **2713** Sq. Ft
(52) Median Type: **NONE** / **NON BARRIE** / **NO JOINT**
(53) Bridge Median: **NO MEDIAN**
(54) Sidewalks: (left) **0** Ft (right) **0** Ft
(55) Type Curb or Sidewalks:
(Left) Matl: **NONE** Type: **NONE**
(Right) Matl: **NONE** Type: **NONE**
(56) Flared: **N** (57) Composite: **non-composite**
(58) Railing: **TUBULAR BACKUP**
(59) Deck Drainage: **OVER THE SIDE (WITH DRIP STRIP)**
(60) Deck Type: **LAMINATED TIMBER STRIP**
(61) Deck Protection: External: **NONE**
Internal: **NONE**
(62) Wearing Surface: **BITUM (ASPHLT CONCRT)**
Thickness: **3.0** in (119) Date of Wearing Surface: **01/01/2006**
Slope Protection: **NONE-NATURAL PROTECTION(GRASS,BUSHES)**

(63) Main Spans Number: **1** Type: **STEEL** / **TRUSS** / **THRU**
Approach Spans Number: **0** Type: **NONE** / **NONE** / **NONE**
Total Spans: **1** (65) Max Span: **118** Ft (66) Overall Leng: **128** Ft

(70) Substructure	(71) Foundation and Scour Information	
Abut-Rear Matl: **CONCRETE**	Type: **SOLID WALL**	Fnd: **SPREAD FOOTING**
Abut-Fwd Matl: **CONCRETE**	Type: **PROPRIETARY WALL W/STUB T**	Fnd: **SPREAD FOOTING**
Pier-Pred Matl: **NONE**	Type: **NONE**	Fnd: **NONE/NOT APPLICABLE (SUCH AS CULVERTS)**
Pier-Other Matl: **NONE**	Type: **NONE**	Fnd: **NONE/NOT APPLICABLE (SUCH AS CULVERTS)**
Pier-Other Matl: **NONE**	Type: **NONE**	Fnd: **NONE/NOT APPLICABLE (SUCH AS CULVERTS)**
No of Piers Predominate: **NN**	Other: **NN**	Other: **NN**

(86) Stream Velocity: **000.0** (74) Scour: **STABLE: EVAL SCOUR ABOVE TOP OF FOOTING**
(189) Dive: **N Freq: 0** Probe: **Y** Freq: **12** (75) Chan Prot: **NONE**
(189) Date of last Dive Insp: (152) Drainage Area: **182** Sq Mi

Clearance Under the Bridge

(156) Min. Horiz Under Clear: NC: **0.0** Ft Card: **0.0** Ft
(157) Prac Max Vrt Under Clear: **0.0** Ft
(77) Min Vert Under Clear: NC: **0.0** Ft Card: **0.0** Ft
(78) Min Lat Under Clear: NC: **0.0 / 0.0** Ft Card: **0.0 / 0.0** Ft

Load Rating Information

(48) Design Load: **HS/20**
(83) Operating: **45** Ton
Inventory: **36** Ton
Ohio Percent of Legal Load **150**
Year of Rating: **2011**
(84) Analysis: **WORKING STRESS (WS)**
(85) Rate Soft: **BARS** Analyzed by:
Analysis on Bars: **NOT ON BARS [DEFAULT]**

(88-89) Appraisal

(Including calculated Items)
(88) Waterway Adequacy **9**
(89) Approach Alignment **7**
Calc Gen Appraisal: **2**
Calc Deck Geometry: **3**
Calc Underclearance: **N**

Approach Information

(109) Approach Guardrail: **STEEL BEAM**
(110) Approach Pavement: **BITUMINOUS** (111) Grade: **GOOD**

Culvert Information

(131) Culvert Type: **NONE/NOT APPLICBLE** (127) Length: **0.0** Ft
(129) Depth of Fill: **0.0** Ft (130) Headwalls: **NONE**

General Information

(121) Main Member **N/A (CULVERTS, TRUSSES, ETC.)** (122) Moment Plate: **NONE**
(169) Expansion Joint: **SLIDING METAL PLATE ANGLE**
(124) Bearing Devices: **ROCKERS/NONE**
(126) Navigation: **Control- X** Vert Clr: **0.0** Ft Horiz Clear:: **0.0** Ft
(193) Spec Insp: **N** Freq: **0** Date:
(188) Fracture Critical Insp: **Y** Freq: **24** Date: **2010-12-11**
(138) Long Member: **TWO TRUSSES (RIVETED)** (135) Hinges: **NOT APPLICABLE**
(141) Structural Steel Memb: **UNKNOWN** (139) Framing: **NONE**
Railing: **UNKNOWN**
Pay Wt: **110** pounds Prime Loc: **UNKNOWN** Paint: **OTHER**
Bridge Dedicated Name:

General Information (Continued)

(---) Hist Significance: **NOT HISTORIC**
(69) NBIS: **Y**
(---) Hist Builder: **UNKNOWN**
Hist Build Year: **1926**
(69) Hist Type: **WARREN (RIVETED)**
(161) Special Features (see below):
(105) Border Bridge State: Resp % (106) SFN:

Proposed Improvements

(90) Type Work: **-**
(90) Length: Ft
(90) Bridge Cost ($1000s): **0**
(90) Roadway Cost ($1000s): **0**
(90) Total Project Cost ($1000s): **0**
(90) Year:
(91) Future ADT (On Bridge): **0**
(92) Year of Future ADT: **2030**

Programming Info

PID Number:
PID Status:
PID Date:

Original Plans Information

(142) Fabricator:
(143) Contractor: **HURON CO HWY**
(144) Ohio Original Construction Project No.:
(---) Microfilm Reel:
(151) Standard Drawing:
Aperture Cards: Orig: **N** Repair: **N** Fabr: **N**
Plan Information Available: **1PLAN INFORMATION AVAILABLE**

(153) Repair Projects

1. **/ 020**	2. **/ 020**	3. **/ MMM**
4. **/ 044**	5. **940000 / 003**	6.
7.	8.	9.
10.		

Inspection Summary

(I-8) Deck:	**5**
(I-32) Superstructure:	**2**
(I-42) Substructure:	**5**
(I-50) Culvert:	
(I-54) Channel:	**4**
(I-60) Approaches:	**4**
(I-66) General Appraisial:	**2**
(I-66) Operational Status:	**P**
Inspection Date:	**06/04/2011**
(94) Desig Insp Freq:	**12 Months**

(I-69) Survey Items

Railings:	**1 MEETS CURRENT STANDARDS**
Transitions:	**0 DOES NOT MEET CURRENT STANDARDS**
Guardrail:	**1 MEETS CURRENT STANDARDS**
Rail Ends:	**0 DOES NOT MEET CURRENT STANDARDS**
In Depth:	**1 MEETS CURRENT STANDARDS**
Fracture Critical:	**1 MEETS CURRENT STANDARDS**
Scour Critical:	**N NONE N/A**
Critical Findings:	**N NONE N/A**
Insp. Update Date:	**07/18/2011**

Utilities

(46) Electric:	**N**
Gas:	**N**
Sanitary Sewer:	**N**
Telephone:	**N**
TV Cable:	**N**
Water:	**N**
Other:	**N**

Special Features

(161) Lighting:	**N**
Fencing:	**N**
Glare-Screen:	**N**
Splash-Guard:	**N**
Catwalks:	**N**
Other-Feat:	**N**
(184) Signs-on:	**N**
Signs-Under:	**N**
(162) Fence-Ht:	**0.0** Ft
(163) Noise Barr:	**N**

SFNs Replacing this retired bridge: **-**
SFNs That where replaced by this bridge: **-**
This bridge was retired and copied to:
The bridge was copied from:

INV Field Bridge Marker: **HUR-T0090-0012 -**
INT Field Bridge Marker: **---**

PONTIS CoRe elements and Condition States

Elem No.	CoRe Element Description	Total Quantity	Unit Meas.	Condition State Percents(*)				
				1	2	3	4	5
		0						

(*) Percentages Should add to 100%

STATE OF OHIO DEPARTMENT OF TRANSPORTATION

BRIDGE INSPECTION REPORT

BR-86 REV 02-95

3	9	3	1	0	7	2

1 Structure File Number 7

Bridge Number **HUR** (CO) **T0090** (ROUTE) **0012** (UNIT) **RIDGEFIELD TWP** **Date Built 07/01/1926 - 1994**

District **03** Bridge Type **STEEL/TRUSS/THRU** Type Service **1** **15 STANDRDSBRG/W BR HRN RVR** **HUR**

DECK Out/Out 21.2			2. Wearing Surface THCK = 3.0 6-BITUM (ASPHLT CONCRT) 41	2	
1. Floor 2-LAMINATED TIMBER STRIP 8	2				
3. Curbs, Sidewalks, Walkways N-NONE N-NONE 9			4. Median W.S. Date = 01/01/2006 42		
5. Railing A-TUBULAR BACKUP 10	1		6. Drainage 6-OVER THE SIDE (WITH DR 43	2	
7. Expansion Joints 2-SLIDING METAL PLATE AN 11	2		**8. Summary** 44	5	
SUPERSTRUCTURE MAX.SPAN=118					
9. Alignment 12	1		10. Beams/Girders/Slab N-N/A (CULVERTS, TRUSSES 45		
TOT.LGTH=128					
11. Diaphragms or Crossframes 13			12. Joists/Stringers 46	2	
13. Floor Beams 14	2		14. Floor Beam Connections 47	2	
15. Verticals 15	2		16. Diagonals 48	2	
17. End Posts 16	2		18. Top Chord 49	2	
19. Lower Chord 17	4		20. Lower Lateral Bracing 50		
21. Top Lateral Bracing 18			22. Sway Bracing 51	2	
23. Portals 19	2		24. Bearing Devices 2-ROCKERS N-NONE 52	3	
25. Arch 20			26. Arch Columns or Hangers 53		
27. Spandrel Walls 21			28. Protective Coating System TYPE = 0-OTHER DATE = 01/01/1980 54	3	
29. Pins/Hangers/Hinges 22			30. Fatigue Prone Connections 55	1	
31. Live Load Response 23	S		**32. Summary** 56	2	
SUBSTRUCTURE 2-CONCRETE			PIERS=0 SPANS = 1		
33. Abutments 2-CONCRETE 24	2		34. Abutment Seats 57	2	
35. Piers TYPE = N-NONE 25			36. Pier Seats 58		
37. Backwalls 26	2		ABUTMENT:=SPREAD / SPREAD 38. Wingwalls 59	2	
39. Fenders and Dolphins 27			40. Scour 8-STABLE: EVAL SCOUR ABO 60	1 2	
41. Slope Protection N-NONE 28			**42. Summary** DIVE DT=N/A 62	5	
CULVERTS					
43. General 29			44. Alignment 63		
45. Shape 30			46. Seams 64		
47. Headwalls or Endwalls 31			48. Scour 65		
49. 32			50. Summary 66		
CHANNEL					
51. Alignment 33	2		52. Protection N-NONE 67		
53. Waterway Adequacy 34	3		**54. Summary** 68	4	
APPROACHES					
55. Pavement 2-BITUMINOUS 35	1		56. Approach Slabs 69		
57. Guardrail 1-STEEL BEAM 36	1		58. Relief Joints 70		
59. Embankment BRDG.WIDTH=19.8 37	3		**60. Summary** PCT.LEGAL=150 71	4	
GENERAL					
61. Navigation Lights 38			62. Warning Signs ROUTINE.RESP: 3-COUNTY MAINT.RESP: 3-COUNTY 72	2	
MVC ON=18.3 UND=0000					
63. Sign Supports 39			64. Utilities 73		
65. Vertical Clearance 40	N		**66. General Appraisal & Operational Status** 74	COND 2	STAT P

67. INSPECTED BY

SIGNED

	5	5	4	8	8

76 PE

J	W	

78 INITIALS

68. REVIEWED BY

SIGNED

81 PE

83 INITIALS

DOT 2852

DECK AREA 2,713

Date | 0 | 6 | 0 | 4 | 1 | 1 | (86–91)

1	0	1	0	1	1	N	N

92 69 Survey 99

Date (100–105)

STATE OF OHIO DEPARTMENT OF TRANSPORTATION

BRIDGE INSPECTION REPORT

BR-86 REV 02-95

3	9	3	1	0	7	2

1 Structure File Number 7

Bridge Number **HUR** (CO) **T0090** (ROUTE) **0012** (UNIT)

Date Built 07/01/1926 - 1994

District **03** Bridge Type **STEEL/TRUSS/THRU**

Type Service **1** **1** **5**

STANDRDSBRG/W BR HRN RVR

00 NO REMARKS FOUND FOR THIS INSPECTION.