The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information							42-41-25 =	077-53-09 = -
New York [36]	Livingston County [05	1]	Mount Morris [48956]	2.3 MI S OF MOUNT	T MORRIS		42.690278	77.885833
3316420 Highway agency district 42		Owner County Highway	wner County Highway Agency [02] Maintenance responsibility			County Highway A	gency [02]	
Route 0 SWANSON ROAD			Toll On fre	Toll On free road [3] Features intersected BUCK RUN			CREEK	
Design - Aluminum, V Iron [9] 1 Truss - Thru	Vrought Iron or Cast	Design - approach O Other	[00]	Kilometerpoint 0 I Year built 1889 Skew angle 0 Historical significance	Structure F	constructed 1955 Flared is eligible for the N		
Total length 18.5 m = 60.7 ft Length of maximum span 17.9 m = 58.7 ft Deck width, out-to-out 3.4 m = 11.2 ft Bridge roadway width, curb-to-curb 3.2 m = 10.5 ft								
Inventory Route, Total Horizontal Clearance 3.2 m = 10.5 ft		Curb or sidewalk w	Curb or sidewalk width - left 0 m = 0.0 ft Curb		Curb or side	walk width - right	0 m = 0.0 ft	
Deck structure type Wood or Timber [8]								
Type of wearing surface Bituminous [6]								
Deck protection								
Type of membrane/wea	aring surface							
Weight Limits								
Bypass, detour length Method to determine inventory rational method.		ne inventory rating	Allowable Stress(AS) [2]		entory rating	rating 5.4 metric ton = 5.9 tons		
0.3 km = 0.2 mi Method to determine operating rating		Allowable Stress(AS) [2] O _j	erating rating	rating rating 10.9 metric ton = 12.0 tons			
	Bridge posting 3	30.0 - 39.9 % belo	w [1]	De	sign Load			

Functional Details								
Average Daily Traffic 39 Average daily tru	uck traffi 3 % Year 2008 Future average daily traffic 54 Year 2028							
Road classification Local (Rural) [09]	Lanes on structure 1 Approach roadway width 3 m = 9.8 ft							
Type of service on bridge Highway [1]	Direction of traffic One lane bridge for 2 - way traffic [3] Bridge median							
Parallel structure designation No parallel structure	e exists. [N]							
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control							
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A							
Minimum navigation vertical clearance, vertical lift brid	Minimum vertical clearance over bridge roadway 99.99 m = 328.1 ft							
Minimum lateral underclearance reference feature Fe	ature not a highway or railroad [N]							
Minimum lateral underclearance on right 99.9 = Unlimited Minimum lateral underclearance on left 0 = N/A								
Minimum Vertical Underclearance 0 = N/A Minimum vertical underclearance reference feature Feature not a highway or railroad [N]								
Appraisal ratings - underclearances N/A [N]								
Repair and Replacement Plans								
·	Work done by Work to be done by contract [1]							
Type of work to be performed	Work done by Work to be done by contract [1]							
Widening of existing bridge with deck rehabilitation or replacement. [34]	Bridge improvement cost 177000 Roadway improvement cost 106000							
	Length of structure improvement 18.5 m = 60.7 ft Total project cost 283000							
	Year of improvement cost estimate 2009							
	Border bridge - state Border bridge - percent responsibility of other state							
	Border bridge - structure number							

Inspection and Sufficiency									
Structure status Bridge close	ed to all traffic [K]	Appraisal ratings - structural							
Condition ratings - superstructur Serious [3]		Appraisal ratings - roadway alignment							
Condition ratings - substructure	Serious [3]	Appraisal ratings -							
Condition ratings - deck	Poor [4]	deck geometry							
Scour	Bridge foundations deter	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]							
Channel and channel protection		Bank and embankment protection is severely undermined. River control devices have severe damage. Large deposits of debris are in the channel. [4]							
Appraisal ratings - water adequae	Meets minimum tolerabl	Meets minimum tolerable limits to be left in place as is [4]			Structurally deficient [1]				
Pier or abutment protection					16.8				
Culverts Not applicable. Used if structure is not a culvert. [N]									
Traffic safety features - railings									
Traffic safety features - transition									
Traffic safety features - approac	h guardrail Inpecte	Inpected feature meets currently acceptable standards. [1]							
Traffic safety features - approach guardrail ends									
Inspection date August 2008	inspection frequency 12	Mont	ths						
Underwater inspection Not needed [N]		Underwater inspec	Underwater inspection date						
Fracture critical inspection	Every year [Y12]	Fracture critical ins	•	August 2008 [08	308]				
Other special inspection	Not needed [N]	Other special inspection date							