

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Illinois [17]	Bureau County [011]	Unknown [00000]	2 MI E OF MINERAL	41-23-12.55 = 4	089-47-57.08 = -8
6424800000000	Highway agency district: 3	Owner	Town or Township Highway Agency [03]	Maintenance responsibility	Town or Township Highway Agency [03]
Route 0	TR 0235	Toll	On free road [3]	Features intersected	COAL CREEK
Design - main	Steel [3]	Design - approach		Kilometerpoint	16.1 km = 10.0 mi
1	Truss - Thru [10]	0	Other [00]	Year built	1920
				Year reconstructed	
				Skew angle	0
				Structure Flared	
				Historical significance	Bridge is not eligible for the NRHP. [5]
Total length	26.7 m = 87.6 ft	Length of maximum span	25.1 m = 82.4 ft	Deck width, out-to-out	5.5 m = 18.0 ft
				Bridge roadway width, curb-to-curb	5.4 m = 17.7 ft
Inventory Route, Total Horizontal Clearance	5.3 m = 17.4 ft	Curb or sidewalk width - left	0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft
Deck structure type	Wood or Timber [8]				
Type of wearing surface	Wood or Timber [7]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length	Method to determine inventory rating		Inventory rating	0 metric ton = 0.0 tons
0.5 km = 0.3 mi	Method to determine operating rating		Operating rating	0 metric ton = 0.0 tons
	Bridge posting		Design Load	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Bridge closed to all traffic [K]	Appraisal ratings - structural	
Condition ratings - superstructure	Critical [2]	Appraisal ratings - roadway alignment	Equal to present minimum criteria [6]
Condition ratings - substructure	Fair [5]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of corrective action [3]
Condition ratings - deck	Satisfactory [6]		
Scour	Bridge foundations determined to be stable for assessed or calculated scour condition. [5]		
Channel and channel protection	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]		
Appraisal ratings - water adequacy	Better than present minimum criteria [7]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	35.7
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	August 2014 [0814]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Every year [Y12]	Other special inspection date	September 2013 [0913]