

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Indiana [18]	Delaware County [035]	Unknown [00000]	00.10 W of CR 450E	40-18-46 = 40.312778	085-18-23 = - 85.306389
1800036	Highway agency district 3	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 80	CR 850N	Toll On free road [3]	Features intersected	MISSISSINEWA River	
Design - main Steel [3]	Design - approach	Kilometerpoint 0 km = 0.0 mi	Year built 1902	Year reconstructed 1985	
1 Truss - Thru [10]	0 Other [00]	Skew angle 0	Structure Flared		
		Historical significance	Bridge is possibly eligible for the NRHP. [3]		
Total length 55.7 m = 182.8 ft	Length of maximum span 54.3 m = 178.2 ft	Deck width, out-to-out 5.1 m = 16.7 ft	Bridge roadway width, curb-to-curb 4.8 m = 15.7 ft		
Inventory Route, Total Horizontal Clearance 4.8 m = 15.7 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Wood or Timber [8]				
Type of wearing surface	Wood or Timber [7]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.5 km = 0.3 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	2.7 metric ton = 3.0 tons
	Method to determine operating rating	No rating analysis performed [5]	Operating rating	2.7 metric ton = 3.0 tons
	Bridge posting		Design Load	

Functional Details

Average Daily Traffic	116	Average daily truck traffi	1	%	Year	2003	Future average daily traffic	200	Year	2029
Road classification	Local (Rural) [09]		Lanes on structure	1	Approach roadway width	5.5 m = 18.0 ft				
Type of service on bridge	Highway [1]		Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0	Navigation control					
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	5.18 m = 17.0 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	1330000	Roadway improvement cost	115000						
	Length of structure improvement	67.1 m = 220.2 ft		Total project cost	1445000					
	Year of improvement cost estimate	2007								
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Posted for load [P]"/>	Appraisal ratings - structural	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - superstructure	<input type="text" value="Serious [3]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Basically intolerable requiring high priority of corrective action [3]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of corrective action [3]"/>
Condition ratings - deck	<input type="text" value="Very Good [8]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for assessed or calculated scour condition. [5]"/>		
Channel and channel protection	<input type="text" value="Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Better than present minimum criteria [7]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="18.7"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="August 2011 [0811]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Unknown [Y06]"/>	Fracture critical inspection date	<input type="text" value="October 2011 [1011]"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>