

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Iowa [19]	Tama County [171]	Unknown [07575]	0	41-57-49 = 41.963611	092-33-44 = - 92.562222
11250	Highway agency district 0	Owner County Highway Agency [02]	Maintenance responsibility	City or Municipal Highway Agency [04]	
Route 0	5TH ST E	Toll On free road [3]	Features intersected DRAINAGE		
Design - main Concrete [1]	Design - approach	Kilometerpoint 0 km = 0.0 mi	Year built 1915	Year reconstructed N/A [0000]	
1 Slab [01]	0 Other [00]	Skew angle 0	Structure Flared		
		Historical significance	Bridge is eligible for the NRHP. [2]		
Total length 6.7 m = 22.0 ft	Length of maximum span 6.1 m = 20.0 ft	Deck width, out-to-out 8.1 m = 26.6 ft	Bridge roadway width, curb-to-curb 7.3 m = 24.0 ft		
Inventory Route, Total Horizontal Clearance 7.3 m = 24.0 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.2 km = 0.1 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	29.3 metric ton = 32.2 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	48.9 metric ton = 53.8 tons
Bridge posting	Equal to or above legal loads [5]	Design Load		

Functional Details

Average Daily Traffic	867	Average daily truck traffi	0	%	Year	2009	Future average daily traffic	1288	Year	2030
Road classification	Collector (Urban) [17]	Lanes on structure	2	Approach roadway width	9.1 m = 29.9 ft					
Type of service on bridge	Highway [1]	Direction of traffic	2 - way traffic [2]		Bridge median					
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]	Lanes under structure	0	Navigation control						
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge	0 m = 0.0 ft			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft					
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A			Minimum lateral underclearance on left	0 = N/A					
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Other structural work, including hydraulic replacements. [38]	Bridge improvement cost	15000	Roadway improvement cost	2000						
	Length of structure improvement	22 m = 72.2 ft		Total project cost						
	Year of improvement cost estimate	2009								
	Border bridge - state		Border bridge - percent responsibility of other state							
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Somewhat better than minimum adequacy to tolerate being left in place as is [5]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Better than present minimum criteria [7]"/>
Condition ratings - substructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - deck geometry	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - deck	<input type="text" value="Fair [5]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]"/>		
Channel and channel protection	<input type="text" value="Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present minimum criteria [6]"/>	Status evaluation	<input type="text"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="66.1"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="September 2010 [0910]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>