

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26]	Dickinson County [043]	Waucedah [84700]	9 MI N OF WAUCEDAH	45-52-37 = 45.876944	087-45-09 = - 87.752500
2193	Highway agency district 1	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 2273	COUNTY HWY 569	Toll On free road [3]	Features intersected	STURGEON RIVER	
Design - main Concrete [1]	Design - approach	Kilometerpoint 1459.2 km = 904.7 mi	Year built 1923	Year reconstructed	
1	Girder and floorbeam system [03]	0	Other [00]	Skew angle 0	Structure Flared
		Historical significance		Bridge is on the NRHP. [1]	
Total length 22.8 m = 74.8 ft	Length of maximum span 21.9 m = 71.9 ft	Deck width, out-to-out 8.6 m = 28.2 ft	Bridge roadway width, curb-to-curb 6.7 m = 22.0 ft		
Inventory Route, Total Horizontal Clearance 6.7 m = 22.0 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 0.6 km = 0.4 mi	Method to determine inventory rating	Allowable Stress(AS) [2]	Inventory rating	33.6 metric ton = 37.0 tons
	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	57.3 metric ton = 63.0 tons
Bridge posting	Equal to or above legal loads [5]	Design Load		

Functional Details

Average Daily Traffic	400	Average daily truck traffi	7	%	Year	1997	Future average daily traffic	600	Year	217
Road classification	Major Collector (Rural) [07]	Lanes on structure	2	Approach roadway width	10.1 m = 33.1 ft					
Type of service on bridge	Highway [1]	Direction of traffic	2 - way traffic [2]		Bridge median					
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]	Lanes under structure	0	Navigation control						
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	245000	Roadway improvement cost	30000						
	Length of structure improvement	27.4 m = 89.9 ft		Total project cost	345000					
	Year of improvement cost estimate									
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Better than present minimum criteria [7]"/>
Condition ratings - superstructure	<input type="text" value="Good [7]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present minimum criteria [6]"/>
Condition ratings - substructure	<input type="text" value="Good [7]"/>	Appraisal ratings - deck geometry	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - deck	<input type="text" value="Good [7]"/>		
Scour	<input type="text" value="Bridge is scour critical; bridge foundations determined to be unstable. [3]"/>		
Channel and channel protection	<input type="text" value="Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Better than present minimum criteria [7]"/>	Status evaluation	<input type="text"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="82.9"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="October 2010 [1010]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>