

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

Michigan [26]	Berrien County [021]	Weesaw [85120]	0.25 MI E OF NEW TROY	41-52-29 = 41.874722	086-32-10 = - 86.536111
11200015000B010	Highway agency district 5	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 1127	GLENDORA ROAD	Toll On free road [3]	Features intersected E BR OF GALIEN RIVER		
Design - main Steel [3]	Design - approach	Kilometerpoint 156.9 km = 97.3 mi	Year built 1941	Year reconstructed N/A [0000]	
1	Stringer/Multi-beam or girder [02]	0	Other [00]	Skew angle 0	Structure Flared
		Historical significance Bridge is not eligible for the NRHP. [5]			
Total length 8.2 m = 26.9 ft	Length of maximum span 7.9 m = 25.9 ft	Deck width, out-to-out 8.5 m = 27.9 ft	Bridge roadway width, curb-to-curb 7.3 m = 24.0 ft		
Inventory Route, Total Horizontal Clearance 7.3 m = 24.0 ft	Curb or sidewalk width - left 0.3 m = 1.0 ft	Curb or sidewalk width - right 0.3 m = 1.0 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

**Weight Limits**

Bypass, detour length 0.5 km = 0.3 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	22.4 metric ton = 24.6 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	47.6 metric ton = 52.4 tons
Bridge posting	Equal to or above legal loads [5]		Design Load	MS 13.5 / HS 15 [3]

### Functional Details

Average Daily Traffic	1037	Average daily truck traffi	4	%	Year	2007	Future average daily traffic	1500	Year	2027
Road classification	Major Collector (Rural) [07]	Lanes on structure	2	Approach roadway width	9.1 m = 29.9 ft					
Type of service on bridge	Highway [1]	Direction of traffic	2 - way traffic [2]		Bridge median					
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]	Lanes under structure	0	Navigation control						
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited			Minimum lateral underclearance on left	0 = N/A					
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

### Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Bridge rehabilitation because of general structure deterioration or inadequate strength. [35]	Bridge improvement cost	45000	Roadway improvement cost	5000						
	Length of structure improvement	8.2 m = 26.9 ft		Total project cost	50000					
	Year of improvement cost estimate	2004								
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

## Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - superstructure	<input type="text" value="Poor [4]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Equal to present desirable criteria [8]"/>
Condition ratings - substructure	<input type="text" value="Satisfactory [6]"/>	Appraisal ratings - deck geometry	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - deck	<input type="text" value="Poor [4]"/>		
Scour	<input type="text" value="Bridge is scour critical; bridge foundations determined to be unstable. [3]"/>		
Channel and channel protection	<input type="text" value="Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present minimum criteria [6]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="42"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="May 2008 [0508]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>