

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

Michigan [26]	Bay County [017]	Pinconning [64180]	600 FT S WHITEFEATHER RD	43-53-41.97 = 43.894992	083-59-09.22 = -83.985894
709	Highway agency district: 4	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0	MACKINAW RD	Toll On free road [3]	Features intersected	WHITEFEATHER DRAIN	
Design - main Steel [3]	Design - approach Stringer/Multi-beam or girder [02]	0	Other [00]	Kilometerpoint 4133.3 km = 2562.6 mi	Year built 1937
1				Year reconstructed	Skew angle 0
				Structure Flared	Historical significance Bridge is not eligible for the NRHP. [5]
Total length 7.3 m = 24.0 ft	Length of maximum span 6.1 m = 20.0 ft	Deck width, out-to-out 9.2 m = 30.2 ft	Bridge roadway width, curb-to-curb 8.2 m = 26.9 ft		
Inventory Route, Total Horizontal Clearance 8.3 m = 27.2 ft	Curb or sidewalk width - left 0 m = 0.0 ft	Curb or sidewalk width - right 0 m = 0.0 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

**Weight Limits**

Bypass, detour length 0.6 km = 0.4 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	15.6 metric ton = 17.2 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	26 metric ton = 28.6 tons
Bridge posting		Design Load	M 13.5 / H 15 [2]	

### Functional Details

Average Daily Traffic	274	Average daily truck traffi	2	%	Year	2000	Future average daily traffic	438	Year	2020
Road classification	Major Collector (Rural) [07]		Lanes on structure	2	Approach roadway width	9.8 m = 32.2 ft				
Type of service on bridge	Highway [1]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0	Navigation control					
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

### Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	137000	Roadway improvement cost	8000						
	Length of structure improvement	9.1 m = 29.9 ft		Total project cost	145000					
	Year of improvement cost estimate									
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

## Inspection and Sufficiency

Structure status	Posted for load [P]	Appraisal ratings - structural	Basically intolerable requiring high priority of corrective action [3]
Condition ratings - superstructure	Serious [3]	Appraisal ratings - roadway alignment	Equal to present desirable criteria [8]
Condition ratings - substructure	Serious [3]	Appraisal ratings - deck geometry	Somewhat better than minimum adequacy to tolerate being left in place as is [5]
Condition ratings - deck	Poor [4]		
Scour	Bridge is scour critical; bridge foundations determined to be unstable. [3]		
Channel and channel protection	Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]		
Appraisal ratings - water adequacy	Equal to present minimum criteria [6]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	28.5
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings			
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	April 2018 [0418]	Designated inspection frequency	12 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	