The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Info	ormation										40-27-50 =	091-34-10 = -
lowa [19] Lee County [111]			Unknov	Unknown [00000] 650604				40.463889	91.569444			
603980		Hig	Highway agency district 5			Owner Local Toll Authority [32]			Maintenance	responsibility	Local Toll Author	ity [32]
Route 27			IA	27		Toll On free road [3]		Fe	Features intersected DES MOINES RIVER (TOLL)			
Design - main Steel [3] Truss - Thru [10]			approach	approach		Kilometerpoint 0 km = 0.0 mi Year built 1937 Year reconstructed N/A Skew angle 0 Structure Flared Historical significance Bridge is eligible for the N						
Total length 232.6 m = 763.2 ft Length of maximum spanning length Length				n = 228.0 ft Curb or sidewalk w	Deck widt		7.2 m = 23.6	ft Bridge roa		-curb 6.6 m = 21.7 ft 0.3 m = 1.0 ft		
Type of wearing surface Deck protection			Bituminous [6]	irridee [i]								
туре ог пг	embrane/we	earing Sun	iace									
Weight Li Bypass, c 6.4 km =	detour length	Metho		ermine inventory of the commine operating Equal to or about	_	o rating analysis pe o rating analysis pe s [5]		Оре	ntory rating rating rating Ign Load	16.9 metric ton 24 metric ton = 13.5 / H 15 [2]		

Functional Details	
Average Daily Traffic 3360 Average daily tr	uck traffi 35 % Year 2007 Future average daily traffic 6068 Year 2027
Road classification	[02] Lanes on structure 2 Approach roadway width 9.1 m = 29.9 ft
Type of service on bridge Highway [1]	Direction of traffic 2 - way traffic [2] Bridge median
Parallel structure designation No parallel structure	e exists. [N]
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A
Minimum navigation vertical clearance, vertical lift brid	dge 0 m = 0.0 ft Minimum vertical clearance over bridge roadway 4.24 m = 13.9 ft
Minimum lateral underclearance reference feature F	eature not a highway or railroad [N]
Minimum lateral underclearance on right 0 = N/A	Minimum lateral underclearance on left 0 = N/A
Minimum Vertical Underclearance 0 = N/A	Minimum vertical underclearance reference feature Feature not a highway or railroad [N]
Appraisal ratings - underclearances N/A [N]	
Repair and Replacement Plans	
Type of work to be performed	Work done by Work to be done by contract [1]
Bridge rehabilitation because of general structure deterioration or inadequate strength. [35]	Bridge improvement cost 755000 Roadway improvement cost 75000
deterioration of madequate strength. [50]	Length of structure improvement 232.6 m = 763.2 ft Total project cost 1132000
	Year of improvement cost estimate
	Border bridge - state Unknown [297] Border bridge - percent responsibility of other state
	Border bridge - structure number 25293

Inspection and Sufficiency										
Structure status Open, no res	striction [A]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4] Equal to present desirable criteria [8]							
Condition ratings - superstructur	Satisfactory [6]	Appraisal ratings - roadway alignment								
Condition ratings - substructure	Fair [5]	Appraisal ratings -	Basically intolerable requiring	high priority of replacement [2]						
Condition ratings - deck	Satisfactory [6]	deck geometry								
Scour	Scour calculation/e	Scour calculation/evaluation has not been made. [6]								
Channel and channel protection	Bank is beginning minor stream bed	to slump. River control devices and movement evident. Debris is restrict	embankment protection have wic iing the channel slightly. [6]	despread minor damage. There is						
Appraisal ratings - water adequace	Equal to present n	ninimum criteria [6]	Status evaluation	Functionally obsolete [2]						
Pier or abutment protection			Sufficiency rating	32.1						
Culverts Not applicable. Used	if structure is not a culvert	t. [N]								
Traffic safety features - railings	In	pected feature meets currently acce								
Traffic safety features - transitions										
Traffic safety features - approach										
Traffic safety features - approach	n guardrail ends									
Inspection date October 200	7 [1007] Design	nated inspection frequency 24	Months							
·	Unknown [N00]	Underwater inspec								
·	Every two years [Y24]	Fracture critical ins		[1007]						
Other special inspection	Unknown [N00]	Other special insp	ection date							

HistoricBridges.org - National Bridge Inventory Data Sheet

The National Bridge Inventory contains data submitted by state transportion departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Info	ormation										40-27-36 =	091-34-00 = -
Missouri [29] Clark County [045]		Des Moines [19234] S 5 T 65 N R 6			NR6W			40.460000	91.566667			
25293		Highway a	Highway agency district: 3		Owner	Owner County Highway Agency [02]		2]	Maintenance responsibility		County Highway Agency [02]	
Route 0000B		F	RT B S	ГВЅ		Toll On free road [3]			Features intersected DES MOINE		ES RVR	
Design - main Steel [3] Truss - Thru [10]			roach	Stringer/Multi-beam or girder [02]		Year built Skew ang	Kilometerpoint 0 km = 0.0 mi Year built 1937					
Total length 232.6 m = 763.2 ft Length of maximum spa Inventory Route, Total Horizontal Clearance 6.6 m = 21.7 ft					= 228.0 ft urb or sidewalk wi	Deck wid		o-out 7.2 m = 23.6	6 ft Bridge roa		0.2 m = 0.7 ft	
Deck prote	earing surface		Concret	e Cast-in-P	Place [1]							
Type of m	embrane/we	earing surface										
Weight Limits Bypass, detour length 6.4 km = 4.0 mi Method to determine inventory rating Method to determine operating rating				Allowable Stress(AS) [2] Allowable Stress(AS) [2]			Inventory rating Operating rating	17.1 metric ton 24.3 metric ton				
		Bridge postir	ng 00.1	- 09.9 % be	elow [4]				Design Load M	13.5 / H 15 [2]		

Functional Details	
Average Daily Traffic 451 Average daily tru	uck traffi 10 % Year 2007 Future average daily traffic 563 Year 2028
Road classification Local (Rural) [09]	Lanes on structure 2 Approach roadway width 9.1 m = 29.9 ft
Type of service on bridge Highway [1]	Direction of traffic 2 - way traffic [2] Bridge median
Parallel structure designation No parallel structure	e exists. [N]
Type of service under bridge Waterway [5]	Lanes under structure 0 Navigation control
Navigation vertical clearanc 0 = N/A	Navigation horizontal clearance 0 = N/A
Minimum navigation vertical clearance, vertical lift brid	Minimum vertical clearance over bridge roadway 4.22 m = 13.8 ft
Minimum lateral underclearance reference feature Fe	eature not a highway or railroad [N]
Minimum lateral underclearance on right 0 = N/A	Minimum lateral underclearance on left 0 = N/A
Minimum Vertical Underclearance 0 = N/A	Minimum vertical underclearance reference feature Feature not a highway or railroad [N]
Appraisal ratings - underclearances N/A [N]	
Repair and Replacement Plans	
Type of work to be performed	Work done by Work to be done by contract [1]
Replacement of bridge or other structure because of substandard load carrying capacity or substantial	Bridge improvement cost 4201000 Roadway improvement cost 420000
bridge roadway geometry. [31]	Length of structure improvement 23.3 m = 76.4 ft Total project cost 6301000
	Year of improvement cost estimate 2008
	Border bridge - state Unknown [197] Border bridge - percent responsibility of other state 1
	Border bridge - structure number 603980

Inspection and Sufficiency							
Structure status Posted for load [P]	Appraisal ratings - structural	Somewhat better than minimum adequacy to tolerate being left in place as is [5]					
Condition ratings - superstructure Sati	sfactory [6]	Appraisal ratings - roadway alignment	Equal to p	ria [8]			
Condition ratings - substructure Fair		Appraisal ratings -	Basically intolerable requiring high priority of replacement [2]				
Condition ratings - deck Fair	[5]	deck geometry					
Scour	Bridge foundations determined						
Channel and channel protection	Bank is beginning to slump. Ri minor stream bed movement ex	ver control devices and vident. Debris is restrict	embankment ting the chann	protection have wide el slightly. [6]	espread minor damage. There is		
Appraisal ratings - water adequacy	Equal to present minimum crite		Status evaluation	Functionally obsolete [2]			
Pier or abutment protection					44		
Culverts Not applicable. Used if stru	cture is not a culvert. [N]						
Traffic safety features - railings	Inpected featu	re meets currently acce	ptable standa	rds. [1]			
Traffic safety features - transitions							
Traffic safety features - approach guar	drail						
Traffic safety features - approach guar	drail ends						
Inspection date October 2007 [100	tion frequency 24	М	onths				
Underwater inspection Not n	eeded [N]	Underwater inspec	ction date				
Fracture critical inspection Every	two years [Y24]	Fracture critical ins	spection date	October 2007 [1	1007]		
Other special inspection Not n	eeded [N]	Other special insp	ection date				