

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

New York [36] Wayne County [117] Macedon [44160] 2.9 MI W JCT RTE 31F + C 43-04-30 = 43.075000 077-21-40 = - 77.361111

4437230 Highway agency district 47 Owner State Highway Agency [01] Maintenance responsibility State Highway Agency [01]

Route 0 NO WAYNEPORT ROAD Toll On free road [3] Features intersected ERIE CANAL

Design - main Steel [3] Design - approach Other [00] Kilometerpoint 0 km = 0.0 mi

1 Truss - Thru [10] 0 Other [00] Year built 1912 Year reconstructed 1965

Skew angle 0 Structure Flared

Historical significance Historical significance is not determinable at this time. [4]

Total length 56.6 m = 185.7 ft Length of maximum span 55.7 m = 182.8 ft Deck width, out-to-out 5 m = 16.4 ft Bridge roadway width, curb-to-curb 4.3 m = 14.1 ft

Inventory Route, Total Horizontal Clearance 4.3 m = 14.1 ft Curb or sidewalk width - left 0 m = 0.0 ft Curb or sidewalk width - right 0 m = 0.0 ft

Deck structure type Open Grating [3]

Type of wearing surface Other [9]

Deck protection

Type of membrane/wearing surface

Weight Limits

Bypass, detour length 0.3 km = 0.2 mi Method to determine inventory rating Load Factor(LF) [1] Inventory rating 24.5 metric ton = 27.0 tons

Method to determine operating rating Load Factor(LF) [1] Operating rating 37.2 metric ton = 40.9 tons

Bridge posting Equal to or above legal loads [5] Design Load M 13.5 / H 15 [2]

Functional Details

Average Daily Traffic	3251	Average daily truck traffi	2	%	Year	2009	Future average daily traffic	4499	Year	2029
Road classification	Local (Urban) [19]		Lanes on structure	1		Approach roadway width	6.7 m = 22.0 ft			
Type of service on bridge	Highway [1]		Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control	Navigation control on waterway (bridge permit required). [1]			
Navigation vertical clearanc	4.8 m = 15.7 ft			Navigation horizontal clearance	53.3 m = 174.9 ft					
Minimum navigation vertical clearance, vertical lift bridge				Minimum vertical clearance over bridge roadway	4.64 m = 15.2 ft					
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited				Minimum lateral underclearance on left	0 = N/A				
Minimum Vertical Underclearance	0 = N/A			Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]					
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by			Work to be done by contract [1]		
Bridge deck rehabilitation with only incidental widening. [36]	Bridge improvement cost	230000	Roadway improvement cost	131000		
	Length of structure improvement	56.6 m = 185.7 ft		Total project cost	361000	
	Year of improvement cost estimate	2009				
	Border bridge - state			Border bridge - percent responsibility of other state		
	Border bridge - structure number					

Inspection and Sufficiency

Structure status	Posted for other load-capacity restriction [R]	Appraisal ratings - structural	Somewhat better than minimum adequacy to tolerate being left in place as is [5]
Condition ratings - superstructure	Fair [5]	Appraisal ratings - roadway alignment	Basically intolerable requiring high priority of replacement [2]
Condition ratings - substructure	Satisfactory [6]	Appraisal ratings - deck geometry	Basically intolerable requiring high priority of replacement [2]
Condition ratings - deck	Fair [5]		
Scour	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]		
Channel and channel protection	Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]		
Appraisal ratings - water adequacy	Equal to present minimum criteria [6]	Status evaluation	Functionally obsolete [2]
Pier or abutment protection	Navigation protection not required [1]	Sufficiency rating	51.9
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - transitions			
Traffic safety features - approach guardrail	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - approach guardrail ends	Inspected feature meets currently acceptable standards. [1]		
Inspection date	August 2009 [0809]	Designated inspection frequency	24 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Every two years [Y24]	Fracture critical inspection date	August 2009 [0809]
Other special inspection	Not needed [N]	Other special inspection date	