

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

New York [36]	Allegany County [003]	Wellsville [79103]	1.5 MI S OF WELLSVILLE	42-06-02.58 = 42.100717	077-56-20.32 = -77.938978
2254400	Highway agency district: 61	Owner: Town or Township Highway Agency [03]	Maintenance responsibility: Town or Township Highway Agency [03]		
Route 0	WEIDRICK ROAD	Toll: On free road [3]	Features intersected: GENESEE RIVER		
Design - main: Steel [3]	Design - approach: Other [00]	Kilometerpoint: 111 km = 68.8 mi	Year built: 1953	Year reconstructed: 1995	
1	Truss - Thru [10]	Skew angle: 0	Structure Flared:	Historical significance: Bridge is not eligible for the NRHP. [5]	
Total length: 31.4 m = 103.0 ft	Length of maximum span: 30.4 m = 99.7 ft	Deck width, out-to-out: 5.2 m = 17.1 ft	Bridge roadway width, curb-to-curb: 4.9 m = 16.1 ft		
Inventory Route, Total Horizontal Clearance: 4.8 m = 15.7 ft	Curb or sidewalk width - left: 0 m = 0.0 ft	Curb or sidewalk width - right: 0 m = 0.0 ft			
Deck structure type: Wood or Timber [8]					
Type of wearing surface: Bituminous [6]					
Deck protection:					
Type of membrane/wearing surface: Other [9]					

Weight Limits

Bypass, detour length: 0.4 km = 0.2 mi	Method to determine inventory rating:	Inventory rating: 2.7 metric ton = 3.0 tons
	Method to determine operating rating:	Operating rating: 2.7 metric ton = 3.0 tons
Bridge posting:	Design Load: MS 18 / HS 20 [5]	

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status

Posted for load [P]

Appraisal ratings -
structural

Basically intolerable requiring high priority of corrective action [3]

Condition ratings - superstructure

Serious [3]

Appraisal ratings -
roadway alignment

Equal to present minimum criteria [6]

Condition ratings - substructure

Fair [5]

Appraisal ratings -
deck geometry

Basically intolerable requiring high priority of replacement [2]

Condition ratings - deck

Very Good [8]

Scour

Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]

Channel and channel protection

Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]

Appraisal ratings - water adequacy

Equal to present minimum criteria [6]

Status evaluation

Structurally deficient [1]

Pier or abutment protection

Sufficiency rating

28.5

Culverts

Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings

Inspected feature meets currently acceptable standards. [1]

Traffic safety features - transitions

Traffic safety features - approach guardrail

Traffic safety features - approach guardrail ends

Inspected feature meets currently acceptable standards. [1]

Inspection date

August 2018 [0818]

Designated inspection frequency

12

Months

Underwater inspection

Not needed [N]

Underwater inspection date

Fracture critical inspection

Every year [Y12]

Fracture critical inspection date

August 2018 [0818]

Other special inspection

Not needed [N]

Other special inspection date