

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Ohio [39] Hancock County [063] Blanchard [06838] 0.30 MI E SR 235 41-00-48 = 41.013333 083-46-54 = - 83.781667

3232239 Highway agency district: 1 Owner County Highway Agency [02] Maintenance responsibility County Highway Agency [02]

Route #Num! BLA TWP RD 84 Toll On free road [3] Features intersected OTTAWA CREEK (CLOSED)

Design - main Steel [3] Design - approach Other [00] Kilometerpoint 0 km = 0.0 mi

1 Truss - Thru [10] 0 Other [00] Year built #Num! Year reconstructed 1955

Skew angle 0 Structure Flared

Historical significance Bridge is not eligible for the NRHP. [5]

Total length 19.5 m = 64.0 ft Length of maximum span 18.9 m = 62.0 ft Deck width, out-to-out 4.9 m = 16.1 ft Bridge roadway width, curb-to-curb 4.7 m = 15.4 ft

Inventory Route, Total Horizontal Clearance 4.7 m = 15.4 ft Curb or sidewalk width - left 0 m = 0.0 ft Curb or sidewalk width - right 0 m = 0.0 ft

Deck structure type Wood or Timber [8]

Type of wearing surface Bituminous [6]

Deck protection Other [9]

Type of membrane/wearing surface Other [9]

Weight Limits

Bypass, detour length 0.3 km = 0.2 mi Method to determine inventory rating No rating analysis performed [5] Inventory rating 0 metric ton = 0.0 tons

Method to determine operating rating No rating analysis performed [5] Operating rating 0 metric ton = 0.0 tons

Bridge posting Design Load

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status	Bridge closed to all traffic [K]	Appraisal ratings - structural	
Condition ratings - superstructure	Poor [4]	Appraisal ratings - roadway alignment	Equal to present minimum criteria [6]
Condition ratings - substructure	Serious [3]	Appraisal ratings - deck geometry	Better than present minimum criteria [7]
Condition ratings - deck	Critical [2]		
Scour	Bridge foundations determined to be stable for the assessed or calculated scour condition. [8]		
Channel and channel protection	Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]		
Appraisal ratings - water adequacy	Equal to present desirable criteria [8]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	26
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - transitions	Not applicable or a safety feature is not required. [N]		
Traffic safety features - approach guardrail	Not applicable or a safety feature is not required. [N]		
Traffic safety features - approach guardrail ends	Not applicable or a safety feature is not required. [N]		
Inspection date	August 2009 [0809]	Designated inspection frequency	12 Months
Underwater inspection	Not needed [N]	Underwater inspection date	
Fracture critical inspection	Not needed [N]	Fracture critical inspection date	
Other special inspection	Not needed [N]	Other special inspection date	