

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.  
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

**Basic Information**

Oregon [41]	Multnomah County [051]	Portland [59000]	N. WILLAMETTE OVER BURLIN	45-34-55.76 = 45.582156	122-44-27.03 = -122.740842
51T102000000000	Highway agency district #Num!	Owner	Railroad [27]	Maintenance responsibility	Railroad [27]
Route 9950	WILLAMETTE BLVD	Toll	On free road [3]	Features intersected	BURLINGTON NORTHERN R&R
Design - main	Steel [3]	Design - approach	Steel [3]	Kilometerpoint	0 km = 0.0 mi
3	Truss - Deck [09]	2	Stringer/Multi-beam or girder [02]	Year built	1909
				Year reconstructed	N/A [0000]
				Skew angle	0
				Structure Flared	
				Historical significance	Bridge is eligible for the NRHP. [2]
Total length	103.6 m = 339.9 ft	Length of maximum span	27.7 m = 90.9 ft	Deck width, out-to-out	18.3 m = 60.0 ft
				Bridge roadway width, curb-to-curb	12.2 m = 40.0 ft
Inventory Route, Total Horizontal Clearance	12.2 m = 40.0 ft	Curb or sidewalk width - left	3 m = 9.8 ft	Curb or sidewalk width - right	3 m = 9.8 ft
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

**Weight Limits**

Bypass, detour length	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	25.4 metric ton = 27.9 tons
0.3 km = 0.2 mi	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	41.7 metric ton = 45.9 tons
	Bridge posting	Equal to or above legal loads [5]	Design Load	M 13.5 / H 15 [2]

### Functional Details

Average Daily Traffic	10361	Average daily truck traffi	10	%	Year	2010	Future average daily traffic	14844	Year	2030
Road classification	Collector (Urban) [17]		Lanes on structure	2		Approach roadway width	12.2 m = 40.0 ft			
Type of service on bridge	Highway-pedestrian [5]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Railroad [2]		Lanes under structure	0		Navigation control	Not applicable, no waterway. [N]			
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	30.48 m = 100.0 ft			
Minimum lateral underclearance reference feature	Railroad beneath structure [R]									
Minimum lateral underclearance on right	5 m = 16.4 ft					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	21.72 m = 71.3 ft		Minimum vertical underclearance reference feature	Railroad beneath structure [R]						
Appraisal ratings - underclearances	Equal to present minimum criteria [6]									

### Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	1198000	Roadway improvement cost	120000						
	Length of structure improvement	114 m = 374.0 ft		Total project cost	1916000					
	Year of improvement cost estimate	2011								
	Border bridge - state					Border bridge - percent responsibility of other state				
	Border bridge - structure number									

## Inspection and Sufficiency

Structure status	Open, no restriction [A]	Appraisal ratings - structural	Meets minimum tolerable limits to be left in place as is [4]
Condition ratings - superstructure	Poor [4]	Appraisal ratings - roadway alignment	Equal to present minimum criteria [6]
Condition ratings - substructure	Fair [5]	Appraisal ratings - deck geometry	Somewhat better than minimum adequacy to tolerate being left in place as is [5]
Condition ratings - deck	Poor [4]		
Scour	Bridge not over waterway. [N]		
Channel and channel protection	Not applicable. [N]		
Appraisal ratings - water adequacy	N/A [N]	Status evaluation	Structurally deficient [1]
Pier or abutment protection		Sufficiency rating	58.4
Culverts	Not applicable. Used if structure is not a culvert. [N]		
Traffic safety features - railings	Inspected feature meets currently acceptable standards. [1]		
Traffic safety features - transitions			
Traffic safety features - approach guardrail			
Traffic safety features - approach guardrail ends			
Inspection date	July 2016 [0716]	Designated inspection frequency	24 Months
Underwater inspection	Unknown [N00]	Underwater inspection date	
Fracture critical inspection	Unknown [N00]	Fracture critical inspection date	
Other special inspection	Unknown [N00]	Other special inspection date	