

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Pennsylvania [42]	Montgomery County [091]	Lower Frederick [44912]	1MI.S.ZIEGLERSVIL. 14A06	40-16-19 = 40.271944	075-28-23 = - 75.473056
460029027000000	Highway agency district 6	Owner State Highway Agency [01]	Maintenance responsibility	State Highway Agency [01]	
Route 29	GRAVEL PIKE	Toll On free road [3]	Features intersected SWAMP CREEK		
Design - main Steel [3]	Design - approach	Kilometerpoint 1831 km = 1135.2 mi	Year built 1947	Year reconstructed N/A [0000]	
3	Stringer/Multi-beam or girder [02]	0	Other [00]	Skew angle 50	Structure Flared
			Historical significance Bridge is not eligible for the NRHP. [5]		
Total length 58.5 m = 191.9 ft	Length of maximum span 18.9 m = 62.0 ft	Deck width, out-to-out 11.6 m = 38.1 ft	Bridge roadway width, curb-to-curb 9.1 m = 29.9 ft		
Inventory Route, Total Horizontal Clearance 9.1 m = 29.9 ft	Curb or sidewalk width - left 0.2 m = 0.7 ft	Curb or sidewalk width - right 1.5 m = 4.9 ft			
Deck structure type	Concrete Cast-in-Place [1]				
Type of wearing surface	Bituminous [6]				
Deck protection					
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length 1.4 km = 0.9 mi	Method to determine inventory rating	Load Factor(LF) [1]	Inventory rating	53.5 metric ton = 58.9 tons
	Method to determine operating rating	Load Factor(LF) [1]	Operating rating	88.9 metric ton = 97.8 tons
Bridge posting	Equal to or above legal loads [5]		Design Load	M 13.5 / H 15 [2]

Functional Details

Average Daily Traffic	14195	Average daily truck traffi	7	%	Year	2008	Future average daily traffic	16712	Year	2013
Road classification	Other Principal Arterial (Urban) [14]		Lanes on structure	2		Approach roadway width	12.2 m = 40.0 ft			
Type of service on bridge	Highway-pedestrian [5]		Direction of traffic	2 - way traffic [2]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge						Minimum vertical clearance over bridge roadway	10 m = 32.8 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by			Work to be done by contract [1]		
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	0	Roadway improvement cost	1000		
	Length of structure improvement	65 m = 213.3 ft		Total project cost	3000	
	Year of improvement cost estimate					
	Border bridge - state			Border bridge - percent responsibility of other state		
	Border bridge - structure number					

Inspection and Sufficiency

Structure status	<input type="text" value="Open, no restriction [A]"/>	Appraisal ratings - structural	<input type="text" value="Meets minimum tolerable limits to be left in place as is [4]"/>
Condition ratings - superstructure	<input type="text" value="Fair [5]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Better than present minimum criteria [7]"/>
Condition ratings - substructure	<input type="text" value="Poor [4]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of corrective action [3]"/>
Condition ratings - deck	<input type="text" value="Poor [4]"/>		
Scour	<input type="text" value="Bridge foundations determined to be stable for assessed or calculated scour condition. [5]"/>		
Channel and channel protection	<input type="text" value="Bank protection is being eroded. River control devices and/or embankment have major damage. Trees and rush restrict the channel. [5]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Superior to present desirable criteria [9]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="36"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text" value="Inspected feature meets currently acceptable standards. [1]"/>		
Inspection date	<input type="text" value="August 2007 [0807]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text" value="Not needed [N]"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Not needed [N]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Not needed [N]"/>	Other special inspection date	<input type="text"/>