

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26] Midland County [111] Jasper [41560] 0.65 MI. E OF LEWIS ROAD 00-00-00 = 0.000000 000-00-00 = 0.000000

56307H00002B010 Highway agency district 4 Owner County Highway Agency [02] Maintenance responsibility County Highway Agency [02]

Route 0 BALL ROAD Toll On free road [3] Features intersected LITTLE SALT CREEK

Design - main Steel [3] Design - approach Other [00] Kilometerpoint 0 km = 0.0 mi

1 Truss - Thru [10] 0 Other [00] Year built 1901 Year reconstructed N/A [0000]

Skew angle 0 Structure Flared

Historical significance Bridge is on the NRHP. [1]

Total length 12.8 m = 42.0 ft Length of maximum span 12.5 m = 41.0 ft Deck width, out-to-out 4.3 m = 14.1 ft Bridge roadway width, curb-to-curb 4 m = 13.1 ft

Inventory Route, Total Horizontal Clearance 4 m = 13.1 ft Curb or sidewalk width - left 0 m = 0.0 ft Curb or sidewalk width - right 0 m = 0.0 ft

Deck structure type Wood or Timber [8]

Type of wearing surface Wood or Timber [7]

Deck protection

Type of membrane/wearing surface

Weight Limits

Bypass, detour length 0.2 km = 0.1 mi Method to determine inventory rating No rating analysis performed [5] Inventory rating 0 metric ton = 0.0 tons

Method to determine operating rating No rating analysis performed [5] Operating rating 0 metric ton = 0.0 tons

Bridge posting Design Load MS 18+Mod / HS 20+Mod [6]

Functional Details

Average Daily Traffic Average daily truck traffi % Year Future average daily traffic Year

Road classification Lanes on structure Approach roadway width

Type of service on bridge Direction of traffic Bridge median

Parallel structure designation

Type of service under bridge Lanes under structure Navigation control

Navigation vertical clearanc Navigation horizontal clearance

Minimum navigation vertical clearance, vertical lift bridge Minimum vertical clearance over bridge roadway

Minimum lateral underclearance reference feature

Minimum lateral underclearance on right Minimum lateral underclearance on left

Minimum Vertical Underclearance Minimum vertical underclearance reference feature

Appraisal ratings - underclearances

Repair and Replacement Plans

Type of work to be performed

Work done by

Bridge improvement cost Roadway improvement cost

Length of structure improvement Total project cost

Year of improvement cost estimate

Border bridge - state Border bridge - percent responsibility of other state

Border bridge - structure number

Inspection and Sufficiency

Structure status

Bridge closed to all traffic [K]

Appraisal ratings -
structural

Condition ratings - superstructure

Appraisal ratings -
roadway alignment

Condition ratings - substructure

Appraisal ratings -
deck geometry

Condition ratings - deck

Scour

Scour calculation/evaluation has not been made. [6]

Channel and channel protection

Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]

Appraisal ratings - water adequacy

Equal to present minimum criteria [6]

Status evaluation

Structurally deficient [1]

Pier or abutment protection

Navigation protection not required [1]

Sufficiency rating

19.4

Culverts

Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings

Traffic safety features - transitions

Traffic safety features - approach guardrail

Traffic safety features - approach guardrail ends

Inspection date

June 1999 [0699]

Designated inspection frequency

24

Months

Underwater inspection

Unknown [N24]

Underwater inspection date

Fracture critical inspection

Unknown [N24]

Fracture critical inspection date

Other special inspection

Unknown [N24]

Other special inspection date