

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.
 Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26] St. Joseph County [149] Unknown [00000] IN MENDON

78315H00034B010 Highway agency district 7 Owner County Highway Agency [02] Maintenance responsibility County Highway Agency [02]

Route 0 BUCKNER ROAD Toll On free road [3] Features intersected ST. JOSEPH RIVER

Design - main Steel [3] Design - approach Other [00] Kilometerpoint Year built #Num! Year reconstructed N/A [0000]

1 Truss - Thru [10] 0 Other [00] Skew angle 0 Structure Flared Historical significance Historical significance is not determinable at this time. [4]

Total length 43 m = 141.1 ft Length of maximum span 42.4 m = 139.1 ft Deck width, out-to-out 4.9 m = 16.1 ft Bridge roadway width, curb-to-curb 4.9 m = 16.1 ft

Inventory Route, Total Horizontal Clearance 4.8 m = 15.7 ft Curb or sidewalk width - left 0 m = 0.0 ft Curb or sidewalk width - right 0 m = 0.0 ft

Deck structure type Wood or Timber [8]

Type of wearing surface Wood or Timber [7]

Deck protection

Type of membrane/wearing surface

Weight Limits

Bypass, detour length 0.3 km = 0.2 mi Method to determine inventory rating Inventory rating 0 metric ton = 0.0 tons

Method to determine operating rating Operating rating 3.4 metric ton = 3.7 tons

Bridge posting Design Load

Functional Details

Average Daily Traffic	0	Average daily truck traffi	0	%	Year	1990	Future average daily traffic	0	Year	2010
Road classification	Local (Rural) [09]		Lanes on structure	2		Approach roadway width	7.9 m = 25.9 ft			
Type of service on bridge	Highway [1]		Direction of traffic			Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge			Minimum vertical clearance over bridge roadway	5.79 m = 19.0 ft						
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	0 = N/A					Minimum lateral underclearance on left				
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]								
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	324000	Roadway improvement cost	24000						
	Length of structure improvement	51.5 m = 169.0 ft		Total project cost	430000					
	Year of improvement cost estimate									
	Border bridge - state				Border bridge - percent responsibility of other state					
	Border bridge - structure number									

Inspection and Sufficiency

Structure status

Bridge closed to all traffic [K]

Appraisal ratings -
structural

Condition ratings - superstructure

Serious [3]

Appraisal ratings -
roadway alignment

Condition ratings - substructure

Poor [4]

Appraisal ratings -
deck geometry

Condition ratings - deck

Imminent Failure [1]

N/A [N]

Scour

Channel and channel protection

Bank protection is in need of minor repairs. River control devices and embankment protection have a little minor damage. Banks and/or channel have minor amounts of drift. [7]

Appraisal ratings - water adequacy

Status evaluation

Structurally deficient [1]

Pier or abutment protection

Sufficiency rating

19.5

Culverts

Not applicable. Used if structure is not a culvert. [N]

Traffic safety features - railings

Traffic safety features - transitions

Traffic safety features - approach guardrail

Traffic safety features - approach guardrail ends

Inspection date

November 1991 [1191]

Designated inspection frequency

24

Months

Underwater inspection

Not needed [N]

Underwater inspection date

Fracture critical inspection

Not needed [N]

Fracture critical inspection date

Other special inspection

Not needed [N]

Other special inspection date