

HistoricBridges.org - National Bridge Inventory Data Sheet

2002 Inventory

The National Bridge Inventory contains data submitted by state transportation departments to the Federal Highway Administration in coded format.

Form Interface Design: www.historicbridges.org. Data Conversion Assistance By www.bridgehunter.com. None of the involved parties make any guarantee of accuracy.

Basic Information

Michigan [26]	Washtenaw County [161]	Bridgewater [10560]	BRIDGWATER TWP SEC 20	00-00-00 = 0.000000	000-00-00 = - 0.000000
81317H00012B010	Highway agency district 6	Owner County Highway Agency [02]	Maintenance responsibility	County Highway Agency [02]	
Route 0		WILBUR ROAD	Toll On free road [3]	Features intersected	RIVER RAISIN
Design - main	Steel [3]	Design - approach		Kilometerpoint	0 km = 0.0 mi
1	Truss - Thru [10]	0	Other [00]	Year built	1953
				Year reconstructed	1953
				Skew angle	0
				Structure Flared	
				Historical significance	Bridge is on the NRHP. [1]
Total length	31.4 m = 103.0 ft	Length of maximum span	30.4 m = 99.7 ft	Deck width, out-to-out	3.6 m = 11.8 ft
Inventory Route, Total Horizontal Clearance	3.2 m = 10.5 ft	Curb or sidewalk width - left	0 m = 0.0 ft	Curb or sidewalk width - right	0 m = 0.0 ft
Deck structure type	Wood or Timber [8]				
Type of wearing surface	Latex Concrete or similar additive [3]				
Deck protection	Epoxy Coated Reinforcing [1]				
Type of membrane/wearing surface					

Weight Limits

Bypass, detour length	Method to determine inventory rating	No rating analysis performed [5]	Inventory rating	0 metric ton = 0.0 tons
1.1 km = 0.7 mi	Method to determine operating rating	Allowable Stress(AS) [2]	Operating rating	0 metric ton = 0.0 tons
	Bridge posting		Design Load	M 9 / H 10 [1]

Functional Details

Average Daily Traffic	160	Average daily truck traffi	0	%	Year	2001	Future average daily traffic	240	Year	2021
Road classification	Local (Rural) [09]		Lanes on structure	1		Approach roadway width	4.8 m = 15.7 ft			
Type of service on bridge	Highway [1]		Direction of traffic	One lane bridge for 2 - way traffic [3]		Bridge median				
Parallel structure designation	No parallel structure exists. [N]									
Type of service under bridge	Waterway [5]		Lanes under structure	0		Navigation control				
Navigation vertical clearanc	0 = N/A		Navigation horizontal clearance	0 = N/A						
Minimum navigation vertical clearance, vertical lift bridge	0 m = 0.0 ft					Minimum vertical clearance over bridge roadway	99.99 m = 328.1 ft			
Minimum lateral underclearance reference feature	Feature not a highway or railroad [N]									
Minimum lateral underclearance on right	99.9 = Unlimited					Minimum lateral underclearance on left	0 = N/A			
Minimum Vertical Underclearance	0 = N/A		Minimum vertical underclearance reference feature	Feature not a highway or railroad [N]						
Appraisal ratings - underclearances	N/A [N]									

Repair and Replacement Plans

Type of work to be performed	Work done by	Work to be done by contract [1]		
Replacement of bridge or other structure because of substandard load carrying capacity or substantial bridge roadway geometry. [31]	Bridge improvement cost	0	Roadway improvement cost	0
	Length of structure improvement	37.8 m = 124.0 ft	Total project cost	0
	Year of improvement cost estimate			
	Border bridge - state		Border bridge - percent responsibility of other state	
	Border bridge - structure number			

Inspection and Sufficiency

Structure status	<input type="text" value="Posted for load [P]"/>	Appraisal ratings - structural	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - superstructure	<input type="text" value="Critical [2]"/>	Appraisal ratings - roadway alignment	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - substructure	<input type="text" value="Poor [4]"/>	Appraisal ratings - deck geometry	<input type="text" value="Basically intolerable requiring high priority of replacement [2]"/>
Condition ratings - deck	<input type="text" value="Fair [5]"/>		
Scour	<input type="text" value="Bridge is scour critical; field review indicates that extensive scour has occurred at bridge foundations. [2]"/>		
Channel and channel protection	<input type="text" value="Bank is beginning to slump. River control devices and embankment protection have widespread minor damage. There is minor stream bed movement evident. Debris is restricting the channel slightly. [6]"/>		
Appraisal ratings - water adequacy	<input type="text" value="Equal to present desirable criteria [8]"/>	Status evaluation	<input type="text" value="Structurally deficient [1]"/>
Pier or abutment protection	<input type="text"/>	Sufficiency rating	<input type="text" value="13.5"/>
Culverts	<input type="text" value="Not applicable. Used if structure is not a culvert. [N]"/>		
Traffic safety features - railings	<input type="text"/>		
Traffic safety features - transitions	<input type="text"/>		
Traffic safety features - approach guardrail	<input type="text"/>		
Traffic safety features - approach guardrail ends	<input type="text"/>		
Inspection date	<input type="text" value="June 2001 [0601]"/>	Designated inspection frequency	<input type="text" value="24"/> Months
Underwater inspection	<input type="text"/>	Underwater inspection date	<input type="text"/>
Fracture critical inspection	<input type="text" value="Unknown [N00]"/>	Fracture critical inspection date	<input type="text"/>
Other special inspection	<input type="text" value="Unknown [N00]"/>	Other special inspection date	<input type="text"/>